1/ 70% 79% 75% 65% 100% 65% 38%	water Falls    12/2008	Stage 3 Weel
1/ 70% 79% 75% 65% 100% 65% 38%	12/2008	
70% 79% 75% 65% 100% 65% 38%	Date inspected	Weel
79% 75% 65% 100% 65% 38%		Weel
79% 75% 65% 100% 65% 38%		Weel
75% 65% 100% 65% 38%		Weel
65% 100% 65% 38%		Weel
100% 65% 38%		Weel
65% 38%		Weel
38%		Weel
		Weel
		Weel
	12/14/07	
	12/14/07	
	12/14/07	
	12/14/07	
	12/14/07	
	12/14/07	
		Weel
		Weel
	12/27/07	
00"		Week 4
	Nono: 1/10/09	
	1/4/2000, NULLE	
00	I	
	00" 03" 00" 00" 01" 00" 00"	03"  00"    00"  00"    01"  None; 1/10/08    00"  1/4/2008; None

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :

Entire Site, grading completed and entire site seeded prior to 2005.

What temporary or permanent stabilization measures listed in this section are being implemented?

Paving, dense vegetation and landscaping

## Comments:

## Comments:

Home construction is active in various areas of the development. Drainage Basin 3 area sanitary and storm sewer construction is on hold due to the winter conditions.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1) No required maintenance in the BMP section.

			Projected		Maintenance		
Unique Name	Туре	Location	Install Date	Status	Scheduled		
		N41d00m00s					
SB 1	Sediment Basin	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition - 10% Filled						
		N41d00m00s					
SB 2	Sediment Basin	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition - 16% Filled						
		N41d00m00s					
SB 3	Sediment Basin	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition-10% Filled						
	-Cleaned out 02/06						
		N41d00m00s					
SB 4	Sediment Basin	W96d00m00s		Removed			
Current Condition:	Removed per Hill-Farrell co	nstruction.					
		N41d00m00s					
SF 1	Silt Fence	W96d00m00s	In Place	Active	No		
Current Condition:	Good Overall Condition						
		N41d00m00s					
SF 2	Silt Fence	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition						
	-Maintenanced 6/7/07						
		N41d00m00s					
SF 3	Silt Fence	W96d00m00s		Removed			
Current Condition:	Removed due to home con	struction.					
		N41d00m00s					
SF 4	Silt Fence	W96d00m00s		Removed			
Current Condition:	Removed due to home construction.						
		N41d00m00s					
SF 5	Silt Fence	W96d00m00s		Removed			
Current Condition:	Removed due to home con	Removed due to home construction.					
		N41d00m00s					
SF 6	Silt Fence	W96d00m00s		Removed			
Current Condition:	Removed due to road cons	·					
		N41d00m00s					
SF 7	Silt Fence	W96d00m00s	In Place	Active	No		
Current Condition:	Good Overall Condition						
	-Maintenanced 05/08/07	-			-		
		N41d00m00s					
SF 8	Silt Fence	W96d00m00s	In Place	Active	No		

Current Condition:	Good Condition -Maintenanced 6/7/07				
		N41d00m00s			
SF 9	Silt Fence	W96d00m00s	In Place	Active	No
Current Condition:	Good Condition				
	-Maintenanced 6/7/07				
		N41d00m00s			
SF 10	Silt Fence	W96d00m00s	In Place	Active	No
Current Condition:	Good Overall Condition				
	-Maintenanced 05/08/07				
		N41d00m00s			
SF 11	Silt Fence	W96d00m00s	In Place	Active	No
Current Condition:	Good Overall Condition				
	-Maintenanced 03/06/06.				
		N41d00m00s			
SF 12	Silt Fence	W96d00m00s	In Place	Active	No
Current Condition:	Good Overall Condition				
	-Maintenanced 05/08/07				
		N41d00m00s			
STR	Street Cleaning	W96d00m00s	5/1/2007	Active	No
Current Condition:	Good Condition - No major	signs of track-off.			
Inspector's Signature:	plached Jawlom		Reviewed By:	Zadhany K.	Jilel