E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager E & A CONSULTING GROUP, INC.

ENGINEERING • PLANNING • ENVIRONMENTAL & FIELD SERVICES

| nspector: Patrick Sechser | | | | Stage | | |
|--|---|--|---|-------|--|--|
| Project Name: | | Clearwater Falls NER110573 | | | | |
| | | 8/23/2014 48th and Fairview Road- Bellevue, NE (Sarpy County) | | | | |
| For Week Ending: Project Location: | 49th an | | | | | |
| roject Location: | 46th an | d Fairview Road- D | ellevue, NE (Sarpy County) | 68123 | | |
| Brading: | 1009 | 1 | | | | |
| Sanitary Sewer: | 1009 | | | | | |
| Storm Sewer: | 1007 | | | | | |
| Paving: | 1007 | | | | | |
| Geeding: | 1007 | | | | | |
| Itilities: | 989 | | | | | |
| Overall Development: | 669 | | | | | |
| | | | | | | |
| AIN FALL AMOUNTS | Amount in tenths | Date inspected | | Wee | | |
| unday: | 0.17" | | | Weel | | |
| londay. | 0.00" | | | | | |
| uesday | 0.00" | 1 | | | | |
| Vednesday | 0.00" | 1 | | | | |
| hursday | 0.00" | 1 | | | | |
| riday | 0.37" | | | | | |
| Saturday | 0.01" | | | | | |
| unday: | 0.00" | | | Wee | | |
| londay | 0.02" | | | | | |
| uesday | 0.00" | | | | | |
| Vednesday | 0.00" | | | | | |
| hursday | 0.05" | 08/21/14 | 95/73 Mostly Cloudy | | | |
| Friday | 0.47" | 08/22/14 | 91/73 Partly Cloudy | | | |
| Saturday | 2.74" | 8/23/2014 | 89/70 Sunny | | | |
| unday: | N/A | N/A | | Wee | | |
| londay | N/A | N/A | | | | |
| uesday | N/A | N/A | | | | |
| Vednesday | N/A | N/A | | | | |
| hursday | N/A | N/A | | | | |
| riday | N/A | N/A | | | | |
| aturday | N/A | N/A | | | | |
| | None | | | | | |
| Complaints: | NOTE | | | | | |
| | | | | | | |
| | | | | | | |
| Construction Sequencing: | | | | | | |
| Vhich portion(s) (i.e. drainage basins) of the | site have had a temporary or permanent c | essation of grading, ea | rthwork, or ground disturbance in the last 14 o | lays? | | |
| Brading completed and entire site seed | • | Il droipogo oron 4 - | nd 2 (11/2000) | | | |
| ntire Site; JC Excavating completed g | | | nu ∠ (11/2009). | | | |
| hich portion(s) (i.e. drainage basins) of the | site do not have grading, earthwork, or gre | ound disturbance sche | duled in the next 14 days? : | | | |
| | | | 2 ° | | | |
| | | | | | | |
| rading completed and entire site seed ntire Site; JC Excavating completed g | rading Lots 346 through 480 Section | | nd 2 (11/2009). | | | |
| rading completed and entire site seed | rading Lots 346 through 480 Section | | nd 2 (11/2009). | | | |

Paving, dense vegetation and landscaping, Seed and straw mulch over ROW in Northwest quarter of SID (10/08), Sod on various lots (Fall '08), New phase, lots 346-480, seeded (4/10); Outlot B was seeded (6/2011); Lots 16-19 was seeded (8/2011); Outlot L was graded, seed and matted (5/22/2014); 42nd Street and 43rd Avenue was temp seeded (5/22/2014); Additional matting was installed on the South side of Outlot L (8/4/2014). Comments: Comments: Celebrity Homes is actively building in the South part of the development. Home Construction is active in the North part of the development by various builders. Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Section. Unique Name Projected Install Date Maintenance Туре Location Status N41d00m00s CE 1 Construction Entrance W96d00m00s Removed Current Condition: Removed-Entrance area was removed and concrete removed by Celebrity Homes prior to the inspection on 12/3/2013 for sidewalk installation. Concrete Washout Lot 348 Removed **Current Condition:** Removed- Bob w/ Celebrity Homes removed washout pit prior to inspection on 8/27/2013. Concrete Washout Lot 414 Removed CW 4 **Current Condition:** Removed-Washout pit was removed by Celebrity Homes prior to the inspection on 4/8/2014. CW 5 Concrete Washout Lot 387 5/12/2014 No Active Current Condition: Good condition-A new washout pit was installed by Celebrity Homes prior to the inspection on 6/27/2014. Lot 15 Silt Fence Lot 15 6/21/2014 Active Yes **Current Condition:** Fair condition- SF was installed on the side of the lot prior to the inspection on 6/21/2014 by Horizon Homes. SF on the East side needs to be entrenched/backfilled. Horizon Homes was informed to complete maintenance by 7/4/2014. Not completed as of the last inspection. Horizon Homes was reminded on 7/15/2014 and on 8/5/2014. Silt Fence Lot 26 Removed Lot 26 Removed-Lot was sodded by Horizon Homes prior to the inspection on 10/29/2013. **Current Condition:** Silt Fence Lot 27 Removed Current Condition: Removed-Lot was sodded by Horizon Homes prior to the inspection on 10/29/2013. Lot 30 Removed Lot 30 Silt Fence Current Condition: Removed- Horizon Homes removed the SF, cleaned up the dirt and sodded the lot prior to the 4/28/2014 inspection. Silt Fence Lot 54 Lot 54 6/18/2014 Active Current Condition: Fair condition- Nick Peterson stood up and extended the SF in the rear prior to the inspection on 8/4/2014. SF needs to be entrenched in the rear as of the inspection on 8/4/2014. Private homeowner Nick Peterson was informed to complete maintenance by 8/11/2014. Not done as of last inspection. Silt Fence Lot 55 Removed Removed-Lot was sodded prior to inspection on 7/16/13 by The Home Company. **Current Condition:** Lot 56 Silt Fence Lot 56 Removed **Current Condition** Removed-The lot was sodded by the home owner prior to the inspection on 5/22/2014. Lot 57 8/11/2014 Yes Silt Fence Lot 57 Active Current Condition: Fair Condition-Silt fence was installed on the North side of the lot by Horizon Homes prior to inspection on 8/21/14. SF is needed in the rear of the lot due to the new excavation. Horizon Homes was requested to install silt fence by 8/11/14. Not done as of last inspection. Silt Fence Lot 72 Removed Current Condition Removed-Lot was sodded by Horizon Homes prior to the inspection on 7/15/2014. Lot 76 Silt Fence Lot 76 6/27/2014 Active No **Current Condition:** Good condition-Proline Homes installed SF in the rear and side of the lot prior to the inspection on 6/27/2014. Lot 80 Lot 80 Silt Fence 8/23/2014 Active No Current Condition: Good condition- Horizon Homes installed SF on the North and Northwest side of the lot prior to the inspection on 8/23/2014. Silt Fence Lot 132 Lot 132 8/11/2014 Active No

| Current Condition: | Good condition- The store 8/21/14. Silt fence was re | | | | | | |
|-------------------------------|---|--|---------------------------------------|---------------------|------------------|--|--|
| Lot 155 | Silt Fence | Lot 155 | 8/11/2014 | Active | Yes | | |
| Current Condition: | Fair condition- The stockpi Silt fence on the Eastern fr | le was removed from the R | OW by Regency Home | s prior to inspect | tion on 8/21/14. | | |
| | | Following rough grading, silt fence is needed on the West side of the lot as of inspection on 8/21/14. | | | | | |
| | Regency Homes was requ | ested to install silt fence by | / 8/28/14. | | | | |
| Lot 255 | Silt Fence | Lot 255 | 8/4/2014 | Pending | Yes | | |
| Current Condition: | | sted to install silt fence by 8 | | | | | |
| Lot 264 | Misc/other | lot 264 | | Removed | | | |
| Current Condition: Lot 268 | Removed- Lot was sodded Misc/other | by Proline Homes prior to Lot 268 | the inspection on 8/4/20 | 14. Removed | | | |
| Current Condition: | Removed-Sherwood Home | | e inspection on 10/15/20 | | | | |
| Lot 271 | Misc/other | Lot 271 | | Removed | | | |
| Current Condition: | Removed-The lot was sode | | prior to the inspection of | | | | |
| Lot 277 | Silt Fence | Lot 277 | | Removed | | | |
| Current Condition: | Removed-Dumpster and P installation. Silt Fence | P were removed on site pr | lor to 7/30/2013 by the ⊢ | lome Company o | due to sod | | |
| Current Condition: | Removed-Charleston Hom | | he inspection on 7/15/20 | | as moved to lo | | |
| | 279. | · · · · · · · · · · · · · · · · · · · | · · · · · · · · · · · · · · · · · · · | | | | |
| Lot 279 | Silt Fence | Lot 279 | 7/15/2014 | Active | No | | |
| Current Condition: | Good condition-Charleston 7/15/14. The lot does not I | | | ne lot prior to ins | pection on | | |
| Lot 283 | Silt fence | Lot 283 | | Removed | | | |
| Current Condition: | | by Sherwood Homes prior | r to the inspection on 6/1 | | 1 | | |
| Lot 286 Current Condition: | Silt fence Sherwood Homes installed | Lot 286 | on 7/30/2013 | Removed | | | |
| Lot 287 | Silt fence | Lot 287 | 0117/30/2013. | Removed | | | |
| Current Condition: | Tom w/ The Home Compa | | inspection on 7/30/2013 | | | | |
| Lot 304 | Misc/other | Lot 304 | | Removed | | | |
| Current Condition: | Removed- Lot was sodded | | the inspection on 7/5/20 | | | | |
| Lot 305 Current Condition: | Silt Fence Removed-Silt fence was re | Lot 305 | inspection on 7/8/13 by | Removed | due to sidewall | | |
| Lot 309 | construction being active in | | | Removed | | | |
| Current Condition: | Removed-The lot was sode | | prior to inspection on 8/2 | | | | |
| Lot 311 | Silt Fence | Lot 311 | | Removed | | | |
| Current Condition: | Removed-Heavican Home | | e inspection on 8/13/201 | | | | |
| Lot 312 | Silt Fence Removed-Banyan Homes | Lot 312 | d SE in the rear prior to t | Removed | | | |
| Current Condition: Lot 313 | Silt Fence | Lot 313 | u or in the rear prior to | Removed | 1 4/20/2014. | | |
| Current Condition: | Removed-Lot 313 was sod | ded by Showcase Homes | prior to inspection on 8/2 | | removed prior | | |
| | to inspection on 9/11/2013 | , | | • | | | |
| Lot 322 | Silt Fence | Lot 322 | | Removed | | | |
| Current Condition: | Removed- Lot was sodded | | to the inspection on 6/18 | | | | |
| Lot 323 Current Condition: | Misc/other Removed-Lot was sodded | Lot 323 | to the inspection on 10/ | Removed | I | | |
| Lot 328 | Misc/other | Lot 328 | 9/19/2013 | Active | Yes | | |
| Current Condition: | | ave been installed as of ins | | | | | |
| | | Sod needed on the lot for final stabilization. Sherwood Homes was informed to complete the stabilization by 5/26/2014. Not completed as of the last | | | | | |
| | inspection. Sherwood Homes | | | - completed do | | | |
| Lot 331 | Silt Fence | Lot 331 | | Removed | | | |
| Current Condition: | Removed-Lot was sodded | | to the inspection on 11/2 | | | | |
| Lot 333 | Silt Fence Removed- All of the torn a | Lot 333 | oved along the netter of | Removed | to increation | | |
| Current Condition: | 8/27/2013 by Regency Hor prior to inspection on 9/1/2 | nes. Gator guards were rei | • • | | • | | |
| Lot 335 | Silt Fence | Lot 335 | 5/22/2014 | Active | No | | |
| LUI 333 | Sittence | LUI 333 | 5/22/2014 | ACIIVE | INU | | |

| SF nee | Silt Fence Indition- The lot was f | Lot 338 | 4/14/2014 | Active | Yes |
|---|---|--|--|---|-----------------|
| Current Condition: Fair co | | | 1/11/2011 | | TAS |
| SF nee | | | ion on 8/21/14. | , 101170 | |
| | | from behind the lot as of t ete SF maintenance by 6/ | he inspection on 6/4/201 | | pection. |
| Lot 339 | Misc/other | Lot 339 | | Removed | |
| | ved-Lot 338 items will 2013. Seeding is no lo | be removed for pending honger needed. | nome construction on lot | 338 as of inspec | tion on |
| Lot 341 | Silt Fence | Lot 341 | | Removed | |
| | | the silt fence was remove on on 6/23/13 by Castlebr | | Castlebridge Ho | mes. The lot |
| Lot 342 | Silt Fence | Lot 342 | | Removed | |
| | | sodded the lot prior to ins | pection on 8/21/14. | | |
| Lot 343 | Misc/other | Lot 343 | | Removed | |
| | | Homes sodded the lot pri | or to the inspection on 6/ | | |
| Outlot D | Misc/other | Outlot D | range tion on 7/0/10 | Removed | |
| Current Condition: The dis | Silt Fence | he inlet has filled in as of i Lots 225-254 | nspection on 7/8/13. 9/4/2012 | Active | No |
| | condition- | LUIS 223-234 | 9/4/2012 | Active | INU |
| | | 6 was repaired by Comm | ercial Seeding prior to th | e inspection on s | 5/28/2014. |
| Pod B | Silt Fence | Lots 212-224 | | Removed | |
| | | n sodded as of inspection | on 6/25/11. | | |
| Pod C | Silt Fence | Lots 175-183; 474-480 | | Removed | |
| | | ave been removed due to | | | on 10/14/12 by |
| | | omes. All other remaining | iots in this pod has been | | |
| Pod D Current Condition: All rem | Silt Fence | Lots 199-210 | a increation on 0/28/12 | Removed | on/Colobrity |
| Homes | | have been sodded prior t | o inspection on 9/28/12 | by Dave Hausina | an/Celebrity |
| Pod E | Silt Fence | Lots 184-198 | | Removed | |
| Current Condition: Lot 194 | | inspection on 5/21/13 by | Dave Hausman/Celebrity | | |
| | | | 11/2/2212 | : | |
| Pod F Current Condition: Fair co | Silt Fence | Lots 426-454 | 11/8/2012 | Active | Yes |
| 2) Silt 1) Bob Homes of last 2) Bob | with Celebrity Homes was reminded again inspection. with Celebrity Hom | d on the back of lot 430 was informed to complet on 12/18/2013, 4/8/2014, es was requested to rep | e sod installation by 11/2 5/2/2014, 5/14/2014 & c air the silt fence by 8/2 | 27/2013. Bob wi on 6/19/2014. No 9/14. | ot completed as |
| Pod G | Silt Fence | Lots 404-425 | 4/8/2014 | Active | No |
| Homes | s installed SF on lots 4 | activity has begun on lot 425 and removed the SF f ot 418 prior to inspection | rom lot 418 prior to the in | | |
| Pod H | Silt Fence | Lots 455-473 | 12/4/2012 | Active | Yes |
| 1) Area | | hould be overseeded in lo need reset along the cu | | | |
| last ins | pection. Bob with Cel | was informed to complet brity Homes was remind es was requested to res | ed on 7/30/14. | · · · · · | ted as of the |
| Pod I | Misc/other | Lots 346-355 | 5/10/2013 | Active | No |
| Current Condition: Active- Excave | ation has begun on lot | 354 as of the inspection basin, SF is not needed | on 5/12/2014 by Celebrit | | |
| SB 1 S | Sediment Basin | N41d00m00s W96d00m00s | In Place | Active | No |

| Current Condition: | Good Condition-30% Filled | | | | |
|--|---|--|---|--|---|
| | Basin cleaned out was corr | | 1 on 6/10/11 by Bob Roth | I. | |
| | Os dires ent Da sin | N41d00m00s | | Demonstra | |
| SB 2 Current Condition: | Sediment Basin Basin was removed and the | W96d00m00s | ed prior to inspection on | Removed | |
| Current Condition. | | N41d00m00s | | 7/12/11 by 000mm | • |
| SB 3 | Sediment Basin | W96d00m00s | In Place | Active | No |
| Current Condition: | Good Condition-20% Filled | | | | |
| | -Cleaned out 02/06 | | | | |
| | | N41d00m00s | | | |
| SB 4 | Sediment Basin | W96d00m00s | | Removed | |
| Current Condition: | Removed per Hill-Farrell co | | T | | |
| SB 5 | Sediment Basin | N41d00m00s W96d00m00s | 11/17/2009 | Active | No |
| Current Condition: | Good Condition- 15% Filled | | 11/11/2000 | 7101170 | 110 |
| | - JC Excavating installed pr | | 3/09. | | |
| | 011 5 | N41d00m00s | | | |
| SF 1 Current Condition: | Silt Fence silt fence was removed by B | W96d00m00s | e vegetation and look of | Removed | 2 2122 |
| Guirent Condition. | sin rence was removed by i | N41d00m00s | | | 5 al Ca. |
| SF 2 | Silt Fence | W96d00m00s | | Removed | |
| Current Condition: | Removed for grading on 8/- | 4/08 | | | |
| | | N41d00m00s | | | |
| SF 3 | Silt Fence | W96d00m00s | | Removed | |
| Current Condition: | Removed due to home con | struction. N41d00m00s | | | |
| SF 4 | Silt Fence | W96d00m00s | | Removed | |
| Current Condition: | Removed due to home con | | | Romorou | |
| | | N41d00m00s | | | |
| SF 5 | Silt Fence | W96d00m00s | | Removed | |
| Current Condition: | Removed due to home con | struction. | | | |
| | | N41d00m00s | | | |
| SF 6 | Silt Fence | W96d00m00s | | Removed | |
| Current Condition: | Removed due to road cons | | | | |
| 05.7 | C'' - | N41d00m00s | | Dem | |
| SF 7 Current Condition: | Silt Fence Silt fence was removed price | W96d00m00s | 3 by Boyer Young | Removed | |
| | | μ_{1} μ_{2} μ_{3} μ_{3} μ_{4} μ_{5} μ_{6} μ_{1} μ_{1} μ_{1} μ_{1} μ_{1} μ_{1} μ_{1} μ_{2} μ_{1} μ_{1} μ_{2} μ_{2} μ_{1} μ_{2} μ_{2} μ_{1} μ_{2} μ_{2} μ_{2} μ_{1} μ_{2} μ_{2 | U UV DUVEL TOUND | | |
| Current Condition: | | | | | |
| SF 8 | Silt Fence | N41d00m00s W96d00m00s | In Place | Active | Yes |
| | | N41d00m00s | | Active | Yes |
| SF 8 | Silt Fence | N41d00m00s W96d00m00s ehind SB 1. d behind the end of 43rd nes was informed to rem nes was informed to inst | In Place Street and in between S ove the SF by 4/21/2014 | B 1 & the end of th I. Not completed a | e road. s of the last |
| SF 8 Current Condition: | Silt Fence Fair Condition 1.) SF removal is needed b 2.) New SF install is needed 1.) Loren with Celebrity Hor inspection. 2.) Loren with Celebrity Hor inspection. | N41d00m00s W96d00m00s ehind SB 1. d behind the end of 43rd nes was informed to rem nes was informed to inst | In Place Street and in between S ove the SF by 4/21/2014 | B 1 & the end of th I. Not completed a: 014. Not complete | e road. s of the last |
| SF 8 Current Condition: SF 9 | Silt Fence Fair Condition 1.) SF removal is needed b 2.) New SF install is needed 1.) Loren with Celebrity Hor inspection. 2.) Loren with Celebrity Hor inspection. Silt Fence | N41d00m00s W96d00m00s ehind SB 1. d behind the end of 43rd nes was informed to rem nes was informed to inst N41d00m00s W96d00m00s | In Place Street and in between S ove the SF by 4/21/2014 all the new SF by 4/21/20 | B 1 & the end of th I. Not completed a 014. Not complete Removed | e road. s of the last d as of the las |
| SF 8 Current Condition: | Silt Fence Fair Condition 1.) SF removal is needed b 2.) New SF install is needed 1.) Loren with Celebrity Hor inspection. 2.) Loren with Celebrity Hor inspection. | N41d00m00s W96d00m00s ehind SB 1. d behind the end of 43rd nes was informed to rem nes was informed to inst N41d00m00s W96d00m00s there is active home cons | In Place Street and in between S ove the SF by 4/21/2014 all the new SF by 4/21/20 | B 1 & the end of th I. Not completed a 014. Not complete 014. Removed this silt fence is lo | e road. s of the last d as of the las cated, |
| SF 8 Current Condition: SF 9 Current Condition: | Silt Fence Fair Condition 1.) SF removal is needed b 2.) New SF install is needed 1.) Loren with Celebrity Hor inspection. 2.) Loren with Celebrity Hor inspection. Silt Fence As of inspection on 8/6/12 therefore the maintenance the builder. | N41d00m00s W96d00m00s ehind SB 1. d behind the end of 43rd nes was informed to rem nes was informed to inst N41d00m00s W96d00m00s here is active home cons on this silt fence is being N41d00m00s | In Place Street and in between S ove the SF by 4/21/2014 all the new SF by 4/21/20 | B 1 & the end of th I. Not completed a 014. Not complete 014. Not complete 014. Removed 1 this silt fence is lo nd it will be the res | e road. s of the last d as of the las cated, |
| SF 8 Current Condition: SF 9 Current Condition: SF 10 | Silt Fence Fair Condition 1.) SF removal is needed b 2.) New SF install is needed 1.) Loren with Celebrity Hor inspection. 2.) Loren with Celebrity Hor inspection. Silt Fence As of inspection on 8/6/12 therefore the maintenance the builder. | N41d00m00s W96d00m00s ehind SB 1. d behind the end of 43rd nes was informed to rem nes was informed to inst mes was informed to inst N41d00m00s there is active home cons on this silt fence is being N41d00m00s W96d00m00s | In Place Street and in between S ove the SF by 4/21/2014 all the new SF by 4/21/2014 struction on the lots were moved to BMP Pod E an | B 1 & the end of the I. Not completed at 014. Not completed at 014. Not complete 014 | e road. s of the last d as of the las cated, ponsibility of |
| SF 8 Current Condition: SF 9 Current Condition: | Silt Fence Fair Condition 1.) SF removal is needed b 2.) New SF install is needed 1.) Loren with Celebrity Hor inspection. 2.) Loren with Celebrity Hor inspection. Silt Fence As of inspection on 8/6/12 therefore the maintenance the builder. | N41d00m00s W96d00m00s ehind SB 1. d behind the end of 43rd nes was informed to rem nes was informed to inst N41d00m00s W96d00m00s here is active home cons on this silt fence is being N41d00m00s W96d00m00s here is active home cons on this silt fence is being N41d00m00s W96d00m00s Sover Young due to dens | In Place Street and in between S ove the SF by 4/21/2014 all the new SF by 4/21/2014 struction on the lots were moved to BMP Pod E an | B 1 & the end of the I. Not completed at 014. Not completed at 014. Not complete 014 | e road. s of the last d as of the las cated, ponsibility of |
| SF 8 Current Condition: SF 9 Current Condition: SF 10 Current Condition: | Silt Fence Fair Condition 1.) SF removal is needed b 2.) New SF install is needed 1.) Loren with Celebrity Hor inspection. 2.) Loren with Celebrity Hor inspection. 3.) Loren with Celebrity Hor inspection. 3.] Loren with Celebrity Hor inspecti | N41d00m00s W96d00m00s ehind SB 1. d behind the end of 43rd mes was informed to rem mes was informed to inst N41d00m00s W96d00m00s here is active home cons on this silt fence is being N41d00m00s W96d00m00s N41d00m00s W96d00m00s N41d00m00s W96d00m00s N41d00m00s N41d00m00s N41d00m00s | In Place Street and in between S ove the SF by 4/21/2014 all the new SF by 4/21/2014 struction on the lots were moved to BMP Pod E an | B 1 & the end of the Not completed at 014. Not completed at 014. Not completed this silt fence is lond it will be the res | e road. s of the last d as of the las cated, ponsibility of |
| SF 8 Current Condition: SF 9 Current Condition: SF 10 | Silt Fence Fair Condition 1.) SF removal is needed b 2.) New SF install is needed 1.) Loren with Celebrity Hor inspection. 2.) Loren with Celebrity Hor inspection. Silt Fence As of inspection on 8/6/12 therefore the maintenance the builder. | N41d00m00s W96d00m00s ehind SB 1. d behind the end of 43rd nes was informed to rem mes was informed to inst N41d00m00s W96d00m00s here is active home cons on this silt fence is being N41d00m00s W96d00m00s Soyer Young due to dens N41d00m00s W96d00m00s | In Place Street and in between S ove the SF by 4/21/2014 all the new SF by 4/21/2014 struction on the lots were moved to BMP Pod E au e vegetation and lack of | B 1 & the end of th I. Not completed a 014. Not complete Removed this silt fence is lo ind it will be the res Removed construction in this Removed | e road. s of the last d as of the las cated, ponsibility of s area. |
| SF 8 Current Condition: SF 9 Current Condition: SF 10 Current Condition: SF 11 | Silt Fence Fair Condition 1.) SF removal is needed b 2.) New SF install is needed 1.) Loren with Celebrity Hor inspection. 2.) Loren with Celebrity Hor inspection. Silt Fence As of inspection on 8/6/12 t therefore the maintenance the builder. Silt Fence silt fence was removed by F Silt Fence | N41d00m00s W96d00m00s ehind SB 1. d behind the end of 43rd nes was informed to rem mes was informed to inst N41d00m00s W96d00m00s here is active home cons on this silt fence is being N41d00m00s W96d00m00s Soyer Young due to dens N41d00m00s W96d00m00s | In Place Street and in between S ove the SF by 4/21/2014 all the new SF by 4/21/2014 struction on the lots were moved to BMP Pod E au e vegetation and lack of | B 1 & the end of th I. Not completed a 014. Not complete Removed this silt fence is lo ind it will be the res Removed construction in this Removed | e road. s of the last d as of the las cated, ponsibility of s area. |
| SF 8 Current Condition: SF 9 Current Condition: SF 10 Current Condition: SF 11 Current Condition: SF 12 | Silt Fence Fair Condition 1.) SF removal is needed b 2.) New SF install is needed 1.) Loren with Celebrity Hor inspection. 2.) Loren with Celebrity Hor inspection. Silt Fence As of inspection on 8/6/12 therefore the maintenance the builder. Silt Fence silt fence was removed by F Silt Fence silt fence was removed by F Silt Fence | N41d00m00s W96d00m00s ehind SB 1. d behind the end of 43rd nes was informed to rem mes was informed to inst M96d00m00s N41d00m00s W96d00m00s here is active home cons on this silt fence is being N41d00m00s W96d00m00s Boyer Young due to dens N41d00m00s W96d00m00s Boyer Young due to dens N41d00m00s W96d00m00s Boyer Young due to dens N41d00m00s W96d00m00s | In Place Street and in between S ove the SF by 4/21/2014 all the new SF by 4/21/2014 struction on the lots were moved to BMP Pod E au e vegetation and lack of | B 1 & the end of th I. Not completed a 014. Not complete Removed this silt fence is lo ind it will be the res Removed construction in this Removed | e road. s of the last d as of the las cated, ponsibility of s area. |
| SF 8 Current Condition: SF 9 Current Condition: SF 10 Current Condition: SF 11 Current Condition: SF 12 Current Condition: | Silt Fence Fair Condition 1.) SF removal is needed b 2.) New SF install is needed 1.) Loren with Celebrity Horispection. 2.) Loren with Celebrity Horispection. 2.) Loren with Celebrity Horispection. Silt Fence As of inspection on 8/6/12 therefore the maintenance the builder. Silt Fence silt fence was removed by Figure Silt fence silt fence was removed by Figure Silt fence Silt Fence Silt Fence Silt fence was removed by Figure Silt fence Silt Fence Silt Fence Silt fence was removed by Figure Silt fence | N41d00m00s W96d00m00s ehind SB 1. d behind the end of 43rd nes was informed to rem mes was informed to inst N41d00m00s W96d00m00s here is active home cons on this silt fence is being N41d00m00s W96d00m00s Boyer Young due to dens N41d00m00s W96d00m00s | In Place Street and in between S ove the SF by 4/21/2014 all the new SF by 4/21/2014 struction on the lots were moved to BMP Pod E au e vegetation and lack of | B 1 & the end of the I. Not completed at 014. Not completed at 014. Not complete the rest of this silt fence is lond it will be the rest construction in this Removed construction in this Removed construction in this Removed | e road. s of the last d as of the last cated, ponsibility of s area. |
| SF 8 Current Condition: SF 9 Current Condition: SF 10 Current Condition: SF 11 Current Condition: SF 12 Current Condition: SF 12 Current Condition: | Silt Fence Fair Condition 1.) SF removal is needed b 2.) New SF install is needed 1.) Loren with Celebrity Horinspection. 2.) Loren with Celebrity Horinspection. 2.) Loren with Celebrity Horinspection. 2.) Loren with Celebrity Horinspection. Silt Fence As of inspection on 8/6/12 therefore the maintenance the builder. Silt Fence Silt Fence Silt Fence Silt Fence Silt fence was removed by Fence Silt Fence | N41d00m00s W96d00m00s ehind SB 1. d behind the end of 43rd mes was informed to rem mes was informed to rem mes was informed to inst N41d00m00s W96d00m00s here is active home cons on this silt fence is being N41d00m00s W96d00m00s Soyer Young due to dens N41d00m00s W96d00m00s Soyer Young due to dens N41d00m00s W96d00m00s Boyer Young due to dens N41d00m00s W96d00m00s M96d00m00s | In Place Street and in between S ove the SF by 4/21/2014 all the new SF by 4/21/2014 struction on the lots were moved to BMP Pod E ar e vegetation and lack of e vegetation and lack of | B 1 & the end of the I. Not completed at 014. Not completed at 014. Not complete the other set of the state of the set of | e road. s of the last d as of the las cated, ponsibility of s area. |
| SF 8 Current Condition: SF 9 Current Condition: SF 10 Current Condition: SF 11 Current Condition: SF 12 Current Condition: | Silt Fence Fair Condition 1.) SF removal is needed b 2.) New SF install is needed 1.) Loren with Celebrity Horispection. 2.) Loren with Celebrity Horispection. 2.) Loren with Celebrity Horispection. 2.) Loren with Celebrity Horispection. Silt Fence As of inspection on 8/6/12 therefore the maintenance the builder. Silt Fence silt fence was removed by Final Silt Fence silt fence was removed by Final Silt Fence | N41d00m00s W96d00m00s ehind SB 1. d behind the end of 43rd nes was informed to rem mes was informed to rem mes was informed to inst N41d00m00s W96d00m00s here is active home cons on this silt fence is being N41d00m00s W96d00m00s Soyer Young due to dens N41d00m00s W96d00m00s Boyer Young due to dens N41400m00s W96d00m00s en moved to Pod C in th | In Place Street and in between S ove the SF by 4/21/2014 all the new SF by 4/21/2014 struction on the lots were moved to BMP Pod E ar e vegetation and lack of e vegetation and lack of | B 1 & the end of the I. Not completed at 014. Not completed at 014. Not complete the rest of this silt fence is lond it will be the rest construction in this Removed construction in this Removed construction in this Removed | e road. s of the last d as of the las cated, ponsibility of s area. |
| SF 8 Current Condition: SF 9 Current Condition: SF 10 Current Condition: SF 11 Current Condition: SF 12 Current Condition: SF 12 Current Condition: | Silt Fence Fair Condition 1.) SF removal is needed b 2.) New SF install is needed 1.) Loren with Celebrity Horinspection. 2.) Loren with Celebrity Horinspection. 2.) Loren with Celebrity Horinspection. 2.) Loren with Celebrity Horinspection. Silt Fence As of inspection on 8/6/12 therefore the maintenance the builder. Silt Fence Silt Fence Silt Fence Silt Fence Silt fence was removed by Fence Silt Fence | N41d00m00s W96d00m00s ehind SB 1. d behind the end of 43rd mes was informed to rem mes was informed to rem mes was informed to inst N41d00m00s W96d00m00s here is active home cons on this silt fence is being N41d00m00s W96d00m00s Soyer Young due to dens N41d00m00s W96d00m00s Soyer Young due to dens N41d00m00s W96d00m00s Boyer Young due to dens N41d00m00s W96d00m00s M96d00m00s | In Place Street and in between S ove the SF by 4/21/2014 all the new SF by 4/21/2014 struction on the lots were moved to BMP Pod E ar e vegetation and lack of e vegetation and lack of | B 1 & the end of the I. Not completed at 014. Not completed at 014. Not complete the rest of this silt fence is lond it will be the rest construction in this Removed construction in this Removed construction in this Removed | e road. s of the last d as of the las cated, ponsibility of s area. |

| STR | Street Cleaning | N41d00m00s W96d00m00s | 5/1/2007 | Active | Yes | |
|----------------------------------|---|--------------------------|--------------|-------------|-------|--|
| Current Condition: | Street Cleaning W96d00m00s 5/1/2007 Active Yes Fair condition- 1) There is minor silt along the curb line of lots 132 and 155 as of inspection on 8/21/14. 2) There is minor silt along the curb line of lots 415, 419, 420, 425, 426, 433 and trackout on Birchwood Dr. as of inspection on 8/21/14. 1) Regency Homes was requested to clean the street by 8/22/14. Not done as of last inspection. 2) Celebrity Homes was requested to clean the street by 8/22/14. Not done as of last inspection. | | | | | |
| SWPPP Sign Current Condition: | Signs Good Condition: 48th and Birchwood Drive | 1 sign on site | 8-19-08 | Active | No | |
| Inspector Signature: | But Sul | | Reviewed By: | Echany K. J | lılıc | |