E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Engineering Answers

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager E & A CONSULTING GROUP, INC. ENGINEERING • PLANNING • ENVIRONMENTAL & FIELD SERVICES

| Environmental Services Dept. Manager ENGINEERING • PLANNING • ENVIRONMENTAL & FIELD SERVICES | | | | | | |
|--|---|---|---|-------------------|----------|--|
| la su sete u Deteisle Os skasa | E&A- | P2005.198.000 | | | Stage | |
| Inspector: Patrick Sechser | | | | | | |
| | | | ter Falls | | Winter | |
| Project Name: | | NER1 | 10573 | | | |
| For Week Ending: | | 1/10/2015 | | | | |
| Project Location: | 48th a | 48th and Fairview Road- Bellevue, NE (Sarpy County) | | | | |
| | | | , | | 68123 | |
| Grading: | 100 | | | | | |
| Sanitary Sewer: | 100 | | | | | |
| Storm Sewer: | 100 | | | | | |
| Paving: | 100 | | | | | |
| Seeding: Utilities: | 100 | | | | | |
| Overall Development: | | 5% | | | | |
| | | 570 | | I | | |
| RAIN FALL AMOUNTS | Amount in tenths | Date inspected | Weather Conditions | | | |
| | | | | | Week 1 | |
| Sunday: | 0.16" | | | | | |
| Monday | 0.78" | 12/15/14 | 54/27 Rain | | | |
| Tuesday Wednesday | 0.00" | | | _ | | |
| Wednesday Thursday | 0.00" | | | + | <u> </u> | |
| Friday | 0.00" | | | | | |
| Saturday | 0.00" | - | | - | | |
| | | | | | Week 2 | |
| Sunday: | 0.00" | | | | | |
| Monday | 0.59" | | | | | |
| Tuesday | 0.22" | 12/23/14 | Rain 37/33 | | | |
| Wednesday | 0.02" | | | | | |
| Thursday | 0.00" | | | | | |
| Friday | 0.01" | | | | | |
| Saturday | 0.00" | | | | March 6 | |
| Sunday: | 0.00" | | | | Week 3 | |
| Monday | 0.00 | | | | | |
| Tuesday | 0.00" | | | | | |
| Wednesday | 0.00" | | | | | |
| Thursday | 0.00" | | | | | |
| Friday | 0.00" | | | | | |
| Saturday | 0.00" | | | | | |
| | | | | | Week 4 | |
| Sunday: | 0.00" | | | | | |
| Monday | 0.00" | | | | | |
| Tuesday | 0.00" | | | | | |
| Wednesday Thursday | 0.00" | | | + | <u> </u> | |
| Friday | 0.00" | | | - | | |
| Saturday | 0.00" | 1 | | 1 | ł | |
| | | | | | Week 5 | |
| Sunday: | N/A | N/A | | | | |
| Monday | N/A | N/A | | | | |
| Tuesday | N/A | N/A | | | | |
| Wednesday | N/A | N/A | | | | |
| Thursday | N/A | N/A | | | | |
| Friday | N/A N/A | N/A N/A | | | | |
| Saturday | IN/A | DW/A | Į | I | Į | |
| | None | | | | | |
| Complaints: | | | | | | |
| • • • | | | | | | |
| | | | | | | |
| | | | | | | |
| Construction Sequencing: | | | | | | |
| Which portion(s) (i.e. drainage basins) of the | ne site have had a temporary or permanent | cessation of grading, ear | thwork, or ground disturbance in | the last 14 days? | | |
| | | | | | | |
| Grading completed and entire site se | | | | | | |
| | grading Lots 346 through 480 Section | | nd 2 (11/2009). | | | |
| Entire site is now inactive for major g | rading activities as of the inspection o | n 11/20/2013. | | | 1 | |
| | | | | | | |

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

| Grading completed and entire site seeded Entire Site; JC Excavating completed grad | • | drainage area 1 and 2 (| 11/2009). | | | | |
|--|---|--|--|--------------------------------|-------------------|--|--|
| Entire site is now inactive for major gradin | | | | | | | |
| What temporary or permanent stabilization mean | sures listed in this section are being imple | emented? | | • | • | | |
| Paving, dense vegetation and landscaping lots 346-480, seeded (4/10); Outlot B was and 43rd Avenue was temp seeded (5/22) side slopes surrounding outlot M Basir | seeded (6/2011); Lots 16-19 was se /2014); Additional matting was instal | eded (8/2011); Outlot L | was graded, seed and m | atted (5/22/2014 | i); 42nd Street | | |
| | | | | | | | |
| Comments: Comments: Celebrity Homes is actively building in the Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the E | BMP Section. | | in the North part of the d | levelopment by v | various builders. | | |
| 2.) Site was moved to Winter Stage on 1/3 | 30/2014 due to frozen and winter cor | nditions. | 1 | | [| | |
| Unique Name | Туре | Location | Projected Install Date | Status | Maintenance | | |
| CE 1 | Construction Entrance | N41d00m00s W96d00m00s | | Removed | | | |
| Current Condition: | Removed-Entrance area wa | s removed and concrete | e removed by Celebrity Ho | | e inspection on | | |
| 01/ 0 | 12/3/2013 for sidewalk insta | | - | Domented | <u> </u> | | |
| CW 3 Current Condition: | Concrete Washout Removed- Bob w/ Celebrity | Lot 348 Homes removed washo | ut pit prior to inspection o | Removed n 8/27/2013. | 1 | | |
| | | | | | | | |
| CW 4 | Concrete Washout | Lot 414 | | Removed | | | |
| Current Condition: | Removed-Washout pit was | removed by Celebrity Ho | omes prior to the inspection | on on 4/8/2014. | | | |
| CW 5 Current Condition: | Concrete Washout Good condition- Celebrity He | Lot 387 omes cleaned out the wa | 5/12/2014 ashout pit prior to the insp | Active pection on 12/2/2 | No 2014. | | |
| Lot 15 | Silt Fence | Lot 15 | | Removed | | | |
| Current Condition: | Removed- Horizon Homes s | | e inspection on 11/18/201 | 4. | | | |
| Lot 26 | Silt Fence | Lot 26 | | Removed | | | |
| Current Condition: | Removed-Lot was sodded b | y Horizon Homes prior t | o the inspection on 10/29/ | /2013. | - | | |
| Lot 27 | Silt Fence | Lot 27 | | Removed | | | |
| Current Condition: | Removed-Lot was sodded b | | o the inspection on 10/29 | | | | |
| Lot 30 Current Condition: | Silt Fence Removed- Horizon Homes r | Lot 30 emoved the SF, cleaned | up the dirt and sodded th | Removed he lot prior to the | e 4/28/2014 | | |
| | inspection. | | - | | - | | |
| Lot 54 Current Condition: | Silt Fence Active- | Lot 54 | 6/18/2014 | Active | Yes | | |
| Lot 55 | Due to the removal of the per Homeowner Nick Peterson Not completed as of the last Silt Fence | was informed to complet | | ermitting wear | ther conditions. | | |
| Current Condition: | Removed-Lot was sodded p | rior to inspection on 7/1 | 6/13 by The Home Compa | any. | 1 | | |
| Lot 56 Current Condition: | Silt Fence Removed-The lot was sodde | Lot 56 | rior to the inspection on 5 | Removed /22/2014 | | | |
| Lot 57 | Silt Fence | Lot 57 | 8/11/2014 | Active | Yes | | |
| Current Condition: | 8/21/14. 1.) SF is needed in the rear 2.) SF needs to be entrench | Fair Condition-Silt fence was installed on the North side of the lot by Horizon Homes prior to inspection on 8/21/14. 1.) SF is needed in the rear of the lot due to the new excavation. 2.) SF needs to be entrenched on the North side of the lot. 3.) SF is ripped on the side of the lot as of inspection on 9/24/14. | | | | | |
| | 1.) Horizon Homes was requ Homes was reminded again 2.) Horizon Homes was requ inspection. Horizon Homes v 3.) Horizon Homes was requ Homes was reminded again | on 9/11/2014, 11/6/2014 uested to complete silt fe was reminded again on t uested to repair the rippe | 4. Ince maintenance by 9/17 11/6/2014. | 7/2014. Not done | e as of last | | |
| Lot 72 | Silt Fence | Lot 72 | | Removed | | | |
| Current Condition: | Removed-Lot was sodded b | y Horizon Homes prior t | o the inspection on 7/15/2 | 2014. | | | |
| Lot 76 | Silt Fence | Lot 76 | 6/27/2014 | Active | No | | |
| Current Condition: | Good condition- Proline Homes installed SF | in the rear and side of th | e lot prior to the inspectio | n on 6/27/2014 | | | |
| Lot 80 | Silt Fence | Lot 80 | 8/23/2014 | Active | Yes | | |
| LULOU | SIIL FEIICE | | 0/20/2014 | Active | 165 | | |

| Current Condition: | Fair Condition-Silt fence wa | s installed on the North si | de of the lot by Horizon | Homes prior to ir | spection on | | |
|-------------------------------|--|---|--|------------------------------|-----------------|--|--|
| | 8/23/14. | | | | | | |
| | SF is needed in the rear of the lot. | | | | | | |
| | Horizon Homes was requested to install silt fence by 9/17/2014. Not done as of last inspection. Horiz Homes was reminded again on 11/6/2014. | | | | | | |
| Lot 132 | Silt Fence | Lot 132 | 8/11/2014 | Active | No | | |
| Current Condition: | Good condition- Regency H | omes installed erosion ee | Is in the front corner of | the lot prior to the | inspection on | | |
| Lot 155 | 12/2/2014. Silt Fence | Lot 155 | 8/11/2014 | Active | No | | |
| Current Condition: | Good condition- Regency H | | | | - | | |
| Lot 255 | Silt Fence | Lot 255 | 8/4/2014 | Active | No | | |
| Current Condition: | Active- Due to the vegetate | | | | - | | |
| | by Legacy Homes. | , | | | | | |
| Lot 258 | Individual Lot | Lot 258 | 10/14/2014 | Pending | Yes | | |
| Current Condition: | | | | | | | |
| | Charleston Homes was req CH was reminded again o | | | leted as of the las | at inspection. | | |
| Lot 259 | Individual Lot | Lot 259 | 10/14/2014 | Pending | Yes | | |
| Current Condition: | Pending-Charleston Homes removed the stockpile prior to the inspection on 11/5/2014. SF or wattles are needed in the front of the lot. Charleston Homes was requested to install a BMP by 11/12/2014. Not completed as of the last inspection. CH was reminded again on 12/29/2014. | | | | | | |
| 1-4-004 | Min o (others | 1-1-001 | | Berneviad | | | |
| Lot 264 Current Condition: | Misc/other Removed- Lot was sodded | lot 264 by Proline Homes prior to | the inspection on 8/4/2 | Removed 014. | 1 | | |
| Lot 268 | Misc/other | Lot 268 | | Removed | 1 | | |
| Current Condition: | Removed-Sherwood Home | | e inspection on 10/15/2 | | | | |
| | | | | | | | |
| Lot 271 Current Condition: | Misc/other Removed-The lot was sodd | Lot 271 | prior to the inspection | Removed | | | |
| Current Condition. | Removed-me lot was soud | ed by the nome Company | phor to the inspection | 011 5/22/2014. | | | |
| Lot 277 | Silt Fence | Lot 277 | | Removed | | | |
| Current Condition: | Removed-Dumpster and Pf installation. | P were removed on site pr | ior to 7/30/2013 by the | Home Company | due to sod | | |
| Lot 278 | Silt Fence | Lot 278 | | Removed | | | |
| Current Condition: | Removed-Charleston Home | es sodded the lot prior to t | he inspection on 7/15/2 | 014. SF check w | as moved to lot | | |
| | 279. | | | 1 | | | |
| Lot 279 Current Condition: | Silt Fence | Lot 279 | 7/15/2014 | Active | Yes | | |
| | Fair Condition SF is full in the SE corner as of inspection on 10/23/14. Charleston Homes was requested to clean out the SF by 10/30/14. Not completed as of the last inspection. CH was reminded again on 12/29/2014. | | | | | | |
| Lot 283 | Silt fence | Lot 283 | | Removed | | | |
| Current Condition: Lot 286 | Removed- Lot was sodded Silt Fence | by Sherwood Homes prio Lot 286 | r to the inspection on 6/ 12/2/2014 | 18/2014. Active | Yes | | |
| Current Condition: | | | | | | | |
| Lot 287 | Fair Condition- Sherwood Homes installed SF in the rear of the lot prior to the inspection on 12/2/2014. Dirt needs to be removed from the ROW. Sherwood Homes was informed to remove the dirt from the ROW by 12/9/2014. Not completed as of the last inspection. | | | | | | |
| Current Condition: | Silt fence Tom w/ The Home Compar | Lot 287 y installed sod prior to the | inspection on 7/30/201 | Removed 3. | 1 | | |
| Lot 300 | Silt Fence | Lot 300 | 12/23/2014 | Active | No | | |
| Current Condition: | Active- Due to the vegetat E&A inspector will monito | r. | SF is not needed at th | nis time by Pineo | crest Homes. | | |
| Lot 304 | Misc/other | Lot 304 | des lass d' | Removed | | | |
| Current Condition: | Removed- Lot was sodded | | the inspection on 7/5/2 | - | [| | |
| Lot 305 Current Condition: | Silt Fence Removed-Silt fence was ren | Lot 305 | inspection on 7/8/13 b | Removed | due to sidewalk | | |
| Current Condition. | construction being active in | | | , Logacy Homes | add to oldewalk | | |
| Lot 309 | Silt Fence | Lot 309 | | Removed | | | |
| Current Condition: | Removed-The lot was sodd | | prior to inspection on 8/2 | | | | |
| Lot 311 Current Condition: | Silt Fence | Lot 311 | inspection on 9/42/20 | Removed | 1 | | |
| | Removed-Heavican Homes | | - mspection on 8/13/20 I | - | r | | |
| Lot 312 Current Condition: | Silt Fence Removed-Banyan Homes s | Lot 312 odded the lot and remove | d SF in the rear prior to | Removed the inspection of | n 4/28/2014. | | |
| Lot 313 | Silt Fence | Lot 313 | | Removed | | | |

| Current Condition: | Removed-Lot 313 was sodd | ed by Showcase Homes | prior to inspection on 8 | /27/2013. SF was | removed prior |
|-------------------------------|---|---|---|-----------------------------|------------------|
| | to inspection on 9/11/2013 b | | | 21/2010101 01 1100 | ionioroa phoi |
| Lot 322 | Silt Fence | Lot 322 | | Removed | |
| Current Condition: | Removed- Lot was sodded b | by Regency Homes prior t Lot 323 | to the inspection on 6/1 | 8/2014. Removed | |
| Lot 323 Current Condition: | Misc/other Removed-Lot was sodded b | | to the inspection on 10 | | |
| Lot 324 | Silt Fence | Lot 324 | 8/30/2014 | Active | No |
| Current Condition: | Good Condition-Sherwood H | | | | |
| Lot 327 | Misc/other | Lot 327 | | Removed | |
| Current Condition: | Removed-Sherwood Homes | | spection on 9/24/14. | Removed | |
| Lot 328 | Silt Fence | Lot 328 | 12/15/2014 | Active | No |
| Current Condition: | Good condition- SF was in 12/15/2014. | stalled on the front and | side by Oakwood Ho | mes prior to the | inspection on |
| Lot 331 | Silt Fence | Lot 331 | | Removed | |
| Current Condition: | Removed-Lot was sodded b | y Sherwood Homes prior | to the inspection on 11 | /20/2013. | |
| Lot 333 | Silt Fence | Lot 333 | | Removed | |
| Current Condition: | Removed- All of the torn and | | oved along the perimet | | to inspection or |
| | 8/27/2013 by Regency Home prior to inspection on 9/1/207 | es. Gator guards were rer | | | |
| Lot 335 | Individual Lot | Lot 335 | | Removed | |
| Current Condition: | Removed-Feldhacker Custo | | prior to inspection on 1 | | |
| Lot 337 | Silt Fence | Lot 337 | 8/30/2014 | Active | Yes |
| Current Condition: | Fair condition- Sherwood Ho | mes removed the stockp | ile from the ROW prior | to inspection on ? | 0/23/14. |
| | SF needs repaired on the N Sherwood Homes was reque Homes was reminded again | ested to repair SF by 10/3 | | | ction. Sherwood |
| Lot 338 | Individual Lot | Lot 338 | | Removed | |
| Current Condition: | Removed- THC sodded the | lot prior to the inspection | on 11/5/2014. | | |
| Lot 339 | Misc/other | Lot 339 | | Removed | |
| Current Condition: | Removed-Lot 338 items will | be removed for pending h | nome construction on lo | | ction on |
| | 10/29/2013. Seeding is no lo | nger needed. | | | |
| Lot 341 | Silt Fence | Lot 341 | | Removed | |
| Current Condition: | As of inspection on 6/15/13 t | | | y Castlebridge Ho | omes. The lot |
| | was sodded prior to inspecti | on on 6/23/13 by Castlebr | ridge Homes. | | |
| Lot 342 | Silt Fence | Lot 342 | | Removed | |
| Current Condition: | Removed-Paradise Homes | sodded the lot prior to insp | pection on 8/21/14. | | |
| Lot 343 | Misc/other | Lot 343 | | Removed | |
| Current Condition: | Removed- Charles Thomas | | or to the inspection on | | |
| | | | | | |
| Outlot D | Misc/other | Outlot D | | Removed | |
| Current Condition: | The disturbed area around the | he inlet has tilled in as of i | nspection on 7/8/13. | | |
| Pod A Current Condition: | Silt Fence Removed- Lot 236 was sodo | | on 11/5/2014 by Celeb | Removed ority Homes. Pod | A is completed |
| De d D | due to the completion of hon | | | Demonst | |
| Pod B | Silt Fence All lots in this Pod have beer | Lots 212-224 | on 6/25/11 | Removed | |
| Current Condition: Pod C | Silt Fence | Lots 175-183; 474-480 | 011 0/25/11. | Removed | |
| Current Condition: | Silt fence on lots 474-480 ha | | the lots being sodded r | | on 10/14/12 by |
| | Dave Hausman/Celebrity Ho | | | | 011 10/1 1/12 0) |
| Pod D | | Lots 199-210 | | | |
| Current Condition: | All remaining lots in this pod | | | | an/Celebrity |
| | Homes. | - | | | - |
| Pod E | Silt Fence | Lots 184-198 | | Removed | |
| Current Condition: | Lot 194 was sodded prior to | | Dave Hausman/Celebr | ity Homes. | |
| | All lots in this Pod have beer | 1 Duilt Out. | | | |
| Pod F | Silt Fence | Lots 426-454 | 11/8/2012 | Active | No |
| Current Condition: | Good Condition-Celebrity Ho rear of lots 430-431 and clea | | | | |
| Pod G | Silt Fence | Lots 404-425 | 4/8/2014 | Active | Yes |
| Current Condition: | Fair condition- Celebrity H | omes sodded lot 414; re | installed the SF arou | nd lot 415; sodd | ed lot 419; |
| | erosion eels added on the the inspection on 12/15/20 | | | between lots 421 | -422 prior to |
| | SF needs to be reinstalled o | | | of the last incr | ection |
| Ded Ll | SF needs to be reinstalled o Celebrity Homes was inform | ed to complete by 12/9/20 | 014. Not completed as | | |
| Pod H | SF needs to be reinstalled o Celebrity Homes was inform Silt Fence | | | of the last insp Active | ection. Yes |
| Pod H Current Condition: | SF needs to be reinstalled o Celebrity Homes was inform | ed to complete by 12/9/20 Lots 455-473 | 014 . Not completed as 12/4/2012 | | |
| | SF needs to be reinstalled o Celebrity Homes was inform Silt Fence Fair condition- | ed to complete by 12/9/20 Lots 455-473 | 014. Not completed as 12/4/2012 lot on 460. | Active | Yes |

| Current Condition: | Good condition-Celebrity H 11/18/2014. | omes removed the dirt pile | from the front of lot 35 | 5 prior to the insp | pection on |
|----------------------------|---|---|---------------------------|---------------------------|------------|
| Pod J | Silt Fence | Lots 381-394 | 11/18/2014 | Active | Yes |
| Current Condition: | Fair condition- Downed SF | and extended to the east or | n the south side of lot 3 | 388. | |
| | Celebrity Homes was inforr | | 14. Not completed as | s of the last insp | ection. |
| SB 1 | Sediment Basin | N41d00m00s W96d00m00s | In Place | Active | No |
| Current Condition: | Good Condition-30% Filled | | | | - |
| | by the SID prior to inspection | | | 1 | |
| SB 2 | Sediment Basin | W96d00m00s | | Removed | |
| Current Condition: | Basin was removed and the | | prior to inspection on | | m. |
| SB 3 | Sediment Basin | N41d00m00s W96d00m00s | In Place | Active | No |
| Current Condition: | Good Condition-20% Filled -Cleaned out 02/06 | | | | _ |
| | | N41d00m00s | | | |
| SB 4 | Sediment Basin | W96d00m00s | | Removed | L |
| Current Condition: | Removed per Hill-Farrell co | N41d00m00s | | | |
| SB 5 | Sediment Basin | W96d00m00s | 11/17/2009 | Active | No |
| Current Condition: | Good Condition- 15% Filled | | | Notive | 110 |
| | | N41d00m00s | | | r |
| SF 1 | Silt Fence | W96d00m00s | | Removed | |
| Current Condition: | silt fence was removed by | | vegetation and lack of | | nis area. |
| ourien conunion. | | N41d00m00s | regetation and later of | | |
| SF 2 | Silt Fence | W96d00m00s | | Removed | |
| Current Condition: | Removed for grading on 8/- | | | | |
| SF 3 | Silt Fence | N41d00m00s W96d00m00s | | Removed | |
| Current Condition: | Removed due to home con | | | | 1 |
| SF 4 | Silt Fence | N41d00m00s W96d00m00s | | Removed | |
| Current Condition: | Removed due to home con | | | Removed | |
| | | N41d00m00s | | | |
| SF 5 | Silt Fence | W96d00m00s | | Removed | |
| Current Condition: | Removed due to home con | struction. | | | |
| | | N41d00m00s | | | |
| SF 6 | Silt Fence | W96d00m00s | | Removed | |
| Current Condition: | Removed due to road cons | truction | | | |
| | | N41d00m00s | | | |
| SF 7 | Silt Fence | W96d00m00s | | Removed | |
| Current Condition: | Silt fence was removed price | or to inspection on 6/23/13 | by Boyer Young. | | |
| | | N41d00m00s | | | |
| SF 8 | Silt Fence | W96d00m00s | to increation 10/00 | Removed | 1 |
| Current Condition: | Removed-Commercial See | N41d00m00s | to inspection on 10/23 | / 14. | |
| SF 9 | Silt Fence | W96d00m00s | | Removed | |
| Current Condition: | As of inspection on 8/6/12 t | | uction on the lots were | | located, |
| | therefore the maintenance the builder. | | | | |
| | | N41d00m00s | | | |
| SF 10 | Silt Fence | W96d00m00s | | Removed | Ļ |
| Current Condition: | silt fence was removed by | | vegetation and lack of | construction in th | nis area. |
| SF 11 | Silt Fence | N41d00m00s W96d00m00s | | Removed | |
| Current Condition: | silt fence was removed by | | vegetation and lack of | | nis area. |
| | | N41d00m00s | | | |
| SF 12 | Silt Fence | W96d00m00s | | Removed | |
| Current Condition: | Removed due to landscapi | ng. | | | |
| SF A | Silt Fence | Lots 474-480 | | Removed | |
| Current Condition: | All this maintenance has be | | BMP section. | | • |
| | | N41d00m00s | | | |
| SF B Current Condition: | Silt Fence Silt fence was removed prio | W96d00m00s or to inspection on 5/10/13 | by Dave Hausman/Ce | Removed lebrity Homes. | |
| | | N41d00m00s | | 1 | |
| STR | Street Cleaning | N41000m00s W96d00m00s | 5/1/2007 | Active | Yes |

| Current Condition: | Fair condition- | | | | | | |
|----------------------|---|--|--------------|---------------|-----|--|--|
| | Street cleaning is needed i | Street cleaning is needed in front of lots 258 and 259. | | | | | |
| | Charleston Homes was info | Charleston Homes was informed to street clean by 12/24/2014. | | | | | |
| SWPPP Sign | Signs | 1 sign on site | 8-19-08 | Active | No | | |
| Current Condition: | Good Condition: 48th and Birchwood Drive | | | | | | |
| Inspector Signature: | Puto Sul | | Reviewed By: | Zachary K. Ji | hk. | | |