E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

lacara eta ur Matthaux Dura ell	Luni	2005.198.000		Stage
Inspector: Matthew Russell				
		Clearwate	er Falls	3
Project Name:		NER110	)573	
-		8/12/20		
For Week Ending:				
Project Location:	48th an	d Fairview Road- Bell	evue, NE (Sarpy County)	68123
Grading:	1009	6		
Sanitary Sewer:	100%			
Storm Sewer:	100%			
Paving:	1009			
Seeding:	100%			
Utilities:	100%			
Overall Development:	879			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	
	0.00			Week
Sunday:	0.00"			<del></del>
Monday	0.01"			
Tuesday	0.00"			
Wednesday	0.12" 0.63"	7/13/2017	Tstorm 85/69	
Thursday	0.63"	1/13/2017	18101111 85/89	
Friday Saturday	0.00"			
Saturday	0.00			Week
Sunday:	0.00"			vveek
Monday	0.00"			
Tuesday	0.04"			<del>-  </del>
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
, and the second				Week
Sunday:	0.00"			
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.92"			
Thursday	0.00"	7/27/2017	S Clouds 85/68	
Friday	0.00"			
Saturday	0.00"			
				Week
Sunday:	0.00"			
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.04"			Mont
Cunday	0.00"			Week
Sunday: Monday	0.00"			
Monday Tuesday	0.00"			
Wednesday	0.00"	+		
Thursday	0.00"		+	
Friday	0.00"		+	
Saturday	0.00"		+	
Outurady	10.00			
	None			
Complaints:	1.55			
F				

# Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading completed and entire site seeded prior to 2005.

Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009).

Entire site is now inactive for major grading activities as of the inspection on 11/20/2013.

Grading completed and entire site seeded prior to 2005.

Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009).

Entire site is now inactive for major grading activities as of the inspection on 11/20/2013.

# What temporary or permanent stabilization measures listed in this section are being impleme

Paving, dense vegetation and landscaping, Seed and straw mulch over ROW in Northwest quarter of SID (10/08), Sod on various lots (Fall '08), New phase, lots 346-480, seeded (4/10); Outlot B was seeded (6/2011); Lots 16-19 was seeded (8/2011); Outlot L was graded, seed and matted (5/22/2014); 42nd Street and 43rd Avenue was temp seeded (5/22/2014); Additional matting was installed on the South side of Outlot L (8/4/2014); Matting has been installed on the side slopes surrounding outlot M Basin (12/15/2014);

# SUMMARY QUESTIONS:

Are approved entrances and adjacent streets being maintained adequately?

No- see BMP section

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

# CHECKLIST QUESTIONS:

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No- see BMP section.

### Yes

Comments:

## Comments:

Home Construction is active in the North part of the development by various builders.

# Findings / Corrective Actions (Date):

## Findings / Corrective Actions (Date):

1.) Some maintenance is required in the BMP Section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
CW 5	Concrete Washout	Lot 387		Removed			
Current Condition:		Removed-Celebrity Homes removed the concrete washout prior to inspection on 11/12/2015.					
CW 6	Concrete Washout	Lot 359	Removed				
Current Condition:	Removed- Washout pit was	Removed- Washout pit was removed by Celebrity Homes prior to 3/30/2016.					
CW 7	Concrete Washout	Lot 361		Removed			
Current Condition:	Builders will washout on thei install a washout.	Removed- due to the progression of the site, individual lots will be responsible for their concrete waste. Builders will washout on their own lots, if a washout becomes needed the inspector will inform the applicant to install a washout.					
Lot 16	Individual Lot	Lot 16		Removed			
Current Condition:	Removed- Outlot B was see		izon Homes prior to 5/27/2				
Lot 17	Individual Lot	Lot 17		Removed			
Current Condition:	Removed- Newport Homes	sodded the lot prior to '	11/12/2015.				
Lot 54	Silt Fence	Lot 54		Removed			
Current Condition:	Removed-Nick Peterson soc	Removed-Nick Peterson sodded the lot prior to inspection on 5/28/15.					
Lot 57	Silt Fence	Lot 57		Removed			
Current Condition:	Removed-Horizon Homes so	Removed-Horizon Homes sodded the lot prior to inspection on 5/28/15.					
Lot 59	Individual Lot	Lot 59		Removed			
Current Condition:	Removed- Horizon Homes s	Removed- Horizon Homes sodded the lot prior to 11/12/2015.					
Lot 60	Silt Fence	Lot 60		Removed			
Current Condition:	Removed- Horizon Homes s	Removed- Horizon Homes sodded the lot prior to 11/1/16.					
Lot 68	Silt Fence	Lot 68	2/3/2017	Active	No		
Current Condition:	Good Condition- Pacesetter Homes installed silt fence in the rear of the lot prior to 6/28/17. Construction is set to begin on the lot.						
Lot 69	Silt Fence	Lot 69		Removed			
Current Condition:	Removed- Sherwood Homes	Removed- Sherwood Homes sodded the lot prior to 7/13/17.					
Lot 76	Silt Fence	Lot 76		Removed			
Current Condition:	Removed- Lot was sodded b	y Proline Homes prior	to 7/31/2015.		· · · · · · · · · · · · · · · · · · ·		
Lot 80	Silt Fence	Lot 80		Removed			
Current Condition:	Removed- Horizon Homes s	odded the lot prior to 6	/11/2015.		-		

Lot 82	Silt Fence	Lot 82		Removed	
Current Condition:	Removed- Lot was sodded	<del>, , , , , , , , , , , , , , , , , , , </del>	9/18/2015.	<del></del>	
Lot 88	Silt Fence Removed- Legacy Homes s	Lot 88	20/46	Removed	
Current Condition:			22/10.		
Lot 89	Individual Lot	Lot 89		Removed	
Current Condition:	Removed- the Home Comp	any sodded the lot prior to	0 11/1/16.		
Lot 132	Silt Fence	Lot 132		Removed	
Current Condition:	Removed- Regency Homes		19/2015.		
Lot 155	Silt Fence	Lot 155	10/0045	Removed	
Current Condition: Lot 209-210	Removed- Regency Homes Silt Fence	Lots 209-210	19/2015. I	Removed	
Current Condition:	Removed- Celebrity Homes		/1/16 Celebrity Homes		l naining silt fence
Garront Gondition.	prior to 3/27/17.	ocadoa ano los pinos so s	, , , , , , , , , , , , , , , , , , , ,		iaii ii g aii tatiaa
Lot 255	Individual Lot	Lot 255		Removed	
Current Condition:	Removed - Legacy Homes	sodded the lot prior to the	6/24/15 inspection.		
Lot 256	Silt Fence	Lot 256		Removed	
Current Condition:	Removed- Regency Homes	sodded the lot prior to 11	/22/16.	•	
Lot 258	Silt Fence	Lot 258	ı	Removed	
Current Condition:	Removed-Charleston Home		nspection on 5/14/15	Removed	
Lot 259	Silt Fence	Lot 259	100000000000000000000000000000000000000	Removed	
Current Condition:	Removed-Charleston Home		nspection on 5/14/15.	•	
			ı		
Lot 260	Individual Lot	Lot 260	107/2016	Removed	
Current Condition: Lot 261	Removed- Sherwood Home Individual Lot	s sodded the lot prior to 5	0/2//2016.	Removed	
Current Condition:	Removed- Sherwood Home		i 5/27/2016.	Literioved	<u> </u>
Lot 272	Silt Fence	Lot 272	1	Removed	
Current Condition:	Removed- Dean Vogel sodo		)16.	Ttomovou	
Lot 273	Silt Fence	Lot 273	<u> </u>	D	
Current Condition:	Removed- Sherwood Home		:/11/17	Removed	
Current Condition:	Removed- Sherwood Home	s souded the lot phor to t	7/11/17.		
Lot 274	Silt Fence	Lot 274		Removed	
Current Condition:	Removed- Regency Homes	sodded the lot prior to 12	/14/16.	•	
Lot 275	Temporary Seeding	Lot 275	4/20/2017	Pending	No
Lot 275	Temporary Seeding Pending- Dean Vogel distur	Lot 275	4/20/2017	Pending 276 Due to a der	No nse vegetative
Lot 275 Current Condition:	Temporary Seeding  Pending- Dean Vogel distur buffer in the rear of the lot the	bed soils on the lot from p	ast construction on lot 2	76. Due to a der	nse vegetative
-	Pending- Dean Vogel distur	bed soils on the lot from p	ast construction on lot 2	76. Due to a der	nse vegetative
Current Condition:	Pending- Dean Vogel distur buffer in the rear of the lot the monitor the lot.	bed soils on the lot from pe inspector will not recon	ast construction on lot 2	76. Due to a der me, inspector will	nse vegetative
Current Condition:  Lot 276	Pending- Dean Vogel distur buffer in the rear of the lot the monitor the lot.  Silt Fence	bed soils on the lot from page inspector will not recon	nast construction on lot 2 nmend seeding at this tir	76. Due to a der	nse vegetative
Current Condition:	Pending- Dean Vogel distur buffer in the rear of the lot the monitor the lot.	bed soils on the lot from page inspector will not recon	nast construction on lot 2 nmend seeding at this tir	76. Due to a der me, inspector will	nse vegetative
Current Condition:  Lot 276	Pending- Dean Vogel distur buffer in the rear of the lot the monitor the lot.  Silt Fence Removed- Dean Vogel sodo Silt Fence	Lot 276 Lot 277 Lot 277	past construction on lot 2 nmend seeding at this tir 1017.	76. Due to a der me, inspector will	nse vegetative
Current Condition:  Lot 276  Current Condition:	Pending- Dean Vogel distur buffer in the rear of the lot th monitor the lot.  Silt Fence Removed- Dean Vogel sodo	Lot 276 Lot 277 Lot 277	past construction on lot 2 nmend seeding at this tir 1017.	Removed	nse vegetative
Current Condition:  Lot 276  Current Condition:  Lot 277	Pending- Dean Vogel distur buffer in the rear of the lot the monitor the lot.  Silt Fence Removed- Dean Vogel sodo Silt Fence	Lot 276 Lot 277 Lot 277	past construction on lot 2 nmend seeding at this tir 1017.	Removed	nse vegetative
Current Condition:  Lot 276  Current Condition:  Lot 277  Current Condition:	Pending- Dean Vogel distur buffer in the rear of the lot the monitor the lot.  Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- the lot was mista Silt Fence Removed - Sherwood Hon	Lot 276 Lot 277 ken as lot 276 This was a Lot 280 Lot 280 Lot 280 Lot 270 Lot 280 Lot 280 Lot 280	past construction on lot 2 nmend seeding at this tir 117.  117.  Ilready sodded.  to inspection on 7/27/7	Removed	nse vegetative
Current Condition:  Lot 276  Current Condition:  Lot 277  Current Condition:  Lot 280  Current Condition:  Lot 281	Pending- Dean Vogel disturbuffer in the rear of the lot the monitor the lot.  Silt Fence Removed- Dean Vogel sode Silt Fence Removed- the lot was mistate Silt Fence Removed - Sherwood Hones Silt Fence	Lot 276 Lot 277 ken as lot 276 This was a Lot 280 Lot 281 Lot 281	past construction on lot 2 nmend seeding at this tir 117.  117.  Ilready sodded.  to inspection on 7/27/	Removed  Removed  Removed  Removed  Removed	se vegetative continue to
Current Condition:  Lot 276  Current Condition:  Lot 277  Current Condition:  Lot 280  Current Condition:	Pending- Dean Vogel distur buffer in the rear of the lot the monitor the lot.  Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- the lot was mista Silt Fence Removed - Sherwood Hon	Lot 276 Lot 277 ken as lot 276 This was a Lot 280 Lot 281 Lot 281	past construction on lot 2 nmend seeding at this tir 117.  117.  Ilready sodded.  to inspection on 7/27/	Removed  Removed  Removed  Removed  Removed	se vegetative continue to
Current Condition:  Lot 276  Current Condition:  Lot 277  Current Condition:  Lot 280  Current Condition:  Lot 281  Current Condition:	Pending- Dean Vogel disturbuffer in the rear of the lot the monitor the lot.  Silt Fence Removed- Dean Vogel sode Silt Fence Removed- the lot was mistate Silt Fence Removed - Sherwood Hone Silt Fence Removed - Dean Vogel sode	Lot 276 Lot 277 ken as lot 276 This was a Lot 280 nes sodded the lot prior to 4/12/20 Lot 281 ded the lot prior to 8/12/20	past construction on lot 2 nmend seeding at this tir 117.  117.  Ilready sodded.  to inspection on 7/27/	Removed	se vegetative continue to
Current Condition:  Lot 276  Current Condition:  Lot 277  Current Condition:  Lot 280  Current Condition:  Lot 281  Current Condition:  Lot 284	Pending- Dean Vogel disturbuffer in the rear of the lot the monitor the lot.  Silt Fence Removed- Dean Vogel sode Silt Fence Removed- the lot was mista Silt Fence Removed - Sherwood Hon Silt Fence Removed - Dean Vogel sode Silt Fence Removed - Dean Vogel sode Silt Fence	Lot 276  Lot 276  ded the lot prior to 4/14/20  Lot 280  Lot 280  Lot 281  Lot 281  Lot 284	past construction on lot 2 nmend seeding at this tir 117.  117.  118.  119.  119.  110.  1	Removed  Removed  Removed  Removed  Removed	se vegetative continue to
Current Condition:  Lot 276  Current Condition:  Lot 277  Current Condition:  Lot 280  Current Condition:  Lot 281  Current Condition:  Lot 284  Current Condition:	Pending- Dean Vogel disturbuffer in the rear of the lot the monitor the lot.  Silt Fence Removed- Dean Vogel sode Silt Fence Removed- the lot was mistate Silt Fence Removed - Sherwood Hone Silt Fence Removed - Dean Vogel sode	Lot 276 Lot 277 ken as lot 276 This was a Lot 280 nes sodded the lot prior to 8/12/20 Lot 281 ded the lot prior to 8/12/20 Lot 284 s sodded the lot prior to 5	past construction on lot 2 nmend seeding at this tir 117.  117.  118.  119.  119.  110.  1	Removed	se vegetative continue to
Current Condition:  Lot 276  Current Condition:  Lot 277  Current Condition:  Lot 280  Current Condition:  Lot 281  Current Condition:  Lot 284  Current Condition:  Lot 284  Current Condition:  Lot 284  Current Condition:	Pending- Dean Vogel disturbuffer in the rear of the lot the monitor the lot.  Silt Fence Removed- Dean Vogel sode Silt Fence Removed- the lot was mistate Silt Fence Removed - Sherwood Hone Silt Fence Removed- Dean Vogel sode Silt Fence Removed- Sherwood Home Silt Fence Removed- Sherwood Home Silt Fence Removed- Sherwood Home	Lot 276 Lot 277 ken as lot 276 This was a Lot 280 Lot 281 Lot 284 Lot 282 Lot 282	past construction on lot 2 nmend seeding at this tire 117.  117.  11ready sodded.  10 inspection on 7/27/-  116 and removed the silt 11/27/2016.	Removed	se vegetative continue to
Current Condition:  Lot 276  Current Condition:  Lot 277  Current Condition:  Lot 280  Current Condition:  Lot 281  Current Condition:  Lot 284  Current Condition:  Lot 284  Current Condition:	Pending- Dean Vogel disturbuffer in the rear of the lot the monitor the lot.  Silt Fence Removed- Dean Vogel sode Silt Fence Removed- the lot was mistate Silt Fence Removed - Sherwood Hone Silt Fence Removed- Dean Vogel sode Silt Fence Removed- Sherwood Home Silt Fence Removed- Sherwood Home Silt Fence Removed- Oakwood Homes	Lot 276 Lot 277 ken as lot 276 This was a Lot 280 nes sodded the lot prior Lot 281 ded the lot prior to 8/12/20 Lot 284 s sodded the lot prior to 5 Lot 282 s removed the silt fence in	past construction on lot 2 nmend seeding at this tire 117.  117.  11ready sodded.  10 inspection on 7/27/-  116 and removed the silt 11/27/2016.	Removed	se vegetative continue to
Current Condition:  Lot 276  Current Condition:  Lot 277  Current Condition:  Lot 280  Current Condition:  Lot 281  Current Condition:  Lot 284  Current Condition:  Lot 282  Current Condition:  Lot 282  Current Condition:	Pending- Dean Vogel disturbuffer in the rear of the lot the monitor the lot.  Silt Fence Removed- Dean Vogel sode Silt Fence Removed- the lot was mistated by the lot was mist	Lot 276  Lot 276  ded the lot prior to 4/14/20  Lot 277  ken as lot 276 This was a  Lot 280  nes sodded the lot prior  Lot 281  ded the lot prior to 8/12/20  Lot 284  es sodded the lot prior to 5  Lot 282  s removed the silt fence in  Lot 285	past construction on lot 2 nmend seeding at this tire.  117.  118.  119.	Removed	se vegetative continue to
Current Condition:  Lot 276  Current Condition:  Lot 277  Current Condition:  Lot 280  Current Condition:  Lot 281  Current Condition:  Lot 284  Current Condition:  Lot 282  Current Condition:  Lot 282  Current Condition:  Lot 285  Current Condition:	Pending- Dean Vogel disturbuffer in the rear of the lot the monitor the lot.  Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- the lot was mistated by the lot was mist	Lot 276 ded the lot prior to 4/14/20 Lot 277 ken as lot 276 This was a Lot 280 nes sodded the lot prior Lot 281 ded the lot prior to 8/12/20 Lot 284 s sodded the lot prior to 5 Lot 282 s removed the silt fence in Lot 285 s sodded the lot prior to 5	past construction on lot 2 nmend seeding at this tire.  117.  118.  119.	Removed	se vegetative continue to
Current Condition:  Lot 276  Current Condition:  Lot 277  Current Condition:  Lot 280  Current Condition:  Lot 281  Current Condition:  Lot 284  Current Condition:  Lot 282  Current Condition:  Lot 285  Current Condition:  Lot 285  Current Condition:  Lot 286	Pending- Dean Vogel disturbuffer in the rear of the lot the monitor the lot.  Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- the lot was mistate in the solon s	Lot 276 ded the lot prior to 4/14/20 Lot 277 ken as lot 276 This was a Lot 280 nes sodded the lot prior Lot 281 ded the lot prior to 8/12/20 Lot 284 s sodded the lot prior to 5 Lot 282 s removed the silt fence in Lot 285 s sodded the lot prior to 5 Lot 285 s sodded the lot prior to 5 Lot 285 Lot 286	past construction on lot 2 nmend seeding at this tire of the seeding at the seeding of the se	Removed	se vegetative continue to
Current Condition:  Lot 276  Current Condition:  Lot 277  Current Condition:  Lot 280  Current Condition:  Lot 281  Current Condition:  Lot 284  Current Condition:  Lot 282  Current Condition:  Lot 285  Current Condition:  Lot 286  Current Condition:	Pending- Dean Vogel disturbuffer in the rear of the lot the monitor the lot.  Silt Fence Removed- Dean Vogel sode Silt Fence Removed- the lot was mistated by the lot was mist	Lot 276 ded the lot prior to 4/14/20 Lot 277 ken as lot 276 This was a Lot 280 nes sodded the lot prior Lot 281 ded the lot prior to 8/12/20 Lot 284 s sodded the lot prior to 5 Lot 282 s removed the silt fence in Lot 285 s sodded the lot prior to 5 Lot 286 s sodded the lot prior to 5 Lot 286 s sodded the lot prior to 5 Lot 286 s sodded the lot prior to 5	past construction on lot 2 nmend seeding at this tire.  117.  117.  118.  119.	Removed	se vegetative continue to
Current Condition:  Lot 276  Current Condition:  Lot 277  Current Condition:  Lot 280  Current Condition:  Lot 281  Current Condition:  Lot 284  Current Condition:  Lot 282  Current Condition:  Lot 285  Current Condition:  Lot 286  Current Condition:  Lot 286  Current Condition:  Lot 292	Pending- Dean Vogel disturbuffer in the rear of the lot the monitor the lot.  Silt Fence Removed- Dean Vogel sode Silt Fence Removed- the lot was mistated by the lot was mist	Lot 276 ded the lot prior to 4/14/20 Lot 277 ken as lot 276 This was a Lot 280 nes sodded the lot prior Lot 281 ded the lot prior to 8/12/20 Lot 284 es sodded the lot prior to 5 Lot 282 s removed the silt fence in Lot 285 es sodded the lot prior to 5 s sodded the lot prior to 5 Lot 286 s sodded the lot prior to 5 Lot 286 s sodded the lot prior to 5 Lot 286 s sodded the lot prior to in Lot 292	past construction on lot 2 nmend seeding at this tire.  1017.  1017.  1018	Removed Active	se vegetative continue to
Current Condition:  Lot 276  Current Condition:  Lot 277  Current Condition:  Lot 280  Current Condition:  Lot 281  Current Condition:  Lot 284  Current Condition:  Lot 282  Current Condition:  Lot 285  Current Condition:  Lot 286  Current Condition:  Lot 292  Current Condition:	Pending- Dean Vogel disturbuffer in the rear of the lot the monitor the lot.  Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- the lot was mistal Silt Fence Removed - Sherwood Home Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Home Silt Fence Removed- Oakwood Home Silt Fence Removed- Sherwood Homes Silt Fence Good Condition- Pacesetter	Lot 276 ded the lot prior to 4/14/20 Lot 277 ken as lot 276 This was a Lot 280 nes sodded the lot prior Lot 281 ded the lot prior to 8/12/20 Lot 284 s sodded the lot prior to 5 Lot 282 s removed the silt fence in Lot 285 s sodded the lot prior to 5 Lot 286 s sodded the lot prior to 5 Lot 286 s sodded the lot prior to in Lot 292 Homes installed silt fence	past construction on lot 2 nmend seeding at this tire.  117.  117.  118.  119.	Removed Active For to 7/13/17	se vegetative continue to
Current Condition:  Lot 276  Current Condition:  Lot 277  Current Condition:  Lot 280  Current Condition:  Lot 281  Current Condition:  Lot 284  Current Condition:  Lot 282  Current Condition:  Lot 285  Current Condition:  Lot 286  Current Condition:  Lot 292  Current Condition:  Lot 294	Pending- Dean Vogel disturbuffer in the rear of the lot the monitor the lot.  Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- the lot was mistate Silt Fence Removed- Sherwood Home Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Home Silt Fence Removed- Sherwood Home Silt Fence Removed- Oakwood Home Silt Fence Removed- Sherwood Home Silt Fence Good Condition- Pacesetter	Lot 276 ded the lot prior to 4/14/20 Lot 277 ken as lot 276 This was a Lot 280 nes sodded the lot prior Lot 281 ded the lot prior to 8/12/20 Lot 284 s sodded the lot prior to 5 Lot 282 s removed the silt fence in Lot 285 s sodded the lot prior to 5 Lot 286 s sodded the lot prior to 5 Lot 292 Thomes installed silt fence Lot 292	past construction on lot 2 nmend seeding at this tire.  1017.  1017.  1018	Removed Active For to 7/13/17 Active	se vegetative continue to  20/2016.  No
Current Condition:  Lot 276  Current Condition:  Lot 277  Current Condition:  Lot 280  Current Condition:  Lot 281  Current Condition:  Lot 284  Current Condition:  Lot 282  Current Condition:  Lot 285  Current Condition:  Lot 286  Current Condition:  Lot 292  Current Condition:	Pending- Dean Vogel disturbuffer in the rear of the lot the monitor the lot.  Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- the lot was mistan Silt Fence Removed- Sherwood Hone Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Home Silt Fence Removed- Oakwood Home Silt Fence Removed- Sherwood Home Silt Fence Fair Condition- Sherwood Home	Lot 276 ded the lot prior to 4/14/20 Lot 277 ken as lot 276 This was a Lot 280 nes sodded the lot prior Lot 281 ded the lot prior to 8/12/20 Lot 284 s sodded the lot prior to 5 Lot 282 s removed the silt fence in Lot 285 s sodded the lot prior to 5 Lot 286 s sodded the lot prior to 5 Lot 292 r Homes installed silt fence in Lot 294 omes installed silt fence in	past construction on lot 2 nmend seeding at this tire.  1017.  1017.  1018	Removed Active For to 7/13/17 Active	se vegetative continue to  20/2016.  No  Yes
Current Condition:  Lot 276  Current Condition:  Lot 277  Current Condition:  Lot 280  Current Condition:  Lot 281  Current Condition:  Lot 284  Current Condition:  Lot 282  Current Condition:  Lot 285  Current Condition:  Lot 286  Current Condition:  Lot 292  Current Condition:  Lot 294	Pending- Dean Vogel disturbuffer in the rear of the lot the monitor the lot.  Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- the lot was mistate Silt Fence Removed- Sherwood Home Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Home Silt Fence Removed- Sherwood Home Silt Fence Removed- Oakwood Home Silt Fence Removed- Sherwood Home Silt Fence Good Condition- Pacesetter	Lot 276 ded the lot prior to 4/14/20 Lot 277 ken as lot 276 This was a Lot 280 nes sodded the lot prior Lot 281 ded the lot prior to 8/12/20 Lot 284 s sodded the lot prior to 5 Lot 282 s removed the silt fence in Lot 285 s sodded the lot prior to 5 Lot 286 s sodded the lot prior to 5 Lot 292 r Homes installed silt fence in Lot 294 omes installed silt fence in	past construction on lot 2 nmend seeding at this tire.  1017.  1017.  1018	Removed Active For to 7/13/17 Active	se vegetative continue to  20/2016.  No  Yes
Current Condition:  Lot 276  Current Condition:  Lot 277  Current Condition:  Lot 280  Current Condition:  Lot 281  Current Condition:  Lot 284  Current Condition:  Lot 282  Current Condition:  Lot 285  Current Condition:  Lot 286  Current Condition:  Lot 292  Current Condition:  Lot 294	Pending- Dean Vogel disturbuffer in the rear of the lot the monitor the lot.  Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- the lot was mistan Silt Fence Removed- Sherwood Hone Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Home Silt Fence Removed- Oakwood Home Silt Fence Removed- Sherwood Home Silt Fence Fair Condition- Sherwood Home	Lot 276 ded the lot prior to 4/14/20 Lot 277 ken as lot 276 This was a Lot 280 nes sodded the lot prior Lot 281 ded the lot prior to 8/12/20 Lot 284 as sodded the lot prior to 5 Lot 282 s removed the silt fence in Lot 285 as sodded the lot prior to 5 Lot 286 s sodded the lot prior to 5 Lot 292 Homes installed silt fence in Lot 294 omes installed silt fence id d prior to 4/20/17.	last construction on lot 2 mmend seeding at this tire.  1017.  1017.  1018.  1019.  10	Removed Active For to 7/13/17 Active	se vegetative continue to  20/2016.  No  Yes
Current Condition:  Lot 276  Current Condition:  Lot 277  Current Condition:  Lot 280  Current Condition:  Lot 281  Current Condition:  Lot 284  Current Condition:  Lot 282  Current Condition:  Lot 285  Current Condition:  Lot 286  Current Condition:  Lot 292  Current Condition:  Lot 294	Pending- Dean Vogel disturbuffer in the rear of the lot the monitor the lot.  Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- the lot was mistal Silt Fence Removed- Sherwood Home Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Home Silt Fence Removed- Oakwood Home Silt Fence Removed- Sherwood Home Silt Fence Fair Condition- Sherwood Homes Silt Fence	Lot 276 ded the lot prior to 4/14/20 Lot 277 ken as lot 276 This was a Lot 280 nes sodded the lot prior Lot 281 ded the lot prior to 8/12/20 Lot 284 ss sodded the lot prior to 5 Lot 282 s removed the silt fence in Lot 285 ss sodded the lot prior to 5 Lot 286 s sodded the lot prior to 5 Lot 292 'Homes installed silt fence in Lot 294 omes installed silt fence in deprior to 4/20/17. The lot needs cleaned out.	past construction on lot 2 nmend seeding at this tire.  117.  118.  119.	Removed Active south side of the	se vegetative continue to  20/2016.  No
Current Condition:  Lot 276  Current Condition:  Lot 277  Current Condition:  Lot 280  Current Condition:  Lot 281  Current Condition:  Lot 284  Current Condition:  Lot 282  Current Condition:  Lot 285  Current Condition:  Lot 286  Current Condition:  Lot 292  Current Condition:  Lot 294	Pending- Dean Vogel disturbuffer in the rear of the lot the monitor the lot.  Silt Fence Removed- Dean Vogel sode Silt Fence Removed- the lot was mistated silt Fence Removed - Sherwood Home Silt Fence Removed - Dean Vogel sode Silt Fence Removed- Dean Vogel sode Silt Fence Removed- Sherwood Home Silt Fence Removed- Oakwood Home Silt Fence Removed- Sherwood Home Silt Fence Fence Good Condition- Pacesetter Silt Fence Fair Condition- Sherwood Home Silt Fence	Lot 276 ded the lot prior to 4/14/20 Lot 277 ken as lot 276 This was a Lot 280 nes sodded the lot prior Lot 281 ded the lot prior to 8/12/20 Lot 284 ss sodded the lot prior to 5 Lot 282 s removed the silt fence in Lot 285 ss sodded the lot prior to 5 Lot 286 s sodded the lot prior to 5 Lot 292 'Homes installed silt fence in Lot 294 omes installed silt fence in deprior to 4/20/17. The lot needs cleaned out.	past construction on lot 2 nmend seeding at this tire.  117.  118.  119.	Removed Active south side of the	se vegetative continue to
Current Condition:  Lot 276  Current Condition:  Lot 277  Current Condition:  Lot 280  Current Condition:  Lot 281  Current Condition:  Lot 284  Current Condition:  Lot 282  Current Condition:  Lot 285  Current Condition:  Lot 286  Current Condition:  Lot 292  Current Condition:  Lot 294	Pending- Dean Vogel disturbuffer in the rear of the lot the monitor the lot.  Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- the lot was mistal Silt Fence Removed- Sherwood Home Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Home Silt Fence Removed- Oakwood Home Silt Fence Removed- Sherwood Home Silt Fence Fair Condition- Sherwood Homes Silt Fence	Lot 276 ded the lot prior to 4/14/20 Lot 277 ken as lot 276 This was a Lot 280 nes sodded the lot prior Lot 281 ded the lot prior to 8/12/20 Lot 284 ss sodded the lot prior to 5 Lot 282 s removed the silt fence in Lot 285 ss sodded the lot prior to 5 Lot 286 s sodded the lot prior to 5 Lot 292 'Homes installed silt fence in Lot 294 omes installed silt fence in deprior to 4/20/17. The lot needs cleaned out.	past construction on lot 2 nmend seeding at this tire.  117.  118.  119.	Removed Active south side of the	se vegetative continue to

Current Condition:	Good Condition- Pine Crest H	Good Condition- Pine Crest Homes removed the stockpile from the ROW prior to 7/13/17.					
Lot 297	Silt Fence	Lot 297	7/13/2017	Active	No		
Current Condition:	Good Condition- Pacesetter Homes installed silt fence in the rear of the lot prior to 7/13/17						
Lot 300	Silt Fence	Lot 300		Removed			
Current Condition:	Removed- Pinecrest Homes s	odded the lot prior to 7/	31/2015.		!		
Lot 302	Silt Fence	Lot 302	6/28/2017	Active	No		
Current Condition:	Good Condition- Sherwood Ho						
	rear of the lot prior to 6/28/17.				ne none and		
Lot 307	Silt Fence	Lot 307		Removed			
Current Condition:	Removed-Sherwood Homes s	odded the lot prior to 8/	20/2016.				
Lot 310	Silt Fence	Lot 310		Removed			
Current Condition:	Removed- Sherwood Home s	odded the lot prior to 6/	14/17.	-	l.		
Lot 314	Silt Fence	Lot 314	5/11/2017	Active	Yes		
Current Condition:	Fair Condition- THC installed sidewalk and driveway prior to The silt fence in the rear of the THC was informed to complete	e lot needs cleaned out.					
Lot 315	Silt Fence	Lot 315		Removed			
Current Condition:	Removed- Legacy Homes soc	Ided the lot prior to 11/2	22/16.				
Lot 316	Silt Fence	Lot 316	4/21/2017	Pending	Yes		
Current Condition:	Pending- THC removed the di			1 chang	103		
Lot 319	Silt fence needs installed alon THC was informed to complete 7/14/17. Silt Fence		ne as of last inspection.	THC was remind	led on 5/20/17,		
Current Condition:	Removed-Sherwood Homes s		13/2016.	- L	l		
Lot 324	Silt Fence	Lot 324		Removed	<u> </u>		
Current Condition:	Removed-Sherwood Homes s		spection on 7/8/15	Removed			
Lot 325	Silt fence	Lot 325		Removed			
Current Condition:	Removed- Lot was sodded by	Sherwood Homes prior	r to 11/17/2015.		•		
Lot 326	Silt Fence	Lot 326		Removed			
Current Condition:	Removed-Sherwood Homes s		spection on 7/16/15.	<del></del>			
Lot 328	Silt Fence	Lot 328		Removed			
Current Condition: Lot 329	Removed-Oakwood Homes re Silt Fence	emoved silt tence and s Lot 329	odded the lot prior to in 3/6/2017	spection on 5/4/1 Active	5.   No		
Current Condition:	Good Condition- Regency Hor gator guard along the front of prior to 6/23/17.	nes removed the dirt st	ockpile from the ROW	prior to 5/11/17 a	nd installed a		
Lot 336	Temp. Seeding	Lot 336		Removed			
Current Condition:	Removed- As of 8/18/2015, lo	t has filled in and temp	seeding is not needed.		•		
Lot 336	Silt Fence	Lot 336		Removed			
Current Condition:	Removed- Sherwood Homes	sodded the lot prior to 1	0/6/16.				
Lot 337	Silt Fence	Lot 337		Removed			
Current Condition:	Removed-Sherwood Homes r	emoved the silt fence a	nd sodded the lot prior	to inspection on s	5/28/15.		
Lot 344	Silt Fence	Lot 344		Removed			
Current Condition:	Removed- the Home Compan	y sodded the lot prior to	11/1/16.				
Pod F	Silt Fence	Lots 426-454		Removed			
Current Condition:	Removed-Lots 427 and 428 w	'	1/2015 by Celebrity Ho				
Pod G	Silt Fence	Lots 404-425		Removed			
Current Condition:	Removed-Lot 404 was sodded	d prior to 6/29/2016. Po	d has been built out.				
Pod H	Silt Fence	Lots 455-473		Removed			
Current Condition:	Removed- Lot 460 was sodde		rior to the inspection or				
Pod I	Silt Fence	Lots 346-355		Removed			
Current Condition: Pod J	Removed-Lot 355 was sodded		Celebrity Homes.				
Dod I	Silt Fence	Lots 381-394	i	Removed	1		

Current Condition:	Removed- Lot 385 was sodded by Celebrity Homes and the silt was removed from behind lot 383 prior to 5/27/2016. Lot 383 was sodded and the silt fence was repaired on the sides of 386 prior to 6/29/2016. Lot 386 was sodded prior to 8/12/2016. Pod J is built out as of 8/12/2016.				
Pod K	Silt Fence	Lots 372-403		Removed	
Current Condition:	Removed-Celebrity Homes front of lots 380, 378-376 p sodded by Celebrity Homes completion of the sidewalk pod.	rior to 9/13/2016. Lot 380 s prior to 11/1/16. The sil	), 376, and 377 were sodo t fence on the front of lot 3	ded prior to 9/26/ 379 isn't needed	16. Lot 378 was anymore due to
Pod L	Silt Fence	Lots 371-356		Removed	
Current Condition:	Removed- Silt fence was repaired in the rear of lot 360 prior to 9/13/2016 by Celebrity Homes. Lot 365 was sodded prior to inspection on 9/26/16. Silt fence was reinstalled on the front of lots 359, and 364, and repaired on the front of lot 360 prior to inspection on 9/26/16 by Celebrity Homes. Lot 262, and 263 were sodded by Celebrity Homes prior to 11/1/16. Celebrity Homes removed the silt fence behind lots 359-364 and on the front of the lots prior to 11/1/16 presumably in preparation for sodding as the lots were fine graded; inspector will monitor for sodding of the lots. Celebrity Homes sodded lots 364, and 361-359 completing the pod.				
SB 1	Sediment Basin	Outlot "M"	In Place	Active	No
Current Condition:	Good Condition-45% Filled. Vegetation was removed from the basin and the slopes were seeded and matted by the SID prior to inspection on 10/23/14.				
SB 3	Sediment Basin	School Lot 165	In Place	Active	No
Current Condition:	Good Condition-20% Filled -Cleaned out 02/06		•		
SB 5	Sediment Basin	Outlot "L"	11/17/2009	Active	No
Current Condition:	Good Condition- 15% Filled - JC Excavating installed prior to inspection on 11/18/09.				
STR	Street Cleaning	streets	5/1/2007	Active	Yes
Current Condition:	Fair Condition- Pacesetter Homes scraped up dirt from the street in front of lot 297 prior to 6/19/17. Pacetter Homes cleaned the track out from along lot 292 prior to 7/13/17.  Sediment needs removed from along lot 329.  Regency Homes was informed to complete by 5/24/17. Not done as of last inspection. Regency Homes was reminded on 6/20/17, 7/1/17.				
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No
Current Condition:	Good Condition: 48th and E	Birchwood Drive			
Inspector Signature:	the		Reviewed By:	G.A. 6	he