E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Friday

Saturday

Engineering Answers

Environmental Services Dept. Manag	ger	Engineering Answers				
	E&A- P2005.198.0 E&A-P2005.198.009	000 (Clearwater Falls (Clearwater Falls Tr				
Inspector: Matthew Russell		•	,		Stage	
Project Name:	Clearwater Falls/Clearwater Falls Trail CSW-201701144					
For Week Ending:		4/14/2018				
Project Location:	48th and Fairview Road- Bellevue, NE (Sarpy County)				68123	
Grading:	100%	100%				
Sanitary Sewer: Storm Sewer:	100% 100%	N/A N/A				
Paving:	100%	100%				
Seeding:	100%	50%				
Utilities:	100%	N/A				
Overall Development:	87%	75%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions			
Cundous	0.00"				Week '	
Sunday: Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	1.20"					
Saturday	0.00"	03/17/18	Cloudy 39/33			
Sunday:	0.12"				Week 2	
Monday	0.09"	03/19/18	Rain 51/33			
Tuesday	0.05	03/13/10	Italii 51/55			
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.02"					
Saturday	0.75"	03/24/18	Tstorm 42/33			
outurally	0.70	33.2 11.10	10001111 12300		Week	
Sunday:	0.00"					
Monday	0.23"					
Tuesday	0.00"	03/27/18	Partly Cloudy 51/30			
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
Sunday:	0.00"				Week 4	
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
	0.000				Week	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday Friday	0.00"					
Friday	10.00"	İ	1			

0.00"

0.00"

	1				
On any lateral	None				
Complaints:	-				
				I	
Construction Sequencing:				ļ.	
Which portion(s) (i.e. drainage basins) of the site have h	ad a temporary or permanent ces	sation of grading, earthwork,	or ground disturbance in th	e last 14 days?	
Grading completed and entire site seeded prior to	o 2005.				
Entire Site; JC Excavating completed grading Lo	ts 346 through 480 Section II	, drainage area 1 and 2 (1	1/2009).		
Entire site is now inactive for major grading activi					
Grading for the Clearwater Falls Trail has ceased	d as of inspection on 12/18/1	7.			
Which portion(s) (i.e. drainage basins) of the site do not		nd disturbance scheduled in	the next 14 days? :		
Grading completed and entire site seeded prior to		-li	4/0000		
Entire Site; JC Excavating completed grading Log Entire site is now inactive for major grading activities.	•	,	1/2009).		
Grading for the Clearwater Falls Trail has ceased	•				
Crading for the cloarwater raile frammae coace	T	' · I		ı	
What temporary or permanent stabilization measures lis	ted in this section are being impl	emented?			
Paving, dense vegetation and landscaping, Seed			ID (10/08) Sod on vario	us lots (Fall '08)	New phase
lots 346-480, seeded (4/10); Outlot B was seede					
and 43rd Avenue was temp seeded (5/22/2014);					
side slopes surrounding outlot M Basin (12/15/20	014); <mark>John Navarro installe</mark> c	I the erosion control ma	tting 1 & 2 for the trail	project (1/17/18).
SUMMARY QUESTIONS:					
Are approved entrances and adjacent streets being main	ntained adequately?				
No- see BMP section	alautikaant alaus of ausalau ausa	diment that would be seen in	4 - d	41-44-2	
Are receiving waters adjacent to the project free of any Yes	significant signs of erosion or se	diment that would be associa	ted with the construction ac	ctivity?	
CHECKLIST QUESTIONS:					
Are waste materials (concrete, construction material, ha	zardous, etc.) being managed pro	operly?			
165				I	
Is dust associated with the construction activity adequa	tely controlled on the site?			•	
Yes	I	I		I	
Comments:					
Comments:					
Home Construction is active in the North part of t	the development by various b	ouilders.			
Outlot J was disturbed when construction equ	uipment used it to access le	ot 279.			
Findings / Corrective Actions (Date):					
Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se	ation				
1.) Some maintenance is required in the BMP Se	cuon.	T			
Unique Name	Type	Location	Projected Install Date	Status	Maintenance
CW 5	Concrete Washout	Lot 387	ojecteu matan Date	Removed	Mannenance
Current Condition:	Removed-Celebrity Homes		shout prior to inspection		
CW 6	Concrete Washout	Lot 359		Removed	
Current Condition:	Removed- Washout pit was	removed by Celebrity Ho	mes prior to 3/30/2016.		
OW 7	0 1 101 1 1	1 1004		Б	
CW 7 Current Condition:	Concrete Washout Removed- due to the progre	Lot 361	l lote will be reconcible	Removed	te waste
Current Condition:	Builders will washout on the		•		
	install a washout.	ii owii iots, ii a wasiiout b	econies needed the msp	Dector will innorm	the applicant to
Lot 16	Individual Lot	Lot 16		Removed	
Current Condition:	Removed- Outlot B was see		on Homes prior to 5/27/2		
Lot 17	Individual Lot	Lot 17		Removed	
Current Condition:	Removed- Newport Homes		12/2015.		
Lot 54	Silt Fence	Lot 54		Removed	
Current Condition:	Removed-Nick Peterson so		ction on 5/28/15.		
Lot 57	Silt Fence	Lot 57		Removed	
Current Condition:	Removed-Horizon Homes s		ection on 5/28/15.	Domessed	
Lot 59 Current Condition:	Individual Lot Removed- Horizon Homes	Lot 59	L 12/2015	Removed	
Lot 60	Silt Fence	Lot 60	12/2010.	Removed	
Current Condition:	Removed- Horizon Homes		1/16.		
Lot 65	Silt Fence	Lot 65	12/18/2017	Active	Yes
1 201.00	J		,		

Current Condition:	Fair Condition - The Home Company began construction on the lot prior to inspection on 12/18/17. No BMPs are required at this time.					
	Sediment in the streets needs to be cleaned daily.					
	The Home Company was	informed to complete by	3/20/18.			
Lot 68	Silt Fence	Lot 68	2/3/2017	Active	No	
Current Condition:	Good Condition - Pacesette		· ·			
	set to begin on the lot. Pace The silt fence alread in pla			rior to inspectio	n on 3/19/18.	
1.100	·	T	l			
Lot 69	Silt Fence	Lot 69	7/40/47	Removed		
Current Condition: Lot 76	Removed- Sherwood Home Silt Fence	Lot 76	/13/17. I	Removed	<u> </u>	
Current Condition:	Removed- Lot was sodded		<u> </u> 7/31/2015.	Removed		
Lot 80	Silt Fence	Lot 80		Removed		
Current Condition: Lot 82	Removed- Horizon Homes	sodded the lot prior to 6/1 Lot 82	1/2015. I	Removed		
Current Condition:	Removed- Lot was sodded		<u> </u> 9/18/2015.	Removed		
Lot 88	Silt Fence	Lot 88		Removed		
Current Condition:	Removed- Legacy Homes s	sodded the lot prior to 11/2	22/16.			
Lot 89	Individual Lot	Lot 89	44/4/40	Removed		
Current Condition: Lot 132	Removed- the Home Comp Silt Fence	any sodded the lot prior to) 11/1/16. I	Removed		
Current Condition:	Removed- Regency Homes		<u> </u> 19/2015	Removed		
Lot 155	Silt Fence	Lot 155		Removed		
Current Condition:	Removed- Regency Homes		19/2015.	D	•	
Lot 209-210 Current Condition:	Silt Fence Removed- Celebrity Homes	Lots 209-210	/1/16 Celebrity Homes	Removed the rem	l naining silt fence	
Garrent Gonation.	prior to 3/27/17.	sodded the lot phor to 11	71710. Ociobility Homes		idining Silt Terroe	
Lot 255	Individual Lot	Lot 255		Removed		
Current Condition:	Removed - Legacy Homes	sodded the lot prior to the	6/24/15 inspection.	1	T	
Lot 256 Current Condition:	Silt Fence Removed- Regency Homes	Lot 256 s sodded the lot prior to 11	/22/16.	Removed		
Lot 257	Individual Lot	Lot 257	3/19/2018	Active	Yes	
Current Condition:	Fair Condition - The Home Home Company installed	Company began const	ruction on the lot prior	to inspection o	n 3/19/18. The	
Current Condition: Lot 258	Home Company installed Silt Fence	e Company began constraint fence around the per	ruction on the lot prior	to inspection o	n 3/19/18. The	
Lot 258 Current Condition:	Silt Fence Removed-Charleston Home	e Company began const silt fence around the per Lot 258 es sodded the lot prior to in	ruction on the lot prior	to inspection of to inspection of Removed	n 3/19/18. The	
Lot 258 Current Condition: Lot 259	Silt Fence Removed-Charleston Home Silt Fence	Lot 258 es sodded the lot prior to in Lot 259	ruction on the lot prior rimeter of the lot pr	to inspection o to inspection or	n 3/19/18. The	
Lot 258 Current Condition:	Silt Fence Removed-Charleston Home	Lot 258 es sodded the lot prior to in Lot 259	ruction on the lot prior rimeter of the lot pr	to inspection of to inspection of Removed	n 3/19/18. The	
Lot 258 Current Condition: Lot 259 Current Condition: Lot 260	Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Individual Lot	Lot 258 es sodded the lot prior to in Lot 259 es sodded the lot prior to in Lot 260	ruction on the lot prior rimeter of the lot pr	to inspection of to inspection of Removed	n 3/19/18. The	
Lot 258 Current Condition: Lot 259 Current Condition: Lot 260 Current Condition:	Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Individual Lot Removed- Sherwood Home	Lot 258 es sodded the lot prior to it Lot 260 es sodded the lot prior to sodded the lot prior to it Lot 260 es sodded the lot prior to 50 Lot 260 es sodded the lot prior to 50 es sodded the lot prior to 50 es sodded the lot prior to 50	ruction on the lot prior rimeter of the lot pr	Removed Removed Removed	n 3/19/18. The	
Lot 258 Current Condition: Lot 259 Current Condition: Lot 260 Current Condition: Lot 261	Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Individual Lot Removed- Sherwood Home Individual Lot	Lot 258 es sodded the lot prior to in Lot 260 es sodded the lot prior to in Lot 260 es sodded the lot prior to 5 Lot 261	ruction on the lot prior rimeter of the lot pr	Removed Removed	n 3/19/18. The	
Lot 258 Current Condition: Lot 259 Current Condition: Lot 260 Current Condition:	Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Individual Lot Removed- Sherwood Home	Lot 258 es sodded the lot prior to in Lot 260 es sodded the lot prior to in Lot 260 es sodded the lot prior to 5 Lot 261	ruction on the lot prior rimeter of the lot pr	Removed Removed Removed	n 3/19/18. The	
Lot 258 Current Condition: Lot 259 Current Condition: Lot 260 Current Condition: Lot 261 Current Condition:	Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Individual Lot Removed- Sherwood Home Individual Lot Removed- Sherwood Home Individual Lot Removed- Sherwood Home	Lot 258 es sodded the lot prior to in Lot 260 es sodded the lot prior to in Lot 260 es sodded the lot prior to 5 Lot 261 es sodded the lot prior to 5 Lot 272	nspection on 5/14/15. nspection on 5/14/15. nspection on 5/14/15.	to inspection of to inspection of to inspection of the inspection	n 3/19/18. The	
Lot 258 Current Condition: Lot 259 Current Condition: Lot 260 Current Condition: Lot 261 Current Condition: Lot 272	Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Individual Lot Removed- Sherwood Home Individual Lot Removed- Sherwood Home Silt Fence	Lot 258 es sodded the lot prior to in Lot 260 es sodded the lot prior to in Lot 260 es sodded the lot prior to 5 Lot 261 es sodded the lot prior to 5 Lot 272	nspection on 5/14/15. nspection on 5/14/15. nspection on 5/14/15.	to inspection of to inspection of to inspection of the inspection	n 3/19/18. The	
Lot 258 Current Condition: Lot 259 Current Condition: Lot 260 Current Condition: Lot 261 Current Condition: Lot 261 Current Condition: Lot 272 Current Condition:	Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Individual Lot Removed- Sherwood Home Individual Lot Removed- Sherwood Home Silt Fence Removed- Dean Vogel sode	Lot 258 es sodded the lot prior to in Lot 260 es sodded the lot prior to 5 Lot 261 es sodded the lot prior to 5 Lot 261 es sodded the lot prior to 5 Lot 272 ded the lot prior to 8/12/20	nspection on 5/14/15. nspection on 5/14/15. nspection on 5/14/15.	to inspection of the inspectio	n 3/19/18. The	
Lot 258 Current Condition: Lot 259 Current Condition: Lot 260 Current Condition: Lot 261 Current Condition: Lot 272 Current Condition: Lot 273 Current Condition:	Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Individual Lot Removed- Sherwood Home Individual Lot Removed- Sherwood Home Silt Fence Removed- Dean Vogel sode Silt Fence Removed- Sherwood Home	Lot 258 es sodded the lot prior to is Lot 260 es sodded the lot prior to is Lot 260 es sodded the lot prior to 5 Lot 261 es sodded the lot prior to 5 Lot 272 ded the lot prior to 8/12/20 Lot 273 es sodded the lot prior to 5	nspection on 5/14/15. nspection on 5/14/15. nspection on 5/14/15.	to inspection of to inspection of to inspection of the inspection	n 3/19/18. The	
Lot 258 Current Condition: Lot 259 Current Condition: Lot 260 Current Condition: Lot 261 Current Condition: Lot 272 Current Condition: Lot 273	Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Individual Lot Removed- Sherwood Home Individual Lot Removed- Sherwood Home Silt Fence Removed- Dean Vogel sode	Lot 258 es sodded the lot prior to in Lot 260 es sodded the lot prior to in Lot 260 es sodded the lot prior to 5 Lot 261 es sodded the lot prior to 5 Lot 272 ded the lot prior to 8/12/20 Lot 273 es sodded the lot prior to 5 Lot 273 es sodded the lot prior to 5 Lot 273 es sodded the lot prior to 5 Lot 274	nspection on the lot prior makes of the lot p	to inspection of the inspectio	n 3/19/18. The	
Lot 258 Current Condition: Lot 259 Current Condition: Lot 260 Current Condition: Lot 261 Current Condition: Lot 272 Current Condition: Lot 273 Current Condition: Lot 273 Current Condition: Lot 274	Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Individual Lot Removed- Sherwood Home Individual Lot Removed- Sherwood Home Silt Fence Removed- Dean Vogel sode Silt Fence Removed- Sherwood Home Silt Fence Removed- Regency Homes	Lot 258 es sodded the lot prior to in Lot 260 es sodded the lot prior to in Lot 260 es sodded the lot prior to 5 Lot 261 es sodded the lot prior to 5 Lot 272 ded the lot prior to 8/12/20 Lot 273 es sodded the lot prior to 5 Lot 273 es sodded the lot prior to 5 Lot 273 es sodded the lot prior to 5 Lot 274	ruction on the lot prior rimeter of the lot pr	to inspection of to inspection of to inspection of to inspection of the inspection o	n 3/19/18. The	
Lot 258 Current Condition: Lot 259 Current Condition: Lot 260 Current Condition: Lot 261 Current Condition: Lot 272 Current Condition: Lot 273 Current Condition: Lot 274 Current Condition:	Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Individual Lot Removed- Sherwood Home Individual Lot Removed- Sherwood Home Silt Fence Removed- Dean Vogel sode Silt Fence Removed- Sherwood Home Silt Fence Removed- Sherwood Home	Lot 258 es sodded the lot prior to in Lot 260 es sodded the lot prior to in Lot 260 es sodded the lot prior to 5 Lot 261 es sodded the lot prior to 5 Lot 272 ded the lot prior to 8/12/20 Lot 273 es sodded the lot prior to 5 Lot 274 s sodded the lot prior to 12 Lot 274 Lot 275	ruction on the lot prior rimeter of the lot pr	to inspection of to inspection of to inspection of to inspection of the inspection o	n 3/19/18. The n 3/19/18.	
Lot 258 Current Condition: Lot 259 Current Condition: Lot 260 Current Condition: Lot 261 Current Condition: Lot 272 Current Condition: Lot 273 Current Condition: Lot 274 Current Condition: Lot 274 Current Condition: Lot 275	Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Individual Lot Removed- Sherwood Home Individual Lot Removed- Sherwood Home Silt Fence Removed- Dean Vogel sode Silt Fence Removed- Sherwood Home Silt Fence Removed- Regency Homes Individual Lot Good Condition - Pacesette Homes installed silt fence in	Lot 258 es sodded the lot prior to is less sodded the lot prior to 5 Lot 260 es sodded the lot prior to 5 Lot 261 es sodded the lot prior to 5 Lot 272 ded the lot prior to 8/12/20 Lot 273 es sodded the lot prior to 5 Lot 274 s sodded the lot prior to 5 Lot 275 er Homes began construct the rear of the lot prior to 5 to 10 t	ruction on the lot prior rimeter of the lot prior to institute of	to inspection of to inspection of to inspection of to inspection of the inspection o	No 18. Pacesetter	
Lot 258 Current Condition: Lot 259 Current Condition: Lot 260 Current Condition: Lot 261 Current Condition: Lot 272 Current Condition: Lot 273 Current Condition: Lot 274 Current Condition: Lot 274 Current Condition: Lot 275	Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Individual Lot Removed- Sherwood Home Individual Lot Removed- Sherwood Home Silt Fence Removed- Dean Vogel sode Silt Fence Removed- Sherwood Home Silt Fence Removed- Regency Homes Individual Lot Good Condition - Pacesette	Lot 258 es sodded the lot prior to is less sodded the lot prior to 5 Lot 260 es sodded the lot prior to 5 Lot 261 es sodded the lot prior to 5 Lot 272 ded the lot prior to 8/12/20 Lot 273 es sodded the lot prior to 5 Lot 274 s sodded the lot prior to 5 Lot 275 er Homes began construct the rear of the lot prior to 5 to 10 t	ruction on the lot prior rimeter of the lot prior to institute of	to inspection of to inspection of to inspection of to inspection of the inspection o	No 18. Pacesetter	
Lot 258 Current Condition: Lot 259 Current Condition: Lot 260 Current Condition: Lot 261 Current Condition: Lot 272 Current Condition: Lot 273 Current Condition: Lot 274 Current Condition: Lot 275 Current Condition:	Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Individual Lot Removed- Sherwood Home Individual Lot Removed- Sherwood Home Silt Fence Removed- Dean Vogel sode Silt Fence Removed- Sherwood Home Silt Fence Removed- Regency Homes Individual Lot Good Condition - Pacesette Homes installed silt fence in	Lot 258 es sodded the lot prior to is less sodded the lot prior to 5 Lot 260 es sodded the lot prior to 5 Lot 261 es sodded the lot prior to 5 Lot 272 ded the lot prior to 8/12/20 Lot 273 es sodded the lot prior to 5 Lot 274 s sodded the lot prior to 5 Lot 275 er Homes began construct the rear of the lot prior to 5 to 10 t	ruction on the lot prior rimeter of the lot prior to institute of	to inspection of to inspection of to inspection of to inspection of the inspection o	No 18. Pacesetter	
Lot 258 Current Condition: Lot 259 Current Condition: Lot 260 Current Condition: Lot 261 Current Condition: Lot 272 Current Condition: Lot 273 Current Condition: Lot 274 Current Condition: Lot 275 Current Condition:	Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Individual Lot Removed- Sherwood Home Individual Lot Removed- Sherwood Home Silt Fence Removed- Dean Vogel sode Silt Fence Removed- Sherwood Home Silt Fence Removed- Regency Homes Individual Lot Good Condition - Pacesette Homes installed silt fence in Pacesetter Homes prior to	Lot 258 es sodded the lot prior to is less sodded the lot prior to 5 Lot 260 es sodded the lot prior to 5 Lot 261 es sodded the lot prior to 5 Lot 272 ded the lot prior to 8/12/20 Lot 273 es sodded the lot prior to 5 Lot 274 s sodded the lot prior to 12 Lot 275 er Homes began construct the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 6 in the rear of the lot prior	ruction on the lot prior rimeter of the lot prior to inspection on 1/24/18.	to inspection of to inspection of to inspection of to inspection of the inspection o	No 18. Pacesetter	
Lot 258 Current Condition: Lot 259 Current Condition: Lot 260 Current Condition: Lot 261 Current Condition: Lot 272 Current Condition: Lot 273 Current Condition: Lot 274 Current Condition: Lot 275 Current Condition:	Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Individual Lot Removed- Sherwood Home Individual Lot Removed- Sherwood Home Silt Fence Removed- Dean Vogel sode Silt Fence Removed- Sherwood Home Silt Fence Removed- Regency Homes Individual Lot Good Condition - Pacesette Homes installed silt fence in Pacesetter Homes prior to	Lot 258 es sodded the lot prior to is less sodded the lot prior to 5 Lot 260 es sodded the lot prior to 5 Lot 261 es sodded the lot prior to 5 Lot 272 ded the lot prior to 8/12/20 Lot 273 es sodded the lot prior to 5 Lot 274 s sodded the lot prior to 12 Lot 275 er Homes began construct the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 5 in the rear of the lot prior to 6 in the rear of the lot prior	ruction on the lot prior rimeter of the lot prior to inspection on 1/24/18.	to inspection of to inspection of to inspection of to inspection of the inspection o	No 18. Pacesetter	
Lot 258 Current Condition: Lot 259 Current Condition: Lot 260 Current Condition: Lot 261 Current Condition: Lot 272 Current Condition: Lot 273 Current Condition: Lot 274 Current Condition: Lot 275 Current Condition: Lot 276 Current Condition:	Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Individual Lot Removed- Sherwood Home Individual Lot Removed- Sherwood Home Silt Fence Removed- Dean Vogel sode Silt Fence Removed- Regency Homes Individual Lot Silt Fence Removed- Sherwood Home Silt Fence Removed- Sherwood Home Silt Fence Removed- Regency Homes Individual Lot Good Condition - Pacesette Homes installed silt fence in Pacesetter Homes prior to Silt Fence Removed- Dean Vogel sode Silt Fence	Lot 258 es sodded the lot prior to is Lot 260 es sodded the lot prior to is Lot 260 es sodded the lot prior to 5 Lot 261 es sodded the lot prior to 5 Lot 272 ded the lot prior to 8/12/20 Lot 273 es sodded the lot prior to 5 Lot 274 es sodded the lot prior to 12 Lot 275 er Homes began construct of the rear of the lot prior to 2 inspection on 3/27/18. Lot 276 ded the lot prior to 4/14/20 Lot 277	ruction on the lot prior rimeter of the lot prior to inspection on the lot prior to inspection on 1/24/18. sinspection on 1/24/18.	to inspection of to inspection of to inspection of to inspection of the inspection o	No 18. Pacesetter	
Lot 258 Current Condition: Lot 259 Current Condition: Lot 260 Current Condition: Lot 261 Current Condition: Lot 272 Current Condition: Lot 273 Current Condition: Lot 274 Current Condition: Lot 275 Current Condition: Lot 276 Current Condition:	Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Silt Fence Removed-Charleston Home Individual Lot Removed- Sherwood Home Individual Lot Removed- Sherwood Home Silt Fence Removed- Dean Vogel sode Silt Fence Removed- Removed- Sherwood Home Silt Fence Removed- Sherwood Home Silt Fence Removed- Sherwood Home Silt Fence Removed- Regency Homes Individual Lot Good Condition - Pacesette Homes installed silt fence in Pacesetter Homes prior to Silt Fence Removed- Dean Vogel sode	Lot 258 es sodded the lot prior to is Lot 260 es sodded the lot prior to is Lot 260 es sodded the lot prior to 5 Lot 261 es sodded the lot prior to 5 Lot 272 ded the lot prior to 8/12/20 Lot 273 es sodded the lot prior to 5 Lot 274 es sodded the lot prior to 12 Lot 275 er Homes began construct of the rear of the lot prior to 2 inspection on 3/27/18. Lot 276 ded the lot prior to 4/14/20 Lot 277	ruction on the lot prior rimeter of the lot prior to inspection on the lot prior to inspection on 1/24/18. sinspection on 1/24/18.	Removed	No 18. Pacesetter	

Current Condition:	Active - The Home Compan	y began construction on t	he lot prior to inspection	on 1/17/18. No	BMPs are need	
Lot 280	Silt Fence	Lot 280		Removed		
Current Condition:	Removed - Sherwood Home		nspection on 7/27/17	Removed		
Lot 281	Silt Fence	Lot 281		Removed		
Current Condition:	Removed- Dean Vogel sodo		16 and removed the silt		20/2016.	
Lot 284	Silt Fence	Lot 284		Removed		
Current Condition:	Removed- Sherwood Home	s sodded the lot prior to 5	/27/2016.	•		
Lot 282	Silt Fence	Lot 282		Removed		
Current Condition:	Removed- Oakwood Homes	s removed the silt fence in	the rear prior to 7/26/20			
Lot 285	Silt Fence	Lot 285	•	Removed		
Current Condition:	Removed- Sherwood Home	es sodded the lot prior to 5	/11/17.			
Lot 286	Silt Fence	Lot 286		Removed		
Current Condition:	Removed-Sherwood Homes	s sodded the lot prior to in	spection on 7/8/15.			
Lot 291	Silt Fence	Lot 291	1/17/2018	Active	Yes	
Current Condition:	Fair Condition-					
	Silt Fence in the back of the Sherwood Homes was info					
Lot 292	Silt Fence	Lot 292		Removed		
Current Condition:	Removed - Pacesetter Hom		inspection on 10/9/17.			
Lot 293	Silt Fence	Lot 293	12/25/2017	Active	No	
Current Condition:	Good Condition- The Home Home Company installed si					
			e of the lot prior to inspe		•	
Lot 294 Current Condition:	Silt Fence	Lot 294	nonaction on 10/0/17	Removed		
Current Condition:	Removed - Sherwood Home	es sodded the lot prior to i	nspection on 10/9/17.	,		
Lot 296 Current Condition:	Silt Fence	Lot 296	6/28/2017	Active	No inkler and	
Current Condition.	Good Condition- Pine Crest Homes removed the stockpile from the ROW prior to 7/13/17. Sprinkler and utilities have been marked and the lot is ready to be stabilized in the spring as of inspection on 1/24/18. Silt fence in the rear of the lot was removed and no additional BMPs will be recommended a this time.					
Lot 297	Silt Fence	Lot 297	7/13/2017	Active	No	
Current Condition:	Good Condition- Pacesetter	Homes installed silt fence	e in the rear of the lot pri	ior to 7/13/17		
Lot 299	Silt Fence	Lot 299	1/25/2018	Pending	Yes	
Current Condition:	Pending - The Home Company Company removed the dirt of the Lorentz State	talled on the front of the lost talled on the front of the lost talled on the front of the lost talled on the curbline. The paired in the NW corner talled on the lost talled on the lo	ot prior to inspection on 1 ot. r of the lot. complete when weather of	conditions allow.		
Lot 300	Silt Fence Removed- Pinecrest Homes	Lot 300	24/2045	Removed		
Current Condition:			J 1/2010.			
Lot 302	Silt Fence	Lot 302		Removed		
Current Condition:	Removed - Sherwood Home	•	nspection on 12/18/17.			
Lot 307	Silt Fence	Lot 307	20/2016	Removed		
Current Condition:	Removed-Sherwood Homes		ZU/ZU10.			
Lot 310	Silt Fence	Lot 310		Removed		
Current Condition:	Removed- Sherwood Home	sodded the lot prior to 6/	14/17.			
Lot 314	Silt Fence	Lot 314		Removed		
Current Condition:	Removed - The Home Com	pany sodded the lot prior	to inspection on 8/22/17		-	
Lot 315	Silt Fence	Lot 315		Removed		
Current Condition:	Removed- Legacy Homes s	odded the lot prior to 11/2	2/16.			
Lot 316	Silt Fence	Lot 316		Removed		
Current Condition:	Removed - THC sodded the	•	9/19/17.			
Lot 319	Silt Fence	Lot 319	140/0040	Removed		
Current Condition:	Removed-Sherwood Homes	s sodded the lot prior to 9/	13/2016.			

Lot 324	Silt Fence	Lot 324	I	Removed	1
Current Condition:	Removed-Sherwood Homes		spection on 7/8/15	Removed	
Lot 325	Silt fence	Lot 325	Specifor on 7/6/13.	Removed	
Current Condition:	Removed- Lot was sodded		r to 11/17/2015.	1.0	
Lot 326	Silt Fence	Lot 326		Removed	
Current Condition:	Removed-Sherwood Homes		spection on 7/16/15.		
Lot 328	Silt Fence	Lot 328		Removed	
Current Condition:	Removed-Oakwood Homes				
Lot 329	Silt Fence	Lot 329	3/6/2017	Active	Yes
Current Condition:	Fair Condition- Regency Ho gator guard along the front of prior to 6/23/17. Regency Hi Regency Homes paved the The silt fence on the side of stabilized.	of the lot. Regency Homes omes replaced the erosion e sidewalk prior to inspe of the lot is damaged an	s reinstalled the gator gan n eels around the lot pri- ection on 3/19/18. d needs to be repaired	aurds along the for to inspection of	ront of the lot on 9/19/17. s to be
Lot 336	Temp. Seeding	Lot 336	l	Removed	l l
Current Condition:	Removed- As of 8/18/2015,		l seeding is not needed	Removed	
Lot 336	Silt Fence	Lot 336		Removed	1
Current Condition:	Removed- Sherwood Home		0/6/16.	rtomovou	
		·			
Lot 337	Silt Fence	Lot 337		Removed	
Current Condition:	Removed-Sherwood Homes	s removed the silt fence a	nd sodded the lot prior t	o inspection on	5/28/15.
				_	
Lot 344	Silt Fence	Lot 344		Removed	
Current Condition:	Removed- the Home Compa		o 11/1/16.		
Pod F	Silt Fence	Lots 426-454		Removed	
Current Condition:	Removed-Lots 427 and 428	were sodded prior to 12/	1/2015 by Celebrity Hon	nes.	
Pod G	Silt Fence	Lots 404-425		Removed	
Current Condition:	Removed-Lot 404 was sodo		L d has been built out.	removed	
		•			
Pod H	Silt Fence	Lots 455-473		Removed	
Current Condition:	Removed- Lot 460 was sod		prior to the inspection on		
Pod I Current Condition:	Silt Fence Removed-Lot 355 was sodo	Lots 346-355	Colobrity Homos	Removed	
Pod J	Silt Fence	Lots 381-394	Telebrity Hornes.	Damayad	1
Current Condition:	Removed - Pod J is built ou			Removed	
Pod K	Silt Fence	Lots 372-403		Removed	ı
Current Condition:	Removed - Celebrity Homes		1/22/16 completing the		
Pod L	Silt Fence	Lots 371-356	I	Removed	1
Current Condition:	Removed - Celebrity Homes		1 350 completing the po		
SB 1	Sediment Basin	Outlot "M"	In Place	Active	No
Current Condition:	Good Condition-45% Filled.				
Current Condition.	by the SID prior to inspection inspection on 9/19/17.				
SB 3		School Lot 165	In Place	Active	No
Current Condition:	Good Condition-20% Filled -Cleaned out 02/06				
SB 5	Sediment Basin	Outlot "L"	11/17/2009	Active	No
Current Condition:	Good Condition- 15% Filled	Juliot L		, 101170	110
3.1.3.1.3.1.3.1.	- JC Excavating installed pri	•	09.		
05		er Falls Trail	10/0/22 :=		
CD 1	Check Dam	Northern side of site	10/2/2017	Active	No
Current Condition:	Good Condition - John Nav				1
EM 1	Erosion Control Matting	East side of site	10/2/2017	Active	No
Current Condition:	Good Condition -John Nava				
EM 2	Erosion Control Matting	West side of site	10/2/2017	Active	Yes
Current Condition:	Fair Condition - BMP will be control matting prior to inspect the erosion control matting	ection on 1/17/18.			the erosion
	John Navarro was informed				
SF 1	Silt Fence	Southern side of site	11/27/2017	Pending	Yes

Current Condition:	Pending - BMP will be installed once grading has begun on site.					
	The silt fence needs to be installed John Navarro was informed to complete by 11/27/17. Not done as of last inspection. John Navarro was reminded on 3/7/18.					
SF 2	Silt Fence	Southern side of site	11/27/2017	Pending	Yes	
Current Condition:	Pending - BMP will be installed once grading has begun on site. The silt fence needs to be installed John Navarro was informed to complete by 11/27/17. Not done as of last inspection. John Navarro was reminded on 3/7/18.					
SF 3	Silt Fence	Southern side of site		Removed		
Current Condition:	Removed - John Navarro s required.	tabilized the area prior to ir	nspection on 3/6/18 and	the silt fence is r	no longer	
SF 4	Silt Fence	Northern side of site	11/27/2017	Pending	Yes	
Current Condition:	Pending - BMP will be insta	illed once grading has begi	un on site.			
	The silt fence needs to be installed John Navarro was informed to complete by 11/27/17. Not done as of last inspection. John Navarro was reminded on 3/7/18.					
IP 1	Inlet Protection	Southern side of site	11/27/2017	Pending	Yes	
Current Condition:	Pending - BMP will be installed once grading has begun on site. The inlet protection needs to be installed John Navarro was informed to complete by 11/27/17. Not done as of last inspection. John Navarro was reminded on 3/7/18.					
STR	Street Cleaning	streets	5/1/2007	Active	Yes	
Current Condition:	Fair Condition- Pacesetter Homes scraped up dirt from the street in front of lot 297 prior to 6/19/17. Pacetter Homes cleaned the track out from along lot 292 prior to 7/13/17. Regency Homes cleaned the track out in front of lot 329. Track out was cleaned in front of lot 302 prior to inspection on 10/9/17. Street in between the trail entrance and the park needs to be cleaned. John Navarro was informed to complete by 12/11/17. Not done as of last inspection. John Navarro was reminded on 3/7/18.					
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No	
Current Condition:	Good Condition: 48th and E	Birchwood Drive				
المجاورة Inspector Signature:	tologe		Reviewed By:	Posts &	he	