E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Environmental Services Dep				Engineering .	Answers	
Inspector: Zach Roza		&A- P2006.056.019	1		Stage	
inspector. Zacii Roza	C	Courtyards @ Iron Horse CSW-202207403				
Project Name:					68003	
For Week Ending:		3/23/2024				
Project Location:	South Lakeview Way	and Courtyard Court -	Ashland, NE (Saunders Cou	inty)		
Grading:	80%					
Sanitary Sewer:	5%					
Storm Sewer:	0%					
Paving:	0%					
Seeding:	80%					
Utilities:	0%					
Overall Development:	10%					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Duration	
		·			Week 1	
Sunday:	0.00"					
Monday:	0.00"					
Tuesday:	0.00"	0/00/0004	Mandle Co. 45 100	40.45.534		
Wednesday:	0.00"	3/20/2024	Mostly Sunny 45 / 33	12:15 PM		
Thursday: Friday:	0.00					
Saturday:	0.00"					
oaturuay.	0.00					
0	None					
Complaints:						
What temporary or permanent stab	ting began (9/13/23). Grading ceased (11/22/23) dilization measures listed in this section are being implication Matting 1,2,3,4,6,7 installed (11/1/23). Se	emented?		eded (3/13/24).		
	nt to the project free of any significant signs	of erosion or sedimen	t that would be associated	with the construction	n activity?	
Yes						
Create Corrective Action? N/A						
Have disturbed areas been s prevent erosion. Yes	seeded or otherwise stabilized as required? I	List inactive portions o	f the project and if stabiliza	tion measure are ad	lequate or needed to	
Create Corrective Action? N/A						
Are waste materials (concretes Yes	te, construction material, hazardous, etc.) be	eing managed properly	7			
Create Corrective Action?						
Are construction entrances	and adjacent streets being maintained adequ	iately?				
No Corrective Action?						
Create Corrective Action? No- See BMP Section						
	construction activity adequately controlled o	n the site?				
Yes Create Corrective Action?						
V/A						
Comments: Comments:						
1.) Site was inactive during the						
1.) Site was inactive during the	e last inspection.					
Findings / Corrective Actions	·					

Unique Name	Tuno	Location	Projected Install Date	Status	Maintenance			
CE 01	Type Construction Entrance	Off 113th Street	9/20/2023	Pending	Yes			
Current Condition:	Pending - Pruss Excavation installed a c		the inspection on 9/20/23.	Pruss Excavation rer	noved the construction			
	entrance prior to the inspection on 10/25/23.							
	Construction entrance should be re-insta	Construction entrance should be re-installed with berm or silt fence should be installed to prevent sediment running onto street.						
	Pruse Excavation was informed to comp	Pruss Excavation was informed to complete by 11/1/23. Not done as of the last inspection. Pruss Excavation was reminded on 12/7/23,						
	3/21/24.	icle by 11/1/20. Not done as	or the last mapeedion. I rus	3 Excavation was ref	minded on 12/1/20,			
DB 01	Diversion Berm	North Side of Site	10/11/2023	Active	No			
Current Condition:	Good Condition- Pruss Excavation instal	led a diversion berm prior to	the inspection on 10/11/23					
DB 02	Diversion Berm	Eastern Side of Site	10/18/2023	Active	No			
Current Condition:	Good Condition- Pruss Excavation instal	•						
DB 03 Current Condition:	Diversion Berm	Eastern Side of Site	10/18/2023	Active	No			
FT 01	Good Condition- Pruss Excavation installed a diversion berm prior to the inspection on 10/18/23. Fuel Tank On Site Removed							
Current Condition:	Removed- Pruss Excavation removed th		L	Removed				
IP 1 - 2	Inlet Protection	Along Courtyard Court	11/8/2023	Active	No			
Current Condition:	Good Condition- Pruss Excavation instal Inlet Protection	led IP 1 and 2 prior to the ins Along Courtyard Court	pection on 11/8/23. 8/5/2023	Pending	No			
Current Condition:	Pending- Inlet protection will be installed		0/3/2020	r criding	140			
IP 5 - 6	Inlet Protection	Along Courtyard Court	8/5/2023	Pending	No			
Current Condition:	Pending- Inlet protection will be installed	once paving is complete.	•	_	•			
IP 7	Inlet Protection	Along Courtyard Court	8/5/2023	Pending	No			
Current Condition:	Pending- Inlet protection will be installed							
MT 01	Erosion Matting	South East portion of the site	11/1/2023	Active	No			
Current Condition:	Good Condition- Pruss Excavation instal		to the inspection on 11/1/2	3.				
	Freeign Motting	South East portion of the	11/1/2022	Active	No			
MT 02	Erosion Matting	site	11/1/2023		No			
Current Condition:	Good Condition- Pruss Excavation instal		to the inspection on 11/1/2	3.				
MT 03	Erosion Matting	South West portion of the site	11/1/2023	Active	No			
Current Condition:	Good Condition- Pruss Excavation instal		to the inspection on 11/1/2	3.				
MT 04	Erosion Matting	ADJ to Private Drive	11/1/2023	Active	No			
Current Condition:	Good Condition- Pruss Excavation instal	led the erosion matting prior	to the inspection on 11/1/2	3.	•			
MT 05	Erosion Matting	ADJ to Private Drive	8/5/2023	Pending	No			
Current Condition:	Pending- Erosion Matting will be installed							
MT 06 Current Condition:	Erosion Matting Good Condition- Pruss Excavation instal	North of Courtyard Court	11/1/2023 to the inspection on 11/1/2	Active	No			
MT 07	Erosion Matting	North of Courtyard Court	11/1/2023	Active	l No			
Current Condition:	Good Condition- Pruss Excavation instal				110			
PT 01	Portable Toilet	On Site		Removed				
Current Condition:	Removed- Pruss Excavation removed th			A 11	I N			
SF 01 - 09 Current Condition:	Silt Fence Good Condition- Pruss Excavation instal	Eastern Perimeter led Silt fence 1-9 prior to the	11/1/2023 inspection on 11/1/23.	Active	No			
SF 10 - 14	Silt Fence	Northern Checks	7/12/2023	Active	No			
Current Condition:	Fair Condition- Pruss Excavation install the inspection on 9/20/23. Due to erosion							
	be recommended as of 11/2/23. Pruss E							
	SF 14 was damaged prior to the inspe	ection on 3/20/24 due to sar	nitary installation. E&A in	spector will continu	ue to monitor.			
SF 15 - 18 Current Condition:	Silt Fence Good Condition- Pruss Excavation instal	Western Perimeter	11/1/2023 inspection on 11/1/23	Active	No			
SF 19	Silt Fence	Northern Perimeter	7/12/2023	Active	No			
Current Condition:	Good Condition- Pruss Excavation instal				down during the			
	inspection on 9/27/23. Pruss Excavation	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·		T			
SF 20 - 30	Silt Fence	Southern Half of Courtyard Court	8/5/2023	Pending	No			
					L			
Current Condition:	Pending- Silt fence will be installed once	grading starts.						
		grading starts. Northern Half of Courtyard	8/5/2022	Danding	No			
Current Condition: SF 31 - 34	Silt Fence	Northern Half of Courtyard Court	8/5/2023	Pending	No			
Current Condition:		Northern Half of Courtyard Court	8/5/2023	Pending	No			
SF 31 - 34 Current Condition:	Silt Fence	Northern Half of Courtyard Court	8/5/2023 11/1/2023	Pending Active	No No			
Current Condition: SF 31 - 34	Silt Fence Pending- Silt fence will be installed once	Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks	11/1/2023		<u> </u>			
SF 31 - 34 Current Condition: SF 35 - 42 Current Condition:	Silt Fence Pending- Silt fence will be installed once Silt Fence Good Condition- Pruss Excavation instal	Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks	11/1/2023 ne inspection on 11/1/23.	Active	No			
SF 31 - 34 Current Condition: SF 35 - 42 Current Condition: SF 35 - 42 SF 43 - 48	Silt Fence Pending- Silt fence will be installed once Silt Fence Good Condition- Pruss Excavation instal Silt Fence	Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to ti Southern Half of Western Perimeter	11/1/2023 ne inspection on 11/1/23.		<u> </u>			
Current Condition: SF 31 - 34 Current Condition: SF 35 - 42 Current Condition: SF 43 - 48 Current Condition:	Silt Fence Pending- Silt fence will be installed once Silt Fence Good Condition- Pruss Excavation instal Silt Fence Good Condition- Pruss Excavation instal	Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to tl Southern Half of Western Perimeter led Silt fence 35-42 prior to tl	11/1/2023 ne inspection on 11/1/23. 11/1/2023 ne inspection on 11/1/23.	Active Active	No No			
SF 31 - 34 Current Condition: SF 35 - 42 Current Condition: SF 43 - 48 Current Condition: SF 49 - 51	Silt Fence Pending- Silt fence will be installed once Silt Fence Good Condition- Pruss Excavation instal Silt Fence Good Condition- Pruss Excavation instal Silt Fence Silt Fence	Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to ti Southern Half of Western Perimeter led Silt fence 35-42 prior to ti West of Courtyard Court	11/1/2023 ne inspection on 11/1/23. 11/1/2023 ne inspection on 11/1/23. 11/1/2023	Active	No			
Current Condition: SF 31 - 34 Current Condition: SF 35 - 42 Current Condition: SF 43 - 48 Current Condition:	Silt Fence Pending- Silt fence will be installed once Silt Fence Good Condition- Pruss Excavation instal Silt Fence Good Condition- Pruss Excavation instal	Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to ti Southern Half of Western Perimeter led Silt fence 35-42 prior to ti West of Courtyard Court	11/1/2023 ne inspection on 11/1/23. 11/1/2023 ne inspection on 11/1/23. 11/1/2023	Active Active	No No			

Current Condition:	Good Condition- Pruss Excavation installed Silt fence 35-42 prior to the inspection on 11/1/23.						
STR	Streets	ADJ and Internal Streets	8/5/2023	Active	No		
Current Condition:	Good Condition- Streets were clean during the inspection on 11/22/23.						
SWPPP Sign	SWPPP Sign	On Site	10/11/2023	Active	No		
Current Condition:	Good Condition- E&A inspector installed a SWPPP sign during the inspection on 10/11/23.						
WO 01	Concrete Washout	On Site		Removed			
Current Condition:	Removed- Pruss Excavation removed the concrete washout prior to the inspection on 11/22/23.						
WS 01	Waste Storage Area	On Site	8/5/2023	Pending	No		
Current Condition:	Pending- Waste storage will be installed as necessary.						
Certification Statement	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."						
Inspector Signature:	3 h Rage			Reviewed By:	to be		