

E&A Consulting Group, Inc.
 330 North 117th Street
 Omaha, NE 68154-2509
 tel 402.895.4700
 fax 402.895.3599
 www.eacg.com



E&A CONSULTING GROUP, INC.
 ENGINEERING • PLANNING • FIELD SERVICES

Zachary A. Jilek, CPESC, CISEC
 Erosion Control Specialist- Manager

E&A - P2004.245.000

Inspector: Patrick Pierce		Stage 3
Project Name:	Elkhorn View NER110687	
For Week Ending:	8/14/2010	
Project Location:	192nd & Bedford Ave- Omaha, NE (Douglas County)	68022


Grading:	100%				
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	100%				
Seeding:	100%				
Utilities:	100%				
Overall Development:	42%				

RAIN FALL AMOUNTS	Amount in inches	Date inspected			
					Week 1
Sunday:	1.58"				
Monday	0.17"	07/12/10			
Tuesday	0.00"				
Wednesday	1.11"				
Thursday	0.00"	07/15/10			
Friday	0.24"				
Saturday	0.00"				
					Week 2
Sunday:	0.01"				
Monday	0.01"				
Tuesday	0.60"	07/20/10			
Wednesday	0.37"				
Thursday	0.00"				
Friday	0.47"				
Saturday	0.00"				
					Week 3
Sunday:	0.00"				
Monday	0.00"	07/26/10			
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Week 4
Sunday:	0.00"				
Monday	1.21"				
Tuesday	0.30"	08/03/10			
Wednesday	0.03"				
Thursday	0.00"				
Friday	0.02"				
Saturday	0.00"				
					Week 5
Sunday:	0.01"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				

Complaints:	None

Construction Sequencing:
Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?
Entire site; grading completed and site seeded Spring 2005.
Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :

Entire site; grading completed and site seeded Spring 2005.					
What temporary or permanent stabilization measures listed in this section are being implemented?					
Paving, dense vegetation and landscaping					
Comments:					
Comments: Home construction is active on lots 19, 26, 34 and 71					
Findings / Corrective Actions (Date):					
Findings / Corrective Actions (Date): 1) Some maintenance is required in the BMP Section.					
Unique Name	Type	Location	Projected Install Date	Status	Maintenance
CE 1	Construction Entrance	N41d17m09s W96d12m58s		Removed	
Current Condition:	Removed				
CE 2	Construction Entrance	N41d17m09s W96d13m05s		Removed	
Current Condition:	Removed - Entrance Paved				
Lot 19	Silt Fence	Lot 19	5/21/2010	Active	Yes
Current Condition:	Fair Condition- silt fence There are a few pieces of silt fence on this lot that are down as of inspection on 7/15/10. Quest Construction was called and requested to have this repaired by 7/22/10. This silt fence was repaired prior to inspection on 7/20/10.				
Lot 26	Silt Fence	Lot 26	5/12/2010	Active	No
Current Condition:	Good Condition - Malibu Homes installed silt fence prior to inspection on 5/12/10.				
Lot 34	Silt Fence	Lot 34	4/19/2010	Active	No
Current Condition:	Good Condition -Mark Hopkins installed silt fence prior to inspection on 4/19/10.				
Lot 56	Silt Fence	Lot 56	4/25/2010	Active	Yes
Current Condition:	Lot was sodded prior to inspection on 7/15/10. Silt fence is no longer needed due to the lot being sodded. Quest construction was called and requested to remove this silt fence by 7/22/10. This was not complete prior to inspection on 7/22/10, but due to recent rains an extension will be given to complete this. The new completion date is 7/28/10. This was not complete prior to inspection on 8/3/10.				
Lot 71	Silt Fence	Lot 71	8/3/2010	Active	No
Current Condition:	Good Condition -Mark Hopkins is building on lot 71 and installed silt fence prior to inspection on 8/3/10.				
SB A	Sediment Basin	N41d17m09s W96d13m14s	In place	Active	No
Current Condition:	Good Condition - 36% Filled -Commercial Seeding completed revegetation prior to inspection on 7/8/09.				
SF 1	Silt Fence	N41d17m12s W96d13m15s		Removed	No
Current Condition:	Silt fence was removed prior to inspection on 8/18/09 by Tim Geis due to dense vegetation. Tom Falcone was notified that this silt fence is to be re-installed once home construction is active in this area.				
SF 2	Silt Fence	N41d17m10s W96d13m03s	In place	Removed	No
Current Condition:	Good Condition Silt fence has been removed. All drainage area is seeded and has grass growing.				
ST B	Sediment Trap	N41d17m18s W96d13m14s		Removed	
Current Condition:	Trap closed August 2006.				
STR	Streets	N41d17m09s W96d13m05s	8/1/2005	Active	No
Current Condition:	Good Condition -No major signs of track-off.				

SWPPP Sign	Signs	2 signs	8-19-08	Active	No
Current Condition:	Good Condition: 192nd and Miami / 192nd and Corby				
Inspector Signature:			Reviewed By: 