E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599

www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Inspector: Joe Manning	E&A - P2018.109.002					Stage
						5195
		COM		/ 23 East		3
Project Name:		CSW-201702253 (Mass Grading)				
For Week Ending:			4/9/	/2022		
Project Location:	County Road U and Lincoln Highway- Fremont, NE (Dodge County)				je County)	68025
	Gallery 23 East					1
Grading:	Gallery 23 East	96%				
Sanitary Sewer:		97%				
Storm Sewer:		95%				
Paving:		99%				
Seeding: Utilities:		1% 99%				
Overall Development:		45%				
						<u>.</u>
RAIN FALL AMOUNTS	Amount in inches	Date i	nspected	Weather Conditions	Time	
						Week 1
Sunday:	0.00"					1
Monday	0.00"					1
Tuesday	0.00"					1
Wednesday	0.00"					1
Thursday	0.03"					
Friday	0.00"					
Saturday	0.00"					
						Week 2
Sunday:	0.00"					
Monday	0.09"					
Tuesday	0.44"					
Wednesday	0.02"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
	0.000					Week 3
Sunday:	0.00"					
Monday	0.00"		3/28/2022	Sunny 56/28	3:25 PM	
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.19"					
Saturday	0.00"					Wook
Sunday	0.00"					Week 4
Sunday:	0.00" 0.00"					+
Monday Tuesday	0.00"					
						+
Wednesday	0.00" 0.00"					
Thursday	0.00"					
Friday	0.00"					+
Saturday	0.00					Mode
Sunday:	N/A					Week 5
Monday:	N/A N/A					
Tuesday	N/A N/A					
Wednesday	N/A					
Thursday	N/A					
rnursuay						+
Friday	N/A					

Complaints:	

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/2018). Grading has temporarily ceased (1/10/2019). Grading in the NE corner of site for sanitary installation (4/5/2019). Grading for roads (6/4/2019). Grading for utilities, storm, and roads throughout project (6/17/2019). Excavation along southwest portion ROW for gas installation (6/18/2019). Excavation in the southeast portion of the site for utilities (6/18/2019). Excavation throughout the site for gas installation (6/24/2019). Excavation for sanitary lift station installation on the west side of the lake (8/26/2019). Fine grading throughout the site in preparation for paving (9/09/2019). Excavation in the northeast corner of the site for culvert installation (9/19/2019). Trenching/excavation in the southeast portion of the site for utility installation (10/22/2019). Trenching throughout site for utility installation (1/27/2020).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/2018). Grading has temporarily ceased (1/10/2019). Grading occurred in between HWY 30 and Menards to still water main between last inspection (2/7/2019) and current inspection (2/20/2019), but grading had ceased at time of inspection. Grading along HWY 275 (4/5/2019). Grading for water main project has ceased (4/19/2019)

Highway 30 intersection improvements have begun for culvert installation (10/02/2019).

Grading for Highway 30 intersection improvements has begun (7/27/2020). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/2020). Stockpiling on Block 1 Lot 9 (4/20/2021). Disturbance along Eastgate Road entrance (8/26/2021). Landscaping along Eastgate Road entrance (10/11/2021).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/2018). Grading has temporarily ceased (1/10/2019). Grading in the NE corner of site for sanitary installation (4/5/2019). Grading for roads (6/4/2019). Grading for utilities, storm, and roads throughout project (6/17/2019). Excavation along southwest portion ROW for gas installation (6/18/2019). Excavation in the southeast portion of the site for utilities (6/18/2019). Excavation throughout the site for gas installation (6/24/2019). Excavation for storm sewer (7/16/2019) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/2019). Fine grading throughout the site in preparation for paving (9/09/2019). Excavation in the northeast corner of the site for culvert installation (9/19/2019). Trenching/excavation in the southeast portion of the site for utility installation (10/22/2019). Trenching throughout site for utility installation (11/18/2019). Minor trenching/excavation west of HWY 275 for communications/data installation (1/27/2020).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/2018). Grading has temporarily ceased (1/10/2019). Grading occurred in between HWY 30 and Menards to still water main between last inspection (2/7/2019) and current inspection (2/20/2019), but grading had ceased at time of inspection. Grading along HWY 275 (4/5/2019). Grading for water main project has ceased (4/19/2019)

Highway 30 intersection improvements have begun for culvert installation (10/02/2019).

Grading for Highway 30 intersection improvements has begun (7/27/2020). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/2020). Stockpiling on Block 1 Lot 9 (4/20/2021). Disturbance along Eastgate Road entrance (8/26/2021). Landscaping along Eastgate Road entrance (10/11/2021).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (8/30/2018). Seeding and matting in ditch for sanitary lift main (9/19/2018). Seeding around banks of E side of lake (11/6/2018). Seeding for Highway 30 Intersection Improvements (10/18/2020). Reseeding along the Highway 30 Improvements (3/15/2021).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

V/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No

Create Corrective Action?

No - See Findings BMP Section (CW on Lots 1-10, Block 1, Replat 2 and Block 7 Lot 6).

Are construction entrances and adjacent streets being maintained adequately?

No

Create Corrective Action? No - See BMPs Section.

Is dust associated with the construction activity adequately controlled on the site?

Create Corrective Action?

Comments:

Comments:

The site was active during the last inspection for home construction.

Lift Station, Sanitary Force Main, and the Intersection Improvements projects are closed.

Water Improvements project is closed.

Highway 30 intersection improvements project is closed.

As of 11/12/2020, E&A was not hired by White Lotus Group to inspect Lot 2 Replat 1.

Due to overall site stabilization and the number of currently active lots, Gallery 23 East will be inspected on a monthly basis as of 12/08/21. E&A inspector will monitor site activity and increase inspection frequency as necessary.

Findings / Corrective Actions (Date):

CE 1 Construction Entrance County Road Blvd U Current Condition: Removed - Thompson Construction removed the construct inspection on 9/9/19. CE 2 Construction Entrance 25/Highway 30 Current Condition: Removed - Pruss was removing the construction entrance CE 3 Construction Entrance NE Corrent - Hwy 30 & Christine Drive Current Condition: Removed - The construction entrance was removed as a part to the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will monitor and CP #2 Culvert protection Southeast corner Current Condition: Pending - Culvert protection will be installed at a later date Northeast corner Current Condition: Removed - The concrete washout pits were removed prior this time. E&A will monitor the need for reinstallation. DW #1 Ditch Wattle Checks Middle Central DW #2 Ditch Wattle Checks Southwest corner Pending - Ditch wattle checks will be installed when grading - Ditch Wattle checks Southwest corner Pending - Ditch wattle checks will be installed when grading - Ditch Wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed	e during inspection on 6	Removed 6/18/19 in preparation Removed intersection improv	on for paving.
CE 1 Construction Entrance County Road Blvd U Removed - Thompson Construction removed the construction premoved the construction on 9/9/19. CE 2 Construction Entrance County Road 25/Highway 30 Current Condition: Removed - Pruss was removing the construction entrance Construction Entrance NE Corner - Hwy 30 & Christine Drive Current Condition: Removed - The construction entrance was removed as a part to the inspection on 8/05/20. E&A inspector will monitor and CP #1 Culvert protection Central portion of site Current Condition: Pending - Culvert protection will be installed at a later date CP #2 Culvert protection Current Condition: Pending - Culvert protection will be installed at a later date Northeast corner Current Condition: Removed - The concrete washout pits were removed prior this time. E&A will monitor the need for reinstallation. DW #1 Ditch Wattle Checks Middle Central DW #2 Ditch Wattle Checks Southwest corner Current Condition: Pending - Ditch wattle checks will be installed when gradin DW #2 Ditch Wattle Checks Southwest corner	e during inspection on 6	Removed Removed Removed Removed Removed intersection improv	on for paving.
CE 1 Current Condition: Removed - Thompson Construction removed the construction proved proved. CE 2 Construction Entrance Current Condition: Removed - Pruss was removing the construction entrance proved proved proved. Current Condition: Removed - The construction entrance was removed as a proved proved proved. Current Condition: Current Condition: Pending - Culvert protection proved proved proved. Current Condition: Pending - Culvert protection will be installed at a later date proved. Current Condition: Pending - Culvert protection proved proved proved. Current Condition: Removed - The concrete washout pits were removed prior this time. E&A will monitor the need for reinstallation. DW #1 Ditch Wattle Checks proved proved. Ditch Wattle Checks proved proved. Ditch Wattle Checks proved proved. Current Condition: Pending - Ditch wattle checks will be installed when grading proved. Ditch Wattle Checks proved. Pending - Ditch wattle checks will be installed when grading proved.	e during inspection on 6	Removed Removed Removed Removed Removed intersection improv	on for paving.
Current Condition: Removed - Thompson Construction removed the construction placed on 9/9/19. CE 2 Construction Entrance Current Condition: Removed - Pruss was removing the construction entrance Current Condition: Removed - Pruss was removing the construction entrance Current Condition: Removed - The construction entrance was removed as a part to the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will be installed at a later date Current Condition: Pending - Culvert protection will be installed at a later date Northeast corner of Southeast corner of Current Condition: Removed - The concrete washout pits were removed prior this time. E&A will monitor the need for reinstallation. DW #1 Ditch Wattle Checks Middle Central DW #2 Ditch Wattle Checks Southwest corner Current Condition: Pending - Ditch wattle checks will be installed when gradin DW #2 Ditch Wattle Checks Southwest corner	e during inspection on 6	Removed Removed Removed Removed Removed intersection improv	on for paving.
inspection on 9/9/19. CE 2 Construction Entrance 25/Highway 30 Current Condition: Removed - Pruss was removing the construction entrance CE 3 Construction Entrance NE Corner - Hwy 30 & Christine Drive Current Condition: Removed - The construction entrance was removed as a pto the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will monitor and CP #1 Current Condition: Pending - Culvert protection will be installed at a later date CP #2 Culvert protection Southeast corner Current Condition: Pending - Culvert protection will be installed at a later date Northeast corner of CW Concrete Washout site Current Condition: Removed - The concrete washout pits were removed prior this time. E&A will monitor the need for reinstallation. DW #1 Ditch Wattle Checks Middle Central DW #2 Ditch Wattle Checks Southwest corner Current Condition: Pending - Ditch wattle checks will be installed when grading - Ditch Wattle Checks Southwest corner Pending - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be instal	e during inspection on 6	Removed 6/18/19 in preparation Removed intersection improv	on for paving.
CE 2 Construction Entrance Current Condition: Removed - Pruss was removing the construction entrance Construction Entrance Removed - Pruss was removing the construction entrance Construction Entrance Removed - The construction entrance was removed as a part to the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will monitor and to the installed at a later date CP #2 Culvert protection Current Condition: Pending - Culvert protection will be installed at a later date Northeast corner of Site Nor	part of the Highway 30	Removed intersection improv	ements prior
Current Condition: CE 3 Construction Entrance Current Condition: Removed - The construction entrance was removed as a properties to the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will monitor and to the inspection of site Current Condition: Pending - Culvert protection will be installed at a later date of the inspection of site of the inspectio	part of the Highway 30	Removed intersection improv	ements prior
CE 3 Construction Entrance Current Condition: Removed - The construction entrance was removed as a part to the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will monitor and to the inspection on 8/05/20. E&A inspector will monitor and to the inspection of site Current Condition: Pending - Culvert protection will be installed at a later date of the inspection of site Current Condition: Pending - Culvert protection will be installed at a later date of the inspection of site Current Condition: Removed - The concrete washout pits were removed prior this time. E&A will monitor the need for reinstallation. DW #1 Ditch Wattle Checks Middle Central DW #2 Ditch Wattle Checks Southwest corner Current Condition: Pending - Ditch wattle checks will be installed when grading - Ditch wattle checks wil	part of the Highway 30	Removed intersection improv	ements prior
Current Condition: Current Condition: CP #1 Culvert protection CP #2 Culvert protection Current Condition: Pending - Culvert protection will be installed at a later date CP #2 Culvert protection Current Condition: Pending - Culvert protection will be installed at a later date CP #2 Culvert protection Current Condition: Pending - Culvert protection will be installed at a later date Northeast corner Current Condition: Removed - The concrete washout pits were removed prior this time. E&A will monitor the need for reinstallation. DW #1 Ditch Wattle Checks DW #2 Ditch Wattle Checks Southwest corner Current Condition: Pending - Ditch wattle checks will be installed when gradin DW #2 Ditch Wattle Checks Pending - Ditch wattle checks will be installed when gradin DW #2 Pending - Ditch wattle checks will be installed when gradin DITCH wattle checks will be installe		intersection improv	
Current Condition: Current Condition: CP #1 Culvert protection Current Condition: Pending - Culvert protection will be installed at a later date CP #2 Culvert protection Current Condition: Pending - Culvert protection will be installed at a later date Current Condition: Pending - Culvert protection will be installed at a later date Current Condition: Pending - Culvert protection will be installed at a later date Northeast corner Current Condition: Removed - The concrete washout pits were removed prior this time. E&A will monitor the need for reinstallation. DW #1 Ditch Wattle Checks DW #2 Ditch Wattle Checks Southwest corner Current Condition: Pending - Ditch wattle checks will be installed when gradin DW #2 Ditch Wattle Checks Pending - Ditch wattle checks will be installed when gradin DW #2 Pending - Ditch wattle checks will be installed when gradin DITCH		intersection improv	
to the inspection on 8/05/20. E&A inspector will monitor ar CP #1 Culvert protection Central portion of site Pending - Culvert protection will be installed at a later date CP #2 Culvert protection Current Condition: Pending - Culvert protection will be installed at a later date Northeast corner of Concrete Washout Current Condition: Removed - The concrete washout pits were removed prior this time. E&A will monitor the need for reinstallation. DW #1 Ditch Wattle Checks Middle Central DW #2 Ditch Wattle Checks Southwast corner Southwast corner Pending - Ditch wattle checks will be installed when gradin Current Condition: Pending - Ditch wattle checks will be installed when gradin			
to the inspection on 8/05/20. E&A inspector will monitor ar CP #1 Culvert protection Central portion of site Current Condition: Pending - Culvert protection will be installed at a later date CP #2 Culvert protection Pending - Culvert protection will be installed at a later date Current Condition: Pending - Culvert protection will be installed at a later date Northeast corner of Concrete Washout Site Current Condition: Removed - The concrete washout pits were removed prior this time. E&A will monitor the need for reinstallation. DW #1 Ditch Wattle Checks Middle Central DW #2 Ditch Wattle Checks Southwest corner Pending - Ditch wattle checks will be installed when gradin Current Condition: Pending - Ditch wattle checks will be installed when gradin			
Current Condition: Pending - Culvert protection will be installed at a later date CP #2 Culvert protection Southeast corner Current Condition: Pending - Culvert protection will be installed at a later date CW Concrete Washout Northeast corner of site Current Condition: Removed - The concrete washout pits were removed prior this time. E&A will monitor the need for reinstallation. DW #1 Ditch Wattle Checks Middle Central Current Condition: Pending - Ditch wattle checks will be installed when grading - Ditch Wattle Checks Southwest corner Current Condition: Pending - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed at a later date will be installed at a later date will be	<u> </u>		
Current Condition: Pending - Culvert protection will be installed at a later date CP #2 Culvert protection Southeast corner Current Condition: Pending - Culvert protection will be installed at a later date CW Concrete Washout Northeast corner of site Current Condition: Removed - The concrete washout pits were removed prior this time. E&A will monitor the need for reinstallation. DW #1 Ditch Wattle Checks Middle Central Current Condition: Pending - Ditch wattle checks will be installed when grading - Ditch Wattle Checks Southwest corner Current Condition: Pending - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed at a later date will be installed at a later date will be			
Current Condition: Pending - Culvert protection will be installed at a later date CP #2 Culvert protection Southeast corner Current Condition: Pending - Culvert protection will be installed at a later date CW Concrete Washout Northeast corner of site Current Condition: Removed - The concrete washout pits were removed prior this time. E&A will monitor the need for reinstallation. DW #1 Ditch Wattle Checks Middle Central Current Condition: Pending - Ditch wattle checks will be installed when grading - Ditch Wattle Checks Southwest corner Current Condition: Pending - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed when	8/30/2018	Pending	No
Current Condition: Pending - Culvert protection will be installed at a later date Concrete Washout site Current Condition: Removed - The concrete washout pits were removed prior this time. E&A will monitor the need for reinstallation. DW #1 Ditch Wattle Checks Middle Central Current Condition: Pending - Ditch wattle checks will be installed when gradin DW #2 Ditch Wattle Checks Southwest corner Current Condition: Pending - Ditch wattle checks will be installed when gradin DW #2 Ditch Wattle Checks Southwest corner Pending - Ditch wattle checks will be installed when gradin DW #2 Ditch Wattle Checks Southwest corner	te.	<u> </u>	
CW Concrete Washout Site Current Condition: DW #1 Ditch Wattle Checks Mild be installed when gradin DW #2 Current Condition: Pending - Ditch Wattle Checks Southwest corner Current Condition: Pending - Ditch wattle checks will be installed when gradin DW #2 Pending - Ditch wattle checks will be installed when gradin DW #2 Current Condition: Pending - Ditch wattle checks will be installed when gradin DW #2 Current Condition:	8/30/2018	Pending	No
CW Concrete Washout site Current Condition: DW #1 Ditch Wattle Checks Mild Divided Washout DW #2 Ditch Wattle Checks Southwest corner Current Condition: Pending - Ditch wattle checks will be installed when gradin DW #2 Current Condition: Pending - Ditch wattle checks will be installed when gradin DW #2 Ditch Wattle Checks Southwest corner Current Condition: Pending - Ditch wattle checks will be installed when gradin pending - Ditch wattle checks will be installed when grading - Ditch wattle che	te.	· · ·	
Current Condition: Removed - The concrete washout pits were removed prior this time. E&A will monitor the need for reinstallation. DW #1 Ditch Wattle Checks Middle Central Current Condition: Pending - Ditch wattle checks will be installed when gradin DW #2 Ditch Wattle Checks Southwest corner Current Condition: Pending - Ditch wattle checks will be installed when gradin pending - Ditch wattle checks will be installed when grading - Ditch wattle checks will be installed wh			
this time. E&A will monitor the need for reinstallation. DW #1 Ditch Wattle Checks Middle Central Current Condition: Pending - Ditch wattle checks will be installed when gradin DW #2 Ditch Wattle Checks Southwest corner Current Condition: Pending - Ditch wattle checks will be installed when gradin		Removed	
DW #1 Ditch Wattle Checks Middle Central Current Condition: Pending - Ditch wattle checks will be installed when gradin DW #2 Ditch Wattle Checks Southwest corner Current Condition: Pending - Ditch wattle checks will be installed when gradin	or to inspection on 10/21	I/19. No paving is u	nderway at
Current Condition: Pending - Ditch wattle checks will be installed when gradin DW #2 Ditch Wattle Checks Southwest corner Current Condition: Pending - Ditch wattle checks will be installed when gradin			
DW #2 Ditch Wattle Checks Southwest corner Current Condition: Pending - Ditch wattle checks will be installed when grading	8/30/2018	Pending	No
Current Condition: Pending - Ditch wattle checks will be installed when grading			
	8/30/2018	Pending	No
DW #3 Ditch Wattle Checks Southeast corner	8/30/2018	Active	No
Current Condition: Good Condition - Wattles checks were installed on the sou	outheast side of the site		
DD #1 Diversion Ditch NW Corner of Lake Current Condition: Removed - The diversion ditch was removed during regrace	- din a/a - vin a in Al	Removed	40/20/40
Current Condition: Removed - The diversion ditch was removed during regrad	ading/paving in the area	prior to inspection	011 12/30/19.
DD #2 Diversion Ditch W side of Lake		Removed	
Current Condition: Removed - Thompson Construction removed the diversion	on ditch prior to inspection		
DD #3 Diversion Ditch SW corner of lake		Removed	
Current Condition: Removed - Thompson Construction removed the diversion	on ditch prior to inspection	on on 9/19/18.	
DD #4 Diversion Ditch S Side of lake		Removed	
Current Condition: Removed - Thompson Construction removed the diversion	on ditch prior to inspection		
DD #5 Diversion Ditch E side of lake		Removed	
Current Condition: Removed - Thompson Construction removed the diversion	on ditch prior to inspection		
DD #6 Diversion Ditch NE corner of lake		Removed	
Current Condition: Removed - The diversion ditch was removed during regrad	ading/paving in the area	prior to inspection	on 12/30/19.
DD #7 Diversion Ditch N side of lake	T	Removed	
Current Condition: Removed - The diversion ditch was removed during regrad			on 12/30/19.
EB #2 Erosion Blanket Northeast corner	ading/paving in the area	Pending	No

Current Condition:	Pending - Erosion control m	natting and seeding will	be installed when grading h	 las ended.			
		Around Lake (Outlot					
EB #3	Erosion Blanket	B)	8/30/2018	Pending	No		
Current Condition:	Pending - Erosion control m	Area Inlet in SE	be installed when grading h I	as ended.			
IP 1	Inlet Protection	portion of the site		Removed			
Current Condition:	Removed - The area east o		stabilized prior to the 8/05/	20 inspection. Inlet I	Protection no		
	longer needed at this time.						
		W Curb inlet on					
IP 2 Current Condition:	Curb Inlet protection Removed - The Home Com	Christine Dr	ior to the inspection on 6/10	Removed	is no longer		
Current Condition.	required.	ipany souded lots 1-0 pi	ior to the inspection on o/ it	Ji20. Illiet protection	is no longer		
		E Curb inlet on					
IP 3	Curb Inlet protection	Christine Dr		Removed			
Current Condition:	Removed - The Home Com	pany sodded lots 1-8 pr	ior to the inspection on 6/10	3/20. Inlet protection	is no longer		
	required.	Disali O Damiet O	Ι				
		Block 2, Replat 2 (Northeast corner of					
Block 1 Replat 2, Lots 1-10	Individual Lots	site)	1/11/2021	Active	Yes		
Current Condition:	Fair Condition - The Home						
	7/27/20. The Home Compa						
	Company secured the porta	able toilet prior to the ins	pection on 3/15/21. The Ho	me Company begar	n excavating lots		
	1 and 2 prior to the inspection	on on 4/7/21. The Home	Company removed the co	ncrete waste from L	ots 1 and 2 prior		
	to the inspection on 5/17/21						
	toilet prior to the inspection	on 9/13/21. The Home	Company removed the port	able toilet prior to the	e inspection on		
	1/03/22.						
	1.) The streets surrounding						
	2.) Silt fence should be installed along the backs of Lots 1-2 or all lots should be stabilized.						
	1) The Hame Company was informed to complete by 2/00/21. Not done as of the last inspection. The Hame						
		1.) The Home Company was informed to complete by 3/09/21. Not done as of the last inspection. The Home Company was reminded on 4/21/21, 6/10/21, 7/21/21, 9/02/21, 10/25/21					
		2.) The Home Company was informed to complete by 4/27/21. Not done as of the last inspection. The Home					
	Company was reminded on			and rade map desirem			
Block 3 Replat 2, Lots 9-12	Individual Lots	Block 3	6/9/2021	Active	No		
Current Condition:	Active - Hubbell Homes beg	gan construction on Lots	9-12 prior to the inspection	n on 6/09/21. Due to	the vegetation		
	surrounding the lots and the	e grade in the area, no E	BMPs will be recommended	at this time. E&A in	spector will		
	monitor.						
Block 3 Replat 2, Lots 13-16	Individual Lots	Block 3	6/9/2021	Pending	Yes		
Current Condition:	Pending - Hubbell Homes b						
	cleaned by rain prior to the inspection on 8/30/21. Hubbell Homes removed the portable toilet prior to the						
	inspection on 1/03/22.						
	1) Silt fonce or straw wattles should be installed along the front of the late						
	 Silt fence or straw wattles should be installed along the front of the lots. The street in front of the lots should be cleaned. 						
	2.) The suger in fluit of the lots should be dediled.						
	1.) The E&A inspector will make an attempt to identify the builder and inform them to complete by 7/16/21. Not						
	done as of the last inspection. Hubbell Homes was informed to complete by 8/20/21. Not done as of the last						
	inspection. Hubbell Homes was reminded on 9/02/21, 10/26/21, 2/01/22, 3/30/22						
	2.) Hubbell Homes was informed to complete by 2/01/22. Not done as of the last inspection. Hubbell Homes was						
	reminded on 3/30/22						
Block 4 Replat 2, Lots 8-12	Individual Lots	Block 4	8/13/2021	Active	Yes		
Current Condition:	Fair Condition - Hubbell Ho						
	vegetation surrounding the lots and the grade in the area, no BMPs will be recommended at this time. E&A inspector will monitor. Hubbell Homes secured a portable toilet on Lot 9 prior to the inspection on 8/13/21.						
	The state of the s						
	The two portable toilets on the lots should be secured.						
	Hubbell Homes was informed	ed to complete by 2/07/2	22. Not done as of the last i	nspection. Hubbell	Homes was		
	reminded on 3/30/22.						
Block 6, Lot 9	Individual Lots	Block 6	8/13/2021	Active	No		
Current Condition:	Active - Hubbell Homes beg						
	and the surrounding vegeta	tion no BMPs will be red	commended at this time. E8	A inspector will mo	nitor. The street		
	in front of the lot was cleaned	ad prior to the inepection	4/00/00				
	in noncortic lot was cleane	ed prior to the inspection	1 on 1/03/22.		l		
Block 6, Lot 23	Individual Lots	Block 6	1/3/2022	Pending	Yes		

Current Condition:	Pending - Hubbell Homes	began construction o	n the lot prior to the inspe	ction on 1/03/22.		
	 The street in front of the lot should be cleaned. Silt fence or straw wattles should be installed along the front of the lot or vehicular access to the lot should be restricted. Concrete waste should be removed from the lot. 					
	1.) Hubbell Homes was int					
	2.) Hubbell Homes was int					
Block 6, Lot 24	3.) Hubbell Homes was inf Individual Lots	ormed to complete by Block 6	<u> 4/04/22.</u>	Removed		
Current Condition:	Removed - Jeff Whearden I		I rior to the inspection on 1/0:			
Block 6, Lot 25	Individual Lots	Block 6	10/25/2021	Active	Yes	
Current Condition:	Fair Condition - Rick Walk Walkup Construction install inspector retied the silt fenc inspection on 1/31/22. A po	up Construction began ed silt fence along the be e during the inspection rtion of the silt fence wa	construction on the lot prior pack of the lot prior to the ins on 1/31/22. A portable toilet is loose during the inspection	to the inspection or spection on 10/25/2 was secured on the	10/25/21. Rick 1. E&A	
Block C. Lat CC	Rick Walkup Construction			D		
Block 6, Lot 26 Current Condition:	Individual Lots Pending - Hubbell Homes b	Block 6	1/3/2022	Pending	Yes	
	 The street in front of the lot should be cleaned. Silt fence or straw wattles should be installed along the front of the lot or vehicular access to the lot should be restricted. Hubbell Homes was informed to complete by 3/29/22. Hubbell Homes was informed to complete by 4/04/22. 					
Block 7, Lot 6	Individual Lots	Block 7		Removed		
Current Condition:	Removed - Rick Walkup Co	nstruction sodded the le	ot and removed the portable	toilet prior to the in	spection on	
	9/27/21.					
SB #1	Sediment Basin	Central portion of site	8/30/2018	Pending	No	
Current Condition: SB #2	Pending - Basin will be insta		commenced at a later date a			
Current Condition:	Sediment Basin Pending - Basin will be insta	Southeast corner		Pending	No	
SF #1	Silt Fence	Southeast corner	8/30/2018	Pending	No	
Current Condition:	Pending - Silt Fence will be			1 0.1.4.1.19		
SF #2	Silt Fence	Northeast corner	8/30/2018	Pending	No	
Current Condition:	Pending - Silt Fence will be					
STR	Street cleaning	Off-Site	In Place	Active	No	
Current Condition:	Good Condition - The street		at time of inspection on 7/8	3/19. The streets we	re clean at the	
SWPPP Sign	time of the inspection on 10 Signs	2 Entrances	10/9/2018	Active	No	
Current Condition:	Good Condition - Inspector installed 1 of 2 SWPPP signs during inspection on 10/9/18. Other SWPPP sign will be installed at the County Rd U Blvd entrance at a later date. The E&A inspector reinstalled the SWPPP sign during inspection on 9/19/19. The E&A inspector reinstalled the SWPPP sign during the 2/24/20 inspection. The E&A inspector reinstalled the SWPPP sign prior to the inspection on 3/31/20. The SWPPP sign was removed during the Highway 30 Intersection Improvements prior to the inspection on 8/17/20. E&A inspector will reinstall as construction allows. E&A inspector reinstalled the SWPPP sign during the inspection on 8/31/20.					
Certification Statement:	I certify, under penalty of law supervision in accordance we evaluated the information so those persons directly respo knowledge and belief, true, false information including t	with a system designed ubmitted. Based on my onsible for gathering the accurate, and complete	to assure that qualified persinquiry of the person or persention, the information, the information. I am aware that there are	sonnel properly gath sons who manage th n submitted is, to the significant penalties	ered and ne system or e best of my	
Inspector Signature:	Jo ling		Reviewed By:	to Sur		