E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Inspector: Josh Ellington		E&A - P2018.109.002					
Draiget Name		<u>Gallery 23 East</u> CSW-201702253 (Mass Grading)					
Project Name:	C		· · · · · · · · · · · · · · · · · · ·				
		5/27/2023					
Project Location:	County Road	County Road U and Lincoln Highway- Fremont, NE (Dodge County)					
	Gallery 23 East						
Grading:	96%						
Sanitary Sewer:	97%						
Storm Sewer:	95%						
Paving:	99%						
Seeding:	1%						
Utilities:	99%						
Overall Development:	45%						
					1		
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions	Time			
	0.00				Wee		
Sunday:	0.00"						
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.00"	5/24/2023	Sunny 78	10:55 AM			
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"						
Complaints:	None						
Construction Sequencing:							
Which portion(a) (i.e. drainage begins)	of the site have had a temporary or perm	anont acception of grad	ing conthucarly or ground dist	when a line the least of a leave)		

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/2018). Grading has temporarily ceased (1/10/2019). Grading in the NE corner of site for sanitary installation (4/5/2019). Grading for roads (6/4/2019). Grading for utilities, storm, and roads throughout project (6/17/2019). Excavation along southwest portion ROW for gas installation (6/18/2019). Excavation in the southeast portion of the site for utilities (6/18/2019). Excavation throughout the site for gas installation (6/24/2019). Excavation for storm sewer (7/16/2019) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/2019). Fine grading throughout the site in preparation for paving (9/09/2019). Excavation in the northeast corner of the site for culvert installation (9/19/2019). Trenching/excavation in the southeast portion of the site for utility installation (11/18/2019). Trenching/excavation west of HWY 275 for communications/data installation (1/27/2020).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/2018). Grading has temporarily ceased (1/10/2019). Grading occurred in between HWY 30 and Menards to still water main between last inspection (2/7/2019) and current inspection (2/20/2019), but grading had ceased at time of inspection. Grading along HWY 275 (4/5/2019). Grading for water main project has ceased (4/19/2019)

Highway 30 intersection improvements have begun for culvert installation (10/02/2019).

Grading for Highway 30 intersection improvements has begun (7/27/2020). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/2020). Stockpiling on Block 1 Lot 9 (4/20/2021). Disturbance along Eastgate Road entrance (8/26/2021). Landscaping along Eastgate Road entrance (10/11/2021).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/2018). Grading has temporarily ceased (1/10/2019). Grading in the NE corner of site for sanitary installation (4/5/2019). Grading for roads (6/4/2019). Grading for utilities, storm, and roads throughout project (6/17/2019). Excavation along southwest portion ROW for gas installation (6/18/2019). Excavation in the southeast portion of the site for utilities (6/18/2019). Excavation throughout the site for gas installation (6/24/2019). Excavation for storm sewer (7/16/2019) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/2019). Fine grading throughout the site in preparation for paving (9/09/2019). Excavation in the northeast corner of the site for culvert installation (9/19/2019). Trenching/excavation in the southeast portion of the site for utility installation (11/18/2019). Trenching/excavation west of HWY 275 for communications/data installation (1/27/2020).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/2018). Grading has temporarily ceased (1/10/2019). Grading occurred in between HWY 30 and Menards to still water main between last inspection (2/7/2019) and current inspection (2/20/2019), but grading had ceased at time of inspection. Grading along HWY 275 (4/5/2019). Grading for water main project has ceased (4/19/2019)

Highway 30 intersection improvements have begun for culvert installation (10/02/2019).

Grading for Highway 30 intersection improvements has begun (7/27/2020). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/2020). Stockpiling on Block 1 Lot 9 (4/20/2021). Disturbance along Eastgate Road entrance (8/26/2021). Landscaping along Eastgate Road entrance (10/11/2021).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (8/30/2018). Seeding and matting in ditch for sanitary lift main (9/19/2018). Seeding around banks of E side of lake (11/6/2018). Seeding for Highway 30 Intersection Improvements (10/18/2020). Reseeding along the Highway 30 Improvements (3/15/2021).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No

No - See Findings and BMP Section.

Are construction entrances and adjacent streets being maintained adequately?

No

Create Corrective Action?

No - See BMPs Section.

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments:

Comments:

The site was active during the last inspection for home construction.

Lift Station, Sanitary Force Main, and the Intersection Improvements projects are closed.

Water Improvements project is closed.

Highway 30 intersection improvements project is closed.

Based on the amount of lot construction active in the development as of the 4/26/23 inspection, Gallery 23 East will be inspected at the Stage 1 frequency. E&A inspector will monitor and adjust inspection frequency as necessary.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) See BMP section for required maintenance.

2.) Waste storage containers should be emptied when the full line is reached and any litter should be picked up. All developers were informed to complete by 9/13/22. Not done as of the last inspection. Builders were reminded on 5/11/23

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
	Ga	llery 23 East		-	
CE 1	Construction Entrance	County Road Blvd U		Removed	
Current Condition:	Removed - Thompson Construction removed the construction entrance in preparation for paving prior to inspec on 9/9/19.				
CE 2	Construction Entrance	County Road 25/Highway 30		Removed	
Current Condition:	Removed - Pruss was remo	wing the construction en	trance during inspection on	6/18/19 in prepara	ation for paving.
		NE Corner - Hwy 30 &			
CE 3	Construction Entrance	Christine Drive	as a part of the Highway 30	Removed	
	the inspection on 8/05/20. E	&A inspector will monito	or and recommend reinstalla	tion at a later date	if necessary.
CIP 1	Curb Inlet protection	Sammy Road			
		Sanning Road		Removed	
Current Condition:	· · · · ·	,	 prior to the inspection on 1/ ²		
	· · · · ·	,	prior to the inspection on 1/7 11/30/2022		No
Current Condition:	Removed - DR Horton remo Curb Inlet protection	oved the inlet protection Sammy Road		17/23. Active	
Current Condition: CIP 2	Removed - DR Horton remo Curb Inlet protection	oved the inlet protection Sammy Road	11/30/2022	17/23. Active	
Current Condition: CIP 2 Current Condition:	Removed - DR Horton remo Curb Inlet protection Good Condition - DR Hortor Curb Inlet protection	Sammy Road Sammy Road n installed inlet protection East 18th Avenue	11/30/2022 n north of Lot 4 Block 12 pric	17/23. Active or to the inspection Active	n on 11/30/22.
Current Condition: CIP 2 Current Condition: CIP 3	Removed - DR Horton remo Curb Inlet protection Good Condition - DR Hortor Curb Inlet protection	Sammy Road Sammy Road n installed inlet protection East 18th Avenue	11/30/2022 n north of Lot 4 Block 12 pric	17/23. Active or to the inspection Active	n on 11/30/22.
Current Condition: CIP 2 Current Condition: CIP 3 Current Condition:	Removed - DR Horton remo Curb Inlet protection Good Condition - DR Hortor Curb Inlet protection Good Condition - DR Hortor Curb Inlet protection Good Condition - DR Hortor Curb Inlet protection Pending - DR Horton installed	byed the inlet protection Sammy Road n installed inlet protection East 18th Avenue n installed inlet protection Kara Way ed inlet protection south	11/30/2022 n north of Lot 4 Block 12 prio 1/17/2023 n south of Lot 15 Block 6 pri	17/23. Active or to the inspection Active or to the inspectio Pending e inspection on 1/ ²	No n on 11/30/22. No n on 1/17/23. No 17/23. DR Hort
Current Condition: CIP 2 Current Condition: CIP 3 Current Condition: CIP 4	Removed - DR Horton remo Curb Inlet protection Good Condition - DR Hortor Curb Inlet protection Good Condition - DR Hortor Curb Inlet protection Good Condition - DR Hortor Curb Inlet protection Pending - DR Horton installer removed the inlet protection	byed the inlet protection Sammy Road n installed inlet protection East 18th Avenue n installed inlet protection Kara Way ed inlet protection south	11/30/2022 n north of Lot 4 Block 12 prio 1/17/2023 n south of Lot 15 Block 6 pri 1/17/2023 of Lot 21 Block 6 prior to the	17/23. Active or to the inspection Active or to the inspectio Pending e inspection on 1/ ²	n on 11/30/22. No n on 1/17/23. No 17/23. DR Horte
Current Condition: CIP 2 Current Condition: CIP 3 Current Condition: CIP 4 Current Condition:	Removed - DR Horton remo Curb Inlet protection Good Condition - DR Hortor Curb Inlet protection Good Condition - DR Hortor Curb Inlet protection Good Condition - DR Hortor Curb Inlet protection Pending - DR Horton installer removed the inlet protection necessary.	ved the inlet protection Sammy Road n installed inlet protection East 18th Avenue n installed inlet protection Kara Way ed inlet protection south prior to the inspection of site	11/30/2022 n north of Lot 4 Block 12 prid 1/17/2023 n south of Lot 15 Block 6 pri 1/17/2023 of Lot 21 Block 6 prior to the on 5/10/23. E&A inspector wi 8/30/2018	17/23. Active or to the inspection Active or to the inspectio Pending e inspection on 1/ ⁷ ill recommend reir	No No n on 11/30/22. No n on 1/17/23. No 17/23. DR Hortonstallation as

Current Condition:	Pending - Culvert protection	n will be installed at a lat	er date.		
CW	Concrete Washout	Block 9, Lot 1	9/6/2022	Active	No
Current Condition:	Good Condition - DR Hortor	'	ashout prior to the inspectio	n on 9/06/22. DR Hor	ton removed
	the concrete washout and ir				
	DR Horton cleaned out the				
DW #1	Ditch Wattle Checks	Middle Central	8/30/2018	Pending	No
Current Condition:	Pending - Ditch wattle check	-			
DW #2	Ditch Wattle Checks	Southwest corner	8/30/2018	Pending	No
Current Condition:	Pending - Ditch wattle check			i enanig	
DW #3	Ditch Wattle Checks	Southeast corner	8/30/2018	Active	No
Current Condition:	Good Condition - Wattles ch				
DD #1	Diversion Ditch	NW Corner of Lake		Removed	
Current Condition:	Removed - The diversion di		I regrading/paying in the are		on 12/30/19
ourient condition.			grograding/paving in the ar		011 12/00/10:
DD #2	Diversion Ditch	W side of Lake		Removed	
Current Condition:	Removed - Thompson Cons	struction removed the di	version ditch prior to inspec	tion on 9/19/18.	
DD #3	Diversion Ditch	SW corner of lake	1	Removed	
Current Condition:	Removed - Thompson Cons	struction removed the di	version ditch prior to inspec	tion on 9/19/18.	
DD #4	Diversion Ditch	S Side of lake	1	Removed	
Current Condition:	Removed - Thompson Cons	struction removed the di	version ditch prior to inspec	tion on 9/19/18.	
DD #5	Diversion Ditch	E side of lake	1	Removed	
Current Condition:	Removed - Thompson Cons		version ditch prior to inspec		
DD #6	Diversion Ditch	NE corner of lake	 	Removed	
Current Condition:	Removed - The diversion di		regrading/paying in the are		on 12/30/19
			, · · g. a ag, p a ·g a · e · a		
DD #7	Diversion Ditch	N side of lake		Removed	
Current Condition:	Removed - The diversion di	itch was removed during	regrading/paving in the are	ea prior to inspection	on 12/30/19.
EB #2	Erosion Blanket	Northeast corner	8/30/2018	Pending	No
Current Condition:	Pending - Erosion control m	atting and seeding will b	be installed when grading ha	as ended.	
		Around Lake (Outlot			
EB #3	Erosion Blanket	B)	8/30/2018	Pending	No
Current Condition:	Pending - Erosion control m		be installed when grading ha	as ended.	
		Area Inlet in SE			
IP 1	Inlet Protection	portion of the site		Removed	
Current Condition:	Removed - The area east o	f the area inlet naturally	stabilized prior to the 8/05/2	20 inspection. Inlet Pr	otection no
	longer needed at this time.				
		W Curb inlet on			
IP 2	Curb Inlet protection	Christine Dr		Removed	
Current Condition:	Removed - The Home Com	pany sodded lots 1-8 pr	ior to the inspection on 6/10	0/20. Inlet protection is	s no longer
	required.				
		E Curb inlet on			
IP 3	Curb Inlet protection	Christine Dr		Removed	
Current Condition:	Removed - The Home Com	pany sodded lots 1-8 pr	ior to the inspection on 6/10	0/20. Inlet protection is	s no longer
	required.				
		Block 2, Replat 2			
		(Northeast corner of			
Block 1 Replat 2, Lots 1-10	Individual Lots	site)		Removed	
Current Condition:	Removed - The Home Com	pany sodded the lots pr	ior to the inspection on 7/11	1/22.	
Block 2 Replat 3, Lot 16	Individual Lots	Block 2, Lot 16		Removed	
	Removed - Lot was added in			· · · · · ·	
Current Condition:					
	Individual Lots	Block 3, Lot 10		Removed	
Current Condition:		-, -		Removed	

Current Condition:	Active - Hubbell Homes began construction on the lots prior to the inspection on 10/05/22. Due to the grade of the lots, no BMPs will be recommended at this time. Hubbell Homes secured the portable toilets on the lots prior to the inspection on 11/30/22. Hubbell Homes removed the portable toilets from the lots prior to the inspection on 2/15/2 Hubbell Homes placed two portable toilets on site prior to the inspection on 3/13/23. Hubbell Homes secured the portable toilets and cleaned the street in front of the lots prior to the inspection on 5/10/23. The street in front of the lots should be cleaned. Hubbell Homes was informed to complete by 5/18/23. Not done as of last inspection.					
Block 3 Replat 2, Lots 9-12	Individual Lots	Block 3		Removed	1	
Current Condition:	Removed - Hubbell Homes	-	the inspection on 7/11/22	Removed		
Block 3 Replat 2, Lots 13-16	Individual Lots	Block 3		Removed		
Current Condition:	Removed - Hubbell Homes	sodded the lots prior to	the inspection on 7/11/22.			
Block 4 Replat 2, Lots 8-12	Individual Lots	Block 4		Removed		
Current Condition:	Removed - Hubbell Homes	sodded the lots and ren	noved portable toilets prior t	o the inspection on	10/05/22.	
Block 4 Replat 2, Lots 1-4	Individual Lots	Block 4	11/30/2022	Active	Yes	
Current Condition:	Active - Hubbell Homes beg lots, no BMPs will be recom The street in front of the lots Hubbell Homes was informe reminded on 3/15/23, 5/11/2	mended at this time. should be cleaned. d to complete by 12/28,			-	
			1 10/2/2020			
Block 4 Replat 2, Lots 5-7 Current Condition:	Individual Lots Active - Hubbell Homes beg	Block 4	10/5/2022	Active	Yes	
	The street in front of the lots Hubbell Homes was informe reminded on 3/15/23, 5/11/2	d to complete by 12/28	/22. Not done as of the last	inspection. Hubbell	Homes was	
Block 4 Replat 2, Lots 13-16	Individual Lots	Block 4	10/5/2022	Active	Yes	
Current Condition:	Active - Hubbell Homes beg lots, no BMPs will be recom The street in front of the lots Hubbell Homes was informe	mended at this time. Lo should be cleaned.	t 13 was sodded prior to t	the 5/24/23 inspect		
Block 5 Replat 2, Lots 7-9	Individual Lots	Block 5	4/26/2023	Active	Yes	
Current Condition:	Active - Hubbell Homes beg lots, no BMPs will be recom The street in front of the lots Hubbell Homes was informe	mended at this time. should be cleaned.			e grade of th	
Block 5 Replat 2, Lots 10-13	Individual Lots	Block 5	10/5/2022	Active	Yes	
Current Condition:	Active - Hubbell Homes beg lots, no BMPs will be recom The street in front of the lots Hubbell Homes was informe	mended at this time. should be cleaned.			the grade of t	
Block 6, Lot 9	Individual Lots	Block 6		Removed		
Current Condition:	Removed - Hubbell Homes	sodded the lot prior to the	ne inspection on 8/8/22.	•	·	
Block 6, Lot 23	Individual Lots	Block 6	1/3/2022	Active	No	
Current Condition:	Good Condition - Hubbell Ho removed the concrete waste toilet prior to the inspection of inspection on 10/05/22. Due 10/05/22. The street was cle	e from the lot prior to the on 10/05/22. No eviden to the front of the lot be	e inspection on 8/8/22. Hubl ce of vehicular access was eing flat, straw wattles will n	bell Homes secured observed on the lot o longer be recomm	the portable during the nended as of	

Block 6. Lot 24	Individual Lots	Block 6		Removed	
Current Condition:	Removed - Jeff Whearden	-	ior to the inspection on 1/0		
Block 6, Lot 25	Individual Lots	Block 6		Removed	
Current Condition:	Removed - Rick Walkup C		l ot prior to the inspection or		
Block 6, Lot 26	Individual Lots	Block 6		Removed	
Current Condition:	Removed - Hubbell Home		to the 5/24/23 inspection		
		Block 6	11/1/2022	Active	No
Block 6, Lot 27	Individual Lots				No Internet
Current Condition:	Active - TJL Consulting Inc. secured on the lot prior to the				
	this time. The portable toile				nimenueu a
Block 7, Lot 6	Individual Lots	Block 7		Removed	
Current Condition:	Removed - Rick Walkup Co 9/27/21.	onstruction sodded the lo	of and removed the portable	e toilet prior to the ins	pection on
Block 10, Lot 1	Individual Lots	Block 10, Lot 1	11/1/2022	Active	No
Current Condition:	Good Condition - DR Horton		around the lot prior to the i	nspection on 11/01/2	2.
Block 10. Lot 2	Individual Lots	Block 10, Lot 2		Removed	
Current Condition:	Removed - DR Horton soc	· · · · · · · · · · · · · · · · · · ·	5/24/23 inspection.		
		-		A	N
Block 10, Lot 3	Individual Lots	Block 10, Lot 3	11/1/2022	Active	No
Current Condition:	Good Condition - DR Horton		•	nspection on 11/01/2	2. DR Horto
	began construction on the l	or prior to the inspection	on 4/19/23.		
Block 10, Lot 4	Individual Lots	Block 10, Lot 4	11/1/2022	Active	No
Current Condition:	Good Condition - DR Horton	n installed straw wattles	around the lot prior to the i	nspection on 11/01/2	2. DR Horto
	began construction on the le	ot prior to the inspection	on 4/19/23.		
Block 10, Lot 5	Individual Lots	Block 10, Lot 5	11/1/2022	Active	No
Current Condition:	Good Condition - DR Horton	n installed straw wattles	around the lot prior to the i	nspection on 11/01/2	2. DR Horto
	began construction on the l		•		
Block 10, Lot 11	Individual Lots	Block 10, Lot 11	2/15/2023	Active	No
Current Condition:	Good Condition - DR Horton	n installed straw wattles	around the lot prior to the i	nspection on 2/15/23	DR Horton
	began construction on the l		•	•	
Block 11, Lot 1	Individual Lots	Block 11, Lot 1	11/1/2022	Active	No
Current Condition:	Good Condition - DR Horton	,	around the lot prior to the i	nspection on 11/01/2	2. DR Horto
	began construction on the l		•	·	
Block 11, Lot 2	Individual Lots	Block 11, Lot 2		Removed	
Current Condition:	Removed - DR Horton sodo	,	spection on 4/19/23		
Block 12, Lot 1	Individual Lots	Block 12, Lot 1		Removed	
Current Condition:	Removed - DR Horton sodo	,	nection on 4/19/23	Homovou	
Block 12, Lot 2	Individual Lots	Block 12, Lot 2		Removed	
Current Condition:	Removed - DR Horton soc		5/24/23 inspection	Removed	
Block 12, Lot 3		Block 12, Lot 3		Bomoved	
Current Condition:	Individual Lots Removed - DR Horton soc		E/24/22 increation	Removed	
Block 12 Replat 3, Lot 4	Removed - DR Horton Soc	Block 12 Replat 3, Lot			
BIOCK 12 Replat 3, LOT 4	Individual Lots			Removed	
Current Condition	Romoved DR Horton code	I d the let prior to the inc		Removed	
Current Condition: Block 13 Replat 3, Lot 1	Removed - DR Horton sodo	Block 13 Replat 3, Lot			
BIOCK TO Replace, LOUT	Individual Lots			Removed	
Current Canditian	Removed - DR Horton sodo	I I I I I I I I I I I I I I I I I I I		Renoveu	
Current Condition:	Removed - DK Horton Sodo			1 1	
Block 13 Replat 3, Lot 2	Individual Lots	Block 13 Replat 3, Lot		Removed	
Current Canditian	Removed - DR Horton sodo	lod the let prior to the in-		Renoveu	
Current Condition:	Removed - DK Horton Sodd				
Block 13 Replat 3, Lot 3	Individual Lots	Block 13 Replat 3, Lot		Domesiad	
			11/00/00	Removed	
Current Condition:	Removed - DR Horton sodo			Δ_1	. ·
STR	Street cleaning	Off-Site	In Place	Active	No No
Current Condition:	Good Condition - The stree time of the inspection on 10		at time of inspection on 7/8	b/ 19. The streets wer	e clean at th
		100/20.			
SWPPP Sign	Signs	2 Entrances	10/9/2018	Active	No

Current Condition:	Good Condition - Inspector installed 1 of 2 SWPPP signs during inspection on 10/9/18. Other SWPPP sign will be installed at the County Rd U Blvd entrance at a later date. The E&A inspector reinstalled the SWPPP sign during inspection on 9/19/19. The E&A inspector reinstalled the SWPPP sign during the 2/24/20 inspection. The E&A inspector reinstalled the SWPPP sign prior to the inspection on 3/31/20. The SWPPP sign was removed during the Highway 30 Intersection Improvements prior to the inspection on 8/17/20. E&A inspector will reinstall as construction allows. E&A inspector reinstalled the SWPPP sign during the inspection on 8/31/20.
Certification Statement:	I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations.
Inspector Signature:	At the Reviewed By: