E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Inspector: Josh Ellington		E&A - P2018.109.002				
Project Name:		1				
		8/31	1/2024			
Project Location:	County	e County)	68025			
	Gallery 23 Eas	t				
Grading:		98%				
Sanitary Sewer:		99%				
Storm Sewer:		99%				
Paving:		99%				
Seeding:		35%				
Utilities:		99%				
Overall Development:		60%				
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions	Time		
					Wee	
Sunday:	0.00"					
Monday:	0.00"	8/26/2024	Sunny 84	10:15 AM		
Tuesday:	0.00"					
Wednesday:	0.00"					
Thursday:	0.06"					
Friday:	0.00"					
Saturday:	0.00"					
	None					
Complaints:						

Complaints:

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/2018). Grading has temporarily ceased (1/10/2019). Grading in the NE corner of site for sanitary installation (4/5/2019). Grading for roads (6/4/2019). Grading for utilities, storm, and roads throughout project (6/17/2019). Excavation along southwest portion ROW for gas installation (6/18/2019). Excavation in the southeast portion of the site for utilities (6/18/2019). Excavation throughout the site for gas installation (6/24/2019). Excavation for storm sewer (7/16/2019) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/2019). Fine grading throughout the site in preparation for paving (9/09/2019). Excavation in the northeast corner of the site for culvert installation (9/19/2019). Trenching/excavation in the southeast portion of the site for utility installation (10/22/2019). Trenching throughout site for utility installation (11/18/2019). Minor trenching/excavation west of HWY 275 for communications/data installation (1/27/2020).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/2018). Grading has temporarily ceased (1/10/2019). Grading occurred in between HWY 30 and Menards to still water main between last inspection (2/7/2019) and current inspection (2/20/2019), but grading had ceased at time of inspection. Grading along HWY 275 (4/5/2019). Grading for water main project has ceased (4/19/2019)

Highway 30 intersection improvements have begun for culvert installation (10/02/2019).

Grading for Highway 30 intersection improvements has begun (7/27/2020). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/2020). Stockpiling on Block 1 Lot 9 (4/20/2021). Disturbance along Eastgate Road entrance (8/26/2021). Landscaping along Eastgate Road entrance (10/11/2021).

Grading for lot construction active (6/2020).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/2018). Grading has temporarily ceased (1/10/2019). Grading in the NE corner of site for sanitary installation (4/5/2019). Grading for roads (6/4/2019). Grading for utilities, storm, and roads throughout project (6/17/2019). Excavation along southwest portion ROW for gas installation (6/18/2019). Excavation in the southeast portion of the site for utilities (6/18/2019). Excavation throughout the site for gas installation (6/24/2019). Excavation for storm sewer (7/16/2019) Trenching for utility installation throughout the site in preparation for paving (9/09/2019). Excavation in the northeast corner of the site for culvert installation (9/19/2019). Trenching/excavation in the southeast portion of the site for utility installation (10/22/2019). Trenching throughout site for utility installation (11/18/2019). Minor trenching/excavation west of HWY 275 for communications/data installation (1/27/2020).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/2018). Grading has temporarily ceased (1/10/2019). Grading occurred in between HWY 30 and Menards to still water main between last inspection (2/7/2019) and current inspection (2/20/2019), but grading had ceased at time of inspection. Grading along HWY 275 (4/5/2019). Grading for water main project has ceased (4/19/2019)

Highway 30 intersection improvements have begun for culvert installation (10/02/2019).

Grading for Highway 30 intersection improvements has begun (7/27/2020). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/2020). Stockpiling on Block 1 Lot 9 (4/20/2021). Disturbance along Eastgate Road entrance (8/26/2021). Landscaping along Eastgate Road entrance (10/11/2021).

Grading for lot construction active (6/2020).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (8/30/2018). Seeding and matting in ditch for sanitary lift main (9/19/2018). Seeding around banks of E side of lake (11/6/2018). Seeding for Highway 30 Intersection Improvements (10/18/2020). Reseeding along the Highway 30 Improvements (3/15/2021).

Checklist Questions:

1.) Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

2.) Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to prevent erosion.

Yes Create Corrective Action?

N/A

3.) Are waste materials (concrete, construction material, hazardous, etc.) being managed properly? Yes **Create Corrective Action?** N/A 4.) Are construction entrances and adjacent streets being maintained adequately? No **Create Corrective Action?**

No - See BMPs section

5.) Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action? N/A

Comments: Comments:

The site was active during the last inspection for home construction.

Based on the amount of lot construction active in the development as of the 4/26/23 inspection, Gallery 23 East will be inspected at the Stage 1 frequency. E&A inspector will monitor and adjust inspection frequency as necessary.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date): 1.) See BMP section for required maintenance.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
	C	Gallery 23 Ea	st			
CE 1	Construction Entrance	County Road Blvd U		Removed		
Current Condition:	Removed - Thompson Construction removed the construction entrance in preparation for paving prior to inspection on 9/9/19.					
CE 2	Construction Entrance	County Road 25/Highway 30		Removed		
Current Condition:	Removed - Pruss was remo	Removed - Pruss was removing the construction entrance during inspection on 6/18/19 in preparation for paving.				
CE 3	Construction Entrance	NE Corner - Hwy 30 & Christine Drive		Removed		
Current Condition:	Removed - The constructio inspection on 8/05/20.	Removed - The construction entrance was removed as a part of the Highway 30 intersection improvements prior to the inspection on 8/05/20.				
CIP 1	Curb Inlet protection	Sammy Road		Removed		
Current Condition:	Removed - DR Horton remo	oved the inlet protection	prior to the inspection on 1/	17/23.		
CIP 2	Curb Inlet protection	Sammy Road		Removed		
Current Condition:	Removed - DR Horton remo	oved the inlet protection	prior to the 11/6/23 inspecti	on.		
CIP 3	Curb Inlet protection	East 18th Avenue		Removed		
Current Condition:	Removed - DR Horton removed the curb inlet filter prior to the 7/15/24 inspection.					
CIP 4	Curb Inlet protection	Kara Way		Removed		
Current Condition:	Removed - DR Horton remo	oved the inlet protection	prior to the 10/16/23 inspec	tion.		
CIP 5	Curb Inlet protection	East 18th Avenue		Removed		
Current Condition:	Removed - DR Horton removed the curb inlet filter prior to the 7/15/24 inspection.					
CIP 6	Curb Inlet protection	Taylor Lane	6/19/2023	Active	No	
Current Condition:	Good Condition - DR Horton installed inlet protection northeast of the concrete washout pit prior to the inspection on 6/19/23. DR Horton repositioned the inlet filter prior to the 6/10/24 inspection.					
CIP 7	Curb Inlet protection	Taylor Lane	6/19/2023	Active	No	
Current Condition:	Good Condition - DR Horton removed the inlet protection prior to the 10/16/23 inspection. DR Horton reinstalled the inl protection prior to the 10/30/23 inspection.					
CIP 8	Curb Inlet protection	Aaron Way	3/25/2024	Active	Yes	
Current Condition:	Fair Condition - DR Horton protection prior to the 5/13/ Horton reinstalled the curb Curb inlet filter should be re	24 inspection. DR Horton inlet filter prior to the 7/1	n removed the inlet protection			
	DR Horton was informed to	complete by 8/26/24. N	ot done as of last inspecti	on.		

	Quela la lata a seta ati a s	A = == = 10/=	0/40/0004	A ative	Na
CIP 9 Current Condition:	Curb Inlet protection	Aaron Way	8/12/2024 ection prior to the 8/12/24 ins	Active	No
Current Condition.					
CIP 10	Curb Inlet protection	Aaron Way	8/12/2024	Active	No
Current Condition:	Good Condition - DR Horton	n installed the inlet prote	ection prior to the 8/12/24 ins	spection.	
CP #1	Culvert protection	Central portion of site	8/30/2018	Pending	No
Current Condition:	Pending - Culvert protection			. enang	
CP #2	Culvert protection	Southeast corner	8/30/2018	Pending	No
Current Condition:	Pending - Culvert protection			. enang	
CW	Concrete Washout	Block 9, Lot 1	9/6/2022	Active	No
Current Condition:	-	2	ashout prior to the inspectio		
DW #1 Current Condition:	Horton cleaned out the con- washout and the surroundir concrete waste outside of the Block 7 Lot 1 prior to the 11 prior to the 11/27/23 inspec	crete washout prior to the ng area prior to the 6/19/ ne washout prior to the 1 /20/23 inspection. DR H tion. DR Horton remove rete waste and installe Middle Central	a berm and plastic liner price e inspection on 4/10/23. DR 23 inspection. DR Horton re 10/16/23 inspection. DR Horton forton removed the concrete d concrete waste outside of d a portable washout pit p 8/30/2018 grading has ended.	R Horton cleaned ou emoved the concrete ton relocated the co waste from lots in l the pit prior to the 6	t the concrete e washout and the oncrete washout to Blocks 7, 8, and 9 5/10/24 inspection.
DW #2	Ditch Wattle Checks	Southwest corner	8/30/2018	Pending	No
Current Condition:	Pending - Ditch wattle chec			ronung	
DW #3	Ditch Wattle Checks	Southeast corner	8/30/2018	Active	No
Current Condition:	_		the southeast side of the site		
DD #1	Diversion Ditch	NW Corner of Lake		Removed	•
Current Condition:			regrading/paving in the are		1 on 12/30/19
DD #2	Diversion Ditch	W side of Lake		Removed	1011 12/00/10:
Current Condition:			version ditch prior to inspec		
DD #3	Diversion Ditch	SW corner of lake		Removed	
Current Condition:			version ditch prior to inspec		
DD #4	Diversion Ditch	S Side of lake		Removed	
Current Condition:			l version ditch prior to inspec		
DD #5	Diversion Ditch	E side of lake		Removed	
Current Condition:			version ditch prior to inspec		
DD #6	Diversion Ditch	NE corner of lake		Removed	
Current Condition:			regrading/paving in the are		n on 12/30/19
		-			
DD #7	Diversion Ditch	N side of lake		Removed	40/00/40
Current Condition:			regrading/paving in the are		
EB #2	Erosion Blanket	Northeast corner	8/30/2018	Pending	No
Current Condition:	Pending - Erosion control m		be installed when grading ha	as ended.	
		Around Lake (Outlot			
EB #3	Erosion Blanket	B)	8/30/2018	Pending	No
Current Condition:	Pending - Erosion control m		be installed when grading ha	as ended.	
		Area Inlet in SE			
IP 1	Inlet Protection	portion of the site		Removed	
Current Condition:		i the area inlet naturally	stabilized prior to the 8/05/2	to inspection. Inlet F	-rotection no longe
	needed at this time.				
		W Curb inlet on			
IP 2	Curb Inlet protection	Christine Dr		Removed	ia na kaona i
Current Condition:	Removed - The Home Com	ipany sodded lots 1-8 pr	ior to the inspection on 6/10	/20. Inlet protection	is no longer requir
		E Curb inlet on			
IP 3	Curb Inlet protection	Christine Dr		Removed	
Current Condition:	Removed - The Home Com	pany sodded lots 1-8 pr	ior to the inspection on 6/10	/20. Inlet protection	is no longer requir
Block 2 Replat 3, Lot 16	Individual Lots	Block 2, Lot 16		Removed	
Current Condition:	Removed - Lot was added i			. tomorou	l
Block 3 Replat 3, Lot 10	Individual Lots	Block 3, Lot 10	[Removed	
Current Condition:	Removed - Lot was added i			. tomorou	
Block 3 Replat 2, Lots 1-7	Individual Lots	Block 3	[Removed	
Current Condition:	Removed - Hubbell Homes	sodded the lots prior to	the 8/14/23 inspection, clea		removed the porta
	toilet prior to the 8/21/23 ins	spection.			
Block 4 Replat 2, Lots 1-4	toilet prior to the 8/21/23 ins	Block 4	[]	Removed	

Current Condition:	Removed - Hubbell Home	s sodded the lots prior to	the 8/14/23 inspection.		
Block 4 Replat 2, Lots 5-7	Individual Lots	Block 4		Removed	
Current Condition:	Removed - Hubbell Home	s sodded the lots prior to	the 8/14/23 inspection.		
Block 2 Replat 3, Lots 15 & 16	Individual Lots	Block 4		Removed	
Current Condition:	Removed - Lots 13 and 14	were sodded prior to the	e 5/24/23 inspection. As of 4	/10/24, Block 4 Re	plat 2, Lots 15 & 16
	have been updated to Bloo Replat 3, Lots 15 & 16.	ck 2 Replat 3, Lots 12-14	and Block 4 Replat 2, Lots	13 & 14 have been	updated to Block 2
Block 2 Replat 3, Lots 7-9	Individual Lots	Block 2	11/6/2023	Pending	Yes
Current Condition:	recommended at this time	Streets were scraped pr the 3/25/24 inspection. A	e 11/6/23. Due to the grad∉ ior to the 1/11/24 inspectior s of 4/10/24, Block 4 Replat er of the lots.	n. Hubbell Homes re	emoved the concre
	Hubbell Homes was inform 5/29/24, 7/23/24, 8/26/24	ned to complete by 5/13/2	24. Not done as of last inspe	ection. Hubbell Hon	nes was reminded o
Block 2 Replat 3, Lots 10 & 11	Individual Lots	Block 2	7/31/2023	Pending	Yes
Current Condition:	Pending - Hubbell Homes	began construction on th	e lots prior to the inspection were scraped prior to the 1	on 7/31/23. Due to	the grade of the lo
	Straw wattles should be in	stalled along the perimet	oilets prior to the 7/1/24 insp er of the lots. 24. Not done as of last inspe		nes was reminded o
Block 2 Replat 3, Lots 12-14	Individual Lots	Block 2		Removed	
Current Condition:	Removed - Hubbell Home	s sodded the lots prior to	the 6/10/24 inspection.		
Block 3 Replat 3, Lots 1-6	Individual Lots	Block 3		Removed	
Current Condition:	Removed - Hubbell Home	s sodded the lots prior to	the 6/10/24 inspection.		
Block 5 Replat 2, Lots 7-9	Individual Lots	Block 5		Removed	
Current Condition:	Removed - Hubbell Home	s sodded the lots prior to	the inspection on 12/11/23.	•	•
Block 5 Replat 2, Lots 10-13	Individual Lots	Block 5		Removed	
			aned the streets prior to the	inspection on 7/6/2	
Current Condition:	Removed - Hubbell Home	s sodded the lots and cle			23.
Block 6, Lot 23	Individual Lots	Block 6		Removed	23.
		Block 6 s sodded the lot prior to t		· · · · · · · · · · · · · · · · · · ·	
Block 6, Lot 23 Current Condition: Block 6, Lot 26	Individual Lots Removed - Hubbell Home Individual Lots	Block 6 s sodded the lot prior to t Block 6	he 6/5/23 inspection.	· · · · · · · · · · · · · · · · · · ·	
Block 6, Lot 23 Current Condition: Block 6, Lot 26 Current Condition:	Individual Lots Removed - Hubbell Home Individual Lots Removed - Hubbell Home	Block 6 s sodded the lot prior to t Block 6 s sodded the lot prior to t	he 6/5/23 inspection.	Removed	23.
Block 6, Lot 23 Current Condition: Block 6, Lot 26 Current Condition: Block 6, Lot 27	Individual Lots Removed - Hubbell Home Individual Lots Removed - Hubbell Home Individual Lots Individual Lots	Block 6 s sodded the lot prior to t Block 6 s sodded the lot prior to t Block 6	he 6/5/23 inspection. he 5/24/23 inspection.	Removed Removed Removed	23.
Block 6, Lot 23 Current Condition: Block 6, Lot 26 Current Condition: Block 6, Lot 27 Current Condition:	Individual Lots Removed - Hubbell Home Individual Lots Removed - Hubbell Home Individual Lots Removed - TJL Consulting	Block 6 s sodded the lot prior to t Block 6 s sodded the lot prior to t Block 6 g Inc. sodded the lot prior	he 6/5/23 inspection. he 5/24/23 inspection. to the inspection on 9/11/23	Removed Removed Removed Removed 3.	
Block 6, Lot 23 Current Condition: Block 6, Lot 26 Current Condition: Block 6, Lot 27 Current Condition: Block 6, Lot 6	Individual Lots Removed - Hubbell Home Individual Lots Removed - Hubbell Home Individual Lots Removed - TJL Consulting Individual Lots	Block 6 s sodded the lot prior to t Block 6 s sodded the lot prior to t Block 6 g Inc. sodded the lot prior Block 6	he 6/5/23 inspection. he 5/24/23 inspection. to the inspection on 9/11/23	Removed Removed Removed Removed Active	23.
Block 6, Lot 23 Current Condition: Block 6, Lot 26 Current Condition: Block 6, Lot 27 Current Condition: Block 6, Lot 6 Current Condition:	Individual Lots Removed - Hubbell Home Individual Lots Removed - Hubbell Home Individual Lots Removed - TJL Consulting Individual Lots Good Condition - DR Hort	Block 6 s sodded the lot prior to t Block 6 s sodded the lot prior to t Block 6 g Inc. sodded the lot prior Block 6 on secured a portable toi	he 6/5/23 inspection. he 5/24/23 inspection. to the inspection on 9/11/23 7/8/2024 let on the lot prior to the 7/8/	Removed Removed Removed Removed Active Z4 inspection.	 No
Block 6, Lot 23 Current Condition: Block 6, Lot 26 Current Condition: Block 6, Lot 27 Current Condition: Block 6, Lot 6 Current Condition: Block 7, Lot 1	Individual Lots Removed - Hubbell Home Individual Lots Removed - Hubbell Home Individual Lots Removed - TJL Consulting Individual Lots Good Condition - DR Horte Individual Lots	Block 6 s sodded the lot prior to t Block 6 s sodded the lot prior to t Block 6 g Inc. sodded the lot prior Block 6 on secured a portable toi Block 7	he 6/5/23 inspection. he 5/24/23 inspection. he 5/24/23 inspection. to the inspection on 9/11/23 to the inspection on 9/11/23 7/8/2024 let on the lot prior to the 7/8, 7/1/2024	Removed Removed Removed Removed Active /24 inspection. Active	 No No
Block 6, Lot 23 Current Condition: Block 6, Lot 26 Current Condition: Block 6, Lot 27 Current Condition: Block 6, Lot 6 Current Condition: Block 7, Lot 1 Current Condition: Block 7, Lot 4	Individual Lots Removed - Hubbell Home Individual Lots Removed - Hubbell Home Individual Lots Removed - TJL Consulting Individual Lots Good Condition - DR Hort Individual Lots Good Condition - DR Hort wattles along the perimete removed prior to the 8/20 reinstallation.	Block 6 s sodded the lot prior to t Block 6 s sodded the lot prior to t Block 6 g Inc. sodded the lot prior Block 6 on secured a portable toil Block 7 on began foundation wor r of the lot prior to the ins 3/24 inspection; due the Block 7	he 6/5/23 inspection. he 5/24/23 inspection. he 5/24/23 inspection. to the inspection on 9/11/23 7/8/2024 let on the lot prior to the 7/8, 7/1/2024 k on the lot prior to the 7/1/2 spection on 7/29/24. Straw flat grade of the lot, E&A 7/1/2024	Removed Removed Removed Removed Removed Removed Active Active Removed	No No orton installed stray aged and partially hitor for No
Block 6, Lot 23 Current Condition: Block 6, Lot 26 Current Condition: Block 6, Lot 27 Current Condition: Block 6, Lot 6 Current Condition: Block 7, Lot 1 Current Condition: Block 7, Lot 4 Current Condition:	Individual Lots Removed - Hubbell Home Individual Lots Removed - Hubbell Home Individual Lots Removed - TJL Consulting Individual Lots Good Condition - DR Hort wattles along the perimete removed prior to the 8/20 reinstallation. Individual Lots	Block 6 s sodded the lot prior to t Block 6 s sodded the lot prior to t Block 6 g Inc. sodded the lot prior Block 6 on secured a portable toil Block 7 on began foundation wor r of the lot prior to the ins S/24 inspection; due the Block 7 on began foundation wor south sides of the lot prior to the 8/26/24 inspection	he 6/5/23 inspection. he 5/24/23 inspection. to the inspection on 9/11/23 7/8/2024 let on the lot prior to the 7/8/ 7/1/2024 k on the lot prior to the 7/1/2 spection on 7/29/24. Straw of flat grade of the lot, E&A 7/1/2024 k on the lot prior to the 7/1/2 or to the 7/15/24 inspection ; due the flat grade of the	Removed Removed Removed Active /24 inspection. Active /24 inspection. Removed Active Active Active Active Active Straw wattles we Iot, E&A inspector	No No No orton installed strat aged and partially nitor for No orton installed strat re damaged and will monitor for
Block 6, Lot 23 Current Condition: Block 6, Lot 26 Current Condition: Block 6, Lot 27 Current Condition: Block 6, Lot 6 Current Condition: Block 7, Lot 1 Current Condition: Block 7, Lot 4 Current Condition: Block 7, Lot 5	Individual Lots Removed - Hubbell Home Individual Lots Removed - Hubbell Home Individual Lots Removed - TJL Consulting Individual Lots Good Condition - DR Hort wattles along the perimete removed prior to the 8/20 reinstallation. Individual Lots Good Condition - DR Hort wattles along the west and partially removed prior to reinstallation.	Block 6 s sodded the lot prior to t Block 6 s sodded the lot prior to t Block 6 g Inc. sodded the lot prior Block 6 g Inc. sodded the lot prior Block 7 on began foundation wor S/24 inspection; due the Block 7 on began foundation wor South sides of the lot prior Block 7 Don began foundation wor	he 6/5/23 inspection. he 5/24/23 inspection. he 5/24/23 inspection. to the inspection on 9/11/23 7/8/2024 let on the lot prior to the 7/8/ 7/1/2024 k on the lot prior to the 7/1/2 spection on 7/29/24. Straw of flat grade of the lot, E&A 7/1/2024 k on the lot prior to the 7/1/2 or to the 7/15/24 inspection ; due the flat grade of the 7/1/2024	Removed Removed Removed 3. Active /24 inspection. DR H wattles were dama inspector will more Active 4 inspection. DR H Straw wattles were Iot, E&A inspector Active	No No No orton installed strat aged and partially hitor for No orton installed strat re damaged and will monitor for No
Block 6, Lot 23 Current Condition: Block 6, Lot 26 Current Condition: Block 6, Lot 27 Current Condition: Block 6, Lot 6 Current Condition: Block 7, Lot 1 Current Condition: Block 7, Lot 4 Current Condition:	Individual Lots Removed - Hubbell Home Individual Lots Removed - Hubbell Home Individual Lots Removed - TJL Consulting Individual Lots Good Condition - DR Hort wattles along the perimeter removed prior to the 8/20 reinstallation. Individual Lots Good Condition - DR Hort wattles along the west and partially removed prior to reinstallation. Individual Lots Good Condition - DR Hort wattles along the west and partially removed prior to reinstallation. Individual Lots	Block 6 s sodded the lot prior to t Block 6 s sodded the lot prior to t Block 6 g Inc. sodded the lot prior to t Block 6 g Inc. sodded the lot prior Block 7 on began foundation wor south sides of the lot prior block 7 on began foundation wor south sides of the lot prior block 7 on began foundation wor block 7 block 7	he 6/5/23 inspection. he 5/24/23 inspection. to the inspection on 9/11/23 7/8/2024 let on the lot prior to the 7/8/ 7/1/2024 k on the lot prior to the 7/1/2 spection on 7/29/24. Straw of flat grade of the lot, E&A 7/1/2024 k on the lot prior to the 7/1/2 or to the 7/15/24 inspection ; due the flat grade of the	Removed Removed Removed 3. Active /24 inspection. DR H wattles were dama inspector will more Active 4 inspection. DR H Straw wattles were lot, E&A inspector Active Active Active Active Active Active Active Inspection. DR H Active Active Active Active Active Active	No No No orton installed stra aged and partially hitor for No orton installed stra re damaged and will monitor for No

Current Condition:	Good Condition - DR Horton began foundation work on the lot prior to the 6/10/24 in wattles along the north and east sides of the lot prior to the 7/15/24 inspection.	spection. DR	Horton installed s
Block 7, Lot 8	Individual Lots Block 7 6/10/2024	Active	No
Current Condition:	Active - DR Horton began foundation work on the lot prior to the 6/10/24 inspection.		1
Block 7, Lot 9	Individual Lots Block 7 5/13/2024	Active	No
Current Condition:	Good Condition - DR Horton began foundation work on the lot prior to the 5/13/24 in		
	wattles along the western side of the lot prior to the 6/10/24 inspection. Straw wattle removed prior to the 8/26/24 inspection; due the flat grade of the lot, E&A inspection; reinstallation.	es were dama ector will mor	aged and partiall nitor for
Block 7, Lot 10	Individual Lots Block 7 5/13/2024	Active	No
Current Condition:	Good Condition - DR Horton began foundation work on the lot prior to the 5/13/24 in wattles along the western side of the lot prior to the 6/10/24 inspection. Straw wattle removed prior to the 8/26/24 inspection; due the flat grade of the lot, E&A inspection; reinstallation.	es were dama	aged and partiall
Block 7, Lot 11	Individual Lots Block 7 5/13/2024	Active	No
Current Condition:	Active - DR Horton began foundation work on the lot prior to the 5/13/24 inspection.		
Block 7, Lot 12	Individual Lots Block 7 4/15/2024	Active	No
Current Condition:	Good Condition - DR Horton began foundation work on the lot prior to the 4/15/24 in	spection. DR	Horton installed s
	wattles along the eastern side of the lot prior to the 4/29/24 inspection.		
Block 7, Lot 13	Individual Lots Block 7 3/11/2024	Active	No
Current Condition:	Good Condition - DR Horton installed a portable toilet on the lot prior to the 3/11/24 i foundation work on the lot prior to the 4/15/24 inspection. DR Horton secured the po wattles along the eastern side of the lot prior to the 4/29/24 inspection. DR Horton re Lot 6 prior to the 7/8/24 inspection.	rtable toilet ar	nd installed straw
Block 7, Lot 14	Individual Lots Block 7	Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the inspection on 7/29/24.		4
Block 7, Lot 15	Individual Lots Block 7	Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the 7/15/24 inspection.		•
Block 7, Lot 16	Individual Lots Block 7	Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the 5/13/24 inspection.		
Block 7, Lot 17	Individual Lots Block 7	Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the 5/13/24 inspection.		4
Block 7, Lot 18	Individual Lots Block 7	Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the 8/5/24 inspection.		
Block 7, Lot 19	Individual Lots Block 7	Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the 8/5/24 inspection.	Kennoved	
Block 7, Lot 20		Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the 8/5/24 inspection.		
Block 7, Lot 21		Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the 8/5/24 inspection.		
Block 7, Lot 22	Individual Lots Block 7	Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the 8/5/24 inspection.		
Block 7, Lot 23	Individual Lots Block 7	Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the 5/13/24 inspection.	Removed	
Block 7, Lot 24		Removed	1
Current Condition:	Removed - DR Horton sodded the lot prior to the 5/13/24 inspection.	Removed	1
		Demosione 1	Τ
Block 7, Lot 25		Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the 5/13/24 inspection.		T
Block 8, Lot 1		Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the 5/13/24 inspection.		
Block 9, Lot 1	Individual Lots Block 9	Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the 12/18/23 inspection.		
Block 10, Lot 1	Individual Lots Block 10, Lot 1	Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the 11/20/23 inspection.		1
Block 10, Lot 2		Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the 5/24/23 inspection.		

Block 10, Lot 5	Removed - DR Horton sod	ded the lot prior to the 5/	13/24 inspection.		
	Individual Lots	Block 10, Lot 5		Removed	
Current Condition:	Removed - DR Horton sod	ded the lot prior to the in	spection on 7/06/23.		
Block 10, Lot 6	Individual Lots	Block 10, Lot 6		Removed	
Current Condition:	Removed - DR Horton sod	Ided the lot prior to the in	spection on 11/6/23.	•	
Block 10, Lot 7	Individual Lots	Block 10, Lot 7		Removed	
Current Condition:	Removed - DR Horton sod	Ided the lot prior to the 12	2/18/23 inspection.	•	•
Block 10, Lot 8	Individual Lots	Block 10, Lot 8		Removed	1
Current Condition:	Removed - DR Horton sod	· · · · · · · · · · · · · · · · · · ·	13/24 inspection	Removed	
ourrent contaition.		•			
Block 10, Lot 9	Individual Lots	Block 10, Lot 9		Removed	
Current Condition:	Removed - DR Horton sod	Ided the lot prior to the 11	1/20/23 inspection.		
Block 10, Lot 10	Individual Lots	Block 10, Lot 10		Removed	
Current Condition:	Removed - DR Horton sod	Ided the lot prior to the 10	0/16/23 inspection.		
Block 10, Lot 11	Individual Lots	Block 10, Lot 11		Removed	
Current Condition:	Removed - DR Horton sod	Ided the lot prior to the 8/	14/23 inspection.		•
Block 10, Lot 12	Individual Lots	Block 10, Lot 12		Removed	
Current Condition:	Removed - DR Horton sod		2/18/23 inspection.		
Block 11, Lot 1	Individual Lots	· ·		Demessed	
1	Removed - DR Horton sod	Block 11, Lot 1		Removed	
Current Condition:		•			
Block 11, Lot 2	Individual Lots	Block 11, Lot 2		Removed	
Current Condition:	Removed - DR Horton sod		spection on 4/19/23.		
Block 12, Lot 1	Individual Lots	Block 12, Lot 1		Removed	
Current Condition:	Removed - DR Horton sod	· · ·	spection on 4/19/23.		
Block 12, Lot 2	Individual Lots	Block 12, Lot 2		Removed	
Current Condition:	Removed - DR Horton sod	· · · · · · · · · · · · · · · · · · ·	24/23 inspection.		
Block 12, Lot 3	Individual Lots	Block 12, Lot 3		Removed	
Current Condition:	Removed - DR Horton sod				
STR	Street cleaning	Off-Site	In Place r to the 2/19/24 inspection.	Active	Yes
	on 2/13/24, 3/12/24, 4/9/24	nformed to complete by 2/ 4, 5/8/24, 5/29/24, 7/23/24	/06/24. Not done as of last i 4, 8/26/24		
	2.) DR Horton was informe 6/25/24, 7/2/24, 7/23/24, 8		Not done as of last inspect	Ion. DR Horton was	reminded on 6/4/24
SWPPP Sign	Signs	Gallery East Drive	10/9/2018	Active	No
Current Condition:			signs during inspection on		
	installed at the County Rd inspection on 9/19/19. The reinstalled the SWPPP sig	U Blvd entrance at a late E&A inspector reinstalle on prior to the inspection of	r date. The E&A inspector r d the SWPPP sign during t on 3/31/20. The SWPPP sig n 8/17/20. E&A inspector re	einstalled the SWP he 2/24/20 inspectio gn was removed du	PP sign during on. The E&A inspec ing the Highway 30
		On Site	11/6/2023	Active	No
WSX	Waste Storage				
WS X Current Condition:	Hubbell Homes emptied th waste storage containers p 1/11/24 inspection. Hubbe	Homes installed several whee waste storage contained prior to the 12/11/23 inspection of the mathematical sectors and the wastern of the mathematical sectors and the mathematical sectors are set of the mathematical sectors are sectors are set of the mathematical sectors are set of	waste storage containers or ers prior to the 11/20/23 ins ection. DR Horton installed ste storage containers prior /12/24 inspection. DR Horto	their lots prior to the pection. Hubbell Ho waste storage conta to the 1/29/24 insp	he 11/6/23 inspection mes emptied the ainers prior to the ection. DR Horton
	Good Condition - Hubbell Hubbell Homes emptied th waste storage containers p 1/11/24 inspection. Hubbe emptied the waste storage	Homes installed several whee waste storage contained prior to the 12/11/23 inspection of the mathematical sectors and the wastern of the mathematical sectors and the mathematical sectors are set of the mathematical sectors are sectors are set of the mathematical sectors are set of	waste storage containers or ers prior to the 11/20/23 ins ection. DR Horton installed ste storage containers prior	their lots prior to the pection. Hubbell Ho waste storage conta to the 1/29/24 insp	he 11/6/23 inspection mes emptied the ainers prior to the ection. DR Horton

- L	Joh 1/	and and
Inspector Signature:		Reviewed By: