E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

Inspector: Josh Ellington	ton E&A - P2018.109.002					
Project Name:	С	Gallery 23 East CSW-201702253 (Mass Grading)				
		9/14	/2024			
Project Location:	County Road	U and Lincoln High	way- Fremont, NE (Dodg	e County)	68025	
	Gallery 23 East					
Grading:	98%					
Sanitary Sewer:	99%					
Storm Sewer:	99%					
Paving:	99%					
Seeding:	35%					
Utilities:	99%					
Overall Development:	60%					
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions	Time		
					Weel	
Sunday:	0.00"					
Monday:	0.00"	9/9/2024	Sunny 77	11:45 AM		
Tuesday:	0.00"					
Wednesday:	0.00"					
Thursday:	0.00"					
Friday:	0.01"					
Saturday:	0.00"					
Complaints:	None					
Construction Sequencing:						

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/2018). Grading has temporarily ceased (1/10/2019). Grading in the NE corner of site for sanitary installation (4/5/2019). Grading for roads (6/4/2019). Grading for utilities, storm, and roads throughout project (6/17/2019). Excavation along southwest portion ROW for gas installation (6/18/2019). Excavation in the southeast portion of the site for utilities (6/18/2019). Excavation throughout the site for gas installation (6/24/2019). Excavation for storm sewer (7/16/2019) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/2019). Fine grading throughout the site in preparation for paving (9/09/2019). Excavation in the northeast corner of the site for culvert installation (9/19/2019). Trenching/excavation in the southeast portion of the site for utility installation (10/22/2019). Trenching throughout site for utility installation (11/18/2019). Minor trenching/excavation west of HWY 275 for communications/data installation (1/27/2020).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/2018). Grading has temporarily ceased (1/10/2019). Grading occurred in between HWY 30 and Menards to still water main between last inspection (2/7/2019) and current inspection (2/20/2019), but grading had ceased at time of inspection. Grading along HWY 275 (4/5/2019). Grading for water main project has ceased (4/19/2019)

Highway 30 intersection improvements have begun for culvert installation (10/02/2019).

Grading for Highway 30 intersection improvements has begun (7/27/2020). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/2020). Stockpiling on Block 1 Lot 9 (4/20/2021). Disturbance along Eastgate Road entrance (8/26/2021). Landscaping along Eastgate Road entrance (10/11/2021).

Grading for lot construction active (6/2020).

#### Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/2018). Grading has temporarily ceased (1/10/2019). Grading in the NE corner of site for sanitary installation (4/5/2019). Grading for roads (6/4/2019). Grading for utilities, storm, and roads throughout project (6/17/2019). Excavation along southwest portion ROW for gas installation (6/18/2019). Excavation in the southeast portion of the site for utilities (6/18/2019). Excavation throughout the site for gas installation (6/24/2019). Excavation for storm sewer (7/16/2019) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/2019). Fine grading throughout the site in preparation for paving (9/09/2019). Excavation in the northeast corner of the site for culvert installation (9/19/2019). Trenching/excavation in the southeast portion of the site for utility installation (10/22/2019). Trenching throughout site for utility installation (11/18/2019). Minor trenching/excavation west of HWY 275 for communications/data installation (1/27/2020).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/2018). Grading has temporarily ceased (1/10/2019). Grading occurred in between HWY 30 and Menards to still water main between last inspection (2/7/2019) and current inspection (2/20/2019), but grading had ceased at time of inspection. Grading along HWY 275 (4/5/2019). Grading for water main project has ceased (4/19/2019)

Highway 30 intersection improvements have begun for culvert installation (10/02/2019).

Grading for Highway 30 intersection improvements has begun (7/27/2020). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/2020). Stockpiling on Block 1 Lot 9 (4/20/2021). Disturbance along Eastgate Road entrance (8/26/2021). Landscaping along Eastgate Road entrance (10/11/2021).

Grading for lot construction active (6/2020).

### What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (8/30/2018). Seeding and matting in ditch for sanitary lift main (9/19/2018). Seeding around banks of E side of lake (11/6/2018). Seeding for Highway 30 Intersection Improvements (10/18/2020). Reseeding along the Highway 30 Improvements (3/15/2021).

#### Checklist Questions:

1.) Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

**Create Corrective Action?** 

N/A

2.) Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to prevent erosion.

Yes

**Create Corrective Action?** 

N/A

## 3.) Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

**Create Corrective Action?** 

N/A

#### 4.) Are construction entrances and adjacent streets being maintained adequately?

No

**Create Corrective Action?** 

No - See BMPs section

## 5.) Is dust associated with the construction activity adequately controlled on the site?

Vac

**Create Corrective Action?** 

N/A

# Comments:

#### Comments:

The site was active during the last inspection for home construction.

Based on the amount of lot construction active in the development as of the 4/26/23 inspection, Gallery 23 East will be inspected at the Stage 1 frequency. E&A inspector will monitor and adjust inspection frequency as necessary.

## Findings / Corrective Actions (Date):

## Findings / Corrective Actions (Date):

1.) See BMP section for required maintenance.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
	(	Sallery 23 Ea	st		
CE 1	Construction Entrance	County Road Blvd U		Removed	
Current Condition:	Removed - Thompson Construction removed the construction entrance in preparation for paving prior to inspection 9/9/19.				
		County Road			
CE 2	Construction Entrance	25/Highway 30		Removed	
Current Condition:	Removed - Pruss was remo	oving the construction er	ntrance during inspection on	6/18/19 in preparat	ion for paving.
		NE Corner - Hwy 30 &			
CE 3	Construction Entrance	Christine Drive		Removed	
Current Condition:	Removed - The constructio inspection on 8/05/20.	n entrance was remove	d as a part of the Highway 3	0 intersection impro	vements prior to t
CIP 1	Curb Inlet protection	Sammy Road		Removed	
Current Condition:	Removed - DR Horton remo	oved the inlet protection	prior to the inspection on 1/	17/23.	
CIP 2	Curb Inlet protection	Sammy Road		Removed	
Current Condition:	Removed - DR Horton remo	oved the inlet protection	prior to the 11/6/23 inspecti	on.	
CIP 3	Curb Inlet protection	East 18th Avenue		Removed	
Current Condition:	Removed - DR Horton remo	oved the curb inlet filter	prior to the 7/15/24 inspection	on.	
CIP 4	Curb Inlet protection	Kara Way		Removed	
Current Condition:			prior to the 10/16/23 inspec	tion.	
CIP 5	Curb Inlet protection	East 18th Avenue		Removed	
Current Condition:		oved the curb inlet filter	prior to the 7/15/24 inspection	on.	
CIP 6	Curb Inlet protection	Taylor Lane	6/19/2023	Active	No
Current Condition:	Good Condition - DR Horton installed inlet protection northeast of the concrete washout pit prior to the inspection on 6/19/23. DR Horton repositioned the inlet filter prior to the 6/10/24 inspection.				
CIP 7	Curb Inlet protection	Taylor Lane	6/19/2023	Active	No
Current Condition:	Good Condition - DR Horton removed the inlet protection prior to the 10/16/23 inspection. DR Horton reinstalled the in protection prior to the 10/30/23 inspection.				
CIP 8	Curb Inlet protection	Aaron Way	3/25/2024	Active	Yes
Current Condition:		24 inspection. DR Horto inlet filter prior to the 7/1 epaired.		on prior to the 7/1/24	

CIP 9	Curb Inlet protection	Aaron Way	8/12/2024	Active	No
Current Condition:	Good Condition - DR Horton	n installed the inlet prote	ection prior to the 8/12/24 in	spection.	
CIP 10	Curb Inlet protection	Aaron Way	8/12/2024	Active	No
Current Condition:	Good Condition - DR Horton	,			140
		<u>.                                      </u>	·		
CP #1	Culvert protection	Central portion of site	8/30/2018	Pending	No
Current Condition:	Pending - Culvert protection				
CP #2	Culvert protection	Southeast corner	8/30/2018	Pending	No
Current Condition:	Pending - Culvert protection				
CW	Concrete Washout	Block 9, Lot 1	9/6/2022	Active	No
Current Condition:	Good Condition - DR Hortor concrete washout and insta Horton cleaned out the conc washout and the surroundin concrete waste outside of the Block 7 Lot 1 prior to the 11 prior to the 11/27/23 inspection removed the concrete bitch Wattle Checks	Iled a new washout with crete washout prior to the g area prior to the 6/19/ ne washout prior to the 1/20/23 inspection. DR H tion. DR Horton remove	a berm and plastic liner price inspection on 4/10/23. DF (23 inspection. DR Horton re 10/16/23 inspection. DR Horton removed the concreted concrete waste outside of	or to the inspection the Horton cleaned out the concret ton relocated the control waste from lots in the pit prior to the 6	on 3/13/23. DR t the concrete e washout and the oncrete washout to Blocks 7, 8, and 9 8/10/24 inspection. DR
Current Condition:	Pending - Ditch wattle check			relialing	NO
DW #2	Ditch Wattle Checks	Southwest corner	8/30/2018	Pending	No
Current Condition:	Pending - Ditch wattle check			l relialing	INU
DW #3	Ditch Wattle Checks	Southeast corner	8/30/2018	Active	No
Current Condition:	Good Condition - Wattles ch				
DD #1	Diversion Ditch	NW Corner of Lake	lile southeast side of the sit	Removed	
Current Condition:	Removed - The diversion di		l regrading/paying in the are		on 12/30/10
DD #2	Diversion Ditch	W side of Lake	I	Removed	1011 12/00/10.
Current Condition:	Removed - Thompson Cons		Vorsion ditch prior to inspec		
DD #3	Diversion Ditch	SW corner of lake	I	Removed	
	Removed - Thompson Cons		Vorsion ditch prior to inspec		
Current Condition:  DD #4	Diversion Ditch	S Side of lake	I	Removed	
Current Condition:	Removed - Thompson Cons		version ditch prior to inspec		
DD #5	Diversion Ditch	E side of lake	T	Removed	
Current Condition:	Removed - Thompson Cons		Version ditch prior to inspec		
DD #6	Diversion Ditch	NE corner of lake	T	Removed	
Current Condition:	Removed - The diversion di		I regrading/paving in the are		on 12/30/19
		<u></u>	,		
DD #7	Diversion Ditch	N side of lake	<u> </u>	Removed	40/00/40
Current Condition:	Removed - The diversion di				
EB #2	Erosion Blanket	Northeast corner	8/30/2018	Pending	No
Current Condition:	Pending - Erosion control m		be installed when grading ha	as ended.	
		Around Lake (Outlot			
EB #3	Erosion Blanket	B)	8/30/2018	Pending	No
Current Condition:	Pending - Erosion control m		be installed when grading ha	as ended.	
ID 4	Inlet Drete - +:	Area Inlet in SE		Domos ( = -1	
IP 1	Inlet Protection  Removed - The area east or	portion of the site	stabilized prior to the SIGE	Removed	Protoction no lenger
Current Condition:	needed at this time.	i the area inlet haturally	stabilized prior to the 6/05/2	to inspection, inlet i	Protection no longer
	nocaca at tillo tillo.	M O	T	<u> </u>	
IP 2	Curb Inlet protection	W Curb inlet on Christine Dr		Removed	
Current Condition:	Curb Inlet protection Removed - The Home Com		ior to the inspection on 6/10		is no longer required
Current Condition:	Removed - The Home Com	party souded lots 1-6 pr	ior to the inspection on o/ ro	720. Iffiet protection	is no longer required.
		E Comb in let en	I		
IP 3	Curb Inlet protection	E Curb inlet on Christine Dr		Removed	
Current Condition:	Removed - The Home Com		ior to the inspection on 6/10		is no longer required
Current Condition:	Tromoved - The Home Com	party souded lots 1-0 pl	ior to the mapeonon on 0/10	, 20. milet protection	io no ionger required.
Block 2 Poplet 2 Let 16	Individual Lots	Plook 2 1 of 46	I	Domested	
Block 2 Replat 3, Lot 16	Removed - Lot was added i	Block 2, Lot 16	l	Removed	
Current Condition:	Individual Lots	Block 3, Lot 10		Removed	
Block 3 Replat 3, Lot 10	Removed - Lot was added i			Removed	
Current Condition: Block 3 Replat 2, Lots 1-7	Individual Lots	Block 3		Removed	
Current Condition:	Removed - Hubbell Homes		the 8/14/23 inspection, clea		removed the portable
	toilet prior to the 8/21/23 ins	spection.			· 
Block 4 Replat 2, Lots 1-4	Individual Lots	Block 4		Removed	
·					

Current Condition:	Removed - Hubbell Homes	s sodded the lots prior to	the 8/14/23 inspection.		
Block 4 Replat 2, Lots 5-7	Individual Lots	Block 4	1	Removed	
Current Condition:	Removed - Hubbell Homes		the 8/14/23 inspection.		
Block 2 Replat 3, Lots 15 & 16	Individual Lots	Block 4	<u> </u>	Removed	1
Current Condition:			e 5/24/23 inspection. As of		l plat 2 Lots 15 & 16
Carrent Condition.			and Block 4 Replat 2, Lots		
Block 2 Replat 3, Lots 7-9	Individual Lots	Block 2	11/6/2023	Pending	Yes
Current Condition:	recommended at this time. waste from the lot prior to to Block 2 Replat 3, Lots 7-9.  Straw wattles should be instituted in the strain of the	Streets were scraped p the 3/25/24 inspection. A stalled along the perimet	the 11/6/23. Due to the graderior to the 1/11/24 inspections of 4/10/24, Block 4 Replater of the lots.  24. Not done as of last inspections.	n. Hubbell Homes re at 2, Lots 23-25 have	emoved the concrete been updated to
Block 2 Replat 3, Lots 10 & 11	Individual Lots	Block 2	7/31/2023	l Pendina	Yes
Current Condition:			ne lots prior to the inspectio	1 3	
	inspection. Hubbell Homes	stalled along the perimet	11. Hubbell Homes secured bilets prior to the 7/1/24 inster of the lots.  24. Not done as of last insp	pection.	
Block 2 Replat 3, Lots 12-14	Individual Lots	Block 2		Removed	
Current Condition:	Removed - Hubbell Homes		the 6/10/24 inspection.		
Block 3 Replat 3, Lots 1-6	Individual Lots	Block 3	<u> </u>	Removed	1
Current Condition:	Removed - Hubbell Homes		the 6/10/24 inspection	Removed	
		•	The of 10/24 mapedian.		
Block 5 Replat 2, Lots 7-9	Individual Lots	Block 5	the simon of the A 0/44/00	Removed	
Current Condition:		s sodded the lots prior to	the inspection on 12/11/23	3.	
Block 5 Replat 2, Lots 10-13	Individual Lots	Block 5		Removed	
Current Condition:			eaned the streets prior to the	<del></del>	23.
Block 6, Lot 23  Current Condition:	Individual Lots Removed - Hubbell Homes	Block 6	the 6/5/22 inspection	Removed	
		<u> </u>	111e 0/3/23 irispection.		1
Block 6, Lot 26	Individual Lots	Block 6	the F/24/22 increation	Removed	
Current Condition:	Removed - Hubbell Homes		T	Damassad	1
Block 6, Lot 27  Current Condition:	Individual Lots	Block 6	_l r to the inspection on 9/11/2	Removed	
Block 6, Lot 6	Individual Lots	Block 6	7/8/2024	Active	No
Current Condition:			ilet on the lot prior to the 7/8		NO
		· · · · · · · · · · · · · · · · · · ·	·	· · · · · · · · · · · · · · · · · · ·	l Ni
Block 7, Lot 1 Current Condition:	Individual Lots	Block 7	7/1/2024 k on the lot prior to the 7/1/	Active	No No ortan installed straw
Current Condition.	wattles along the perimete	r of the lot prior to the ins	spection on 7/29/24. Straw at grade of the lot, E&A insp	wattles were damag	ed and partially
Block 7, Lot 4	Individual Lots	Block 7	7/1/2024	Active	No
Current Condition:	wattles along the west and	south sides of the lot pr	k on the lot prior to the 7/1/ ior to the 7/15/24 inspection ue the flat grade of the lot, I	n. Straw wattles were	e damaged and
Block 7, Lot 5	Individual Lots	Block 7	7/1/2024	Active	No
Current Condition:	Good Condition - DR Horto wattles along the south and		rk on the lot prior to the 7/1/ for to the 7/15/24 inspection		orton installed straw
Block 7, Lot 7	Individual Lots	Block 7	6/10/2024	Active	No
Current Condition:			k on the lot prior to the 6/10		Horton installed straw
	wattles along the north and	d east sides of the lot pri	or to the 7/15/24 inspection		

Block 7, Lot 8	Individual Lots	Block 7	6/10/2024	Active	No
Current Condition:	Active - DR Horton began fo				140
Block 7, Lot 9	Individual Lots	Block 7	5/13/2024	Active	No
Current Condition:	Good Condition - DR Horton				
	wattles along the western s removed prior to the 8/26/24	ide of the lot prior to the	6/10/24 inspection. Straw v	vattles were damag	ed and partially
Block 7, Lot 10	Individual Lots	Block 7	5/13/2024	Active	No
Current Condition:	Good Condition - DR Horton wattles along the western s removed prior to the 8/26/24	ide of the lot prior to the	6/10/24 inspection. Straw w	vattles were damag	ed and partially
Block 7, Lot 11	Individual Lots	Block 7	5/13/2024	Active	No
Current Condition:	Active - DR Horton began for	oundation work on the lo	ot prior to the 5/13/24 inspec	tion.	
Block 7, Lot 12	Individual Lots	Block 7	4/15/2024	Active	No
Current Condition:	Good Condition - DR Horto			24 inspection. DR	Horton installed straw
	wattles along the eastern si				
Block 7, Lot 13  Current Condition:	Individual Lots Good Condition - DR Horto	Block 7	3/11/2024	Active	No No
	foundation work on the lot p wattles along the eastern si Lot 6 prior to the 7/8/24 insp due the flat grade of the lot,	de of the lot prior to the pection. Straw wattles w E&A inspector will mon	4/29/24 inspection. DR Hor ere damaged and partially r	ton relocated the po emoved prior to the	ortable toilet to Block 6
Block 7, Lot 14	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodo		spection on 7/29/24.	T =	
Block 7, Lot 15	Individual Lots	Block 7	145/04:	Removed	
Current Condition:	Removed - DR Horton sodo		15/24 inspection.		
Block 7, Lot 16	Individual Lots	Block 7	10.00.1	Removed	
Current Condition:	Removed - DR Horton sodo	· · · · · · · · · · · · · · · · · · ·	13/24 inspection.		_
Block 7, Lot 17	Individual Lots	Block 7	110/04:	Removed	
Current Condition:	Removed - DR Horton sodo		13/24 inspection.		
Block 7, Lot 18	Individual Lots	Block 7	7.04	Removed	
Current Condition:	Removed - DR Horton sodo	ded the lot prior to the 8/	5/24 inspection.		
Block 7, Lot 19	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodo	ded the lot prior to the 8/	5/24 inspection.		
Block 7, Lot 20	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodo	ded the lot prior to the 8/	5/24 inspection.		
Block 7, Lot 21	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodo	led the lot prior to the 8/	5/24 inspection.	•	•
Block 7, Lot 22	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodo		5/24 inspection.	rtemoved	
Block 7, Lot 23	Individual Lots	Block 7	<u> </u>	Removed	
Current Condition:	Removed - DR Horton sodo		13/24 inspection	Removed	
Block 7, Lot 24		Block 7	T0/21 moposion.	Removed	
Current Condition:	Individual Lots Removed - DR Horton sodo		13/24 inspection	Removed	
			Толда півросцоп.	D	
Block 7, Lot 25  Current Condition:	Individual Lots Removed - DR Horton sodo	Block 7	13/24 inspection	Removed	
			13/24 III3pection.		
Block 8, Lot 1  Current Condition:	Individual Lots Removed - DR Horton sodo	Block 8	13/24 inspection	Removed	
			13/24 Inspection.		
Block 9, Lot 1	Individual Lots	Block 9	2/40/00 in an att	Removed	
Current Condition:	Removed - DR Horton sodo	·	2/18/23 inspection.		
Block 10, Lot 1	Individual Lots	Block 10, Lot 1		Removed	
Current Condition:	Removed - DR Horton sodo		1/20/23 inspection.		
Block 10, Lot 2	Individual Lots	Block 10, Lot 2	24/22 inapartian	Removed	
Current Condition:	Removed - DR Horton sodo		z4/z3 inspection.		
Block 10, Lot 4	Individual Lots	Block 10, Lot 4		Removed	
Current Condition:	Removed - DR Horton sodo	iea the lot prior to the 5/	13/24 inspection.		

Block 10, Lot 5	Individual Lots	Block 10, Lot 5		Removed		
Current Condition:	Removed - DR Horton sodo		spection on 7/06/23.	1		
Block 10, Lot 6	Individual Lots	Block 10, Lot 6		Removed		
Current Condition:	Removed - DR Horton sodd		spection on 11/6/23.			
Block 10, Lot 7	Individual Lots	Block 10, Lot 7		Removed		
Current Condition:	Removed - DR Horton sodd	led the lot prior to the 12	2/18/23 inspection.			
Block 10, Lot 8	Individual Lots	Block 10, Lot 8		Removed		
Current Condition:	Removed - DR Horton sodo	led the lot prior to the 5/	13/24 inspection.	•		
Block 10, Lot 9	Individual Lots	Block 10, Lot 9		Removed		
Current Condition:	Removed - DR Horton sodo	· · · · · · · · · · · · · · · · · · ·	1/20/23 inspection.			
Block 10, Lot 10	Individual Lots	Block 10, Lot 10	· ·· · ·	Removed		
Current Condition:	Removed - DR Horton sodo		I )/16/23 inspection	rtemoved		
Block 10, Lot 11	Individual Lots	Block 10, Lot 11		Removed		
Current Condition:	Removed - DR Horton sodo		L 14/23 inspection	rtemoved		
			T 1/20 Inoposion:			
Block 10, Lot 12	Individual Lots	Block 10, Lot 12	)/10/02 increation	Removed		
Current Condition:	Removed - DR Horton sodd	<u> </u>	2/16/23 Inspection.			
Block 11, Lot 1	Individual Lots	Block 11, Lot 1		Removed		
Current Condition:	Removed - DR Horton sodo	led the lot prior to the 1	1/20/23 inspection.			
Block 11, Lot 2	Individual Lots	Block 11, Lot 2		Removed		
Current Condition:	Removed - DR Horton sodo		spection on 4/19/23.			
Block 12, Lot 1	Individual Lots	Block 12, Lot 1	<u>'</u>	Removed		
Current Condition:	Removed - DR Horton sodd	led the lot prior to the in	spection on 4/19/23.	!		
Block 12, Lot 2	Individual Lots	Block 12, Lot 2		Removed		
Current Condition:	Removed - DR Horton sodd	led the lot prior to the 5/	24/23 inspection.	•	•	
Block 12, Lot 3	Individual Lots	Block 12, Lot 3		Removed		
Current Condition:	Removed - DR Horton sodd	led the lot prior to the 5/	24/23 inspection.	!		
STR	Street cleaning	Off-Site	In Place	Active	Yes	
Current Condition:	Fair Condition - DR Horton	cleaned the streets prior	to the 2/19/24 inspection. I	OR Horton partially	cleaned the streets	
	<ul> <li>2.) Streets along all active lots should be cleaned.</li> <li>1.) Hubbell Homes were informed to complete by 2/06/24. Not done as of last inspection. Hubbell Homes on 2/13/24, 3/12/24, 4/9/24, 5/8/24, 5/29/24, 7/23/24, 8/26/24</li> <li>2.) DR Horton was informed to complete by 5/2/24. Not done as of last inspection. DR Horton was remined.</li> </ul>					
	6/25/24, 7/2/24, 7/23/24, 8/5	5/24, 8/21/24				
SWPPP Sign	Signs	Gallery East Drive	10/9/2018	Active	No	
Current Condition:	Good Condition - Inspector					
	installed at the County Rd L inspection on 9/19/19. The reinstalled the SWPPP sign Intersection Improvements inspection on 8/31/20.	E&A inspector reinstalle prior to the inspection of	d the SWPPP sign during the months of the SWPPP sign 3/31/20. The SWPPP sign	ne 2/24/20 inspection In was removed dui	on. The E&A inspector ring the Highway 30	
WSX	Waste Storage	On Site	11/6/2023	Active	No	
Current Condition:	Good Condition - Hubbell H Hubbell Homes emptied the waste storage containers pr 1/11/24 inspection. Hubbell emptied the waste storage of prior to the 4/29/24.	omes installed several waste storage container ior to the 12/11/23 insperior to the material to the wa	waste storage containers or ers prior to the 11/20/23 inspection. DR Horton installed ste storage containers prior	pection. Hubbell Howaste storage conta to the 1/29/24 insp	mes emptied the ainers prior to the ection. DR Horton	
Certification Statement:	I certify, under penalty of lavaccordance with a system desubmitted. Based on my independent of gathering the information complete. I am aware that the land imprisonment for knowing	lesigned to assure that on the person or pe to the information submit there are significant pend	rsons who manage the syst tted is, to the best of my kno	gathered and evaluem or those person owledge and belief,	uated the information s directly responsible true, accurate, and	
Inspector Signature:	HE		Reviewed By:	Et Se		