E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



## Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Inspector: Josh Ellington		Stage				
Project Name:		1				
		CSW-201702253 (Mass Grading) 10/12/2024				
Project Location:	County R	e County)	68025			
	Gallery 23 East					
Grading:		98%				
Sanitary Sewer:		99%				
Storm Sewer:		99%				
Paving:		99%				
Seeding:		35%				
Utilities:		99%				
Overall Development:		60%				
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions	Time		
Sunday:	0.00"				Week	
Monday:	0.00"	10/7/2024	Sunny 71	1:50 PM		
Tuesday:	0.00"					
Wednesday:	0.00"					
Thursday:	0.00"					
Friday:	0.00"					
Saturday:	0.00"					

Complaints:

Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/2018). Grading has temporarily ceased (1/10/2019). Grading in the NE corner of site for sanitary installation (4/5/2019). Grading for roads (6/4/2019). Grading for utilities, storm, and roads throughout project (6/17/2019). Excavation along southwest portion ROW for gas installation (6/18/2019). Excavation in the southeast portion of the site for utilities (6/18/2019). Excavation throughout the site for gas installation (6/24/2019). Excavation for storm sewer (7/16/2019) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/2019). Fine grading throughout the site in preparation for paving (9/09/2019). Excavation in the northeast corner of the site for culvert installation (9/19/2019). Trenching/excavation in the southeast portion of the site for utility installation (10/22/2019). Trenching throughout site for utility installation (11/18/2019). Minor trenching/excavation west of HWY 275 for communications/data installation (1/27/2020).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/2018). Grading has temporarily ceased (1/10/2019). Grading occurred in between HWY 30 and Menards to still water main between last inspection (2/7/2019) and current inspection (2/20/2019), but grading had ceased at time of inspection. Grading along HWY 275 (4/5/2019). Grading for water main project has ceased (4/19/2019)

Highway 30 intersection improvements have begun for culvert installation (10/02/2019).

Grading for Highway 30 intersection improvements has begun (7/27/2020). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/2020). Stockpiling on Block 1 Lot 9 (4/20/2021). Disturbance along Eastgate Road entrance (8/26/2021). Landscaping along Eastgate Road entrance (10/11/2021).

Grading for lot construction active (6/2020).

### Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/2018). Grading has temporarily ceased (1/10/2019). Grading in the NE corner of site for sanitary installation (4/5/2019). Grading for roads (6/4/2019). Grading for utilities, storm, and roads throughout project (6/17/2019). Excavation along southwest portion ROW for gas installation (6/18/2019). Excavation in the southeast portion of the site for utilities (6/18/2019). Excavation throughout the site for gas installation (6/24/2019). Excavation for storm sewer (7/16/2019) Trenching for utility installation throughout the site in preparation for paving (9/09/2019). Excavation in the northeast corner of the site for culvert installation (9/19/2019). Trenching/excavation in the southeast portion of the site for utility installation (10/22/2019). Trenching throughout site for utility installation (11/18/2019). Minor trenching/excavation west of HWY 275 for communications/data installation (1/27/2020).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/2018). Grading has temporarily ceased (1/10/2019). Grading occurred in between HWY 30 and Menards to still water main between last inspection (2/7/2019) and current inspection (2/20/2019), but grading had ceased at time of inspection. Grading along HWY 275 (4/5/2019). Grading for water main project has ceased (4/19/2019)

Highway 30 intersection improvements have begun for culvert installation (10/02/2019).

Grading for Highway 30 intersection improvements has begun (7/27/2020). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/2020). Stockpiling on Block 1 Lot 9 (4/20/2021). Disturbance along Eastgate Road entrance (8/26/2021). Landscaping along Eastgate Road entrance (10/11/2021).

Grading for lot construction active (6/2020).

### What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (8/30/2018). Seeding and matting in ditch for sanitary lift main (9/19/2018). Seeding around banks of E side of lake (11/6/2018). Seeding for Highway 30 Intersection Improvements (10/18/2020). Reseeding along the Highway 30 Improvements (3/15/2021).

Checklist Questions:

1.) Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

2.) Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to prevent erosion.

### Yes Create Corrective Action?

N/A

# 3.) Are waste materials (concrete, construction material, hazardous, etc.) being managed properly? Yes Create Corrective Action? N/A 4.) Are construction entrances and adjacent streets being maintained adequately?

No Create Corrective Action?

No - See BMPs section

5.) Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

Comments:

Comments:

The site was active during the last inspection for home construction.

Based on the amount of lot construction active in the development as of the 4/26/23 inspection, Gallery 23 East will be inspected at the Stage 1 frequency. E&A inspector will monitor and adjust inspection frequency as necessary.

# Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date): 1.) See BMP section for required maintenance.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
		Gallery 23 Eas	st				
CE 1	Construction Entrance	County Road Blvd U		Removed			
Current Condition:	Removed - Thompson Construction removed the construction entrance in preparation for paving prior to inspection on 9/9/19.						
CE 2	Construction Entrance	County Road 25/Highway 30		Removed			
Current Condition:	Removed - Pruss was remo	oving the construction er	trance during inspection on	n 6/18/19 in preparat	tion for paving.		
CE 3	Construction Entrance	NE Corner - Hwy 30 & Christine Drive		Removed			
Current Condition:	Removed - The constructio inspection on 8/05/20.		as a part of the Highway 3	0 intersection impro	vements prior to the		
CIP 1	Curb Inlet protection	Sammy Road		Removed			
Current Condition:	Removed - DR Horton rem	oved the inlet protection	prior to the inspection on 1/	/17/23.			
CIP 2	Curb Inlet protection	Sammy Road		Removed			
Current Condition:	Removed - DR Horton rem	oved the inlet protection	prior to the 11/6/23 inspecti	ion.			
CIP 3	Curb Inlet protection	East 18th Avenue		Removed			
Current Condition:	Removed - DR Horton rem	Removed - DR Horton removed the curb inlet filter prior to the 7/15/24 inspection.					
CIP 4	Curb Inlet protection	Kara Way		Removed			
Current Condition:	Removed - DR Horton rem	oved the inlet protection	prior to the 10/16/23 inspec	tion.			
CIP 5	Curb Inlet protection	East 18th Avenue		Removed			
Current Condition:	Removed - DR Horton rem	oved the curb inlet filter	prior to the 7/15/24 inspection	on.			
CIP 6	Curb Inlet protection	Taylor Lane	6/19/2023	Active	No		
Current Condition:	Good Condition - DR Horto 6/19/23. DR Horton reposit			washout pit prior to	the inspection on		
CIP 7	Curb Inlet protection	Taylor Lane	6/19/2023	Active	No		
Current Condition:	Good Condition - DR Horto protection prior to the 10/30		ection prior to the 10/16/23	inspection. DR Hort	on reinstalled the ir		
CIP 8	Curb Inlet protection	Aaron Way	3/25/2024	Active	No		
Current Condition:	Good Condition - DR Horto protection prior to the 5/13/ Horton reinstalled the curb 9/30/24 inspection.	24 inspection. DR Horton	n removed the inlet protection	on prior to the 7/1/24	4 inspection. DR		
CIP 9	Curb Inlet protection	Aaron Way	8/12/2024	Active	No		
Current Condition:	Good Condition - DR Horto	n installed the inlet prote	ection prior to the 8/12/24 in	spection.			

	Quality is the second section.	A	0/40/0004	A	NL.
CIP 10 CIP 10	Curb Inlet protection Good Condition - DR Horto	Aaron Way	8/12/2024	Active	No
Current Condition:	Good Condition - DR Holto				
CP #1	Culvert protection	Central portion of site	8/30/2018	Pending	No
Current Condition:	Pending - Culvert protection	1			
CP #2	Culvert protection	Southeast corner	8/30/2018	Pending	No
Current Condition:	Pending - Culvert protection				
CW	Concrete Washout	Block 9, Lot 1	9/6/2022	Active	No
Current Condition:	Good Condition - DR Horto				
	concrete washout and insta Horton cleaned out the con washout and the surroundir concrete waste outside of th Block 7 Lot 1 prior to the 11 prior to the 11/27/23 inspec Horton removed the concre	crete washout prior to th ng area prior to the 6/19, ne washout prior to the 2 /20/23 inspection. DR H tion. DR Horton remove te waste and installed a	e inspection on 4/10/23. D /23 inspection. DR Horton /0/16/23 inspection. DR Ho lorton removed the concre d concrete waste outside o portable washout pit prior	R Horton cleaned out removed the concrete orton relocated the con te waste from lots in Bl of the pit prior to the 6/ to the 8/26/24 inspecti	the concrete washout and the crete washout to ocks 7, 8, and 9 10/24 inspection. D
DW #1	Ditch Wattle Checks	Middle Central	8/30/2018	Pending	No
Current Condition:	Pending - Ditch wattle chec	ks will be installed wher	grading has ended.		
DW #2	Ditch Wattle Checks	Southwest corner	8/30/2018	Pending	No
Current Condition:	Pending - Ditch wattle chec	ks will be installed wher	grading has ended.		
DW #3	Ditch Wattle Checks	Southeast corner	8/30/2018	Active	No
Current Condition:	Good Condition - Wattles c	hecks were installed on	the southeast side of the s	ite prior to 8/30/2018.	
DD #1	Diversion Ditch	NW Corner of Lake		Removed	
Current Condition:	Removed - The diversion d		regrading/paving in the a	rea prior to inspection	on 12/30/19.
DD #2	Diversion Ditch	W side of Lake		Removed	
Current Condition:	Removed - Thompson Con	struction removed the di	version ditch prior to inspe	ection on 9/19/18.	
DD #3	Diversion Ditch	SW corner of lake		Removed	
Current Condition:	Removed - Thompson Con	struction removed the d	version ditch prior to inspe	ection on 9/19/18.	
DD #4	Diversion Ditch	S Side of lake		Removed	
Current Condition:	Removed - Thompson Con	struction removed the di	version ditch prior to inspe	ection on 9/19/18.	
DD #5	Diversion Ditch	E side of lake		Removed	
Current Condition:	Removed - Thompson Con	struction removed the di	version ditch prior to inspe	ection on 9/19/18.	
DD #6	Diversion Ditch	NE corner of lake		Removed	
Current Condition:	Removed - The diversion d	itch was removed during	regrading/paving in the a	rea prior to inspection	on 12/30/19.
DD #7	Diversion Ditch	N side of lake		Removed	
Current Condition:	Removed - The diversion d		l regrading/paving in the a		on 12/30/19
		-			
EB #2	Erosion Blanket	Northeast corner	8/30/2018	Pending	No
Current Condition:	Pending - Erosion control m		le installed when grading i	nas ended.	
FD #2	Encoion Diaminat	Around Lake (Outlot	0/20/2040	Dandina	Na
EB #3	Erosion Blanket Pending - Erosion control m	B)	8/30/2018	Pending	No
Current Condition:	Fending - Erosion control n		l installed when grading i		
IP 1	Inlet Protection	Area Inlet in SE portion of the site		Removed	
	Removed - The area east o		atabilizad prior to the 8/05		ataction no longor
Current Condition:	needed at this time.	i the area miet haturany	stabilized prior to the 0/05	20 Inspection. Intel FI	olection no longer
		W Curb inlet on		1	
IP 2	Curb Inlet protection	Christine Dr		Removed	
Current Condition:	Removed - The Home Com		ior to the inspection on 6/1		s no longer require
Current Condition.		ipany souded lots 1-0 pi		0/20. milet protection it	
		E Curb inlet on		T T	
IP 3	Curb Inlet protection	Christine Dr		Removed	
Current Condition:	Removed - The Home Com		ior to the inspection on 6/1		
Current Condition.	Removed - The Home Com	ipally source lots 1-0 pl	ion to the inspection on o/i	0/20. Inter protection is	
		Disale 0. Lat 40		Demoved	
Block 2 Replat 3, Lot 16	Individual Lots	Block 2, Lot 16		Removed	
Current Condition:	Removed - Lot was added i			Domessed	
Block 3 Replat 3, Lot 10	Individual Lots	Block 3, Lot 10		Removed	
Current Condition:	Removed - Lot was added i			Demand	
Block 3 Replat 2, Lots 1-7	Individual Lots	Block 3	the 0/11/00 image of the 1	Removed	
Oursel One little	Removed - Hubbell Homes	-	ule o/ 14/23 Inspection, cle	aneu the streets and r	emoved the portab
Current Condition:	toilet prior to the 8/21/23 ins	spection.			
		-		Removed	
Block 4 Replat 2, Lots 1-4	Individual Lots	Block 4	the 8/14/23 inspection	Removed	
		Block 4	the 8/14/23 inspection.	Removed	

Current Condition:	Removed - Hubbell Home	· · · · · · · · · · · · · · · · · · ·			
Block 2 Replat 3, Lots 15 & 16	Individual Lots	Block 4		Removed	
Current Condition:			he 5/24/23 inspection. As o 4 and Block 4 Replat 2, Lo		
Block 2 Replat 3, Lots 7-9	Individual Lots	Block 2	11/6/2023	Pending	Yes
Current Condition:	recommended at this time waste from the lot prior to Block 2 Replat 3, Lots 7-9 Straw wattles should be in	<ul> <li>Streets were scraped p the 3/25/24 inspection. / .</li> <li>Installed along the perime med to complete by 5/13.</li> </ul>	the 11/6/23. Due to the gra prior to the 1/11/24 inspect As of 4/10/24, Block 4 Rep eter of the lots. 9/24. Not done as of last in:	tion. Hubbell Homes re plat 2, Lots 23-25 have	moved the concre been updated to
Block 2 Poplat 3 Lats 10 8 11	Individual Lots	Block 2	7/31/2023	Ponding	Yes
Block 2 Replat 3, Lots 10 & 11 Current Condition:			the lots prior to the inspect	tion on 7/31/23 Due to	
	have been updated to Blo inspection. Hubbell Home Straw wattles should be in	ock 2 Replat 3, Lots 10 & es removed the portable t installed along the perime med to complete by 5/13	the 2/26/24 inspection. As 11. Hubbell Homes secur toilets prior to the 7/1/24 ir eter of the lots. 3/24. Not done as of last in:	red the portable toilets   nspection.	prior to the 4/15/2
Block 2 Replat 3, Lots 12-14	Individual Lots	Block 2		Removed	
Current Condition:	Removed - Hubbell Home	s sodded the lots prior to	o the 6/10/24 inspection.		
Block 3 Replat 3, Lots 1-6	Individual Lots	Block 3		Removed	
Current Condition:	Removed - Hubbell Home	-	 o the 6/10/24 inspection.	rtemoved	
		•			
Block 5 Replat 2, Lots 7-9	Individual Lots	Block 5	to the inspection on 12/11/2	Removed	L
Current Condition:					
Block 5 Replat 2, Lots 10-13	Individual Lots	Block 5		Removed	
Current Condition:		Block 6	leaned the streets prior to t		3.
Block 6, Lot 23 Current Condition:	Individual Lots Removed - Hubbell Home		the 6/5/23 inspection	Removed	
Block 6, Lot 26 Current Condition:	Individual Lots Removed - Hubbell Home	Block 6	the 5/21/23 inspection	Removed	
Block 6. Lot 27	Individual Lots	Block 6		Removed	
Current Condition:		-	I or to the inspection on 9/11		
Block 6, Lot 6	Individual Lots	Block 6	7/8/2024	Active	No
Current Condition:		-	pilet on the lot prior to the 7		
Block 7, Lot 1	Individual Lots	Block 7	7/1/2024	Active	No
Current Condition:			ork on the lot prior to the 7		
	wattles along the perimeter removed prior to the 8/26/ Horton removed the com portion of the lot prior to	er of the lot prior to the in /24 inspection; due the fl icrete washout pit and o the 10/7/24 inspection	nspection on 7/29/24. Stram lat grade of the lot, E&A in: the concrete waste and i 1.	w wattles were damage spector will monitor for installed straw wattle	ed and partially reinstallation. <b>DF</b> s along the east
Block 7, Lot 4	Individual Lots	Block 7	7/1/2024	Active	No
Current Condition:	wattles along the west and	d south sides of the lot p	ork on the lot prior to the 7/ prior to the 7/15/24 inspecti due the flat grade of the lot	ion. Straw wattles were	e damaged and
Block 7, Lot 5	Individual Lots	Block 7	7/1/2024	Active	No
Current Condition:	Active - DR Horton begar along the south and east	n foundation work on the sides of the lot prior to th	lot prior to the 7/1/24 insp ne 7/15/24 inspection. <b>DR</b>	pection. DR Horton insta Horton removed the s	alled straw wattle
	the 10/7/24 inspection; E	A inspector will mon	itor for reinstallation or s	sou installation.	
Block 7, Lot 7	the 10/7/24 inspection; E Individual Lots	Block 7	6/10/2024	Active	No

Block 7, Lot 8	Individual Lots	Block 7	6/10/2024	Active	No
Current Condition:			of prior to the 6/10/24 inspect		NO
	_				
Block 7, Lot 9 Current Condition:	Individual Lots Removed - DR Horton sod	Block 7	10/7/24 increation	Removed	
Block 7, Lot 10	Individual Lots	Block 7	40/7/24 increation	Removed	
Current Condition:	Removed - DR Horton sod		e 10/7/24 inspection.		
Block 7, Lot 11	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sod		e 10/7/24 inspection.		
Block 7, Lot 12	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodd	ed the lot prior to the 9/	23/24 inspection.		
Block 7, Lot 13	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodd	ed the lot prior to the 9/	23/24 inspection.		
Block 7, Lot 14	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodd	ed the lot prior to the in	spection on 7/29/24.		
Block 7, Lot 15	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodd	ed the lot prior to the 7/	15/24 inspection.		
Block 7, Lot 16	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodd		13/24 inspection.		
Block 7, Lot 17	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodd	ed the lot prior to the 5/	13/24 inspection.		
Block 7, Lot 18	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodd	ed the lot prior to the 8/	5/24 inspection.		
Block 7, Lot 19	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodd	ed the lot prior to the 8/	5/24 inspection.		
Block 7, Lot 20	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodd	ed the lot prior to the 8/	5/24 inspection.		
Block 7, Lot 21	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodd		5/24 inspection.	. tomorou	
Block 7, Lot 22	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodd		5/24 inspection	Kellioved	
				D	
Block 7, Lot 23 Current Condition:	Individual Lots Removed - DR Horton sodd	Block 7	13/24 inspection	Removed	
		•			
Block 7, Lot 24 Current Condition:	Individual Lots Removed - DR Horton sodd	Block 7	12/24 increation	Removed	
Block 7, Lot 25	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodd	-	13/24 inspection.		
Block 8, Lot 1	Individual Lots	Block 8		Removed	
Current Condition:	Removed - DR Horton sodd	•	13/24 inspection.		
Block 9, Lot 1	Individual Lots	Block 9		Removed	
Current Condition:	Removed - DR Horton sodd	ed the lot prior to the 12	2/18/23 inspection.		
Block 10, Lot 1	Individual Lots	Block 10, Lot 1		Removed	
Current Condition:	Removed - DR Horton sodd		1/20/23 inspection.		
Block 10, Lot 2	Individual Lots	Block 10, Lot 2		Removed	
Current Condition:	Removed - DR Horton sodd	ed the lot prior to the 5/	24/23 inspection.		
Block 10, Lot 4	Individual Lots	Block 10, Lot 4		Removed	
Current Condition:	Removed - DR Horton sodd	ed the lot prior to the 5/	13/24 inspection.		
Block 10, Lot 5	Individual Lots	Block 10, Lot 5		Removed	
Current Condition:	Removed - DR Horton sodd	ed the lot prior to the in	spection on 7/06/23.	Į	
Block 10, Lot 6	Individual Lots	Block 10, Lot 6		Removed	
Current Condition:	Removed - DR Horton sodd		spection on 11/6/23.		
Block 10, Lot 7	Individual Lots	Block 10, Lot 7		Removed	
Current Condition:	Removed - DR Horton sodd	ed the lot prior to the 12	2/18/23 inspection.		
Block 10, Lot 8	Individual Lots	Block 10, Lot 8		Removed	
Current Condition:	Removed - DR Horton sodd		13/24 inspection.		
Block 10, Lot 9	Individual Lots	Block 10, Lot 9	1	Domoved	
BIOCK TO, LOUS		DIOCK TO, LOU 9	1	Removed	

Current Condition:	Removed - DR Horton sode	ded the lot prior to the 11	/20/23 inspection		
Block 10, Lot 10	Individual Lots	Block 10, Lot 10		Removed	
Current Condition:	Removed - DR Horton sode	,	/ 1/16/23 inspection	Removed	
Block 10, Lot 11	Individual Lots	Block 10, Lot 11		Removed	
Current Condition:	Removed - DR Horton sode		14/23 inspection	Removed	
		· ·		Domovod	1
Block 10, Lot 12 Current Condition:	Individual Lots Removed - DR Horton sode	Block 10, Lot 12	/18/23 inspection	Removed	
		•			
Block 11, Lot 1	Individual Lots	Block 11, Lot 1		Removed	
Current Condition:	Removed - DR Horton sode	ded the lot prior to the 11	/20/23 inspection.		
Block 11, Lot 2	Individual Lots	Block 11, Lot 2		Removed	
Current Condition:	Removed - DR Horton sode	· · · · · · · · · · · · · · · · · · ·	spection on 4/19/23.		
Block 12, Lot 1	Individual Lots	Block 12, Lot 1		Removed	
Current Condition:	Removed - DR Horton sode		spection on 4/19/23.		1
Block 12, Lot 2	Individual Lots	Block 12, Lot 2		Removed	
Current Condition:	Removed - DR Horton sode	· · · · · · · · · · · · · · · · · · ·	24/23 inspection.	- 1	1
Block 12, Lot 3	Individual Lots	Block 12, Lot 3		Removed	
Current Condition:	Removed - DR Horton sode				
STR Current Condition:	Street cleaning Fair Condition - DR Horton	Off-Site	In Place	Active	Yes
SWPPP Sign Current Condition:	<ul> <li>1.) Streets along all active I</li> <li>2.) Streets along all active I</li> <li>1.) Hubbell Homes were int on 2/13/24, 3/12/24, 4/9/24</li> <li>2.) DR Horton was informe 6/25/24, 7/2/24, 7/23/24, 8/</li> <li>Signs</li> <li>Good Condition - Inspector installed at the County Rd I inspection on 9/19/19. The reinstalled the SWPPP sign Intersection Improvements inspection on 8/31/20.</li> </ul>	ots should be cleaned. formed to complete by 2/ , 5/8/24, 5/29/24, 7/23/24 d to complete by 5/2/24. 5/24, 8/21/24, 10/1/24 Gallery East Drive installed 1 of 2 SWPPP J Blvd entrance at a late E&A inspector reinstalle o prior to the inspection of	<ul> <li>4, 8/26/24, 10/1/24</li> <li>Not done as of last inspection</li> <li>10/9/2018</li> <li>signs during inspection o</li> <li>r date. The E&amp;A inspector</li> <li>d the SWPPP sign during</li> <li>on 3/31/20. The SWPPP s</li> </ul>	Active Active Active N 10/9/18. Other SWP the 2/24/20 inspectio ign was removed dui	reminded on 6/4/24, No PPP sign will be PP sign during on. The E&A inspector ring the Highway 30
WS X Current Condition:	Waste Storage Good Condition - Hubbell H	On Site	11/6/2023	Active	No No
	Hubbell Homes emptied th waste storage containers p 1/11/24 inspection. Hubbel emptied the waste storage prior to the 4/29/24.	e waste storage containe rior to the 12/11/23 inspe I Homes emptied the wa	ers prior to the 11/20/23 in ection. DR Horton installed ste storage containers prio	spection. Hubbell Ho d waste storage conta or to the 1/29/24 insp	mes emptied the ainers prior to the ection. DR Horton
Certification Statement:	I certify, under penalty of la accordance with a system of submitted. Based on my ind for gathering the informatio complete. I am aware that the and imprisonment for know	designed to assure that o quiry of the person or pe n, the information submi here are significant pena	ualified personnel proper rsons who manage the sy tted is, to the best of my k	ly gathered and evalu stem or those person nowledge and belief,	uated the information s directly responsible true, accurate, and
Inspector Signature:	Je e		Reviewed By:	Put Sul	