E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

E&A - P2018.109.002 Stage Inspector: Josh Ellington **Gallery 23 East** 1 **CSW-201702253** (Mass Grading) **Project Name:** 10/19/2024 County Road U and Lincoln Highway- Fremont, NE (Dodge County) 68025 Project Location: Gallery 23 East Grading: Sanitary Sewer: 99% Storm Sewer: 99% Paving: 99% Seeding: 35% Utilities: 99% **Overall Development:** 60% RAIN FALL AMOUNTS Amount in inches Date inspected Weather Conditions Time Week 1 Sunday: 0.00" Monday: 0.00" 10/14/2024 Sunny 61 4:30 PM Tuesday: 0.00" Wednesday: 0.00" Thursday: 0.00" Friday: 0.00" Saturday: 0.00" None Complaints: **Construction Sequencing:** Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/2018). Grading has temporarily ceased (1/10/2019). Grading in the NE corner of site for sanitary installation (4/5/2019). Grading for roads (6/4/2019). Grading for utilities, storm, and roads throughout project (6/17/2019). Excavation along southwest portion ROW for gas installation (6/18/2019). Excavation in the southeast portion of the site for utilities (6/18/2019). Excavation throughout the site for gas installation (6/24/2019). Excavation for storm sewer (7/16/2019) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/2019). Fine grading throughout the site in preparation for paving (9/09/2019). Excavation in the northeast corner of the site for culvert installation (9/19/2019). Trenching/excavation in the southeast portion of the site for utility installation (10/22/2019). Trenching throughout site for utility installation (11/18/2019). Minor trenching/excavation west of HWY 275 for communications/data installation (1/27/2020).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/2018). Grading has temporarily ceased (1/10/2019). Grading occurred in between HWY 30 and Menards to still water main between last inspection (2/7/2019) and current inspection (2/20/2019), but grading had ceased at time of inspection. Grading along HWY 275 (4/5/2019). Grading for water main project has ceased (4/19/2019)

Highway 30 intersection improvements have begun for culvert installation (10/02/2019).

Grading for Highway 30 intersection improvements has begun (7/27/2020). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/2020). Stockpiling on Block 1 Lot 9 (4/20/2021). Disturbance along Eastgate Road entrance (8/26/2021). Landscaping along Eastgate Road entrance (10/11/2021).

Grading for lot construction active (6/2020).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/2018). Grading has temporarily ceased (1/10/2019). Grading in the NE corner of site for sanitary installation (4/5/2019). Grading for roads (6/4/2019). Grading for utilities, storm, and roads throughout project (6/17/2019). Excavation along southwest portion ROW for gas installation (6/18/2019). Excavation in the southeast portion of the site for utilities (6/18/2019). Excavation throughout the site for gas installation (6/24/2019). Excavation for storm sewer (7/16/2019) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/2019). Fine grading throughout the site in preparation for paving (9/09/2019). Excavation in the northeast corner of the site for culvert installation (9/19/2019). Trenching/excavation in the southeast portion of the site for utility installation (10/22/2019). Trenching throughout site for utility installation (11/18/2019). Minor trenching/excavation west of HWY 275 for communications/data installation (1/27/2020).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/2018). Grading has temporarily ceased (1/10/2019). Grading occurred in between HWY 30 and Menards to still water main between last inspection (2/7/2019) and current inspection (2/20/2019), but grading had ceased at time of inspection. Grading along HWY 275 (4/5/2019). Grading for water main project has ceased (4/19/2019)

Highway 30 intersection improvements have begun for culvert installation (10/02/2019).

Grading for Highway 30 intersection improvements has begun (7/27/2020). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/2020). Stockpiling on Block 1 Lot 9 (4/20/2021). Disturbance along Eastgate Road entrance (8/26/2021). Landscaping along Eastgate Road entrance (10/11/2021).

Grading for lot construction active (6/2020).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (8/30/2018). Seeding and matting in ditch for sanitary lift main (9/19/2018). Seeding around banks of E side of lake (11/6/2018). Seeding for Highway 30 Intersection Improvements (10/18/2020). Reseeding along the Highway 30 Improvements (3/15/2021).

Checklist Questions:

1.) Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

2.) Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

3.) Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

/ac

Create Corrective Action?

N/A

4.) Are construction entrances and adjacent streets being maintained adequately?

No

Create Corrective Action?

No - See BMPs section

5.) Is dust associated with the construction activity adequately controlled on the site?

Vaa

Create Corrective Action?

N/A

Comments:

Comments:

The site was active during the last inspection for home construction.

Based on the amount of lot construction active in the development as of the 4/26/23 inspection, Gallery 23 East will be inspected at the Stage 1 frequency. E&A inspector will monitor and adjust inspection frequency as necessary.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) See BMP section for required maintenance.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
	G	Sallery 23 Eas	st		
CE 1	Construction Entrance	County Road Blvd U		Removed	
Current Condition:	Removed - Thompson Cons 9/9/19.	struction removed the co	onstruction entrance in prep	aration for paving pri	or to inspection of
CE 2	Construction Entrance	County Road 25/Highway 30		Removed	
Current Condition:	Removed - Pruss was remo	ving the construction er	trance during inspection on	6/18/19 in preparati	on for paving.
CE 3	Construction Entrance	NE Corner - Hwy 30 & Christine Drive		Removed	
Current Condition:	Removed - The construction inspection on 8/05/20.	n entrance was removed	d as a part of the Highway 3	0 intersection improv	ements prior to t
CIP 1	Curb Inlet protection	Sammy Road		Removed	
Current Condition:	Removed - DR Horton remo	oved the inlet protection	prior to the inspection on 1/	17/23.	
CIP 2	Curb Inlet protection	Sammy Road		Removed	
Current Condition:	Removed - DR Horton remo	oved the inlet protection	prior to the 11/6/23 inspecti	on.	
CIP 3	Curb Inlet protection	East 18th Avenue		Removed	
Current Condition:	Removed - DR Horton remo	oved the curb inlet filter	prior to the 7/15/24 inspection	on.	
CIP 4	Curb Inlet protection	Kara Way		Removed	
Current Condition:	Removed - DR Horton remo	oved the inlet protection	prior to the 10/16/23 inspec	tion.	
CIP 5	Curb Inlet protection	East 18th Avenue		Removed	
Current Condition:	Removed - DR Horton remo	oved the curb inlet filter	prior to the 7/15/24 inspection	on.	
CIP 6	Curb Inlet protection	Taylor Lane	6/19/2023	Active	No
Current Condition:	Good Condition - DR Horton 6/19/23. DR Horton repositi			washout pit prior to t	he inspection on
CIP 7	Curb Inlet protection	Taylor Lane	6/19/2023	Active	No
Current Condition:	Good Condition - DR Horton removed the inlet protection prior to the 10/16/23 inspection. DR Horton reinstalled the in protection prior to the 10/30/23 inspection.				
CIP 8	Curb Inlet protection	Aaron Way	3/25/2024	Active	No
Current Condition:	Good Condition - DR Horton protection prior to the 5/13/2 Horton reinstalled the curb i 9/30/24 inspection.	24 inspection. DR Horton	n removed the inlet protection	on prior to the 7/1/24	inspection. DR
CIP 9	Curb Inlet protection	Aaron Way	8/12/2024	Active	No
Current Condition:	Good Condition - DR Horton	n installed the inlet prote	ection prior to the 8/12/24 in	enection	

CIP 10	Curb Inlet protection	Aaron Way	8/12/2024	Active	No
Current Condition:	Good Condition - DR Hortor	n installed the inlet prote	ection prior to the 8/12/24 in	spection.	
CP #1	Culvert protection	Central portion of site	8/30/2018	Pending	No
Current Condition:	Pending - Culvert protection	will be installed at a lat	er date.		
CP #2	Culvert protection	Southeast corner	8/30/2018	Pending	No
Current Condition:	Pending - Culvert protection				T
CW	Concrete Washout	Block 9, Lot 1	9/6/2022	Active	No
Current Condition:	Good Condition - DR Hortor concrete washout and instal Horton cleaned out the conc washout and the surroundin concrete waste outside of the Block 7 Lot 1 prior to the 11 prior to the 11/27/23 inspect Horton removed the concrete that the concrete	lled a new washout with crete washout prior to the g area prior to the 6/19/ le washout prior to the 1/20/23 inspection. DR H tion. DR Horton remove te waste and installed a	a berm and plastic liner price inspection on 4/10/23. DF /23 inspection. DR Horton re 10/16/23 inspection. DR Hor lorton removed the concrete d concrete waste outside of portable washout pit prior to	or to the inspection R Horton cleaned ou emoved the concret ton relocated the constant of the pit prior to the 6 to the 8/26/24 inspection.	on 3/13/23. DR at the concrete e washout and the concrete washout to Blocks 7, 8, and 9 6/10/24 inspection. DR ction.
DW #1	Ditch Wattle Checks	Middle Central	8/30/2018	Pending	No
Current Condition: DW #2	Pending - Ditch wattle check Ditch Wattle Checks	Southwest corner	8/30/2018	Pending	No
Current Condition:	Pending - Ditch wattle check			Pending	INO
DW #3	Ditch Wattle Checks	Southeast corner	8/30/2018	Active	No
Current Condition:	Good Condition - Wattles ch				
DD #1	Diversion Ditch	NW Corner of Lake		Removed	
Current Condition:	Removed - The diversion di		regrading/paving in the are		n on 12/30/19.
DD #2	Diversion Ditch	W side of Lake	3 31 3	Removed	
Current Condition:	Removed - Thompson Cons		version ditch prior to inspec		
DD #3	Diversion Ditch	SW corner of lake	<u> </u>	Removed	
Current Condition:	Removed - Thompson Cons	struction removed the di	version ditch prior to inspec	tion on 9/19/18.	
DD #4	Diversion Ditch	S Side of lake	<u> </u>	Removed	
Current Condition:	Removed - Thompson Cons	struction removed the di	version ditch prior to inspec	tion on 9/19/18.	!
DD #5	Diversion Ditch	E side of lake		Removed	
Current Condition:	Removed - Thompson Cons	struction removed the di	version ditch prior to inspec	tion on 9/19/18.	•
DD #6	Diversion Ditch	NE corner of lake		Removed	
Current Condition:	Removed - The diversion di	tch was removed during	regrading/paving in the are	ea prior to inspectio	n on 12/30/19.
DD #7	Diversion Ditch	N side of lake		Removed	
Current Condition:	Removed - The diversion di	tch was removed during	regrading/paving in the are	ea prior to inspectio	n on 12/30/19.
EB #2	Erosion Blanket	Northeast corner	8/30/2018	Pending	No
Current Condition:	Pending - Erosion control m	atting and seeding will l	be installed when grading h	as ended.	
		Around Lake (Outlot			
EB #3	Erosion Blanket	В)	8/30/2018	Pending	No
Current Condition:	Pending - Erosion control m		be installed when grading h	as ended.	
		Area Inlet in SE			
IP 1	Inlet Protection	portion of the site		Removed	
Current Condition:	Removed - The area east of needed at this time.	f the area inlet naturally	stabilized prior to the 8/05/2	20 inspection. Inlet	Protection no longer
	needed at this time.	W Comb in let en	I	I	<u> </u>
IP 2	Curb Inlot protection	W Curb inlet on Christine Dr		Removed	
Current Condition:	Curb Inlet protection Removed - The Home Com		ior to the inspection on 6/10		is no longer required
Current Condition.	Removed - The Home Com	party souded lots 1-0 pr	ior to the mapection on of to	//20. Iffiet protection	i is no longer required.
IP 3 Current Condition:	Curb Inlet protection Removed - The Home Com	E Curb inlet on Christine Dr pany sodded lots 1-8 pr	ior to the inspection on 6/10	Removed //20. Inlet protection	is no longer required.
Block 2 Replat 3, Lot 16	Individual Lots	Block 2, Lot 16		Removed	
Current Condition:	Removed - Lot was added in		•	•	•
Block 3 Replat 3, Lot 10	Individual Lots	Block 3, Lot 10		Removed	
Current Condition:	Removed - Lot was added i		•	•	
Block 3 Replat 2, Lots 1-7	Individual Lots	Block 3		Removed	
Current Condition:	Removed - Hubbell Homes toilet prior to the 8/21/23 ins		the 8/14/23 inspection, clea	ined the streets and	removed the portable
Block 4 Replat 2, Lots 1-4	Individual Lots	Block 4		Removed	
Current Condition:	Removed - Hubbell Homes	sodded the lots prior to	the 8/14/23 inspection.		
Block 4 Replat 2, Lots 5-7	Individual Lots	Block 4		Removed	
		•	•	•	•

Current Condition:	Removed - Hubbell Home	s sodded the lots prior to	the 8/14/23 inspection.		
Block 2 Replat 3, Lots 15 & 16	Individual Lots	Block 4		Removed	
Current Condition:	Removed - Lots 13 and 14		e 5/24/23 inspection. As of 4 and Block 4 Replat 2, Lots	4/10/24, Block 4 Rep	
Block 2 Replat 3, Lots 7-9	Individual Lots	Block 2	11/6/2023	Pending	Yes
Current Condition:	recommended at this time waste from the lot prior to Block 2 Replat 3, Lots 7-9. Straw wattles should be in	Streets were scraped puthe 3/25/24 inspection. A stalled along the perimenant to complete by 5/13.	the 11/6/23. Due to the grad vrior to the 1/11/24 inspection As of 4/10/24, Block 4 Replant ter of the lots.	n. Hubbell Homes re at 2, Lots 23-25 have	emoved the concrete been updated to
Block 2 Replat 3, Lots 10 & 11	Individual Lots	Block 2	7/31/2023	Pending	Yes
	no BMPs will be recomme relocated the portable toile have been updated to Blod inspection. Hubbell Homes	nded at this time. Street ets to these lots prior to to ck 2 Replat 3, Lots 10 & s removed the portable to stalled along the perimenad to complete by 5/13.	the lots prior to the inspections were scraped prior to the he 2/26/24 inspection. As on 11. Hubbell Homes secured oilets prior to the 7/1/24 inster of the lots. 1/24. Not done as of last inspections.	1/11/24 inspection. F f 4/10/24, Block 4 Re d the portable toilets pection.	Hubbell Homes eplat 2, Lots 20-22 prior to the 4/15/24
Block 2 Replat 3, Lots 12-14	Individual Lots	Block 2		Removed	
Current Condition:	Removed - Hubbell Home	s sodded the lots prior to	the 6/10/24 inspection.	1	•
Block 3 Replat 3, Lots 1-6	Individual Lots	Block 3		Removed	
Current Condition:	Removed - Hubbell Home		the 6/10/24 inspection.	rtemoved	
D. 15D. 140.14.70		<u> </u>	<u>'</u>	T 5 .	1
Block 5 Replat 2, Lots 7-9	Individual Lots	Block 5	the inspection on 12/11/23	Removed	
Current Condition:		s souded the lots phor to	the inspection on 12/11/23). 	
Block 5 Replat 2, Lots 10-13	Individual Lots	Block 5		Removed	
Current Condition:			eaned the streets prior to th		23.
Block 6, Lot 23	Individual Lots	Block 6		Removed	
Current Condition:	Removed - Hubbell Home	s sodded the lot prior to	the 6/5/23 inspection.		
Block 6, Lot 26	Individual Lots	Block 6		Removed	
Current Condition:	Removed - Hubbell Home	s sodded the lot prior to	the 5/24/23 inspection.	•	
Block 6, Lot 27	Individual Lots	Block 6		Removed	
Current Condition:	Removed - TJL Consulting	Inc. sodded the lot price	r to the inspection on 9/11/2	23.	
Block 6, Lot 6	Individual Lots	Block 6	7/8/2024	Active	No
Current Condition:	Good Condition - DR Horte	on secured a portable to	ilet on the lot prior to the 7/8	3/24 inspection.	
Block 7, Lot 1	Individual Lots	Block 7	7/1/2024	Active	No
Current Condition:	Good Condition - DR Hortwattles along the perimete removed prior to the 8/26/2 Horton removed the concruthe lot prior to the 10/7/24	on began foundation wo or of the lot prior to the in 24 inspection; due the fl ete washout pit and the inspection.	rk on the lot prior to the 7/1/ spection on 7/29/24. Straw at grade of the lot, E&A insp concrete waste and installe	24 inspection. DR H wattles were damag sector will monitor for d straw wattles along	orton installed straw ed and partially r reinstallation. DR g the eastern portion o
Block 7, Lot 4	Individual Lots	Block 7	7/1/2024	Active	No
Current Condition:	wattles along the west and	south sides of the lot p	rk on the lot prior to the 7/1/ rior to the 7/15/24 inspection ue the flat grade of the lot, I	n. Straw wattles were	e damaged and
Block 7, Lot 5	Individual Lots	Block 7	7/1/2024	Active	No
Current Condition:	along the south and east s	sides of the lot prior to th	ot prior to the 7/1/24 inspect e 7/15/24 inspection. DR Ho reinstallation or sod installat	orton removed the st	
Block 7, Lot 7	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton so	odded the lot prior to th	e 10/14/24 inspection.		
Block 7, Lot 8	Individual Lots	Block 7	6/10/2024	Active	No

Current Condition:	Active - DR Horton began foundation work on the lot prior to the 6/10/24 inspection.
Block 7, Lot 9	Individual Lots Block 7 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 10/7/24 inspection.
Block 7, Lot 10 Current Condition:	Individual Lots Block 7 Removed Removed Removed - DR Horton sodded the lot prior to the 10/7/24 inspection.
Block 7, Lot 11	Individual Lots Block 7 Removed Removed - DR Horton sodded the lot prior to the 10/7/24 inspection.
Current Condition:	
Block 7, Lot 12	Individual Lots Block 7 Removed Removed - DR Horton sodded the lot prior to the 9/23/24 inspection.
Current Condition:	Removed - DR Horton sodded the lot prior to the 9/25/24 inspection.
Block 7, Lot 13	Individual Lots Block 7 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 9/23/24 inspection.
Block 7, Lot 14	Individual Lots Block 7 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the inspection on 7/29/24.
Block 7, Lot 15	Individual Lots Block 7 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 7/15/24 inspection.
Block 7, Lot 16	Individual Lots Block 7 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 5/13/24 inspection.
Block 7, Lot 17	Individual Lots Block 7 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 5/13/24 inspection.
Block 7, Lot 18	Individual Lots Block 7 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 8/5/24 inspection.
Block 7, Lot 19	Individual Lots Block 7 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 8/5/24 inspection.
Block 7, Lot 20	Individual Lots Block 7 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 8/5/24 inspection.
Block 7, Lot 21	Individual Lots Block 7 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 8/5/24 inspection.
Block 7, Lot 22	Individual Lots Block 7 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 8/5/24 inspection.
Block 7, Lot 23	Individual Lots Block 7 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 5/13/24 inspection.
Block 7. Lot 24	Individual Lots Block 7 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 5/13/24 inspection.
Block 7, Lot 25	Individual Lots Block 7 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 5/13/24 inspection.
Block 8, Lot 1	Individual Lots Block 8 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 5/13/24 inspection.
Block 9, Lot 1 Current Condition:	Individual Lots Block 9 Removed Removed Removed - DR Horton sodded the lot prior to the 12/18/23 inspection.
Block 10, Lot 1	Individual Lots Block 10, Lot 1 Removed
Current Condition: Block 10, Lot 2	Removed - DR Horton sodded the lot prior to the 11/20/23 inspection. Individual Lots Block 10, Lot 2 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 5/24/23 inspection.
Block 10, Lot 4 Current Condition:	Individual Lots Block 10, Lot 4 Removed Removed - DR Horton sodded the lot prior to the 5/13/24 inspection.
Block 10, Lot 5	Individual Lots Block 10, Lot 5 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the inspection on 7/06/23.
Block 10, Lot 6 Current Condition:	Individual Lots Block 10, Lot 6 Removed Removed Removed - DR Horton sodded the lot prior to the inspection on 11/6/23.
Block 10, Lot 7	
Current Condition:	Individual Lots Block 10, Lot 7 Removed Removed - DR Horton sodded the lot prior to the 12/18/23 inspection.
Block 10, Lot 8	Individual Lots Block 10, Lot 8 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 5/13/24 inspection.
Block 10, Lot 9	Individual Lots Block 10, Lot 9 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 11/20/23 inspection.

				_	
Block 10, Lot 10	Individual Lots	Block 10, Lot 10		Removed	
Current Condition:	Removed - DR Horton sodo	ded the lot prior to the 10	0/16/23 inspection.		
Block 10, Lot 11	Individual Lots	Block 10, Lot 11		Removed	
Current Condition:	Removed - DR Horton sodo	ded the lot prior to the 8/	14/23 inspection.		
Block 10, Lot 12	Individual Lots	Block 10, Lot 12		Removed	
Current Condition:	Removed - DR Horton sodo	ded the lot prior to the 12	2/18/23 inspection.	1	
Block 11, Lot 1	Individual Lots	Block 11, Lot 1		Removed	
Current Condition:	Removed - DR Horton sodo	ded the lot prior to the 11	/20/23 inspection.		•
Block 11, Lot 2	Individual Lots	Block 11, Lot 2		Removed	
Current Condition:	Removed - DR Horton sodo	ded the lot prior to the in:	spection on 4/19/23.		
Block 12, Lot 1	Individual Lots	Block 12, Lot 1		Removed	
Current Condition:	Removed - DR Horton sodo	led the lot prior to the in	spection on 4/19/23.		•
Block 12, Lot 2	Individual Lots	Block 12, Lot 2		Removed	
Current Condition:	Removed - DR Horton sodo	ded the lot prior to the 5/	24/23 inspection.		
Block 12, Lot 3	Individual Lots	Block 12, Lot 3		Removed	
Current Condition:	Removed - DR Horton sodo	ded the lot prior to the 5/2	24/23 inspection.		
STR	Street cleaning	Off-Site	In Place to the 2/19/24 inspection. [Active	Yes
	2.) Streets along all active I	The state of the s			
	1.) Hubbell Homes were inf on 2/13/24, 3/12/24, 4/9/24, 2.) DR Horton was informed	5/8/24, 5/29/24, 7/23/24 to complete by 5/2/24.	4, 8/26/24, 10/1/24		
	on 2/13/24, 3/12/24, 4/9/24, 2.) DR Horton was informed 6/25/24, 7/2/24, 7/23/24, 8/5	5/8/24, 5/29/24, 7/23/24 I to complete by 5/2/24. 5/24, 8/21/24, 10/1/24	4, 8/26/24, 10/1/24 Not done as of last inspection	on. DR Horton was	reminded on 6/4/24,
SWPPP Sign Current Condition:	on 2/13/24, 3/12/24, 4/9/24, 2.) DR Horton was informed 6/25/24, 7/2/24, 7/23/24, 8/8	5/8/24, 5/29/24, 7/23/24 d to complete by 5/2/24. 5/24, 8/21/24, 10/1/24 Gallery East Drive	1, 8/26/24, 10/1/24 Not done as of last inspection 10/9/2018	on. DR Horton was	reminded on 6/4/24,
-	on 2/13/24, 3/12/24, 4/9/24, 2.) DR Horton was informed 6/25/24, 7/2/24, 7/23/24, 8/8 Signs Good Condition - Inspector installed at the County Rd L inspection on 9/19/19. The	5/8/24, 5/29/24, 7/23/24 to complete by 5/2/24. 5/24, 8/21/24, 10/1/24 Gallery East Drive installed 1 of 2 SWPPP J Blvd entrance at a late E&A inspector reinstalle	1, 8/26/24, 10/1/24 Not done as of last inspection 10/9/2018 signs during inspection on redate. The E&A inspector red the SWPPP sign during the n 3/31/20. The SWPPP sign	Active 10/9/18. Other SWI einstalled the SWP ne 2/24/20 inspection n was removed dur	No PPP sign will be PP sign during on. The E&A inspector ring the Highway 30
Current Condition: WS X	on 2/13/24, 3/12/24, 4/9/24, 2.) DR Horton was informed 6/25/24, 7/2/24, 7/23/24, 8/3 Signs Good Condition - Inspector installed at the County Rd L inspection on 9/19/19. The reinstalled the SWPPP sign Intersection Improvements inspection on 8/31/20. Waste Storage	5/8/24, 5/29/24, 7/23/24 to complete by 5/2/24. 5/24, 8/21/24, 10/1/24 Gallery East Drive installed 1 of 2 SWPPP J Blvd entrance at a late E&A inspector reinstalle in prior to the inspection of prior to the inspection of	10/9/2018 10/9/2018 signs during inspection on a date. The E&A inspector red the SWPPP sign during the non 3/31/20. The SWPPP sign a/17/20. E&A inspector rei	Active Active Active 10/9/18. Other SWI einstalled the SWP ne 2/24/20 inspection n was removed dur nstalled the SWPP Active	No PPP sign will be PP sign during on. The E&A inspector ring the Highway 30 P sign during the No
Current Condition:	on 2/13/24, 3/12/24, 4/9/24, 2.) DR Horton was informed 6/25/24, 7/2/24, 7/23/24, 8/8 Signs Good Condition - Inspector installed at the County Rd L inspection on 9/19/19. The reinstalled the SWPPP sign Intersection Improvements inspection on 8/31/20. Waste Storage Good Condition - Hubbell Hubbell Homes emptied the waste storage containers presented for the storage containers	5/8/24, 5/29/24, 7/23/24 to complete by 5/2/24. 5/24, 8/21/24, 10/1/24 Gallery East Drive installed 1 of 2 SWPPP J Blvd entrance at a late E&A inspector reinstalle a prior to the inspection or On Site On Site To waste storage container ior to the 12/11/23 inspection to the 12/11/23 inspection to the waste semptied the waste semptied the waste semptied the waste semptied the waste storage container.	10/9/2018 signs during inspection on a date. The E&A inspector red the SWPPP sign during the sign 3/31/20. The SWPPP sign 8/17/20. E&A inspector red the supplemental signs and signs and signs are storage containers on the supplemental signs are prior to the 11/20/23 inspection. DR Horton installed waste storage containers prior signs are storage	Active 10/9/18. Other SWI einstalled the SWP ne 2/24/20 inspection n was removed dur nstalled the SWPP Active their lots prior to the dection. Hubbell Howaste storage contato the 1/29/24 inspection.	No PPP sign will be PP sign during on. The E&A inspector ring the Highway 30 P sign during the No ne 11/6/23 inspection. mes emptied the ainers prior to the ection. DR Horton
Current Condition: WS X	on 2/13/24, 3/12/24, 4/9/24, 2.) DR Horton was informed 6/25/24, 7/2/24, 7/23/24, 8/8 Signs Good Condition - Inspector installed at the County Rd L inspection on 9/19/19. The reinstalled the SWPPP sign Intersection Improvements inspection on 8/31/20. Waste Storage Good Condition - Hubbell Hubbell Homes emptied the waste storage containers proceed that the storage containers proceed that the storage containers proceed the waste storage of the waste storage prior to the 4/29/24.	5/8/24, 5/29/24, 7/23/24 It to complete by 5/2/24. It to complete by 5	10/9/2018 signs during inspection on a date. The E&A inspector red the SWPPP sign during the signs 3/31/20. The SWPPP sign 8/17/20. E&A inspector red the SWPPP sign during the signs and signs and signs are storage containers on the sprior to the 11/20/23 inspection. DR Horton installed waste storage containers prior signs are storage containers are storage containers prior signs are storage containers are storage containers are storage containers prior signs are storage containers are storage container	Active 10/9/18. Other SWI einstalled the SWP the 2/24/20 inspection was removed dur installed the SWPP Active Active their lots prior to the their lots prior to the their lots prior to the to the 1/29/24 inspection. Hubbell Ho waste storage conta to the 1/29/24 inspense and the waste	No PPP sign will be PP sign during on. The E&A inspector ring the Highway 30 P sign during the No ne 11/6/23 inspection. mes emptied the ainers prior to the ection. DR Horton e storage containers ection or supervision in usated the information s directly responsible true, accurate, and