E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Inspector: Josh Ellington	E&A - P2018.109.002			Stage	
Project Name:	Gallery 23 East CSW-201702253 (Mass Grading)				1
		11/2/	2024		
Project Location:	County Road U and Lincoln Highway- Fremont, NE (Dodge County)				68025
	Gallery 23 East		1	1	
Grading:	98%				
Sanitary Sewer:	99%				
Storm Sewer:	99%				
Paving:	99%				
Seeding:	35%				
Utilities:	99%				
Overall Development:	60%				
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions	Time	
					Wee
Sunday:	0.00"				
Monday:	0.00"	10/28/2024	Mostly cloudy 76	5:25 PM	
Tuesday:	0.00"				
Wednesday:	0.69" [02:55 - 14:15]				
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.00"				
Complaints:	None				

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/2018). Grading has temporarily ceased (1/10/2019). Grading in the NE corner of site for sanitary installation (4/5/2019). Grading for roads (6/4/2019). Grading for utilities, storm, and roads throughout project (6/17/2019). Excavation along southwest portion ROW for gas installation (6/18/2019). Excavation in the southeast portion of the site for utilities (6/18/2019). Excavation throughout the site for gas installation (6/24/2019). Excavation for storm sewer (7/16/2019) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/2019). Fine grading throughout the site in preparation for paving (9/09/2019). Excavation in the northeast corner of the site for culvert installation (9/19/2019). Trenching/excavation in the southeast portion of the site for utility installation (10/22/2019). Trenching throughout site for utility installation (11/18/2019). Minor trenching/excavation west of HWY 275 for communications/data installation (1/27/2020).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/2018). Grading has temporarily ceased (1/10/2019). Grading occurred in between HWY 30 and Menards to still water main between last inspection (2/7/2019) and current inspection (2/20/2019), but grading had ceased at time of inspection. Grading along HWY 275 (4/5/2019). Grading for water main project has ceased (4/19/2019)

Highway 30 intersection improvements have begun for culvert installation (10/02/2019).

Grading for Highway 30 intersection improvements has begun (7/27/2020). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/2020). Stockpiling on Block 1 Lot 9 (4/20/2021). Disturbance along Eastgate Road entrance (8/26/2021). Landscaping along Eastgate Road entrance (10/11/2021).

Grading for lot construction active (6/2020).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/2018). Grading has temporarily ceased (1/10/2019). Grading in the NE corner of site for sanitary installation (4/5/2019). Grading for roads (6/4/2019). Grading for utilities, storm, and roads throughout project (6/17/2019). Excavation along southwest portion ROW for gas installation (6/18/2019). Excavation in the southeast portion of the site for utilities (6/18/2019). Excavation throughout the site for gas installation (6/24/2019). Excavation for storm sewer (7/16/2019) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/2019). Fine grading throughout the site in preparation for paving (9/09/2019). Excavation in the northeast corner of the site for culvert installation (9/19/2019). Trenching/excavation in the southeast portion of the site for utility installation (10/22/2019). Trenching throughout site for utility installation (11/18/2019). Minor trenching/excavation west of HWY 275 for communications/data installation (1/27/2020).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/2018). Grading has temporarily ceased (1/10/2019). Grading occurred in between HWY 30 and Menards to still water main between last inspection (2/7/2019) and current inspection (2/20/2019), but grading had ceased at time of inspection. Grading along HWY 275 (4/5/2019). Grading for water main project has ceased (4/19/2019)

Highway 30 intersection improvements have begun for culvert installation (10/02/2019).

Grading for Highway 30 intersection improvements has begun (7/27/2020). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/2020). Stockpiling on Block 1 Lot 9 (4/20/2021). Disturbance along Eastgate Road entrance (8/26/2021). Landscaping along Eastgate Road entrance (10/11/2021).

Grading for lot construction active (6/2020).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (8/30/2018). Seeding and matting in ditch for sanitary lift main (9/19/2018). Seeding around banks of E side of lake (11/6/2018). Seeding for Highway 30 Intersection Improvements (10/18/2020). Reseeding along the Highway 30 Improvements (3/15/2021).

Checklist Questions:

1.) Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

2.) Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

3.) Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

/ac

Create Corrective Action?

N/A

4.) Are construction entrances and adjacent streets being maintained adequately?

No

Create Corrective Action?

No - See BMPs section

5.) Is dust associated with the construction activity adequately controlled on the site?

Vaa

Create Corrective Action?

N/A

Comments:

Comments:

The site was active during the last inspection for home construction.

Based on the amount of lot construction active in the development as of the 4/26/23 inspection, Gallery 23 East will be inspected at the Stage 1 frequency. E&A inspector will monitor and adjust inspection frequency as necessary.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) See BMP section for required maintenance.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
	G	Sallery 23 Eas	st			
CE 1	Construction Entrance	County Road Blvd U		Removed		
Current Condition:	Removed - Thompson Construction removed the construction entrance in preparation for paving prior to inspection on 9/9/19.					
CE 2	Construction Entrance	County Road 25/Highway 30		Removed		
Current Condition:	Removed - Pruss was remo	ving the construction er	trance during inspection on	6/18/19 in preparati	on for paving.	
CE 3	Construction Entrance	NE Corner - Hwy 30 & Christine Drive		Removed		
Current Condition:	Removed - The construction inspection on 8/05/20.	n entrance was removed	d as a part of the Highway 3	0 intersection improv	ements prior to t	
CIP 1	Curb Inlet protection	Sammy Road		Removed		
Current Condition:	Removed - DR Horton remo	oved the inlet protection	prior to the inspection on 1/	17/23.		
CIP 2	Curb Inlet protection	Sammy Road		Removed		
Current Condition:	Removed - DR Horton remo	oved the inlet protection	prior to the 11/6/23 inspecti	on.		
CIP 3	Curb Inlet protection	East 18th Avenue		Removed		
Current Condition:	Removed - DR Horton remo	Removed - DR Horton removed the curb inlet filter prior to the 7/15/24 inspection.				
CIP 4	Curb Inlet protection	Kara Way		Removed		
Current Condition:	Removed - DR Horton remo	oved the inlet protection	prior to the 10/16/23 inspec	tion.		
CIP 5	Curb Inlet protection	East 18th Avenue		Removed		
Current Condition:	Removed - DR Horton remo	oved the curb inlet filter	prior to the 7/15/24 inspection	on.		
CIP 6	Curb Inlet protection	Taylor Lane	6/19/2023	Active	No	
Current Condition:	Good Condition - DR Horton 6/19/23. DR Horton repositi			washout pit prior to t	he inspection on	
CIP 7	Curb Inlet protection	Taylor Lane	6/19/2023	Active	No	
Current Condition:	Good Condition - DR Horton protection prior to the 10/30		ection prior to the 10/16/23 i	nspection. DR Horto	n reinstalled the	
CIP 8	Curb Inlet protection	Aaron Way	3/25/2024	Active	No	
Current Condition:	Good Condition - DR Horton protection prior to the 5/13/2 Horton reinstalled the curb i 9/30/24 inspection.	24 inspection. DR Horton	n removed the inlet protection	on prior to the 7/1/24	inspection. DR	
CIP 9	Curb Inlet protection	Aaron Way	8/12/2024	Active	No	
Current Condition:	Good Condition - DR Horton	n installed the inlet prote	ection prior to the 8/12/24 in	enection		

CIP 10	Curb Inlet protection	Aaron Way	8/12/2024	Active	No
Current Condition:	Good Condition - DR Hortor				NO
		·	·		
CP #1	Culvert protection	Central portion of site		Pending	No
Current Condition:	Pending - Culvert protection				
CP #2	Culvert protection	Southeast corner	8/30/2018	Pending	No
Current Condition:	Pending - Culvert protection			1 4 0	
CW	Concrete Washout	Block 9, Lot 1	9/6/2022	Active	No
Current Condition:	Good Condition - DR Hortor concrete washout and instal				
	Horton cleaned out the cond				
	washout and the surroundin	•	•		
	concrete waste outside of the				
	Block 7 Lot 1 prior to the 11				
	prior to the 11/27/23 inspect				
	Horton removed the concret	te waste and installed a	portable washout pit prior to	o the 8/26/24 inspec	ction.
DW #1	Ditch Wattle Checks	Middle Central	8/30/2018	Pending	No
Current Condition:	Pending - Ditch wattle check			Fending	INO
DW #2	Ditch Wattle Checks	Southwest corner	8/30/2018	Pending	No
Current Condition:	Pending - Ditch wattle check			1 chang	140
DW #3	Ditch Wattle Checks	Southeast corner	8/30/2018	Active	No
Current Condition:	Good Condition - Wattles ch				
DD #1	Diversion Ditch	NW Corner of Lake		Removed	
Current Condition:	Removed - The diversion di	tch was removed during	regrading/paving in the are	ea prior to inspection	n on 12/30/19.
DD #2	Diversion Ditch	W side of Lake		Removed	
Current Condition:	Removed - Thompson Cons		version ditch prior to inspec	tion on 9/19/18.	
DD #3	Diversion Ditch	SW corner of lake		Removed	
Current Condition:	Removed - Thompson Cons		version ditch prior to inspec		
DD #4	Diversion Ditch	S Side of lake		Removed	
Current Condition:	Removed - Thompson Cons		version ditch prior to inspec		
DD #5	Diversion Ditch	E side of lake	varaion ditab prior to inche	Removed	
Current Condition: DD #6	Removed - Thompson Cons Diversion Ditch	NE corner of lake	T	Removed	
Current Condition:	Removed - The diversion di		regrading/naving in the are		on 12/30/19
			Tograding/paving in the are		1011 12/30/13.
DD #7	Diversion Ditch	N side of lake	rograding/paving in the are	Removed	a an 10/20/10
Current Condition:	Removed - The diversion di				
EB #2	Erosion Blanket	Northeast corner	8/30/2018	Pending	No
Current Condition:	Pending - Erosion control m		pe installed when grading h	as ended. T	
EB #3	Erosion Blanket	Around Lake (Outlot B)	8/30/2018	Pending	No
Current Condition:	Pending - Erosion control m				NO
Guitent Condition.	r chang Licelen control in	Area Inlet in SE			
IP 1	Inlet Protection	portion of the site		Removed	
Current Condition:	Removed - The area east of	f the area inlet naturally	stabilized prior to the 8/05/2	20 inspection. Inlet F	Protection no longer
	needed at this time.				-
		W Curb inlet on			
IP 2	Curb Inlet protection	Christine Dr		Removed	
Current Condition:	Removed - The Home Com	pany sodded lots 1-8 pr	ior to the inspection on 6/10	0/20. Inlet protection	is no longer required.
	.	E Curb inlet on			
IP 3	Curb Inlet protection	Christine Dr		Removed	I
Current Condition:	Removed - The Home Com	pany sodded lots 1-8 pr	for to the inspection on 6/10	1/20. Inlet protection	is no longer required.
Plack 2 Poplet 2 Let 16	Individual Lots	Dioak 2. Lat 16	I	Domoved	
Block 2 Replat 3, Lot 16 Current Condition:	Removed - Lot was added in	Block 2, Lot 16		Removed	
Block 3 Replat 3, Lot 10	Individual Lots	Block 3, Lot 10		Removed	
Current Condition:	Removed - Lot was added in	·	I	I Romoveu	
Block 3 Replat 2, Lots 1-7	Individual Lots	Block 3		Removed	
Current Condition:	Removed - Hubbell Homes		the 8/14/23 inspection, clea		removed the portable
	toilet prior to the 8/21/23 ins		• •		•
Block 3 Poplet 2 Lete 49 22	Individual Loto	Plook 2	10/20/2024	Donding	Voc
Block 3 Replat 2, Lots 19-22	Individual Lots	Block 3	10/28/2024	Pending	Yes

Current Condition:	Pending - An unidentified	contractor began cons	struction on the lots prior	to the 10/28/24 ins	pection.
	Perimeter controls should	be installed around th	ne lots.		
	E&A inspector will attemp	t to identify the builde	r by 11/4/24.		
Block 4 Replat 2, Lots 1-4	Individual Lots	Block 4		Removed	
Current Condition:	Removed - Hubbell Homes		the 8/14/23 inspection.		
Block 4 Replat 2, Lots 5-7	Individual Lots	Block 4	·	Removed	
Current Condition:	Removed - Hubbell Homes		the 8/14/23 inspection.		
Block 2 Replat 3, Lots 15 & 16	Individual Lots	Block 4	· I	Removed	
Current Condition:	Removed - Lots 13 and 14 v		L 5/24/23 inspection. As of 4		l plat 2_Lots 15 & 16
Ganoni Gonaldon	have been updated to Block Replat 3, Lots 15 & 16.				
Block 2 Replat 3, Lots 7-9	Individual Lots	Block 2	11/6/2023	Pending	Yes
Current Condition:	Pending - Hubbell Homes grecommended at this time. Swaste from the lot prior to the Block 2 Replat 3, Lots 7-9. If Straw wattles should be instantially Hubbell Homes was informed 5/29/24, 7/23/24, 8/26/24, 1	Streets were scraped price 3/25/24 inspection. And the screen Albert Homes regradicalled along the perimeted to complete by 5/13/2	ior to the 1/11/24 inspections of 4/10/24, Block 4 Replated the lots prior to the 10/er of the lots.	n. Hubbell Homes re 2, Lots 23-25 have (28/24 inspection.	emoved the concrete been updated to
Block 2 Replat 3, Lots 10 & 11	Individual Lots	Block 2	7/31/2023	Pending	Yes
	no BMPs will be recommended relocated the portable toilets have been updated to Block inspection. Hubbell Homes lots prior to the 10/28/24 in Straw wattles should be instrumental Hubbell Homes was informed 5/29/24, 7/23/24, 8/26/24, 1	s to these lots prior to the 2 Replat 3, Lots 10 & 1 removed the portable to aspection. Called along the perimeted to complete by 5/13/2	e 2/26/24 inspection. As of 1. Hubbell Homes secured illets prior to the 7/1/24 inspection of the lots.	4/10/24, Block 4 Rethe portable toilets ection. Hubbell Ho	plat 2, Lots 20-22 prior to the 4/15/24 mes regraded the
Block 2 Replat 3, Lots 12-14	Individual Lots	Block 2		Removed	
Current Condition:	Removed - Hubbell Homes		the 6/10/24 inspection.		
Block 3 Replat 3, Lots 1-6	Individual Lots	Block 3	· ·	Removed	
Current Condition:	Removed - Hubbell Homes		the 6/10/24 inspection.	rtemoved	
Display F Domint 2 Late 7 0			· 	Damayad	
Block 5 Replat 2, Lots 7-9 Current Condition:	Individual Lots Removed - Hubbell Homes	Block 5 sodded the lots prior to	Lethe inspection on 12/11/23.	Removed	
Block 5 Replat 2, Lots 10-13	Individual Lots	Block 5		Removed	
Current Condition:	Removed - Hubbell Homes		aned the streets prior to the		23. I
Block 6, Lot 23 Current Condition:	Individual Lots Removed - Hubbell Homes	Block 6	he 6/5/23 inspection	Removed	
	Individual Lots	Block 6	T	Damayad	
Block 6, Lot 26 Current Condition:	Removed - Hubbell Homes		he 5/24/23 inspection	Removed	
Block 6, Lot 27	Individual Lots	Block 6		Removed	
Current Condition:	Removed - TJL Consulting		to the inspection on 9/11/23		
Block 6, Lot 6	Individual Lots	Block 6	7/8/2024	Active	No
Current Condition:	Good Condition - DR Hortor				110
Block 7, Lot 1	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodd		I 0/21/24 inspection.	Nemoved	<u> </u>
Block 7, Lot 4	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodd	ed the lot prior to the 10	0/21/24 inspection.		
Block 7, Lot 5	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodd		0/21/24 inspection.		

Current Condition:	Removed - DR Horton sodo	ded the lot prior to the 10	0/14/24 inspection.		
Block 7, Lot 8	Individual Lots	Block 7	6/10/2024	Active	No
Current Condition:	Good Condition - DR Horton				orton partially
	installed straw wattles along		r to the 10/21/24 inspection		
Block 7, Lot 9	Individual Lots	Block 7	77/04 :	Removed	
Current Condition:	Removed - DR Horton sodo	•	orriza inspection.		
Block 7, Lot 10	Individual Lots	Block 7	77/04 :	Removed	
Current Condition:	Removed - DR Horton sodo	·	J///24 Inspection.		
Block 7, Lot 11	Individual Lots	Block 7	2/7/04 :	Removed	
Current Condition:	Removed - DR Horton sodo	<u> </u>	0///24 inspection.		
Block 7, Lot 12	Individual Lots	Block 7	(00/04 in a neation	Removed	
Current Condition:	Removed - DR Horton sodo	ied the lot phor to the 9/	23/24 inspection.		
Block 7, Lot 13	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodo	ded the lot prior to the 9/	23/24 inspection.		
Block 7, Lot 14	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodo		spection on 7/29/24.		
Block 7, Lot 15 Current Condition:	Individual Lots Removed - DR Horton sodo	Block 7	15/24 inspection	Removed	
	Individual Lots	Block 7	To/24 inspection.	Domeyod	
Block 7, Lot 16 Current Condition:	Removed - DR Horton sodo		13/24 inspection	Removed	
Block 7, Lot 17	Individual Lots	Block 7	To/2 i mopodiom	Removed	
Current Condition:	Removed - DR Horton sodo		13/24 inspection.	rtemoved	
Block 7, Lot 18	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodo		5/24 inspection.	rtomovou	
Block 7, Lot 19	Individual Lots	Block 7	· 	Removed	
Current Condition:	Removed - DR Horton sodo		1 5/24 inspection.	rtemoved	
Block 7, Lot 20	Individual Lots	Block 7	<u> </u>	Removed	
Current Condition:	Removed - DR Horton sodo		L 5/24 inspection	Removed	
	Individual Lots	Block 7	T	Damassad	
Block 7, Lot 21 Current Condition:	Removed - DR Horton sodo		 5/24 inspection	Removed	
			T	Damas d	
Block 7, Lot 22 Current Condition:	Individual Lots Removed - DR Horton sodo	Block 7	 5/24 inspection	Removed	
		Block 7	Т		
Block 7, Lot 23 Current Condition:	Individual Lots Removed - DR Horton sodo		13/24 inspection	Removed	
Block 7, Lot 24	Individual Lots	Block 7	Толга пореодон.	Removed	
Current Condition:	Removed - DR Horton sodo		13/24 inspection	Removed	
Block 7, Lot 25	Individual Lots	Block 7	To/2 i mopodadii.	Removed	
Current Condition:	Removed - DR Horton sodo		13/24 inspection	Removed	
Block 8, Lot 1	Individual Lots	Block 8	T	Removed	
Current Condition:	Removed - DR Horton sodo		13/24 inspection.	Removed	
Block 9, Lot 1	Individual Lots	Block 9	<u>'</u>	Removed	
Current Condition:	Removed - DR Horton sodo		1 2/18/23 inspection.	Removed	
Block 10, Lot 1	Individual Lots	Block 10, Lot 1	· T	Removed	
Current Condition:	Removed - DR Horton sodo		1/20/23 inspection.	Removed	
Block 10, Lot 2	Individual Lots	Block 10, Lot 2		Removed	
Current Condition:	Removed - DR Horton sodo	led the lot prior to the 5/	24/23 inspection.		
Block 10, Lot 4	Individual Lots	Block 10, Lot 4		Removed	
Current Condition:	Removed - DR Horton sodo	led the lot prior to the 5/	13/24 inspection.	'	
Block 10, Lot 5	Individual Lots	Block 10, Lot 5		Removed	
Current Condition:	Removed - DR Horton sodo		spection on 7/06/23.		
Block 10, Lot 6	Individual Lots	Block 10, Lot 6		Removed	
Current Condition:	Removed - DR Horton sodo		spection on 11/6/23.		
Block 10, Lot 7	Individual Lots	Block 10, Lot 7		Removed	
Current Condition:	Removed - DR Horton sodo	ted the lot prior to the 12	2/18/23 inspection.		
Block 10, Lot 8	Individual Lots	Block 10, Lot 8		Removed	

Current Condition:	Removed - DR Horton sodded the lot prior to the 5/13/24 inspection.
Block 10, Lot 9	Individual Lots Block 10, Lot 9 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 11/20/23 inspection.
Block 10, Lot 10	Individual Lots Block 10, Lot 10 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 10/16/23 inspection.
Block 10, Lot 11	Individual Lots Block 10, Lot 11 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 8/14/23 inspection.
Block 10, Lot 12	Individual Lots Block 10, Lot 12 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 12/18/23 inspection.
Block 11, Lot 1	Individual Lots Block 11, Lot 1 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 11/20/23 inspection.
Block 11, Lot 2	Individual Lots Block 11, Lot 2 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the inspection on 4/19/23.
Block 12, Lot 1	Individual Lots Block 12, Lot 1 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the inspection on 4/19/23.
Block 12, Lot 2	Individual Lots Block 12, Lot 2 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 5/24/23 inspection.
Block 12, Lot 3	Individual Lots Block 12, Lot 3 Removed
Current Condition:	Removed - DR Horton sodded the lot prior to the 5/24/23 inspection.
STR Current Condition:	Street cleaning Off-Site In Place Active Yes Fair Condition - DR Horton cleaned the streets prior to the 2/19/24 inspection. DR Horton partially cleaned the streets
	on 2/13/24, 3/12/24, 4/9/24, 5/8/24, 5/29/24, 7/23/24, 8/26/24, 10/1/24, 10/30/24 2.) DR Horton was informed to complete by 5/2/24. Not done as of last inspection. DR Horton was reminded on 6/4/24 6/25/24, 7/2/24, 7/23/24, 8/5/24, 8/21/24, 10/1/24
SWPPP Sign	Signs Gallery East Drive 10/9/2018 Active No
Current Condition:	Good Condition - Inspector installed 1 of 2 SWPPP signs during inspection on 10/9/18. Other SWPPP sign will be installed at the County Rd U Blvd entrance at a later date. The E&A inspector reinstalled the SWPPP sign during inspection on 9/19/19. The E&A inspector reinstalled the SWPPP sign during the 2/24/20 inspection. The E&A inspect reinstalled the SWPPP sign prior to the inspection on 3/31/20. The SWPPP sign was removed during the Highway 30 Intersection Improvements prior to the inspection on 8/17/20. E&A inspector reinstalled the SWPPP sign during the inspection on 8/31/20.
WSX	Waste Storage On Site 11/6/2023 Active No
Current Condition:	Good Condition - Hubbell Homes installed several waste storage containers on their lots prior to the 11/6/23 inspection Hubbell Homes emptied the waste storage containers prior to the 11/20/23 inspection. Hubbell Homes emptied the waste storage containers prior to the 12/11/23 inspection. DR Horton installed waste storage containers prior to the 1/11/24 inspection. Hubbell Homes emptied the waste storage containers prior to the 1/29/24 inspection. DR Horton emptied the waste storage containers prior to the 2/12/24 inspection. DR Horton emptied the waste storage containers prior to the 4/29/24.
Certification Statement:	I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsibl for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fine and imprisonment for knowing violations.
ector Signature:	Reviewed By: