E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Environmental Services Dept. Manager E&A- P2022.210.004 Stage Inspector: Ethan Anderson **Hidden Acres** 1 CSW-202308260 **Project Name:** 8/31/2024 For Week Ending: Project Location: NW 49th Street & W Madison Avenue in Lincoln, NE 68506 20% Grading: Sanitary Sewer: 0% Storm Sewer: 5% 0% Paving: 25% Seeding: **Utilities:** 0% **Overall Development:** 2% Amount in tenths RAIN FALL AMOUNTS Date inspected Weather Conditions Time Storm Event Duration Week 1 Sunday 0.00" Monday 0.00" Tuesday 0.00" 8/28/2024 Wednesday 0.00" Sunny 97/70 10:50 AM Thursday 0.46" 0.00" Friday 0.00" Saturday None Complaints: **Construction Sequencing:** Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days? Rough grading began (8/21/24). Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? Rough grading began (8/21/24). What temporary or permanent stabilization measures listed in this section are being implemented?

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Existing vegetation (8/21/24). Erosion control matting installed around outfall and inlet to the west (8/21/24).

Create Corrective Action?

No. See BMP Section.

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action?

N/A

Are construction entrances and adjacent streets being maintained adequately?

NIa

Create Corrective Action?

No, See BMP Section.

Is dust associated with the construction activity adequately controlled on the site?

Vac

Create Corrective Action?

N/A

Comments:

Comments:

1.) Site was active during the most recent inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) Some maintenance is required in the BMP section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance			
CE 01	Construction Entrance	W. Madison Ave	8/28/2024	Pending	Yes			
Current Condition:	Pending -							
	Construction automos should be installed							
	Construction entrance should be installed.							
	Gana Trucking was informed to complete by 8/28/24. Not done as of last inspection.							
EM 01	Erosion Control Matting	SW corner of site	9/25/2024	Pending	No			
Current Condition:	Pending - Erosion control matting will be installed as necessary.							
EM 02	Erosion Control Matting	SE corner of site	9/25/2024	Pending	No			
Current Condition:	Pending - Erosion control matting will be installed as necessary.							
EM 03	Erosion Control Matting	Along silt fence 3	9/25/2024	Pending	No			
Current Condition:	Pending - Erosion control matting will be installed as necessary.							
EM 04	Erosion Control Matting	NE corner of site	9/25/2024	Pending	No			
Current Condition:	Pending - Erosion control matting will be installed as necessary.							
EM 05	Erosion Control Matting	Central section of site	9/25/2024	Pending	No			
Current Condition:	Pending - Erosion control matting will be installed as necessary.							
EM 06	Erosion Control Matting	Along eastern crossover	9/25/2024	Pending	No			
Current Condition:	Pending - Erosion control matting will be installed as necessary.							
EM 07	Erosion Control Matting	Around western slopes	8/21/24.	Active	No			
Current Condition:	Good Condition - Gana Trucking installed matting prior to the inspection on 8/21/24.							
EM 08	Erosion Control Matting	East of silt fence 6	9/25/2024	Pending	No			
Current Condition:	Pending - Erosion control matting will be installed as necessary.							
EM 09	Erosion Control Matting	Along southern slope	9/25/2024	Pending	No			
Current Condition:	Pending - Erosion control matting will be installed as necessary.							
MS 01	Material Storage	On Site	8/21/2024	Active	No			
Current Condition:	Good Condition - Gana Trucking began storing materials onsite prior to the inspection on 8/21/24.							
PT 01	Portable Toilet	On Site	8/21/2024	Active	No			
Current Condition:	Good Condition - Gana Trucking installed and secured a portable toilet onsite prior to the inspection on 8/21/24.							
SF 01	Silt Fence	Along construction entrance	8/28/2024	Active	No			
Current Condition:	Good Condition - Gana Trucking installed the silt fence prior to the inspection on 8/28/24.							
SF 02	Silt fence	Along construction entrance	8/28/2024	Active	No			
Current Condition:	Good Condition - Gana Trucki	ng installed the silt fence pri	or to the inspection on 8	/28/24.				
SF 03	Silt fence	Along eastern perimeter	9/25/2024	Pending	No			
Current Condition:	Pending - Silt fence will be installed when work begins in the area.							
SF 04	Silt fence	Along eastern perimeter	9/25/2024	Pending	No			
Current Condition:	Pending - Silt fence will be installed when work begins in the area.							
SF 05	Silt fence	Along northern perimeter	9/25/2024	Pending	No			

Current Condition:	Pending - Silt fence will be ins	talled when work begins in t	ne area.					
SF 06	Silt fence	In low lying area	9/25/2024	Pending	No			
Current Condition:	Pending - Silt fence will be installed when work begins in the area.							
SF 07	Silt fence	Along northern perimeter	8/28/2024	Active	No			
Current Condition:	Good Condition - Gana Trucking installed the silt fence prior to the inspection on 8/28/24.							
SF 08	Silt fence	Along northern perimeter	8/28/2024	Active	No			
Current Condition:	Good Condition - Gana Trucking installed the silt fence prior to the inspection on 8/28/24.							
SF 09	Silt fence	Along western perimeter	8/28/2024	Active	No			
Current Condition:	Good Condition - Gana Truck	ing installed the silt fence pri	or to the inspection or	8/28/24.				
SF 10	Silt fence	Along crossover	8/28/2024	Active	No			
Current Condition:	Good Condition - Gana Truck	ing installed the silt fence pri	or to the inspection or	8/28/24.				
STR	Streets	On Site	8/21/2024	Active	No			
Current Condition:	Good Condition - Streets were in good condition during latest inspection.							
SW 01	Straw Wattle	SE corner of site	9/25/2024	Pending	No			
Current Condition:	Pending - Wattles will be installed as necessary.							
SW 02	Straw Wattle	NE corner of site	9/25/2024	Pending	No			
Current Condition:	Pending - Wattles will be installed as necessary.							
SW 03	Straw Wattle	NE corner of site	9/25/2024	Pending	No			
Current Condition:	Pending - Wattles will be installed as necessary.							
SW 04	Straw Wattle	NE corner of site	9/25/2024	Pending	No			
Current Condition:	Pending - Wattles will be installed as necessary.							
SW 05	Straw Wattle	Along construction entrance	8/28/2024	Active	No			
Current Condition:	Good Condition - Gana Truck	ing installed wattles along th	e construction entranc	e prior to the inspect	tion on 8/28/24.			
SWPPP Sign	SWPPP Sign	Site entrance	8/21/2024	Pending	Yes			
Current Condition:	Pending -							
	SWPPP sign should be installed.							
	E&A will install SWPPP sign when the order arrives.							
WO 01	Concrete Washout	Onsite	9/25/2024	Pending	No			
Current Condition:	Pending - A washout will be ins	talled as necessary.		• •				
WS 01	Waste Storage Area	On Site	9/25/2024	Active	No			
Current Condition:	Pending - Waste storage will be	installed as necessary.		'				
Certification Statement	"I certify, under penalty of law, t with a system designed to assu inquiry of the person or persons information submitted is, to the penalties for submitting false inf	re that qualified personnel prop who manage the system or the best of my knowledge and beli	erly gathered and evalu ose persons directly res ef, true, accurate, and co	ated the information so ponsible for gathering omplete. I am aware the	the information, the nat there are significant			
spector Signature:	En Carlon			Reviewed By:	Post Sur			