E & A Consulting A3724:F3797c. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

		E&A- P2022.21	0.004				
Inspector: Ethan Anderson					Stage		
Project Name:		1					
For Week Ending:		8/24/2024					
Project Location:	NW 4	68506					
Grading:	20%						
Sanitary Sewer:	0%						
Storm Sewer:	5%						
Paving:	0%						
Seeding:	25%						
Utilities:	0%						
Overall Development:	2%	6					
				•			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Duration		
Sunday	0.18"				Week		
Sunday Monday	0.18			-			
Tuesday	0.09"						
Wednesday	0.00"	8/21/2024	Foggy 87/69	1:40 PM			
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"						
·····,							
Complaints:	None						
Complaints:	-						
	•						
Construction Sequencing:							
Which portion(s) (i.e. drainage bas	ins) of the site have had a temporary or	permanent cessation of gradi	ng, earthwork, or ground disturbar	nce in the last 14 days?			
Rough grading began (8/21	/24).						
	ins) of the site do not have grading, ear	thwork, or ground disturbance	scheduled in the next 14 days?				
Rough grading began (8/21	/24).						
What tomporany or permanent stab	bilization measures listed in this section	are being implemented?					
	4). Erosion control matting inst		inlot to the west (8/21/24)				
Existing vegetation (0/21/24	+). Erosion control matting inst	alleu arounu outiali anu	iniet to the west (0/21/24).				
Checklist Questions:							
checklist questions.							
Are receiving waters adjace	ent to the project free of any sig	inificant signs of erosio	n or sediment that would b	e associated with th	e construction activity?		
No		,			,		
Create Corrective Action?							
No, See BMP Section.							
Have disturbed areas been	seeded or otherwise stabilized	as required? List inacti	ve portions of the project a	nd if stabilization m	easure are adequate or		
needed to prevent erosion.							
Yes							
Create Corrective Action?							
N/A							
Are waste materials (concr	ete, construction material, haza	ardous, etc.) being mana	ged properly?				
Yes							
Create Corrective Action?							
N/A							
Ann ann ann an 1	and address what is a state	intelined and the first of					
	and adjacent streets being ma	intained adequately?					
No							
Create Corrective Action?							

No, See BMP Section.

Is dust associated with the construction activity adequately controlled on the site? Yes Create Corrective Action?

N/A

Comments:

Comments: 1.) Site was inactive during the most recent inspection. Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance			
CE 01	Construction Entrance	W. Madison Ave	8/28/2024	Pending	Yes			
Current Condition:	Pending -	W. Induison Are	0/20/2024	renaing	105			
	Construction entrance should be installed.							
EM 01	Gana Trucking was informed		0/05/0004	Densilian	N -			
	Erosion Control Matting	SW corner of site	9/25/2024	Pending	No			
Current Condition: EM 02	Pending - Erosion control ma			Densilian	N -			
Current Condition:	Erosion Control Matting SE corner of site 9/25/2024 Pending No							
EM 03	Pending - Erosion control matting will be installed as necessary.							
Current Condition:	Erosion Control Matting Along silt fence 3 9/25/2024 Pending No							
EM 04	Pending - Erosion control matting will be installed as necessary.							
Current Condition:	Erosion Control Matting Pending - Erosion control ma	NE corner of site	9/25/2024	Pending	No			
EM 05			9/25/2024	Donding	No			
Current Condition:	Erosion Control Matting Pending - Erosion control ma	Central section of site		Pending				
EM 06	Erosion Control Matting	Along eastern crossover	9/25/2024	Pending	No			
Current Condition:	Pending - Erosion control ma			rending				
EM 07	Erosion Control Matting	Around western slopes	8/21/24.	Active	No			
Current Condition:	Good Condition - Gana Truck				110			
EM 08	Erosion Control Matting	East of silt fence 6	9/25/2024	Pending	No			
Current Condition:	Pending - Erosion control ma			rending				
EM 09	Erosion Control Matting	Along southern slope	9/25/2024	Pending	No			
Current Condition:	Pending - Erosion control ma			renaing				
MS 01	Material Storage	On Site	8/21/2024	Active	No			
Current Condition:	Good Condition - Gana Truck							
PT 01	Portable Toilet	On Site	8/21/2024	Active	No			
Current Condition:	Good Condition - Gana Truck							
		Along construction	-					
SF 01	Silt Fence	entrance	9/25/2024	Pending	Yes			
Current Condition:	Pending -							
	Silt fence should be installed. Gana Trucking was informed to complete by 8/28/24.							
		Along construction						
SF 02	Silt fence	entrance	9/25/2024	Pending	Yes			
Current Condition:	Pending -							
	Silt fence should be installed.							
SF 03	Gana Trucking was informed Silt fence	Along eastern perimeter	9/25/2024	Pending	Yes			
Current Condition:	Pending -							
	Silt fence should be installed.							
OF A4	Gana Trucking was informed		0/05/0004	Densti	N			
SF 04 Current Condition:	Silt fence	Along eastern perimeter	9/25/2024	Pending	Yes			
Current Condition:	Pending -							
	Silt fence should be installed.							
	Gana Trucking was informed to complete by 8/28/24.							
SF 05	Silt fence	Along northern perimeter	9/25/2024	Pending	Yes			
31 05								

Current Condition:	Pending -						
	Silt fence should be installed.						
	Gana Trucking was informed						
SF 06	Silt fence	In low lying area	9/25/2024	Pending	Yes		
Current Condition:	Pending -						
	High porosity silt fence should be installed.						
	Gana Trucking was informed to complete by 8/28/24.						
SF 07	Silt fence	Along northern perimeter	9/25/2024	Pending	Yes		
Current Condition:	Pending -						
	Silt fence should be installed.						
	Gana Trucking was informed to complete by 8/28/24.						
	Silt fence	Along northern perimeter	9/25/2024	Pending	Yes		
SF 08 Current Condition:		Along northern permitter	5/20/2024	T chung			
Current Condition:	Pending -						
	Silt fence should be installed.						
SF 09	Gana Trucking was informed Silt fence	to complete by 8/28/24. Along western perimeter	9/25/2024	Pending	Yes		
Current Condition:	Pending -	Along western perimeter	512512024	Fending	165		
	Silt fence should be installed or the matting installed in the area.						
	Gana Trucking was informed						
SF 10	Silt fence	Along crossover	9/25/2024	Pending	Yes		
Current Condition:	Pending -						
	Silt fence should be installed.						
STR	Gana Trucking was informed		0/04/0004	A = 41	N -		
Current Condition:	Streets Good Condition - Streets wer	On Site e in good condition during late	8/21/2024	Active	No		
SW 01	Straw Wattle	SE corner of site	9/25/2024	Pending	No		
Current Condition:	Pending - Wattles will be inst						
SW 02	Straw Wattle	NE corner of site	9/25/2024	Pending	No		
Current Condition:	Pending - Wattles will be inst	alled as necessary.					
SW 03	Straw Wattle	NE corner of site	9/25/2024	Pending	No		
Current Condition:	Pending - Wattles will be inst	T					
SW 04	Straw Wattle	NE corner of site	9/25/2024	Pending	No		
Current Condition: SWPPP Sign	Pending - Wattles will be inst		0/04/00004				
Current Condition:	SWPPP Sign Pending -	Site entrance	8/21/2024	Pending	Yes		
Current Condition:	Pending -						
	SWPPP sign should be installed.						
	E&A will install SWPPP sign	when the order arrives.					
WO 01	Concrete Washout	Onsite	9/25/2024	Pending	No		
Current Condition:	Pending - A washout will be i	T					
WS 01 Current Condition:	Waste Storage Area	On Site	9/25/2024	Active	No		
Current Condition: Certification Statement	Pending - Waste storage will be installed as necessary. "I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in						
Certification Statement	accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted.						
	Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the						
	information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing						
	violations."	or submitting talse information in	icidating the possibility (innes and imprisonm	ent for knowing		
anastan Cinn -tomas	En Carlos			Deviewe d D	Parts Sul		
spector Signature:	an any - c	1		Reviewed By:	and and		