E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Yes

N/A

Yes

N/A

Inspector: Ethan Anderson Stage **Hoppe Office Building** 1 CSW-202308060 Project Name: 68506 For Week Ending: 11/23/2024 Project Location: 1620 South 84th Street - Lincoln, NE (Lancaster County) Grading: 70% Sanitary Sewer: 100% Storm Sewer: 0% 45% Paving: Seeding: 0% Utilities: 0% Overall Development: 20% RAIN FALL AMOUNTS Amount in tenths Date inspected Weather Conditions Time Storm Event Duration Week 1 Sunday 0.00" 6:55 - 22:54 Monday 1.72" Tuesday 0.00" Wednesday 0.00" 11/20/2024 Sunny 51/36 2:15 PM Thursday 0.00" Friday 0.00" Saturday 0.00" None Complaints: **Construction Sequencing:** Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days? Grading began (11/29/23). Building Construction began (12/27/23). Sanitary installation (4/24/24). Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? Grading began (11/29/23). Building Construction began (12/27/23). Sanitary installation (4/24/24). What temporary or permanent stabilization measures listed in this section are being implemented? Existing vegetation (11/29/23). **Checklist Questions:** Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Create Corrective Action? No. See BMP Section Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion. **Create Corrective Action?** Are waste materials (concrete, construction material, hazardous, etc.) being managed properly? Create Corrective Action? Are construction entrances and adjacent streets being maintained adequately? **Create Corrective Action?**

E&A- P2022.259.004

No, See BMP Section.

Is dust associated with the construction activity adequately controlled on the site? Yes Create Corrective Action?

N/A

Comments:

Comments:

Site was active for building construction during the last inspection. Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): Some maintenance is required in the BMP section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance			
CE 01	Construction Entrance	Off 84th Street	-	Removed				
Current Condition:	Removed - Hoppe Developmen	t was paving the entrance dur	ing the inspection on 9/11	/24.				
CE 02	Construction Entrance	Stony Hill Road	7/17/2024	Active	No			
Current Condition:	Good Condition - 75% effective	- Area is currently paved, E&A	inspector will monitor for	trackout and/or re	moval of paved entrance			
	Hoppe Development was in the process of installing a construction entrance to the east at Stony Hill Road prior to the inspection on 7/17/24. Hoppe Development installed a rock construction entrance prior to the inspection on 7/31/24.							
EB 01	Erosion Control Matting	Water Quality Swale 1	12/29/2023	Pending	No			
Current Condition:	Pending- Matting will be installe			rending	NO			
EB 02	Erosion Control Matting	Water Quality Swale 3	12/29/2023	Pending	No			
Current Condition:	Pending- Matting will be installe	,		renaing	110			
EB 03	Erosion Control Matting	Water Quality Swale 2	12/29/2023	Pending	No			
Current Condition:	Pending- Matting water Quality Swale 2 12/29/2023 Pending No							
EB 04	Erosion Control Matting	End of Culvert Pipe	12/29/2023	Pending	No			
Current Condition:	Pending- Matting will be installe			ronding				
IP 1	Inlet protection	Culvert Pipe 1	7/24/2024	Active	No			
Current Condition:	Good Condition - Hoppe Develo							
IP 2	Inlet protection	Culvert Pipe 2	7/24/2024	Active	No			
Current Condition:	Good Condition - Hoppe Develo							
MS 01	Material Storage	On Site	5/8/2024	Active	No			
Current Condition:	Good Condition - Hoppe Develo							
PT 01	Portable Toilet	On Site	4/17/2024	Active	No			
Current Condition:	Good Condition - Hoppe Develo							
	Development installed and secu removed the secondary portable							
	portable toilet on site prior to the	e inspection on 10/2/24.						
SF 01 Current Condition:	portable toilet on site prior to the Silt Fence Fair Condition - Hoppe Develop Development installed the silt fe inspection on 6/26/24. Hoppe D	Perimeter ment was in the process of ins ence prior to the inspection on	12/13/23. Hoppe Develop	ment repaired the	silt fence prior to the			
-	portable toilet on site prior to the Silt Fence Fair Condition - Hoppe Develop Development installed the silt fe inspection on 6/26/24. Hoppe D inspection on 7/17/24. Silt fence or wattles should be in seeding and matting.	Perimeter ment was in the process of ins ence prior to the inspection on evelopment removed a section installed along remaining sides	stalling the silt fence prior 12/13/23. Hoppe Develop n of the silt fence to instal of construction entrance	to the inspection o oment repaired the I a construction en or the areas shoul	n 12/6/23. Hoppe silt fence prior to the trance prior to the d be stabilized with			
-	portable toilet on site prior to the Silt Fence Fair Condition - Hoppe Develop Development installed the silt fe inspection on 6/26/24. Hoppe D inspection on 7/17/24. Silt fence or wattles should be in seeding and matting. Hoppe Development was inform 10/3/24. 11/8/24	Perimeter ment was in the process of ins ence prior to the inspection on evelopment removed a section installed along remaining sides ned to complete by 9/4/24. Not	stalling the silt fence prior 12/13/23. Hoppe Develop n of the silt fence to instal of construction entrance done as of last inspection	to the inspection o oment repaired the I a construction en or the areas shoul n. Hoppe Developr	n 12/6/23. Hoppe silt fence prior to the trance prior to the d be stabilized with nent was reminded on			
Current Condition: SF 02	portable toilet on site prior to the Silt Fence Fair Condition - Hoppe Develop Development installed the silt fe inspection on 6/26/24. Hoppe D inspection on 7/17/24. Silt fence or wattles should be in seeding and matting. Hoppe Development was inform 10/3/24. 11/8/24 Silt fence	Perimeter ment was in the process of ins ence prior to the inspection on evelopment removed a section installed along remaining sides	stalling the silt fence prior 12/13/23. Hoppe Develop n of the silt fence to instal of construction entrance	to the inspection o oment repaired the I a construction en or the areas shoul	n 12/6/23. Hoppe silt fence prior to the trance prior to the d be stabilized with			
Current Condition:	portable toilet on site prior to the Silt Fence Fair Condition - Hoppe Develop Development installed the silt fe inspection on 6/26/24. Hoppe D inspection on 7/17/24. Silt fence or wattles should be in seeding and matting. Hoppe Development was inform 10/3/24. 11/8/24	Perimeter ment was in the process of insence prior to the inspection on evelopment removed a section installed along remaining sides ned to complete by 9/4/24. Not Along construction entrance	stalling the silt fence prior 12/13/23. Hoppe Develop n of the silt fence to instal of construction entrance done as of last inspection 7/24/2024	to the inspection o oment repaired the I a construction en or the areas shoul n. Hoppe Developr Pending	n 12/6/23. Hoppe silt fence prior to the trance prior to the d be stabilized with nent was reminded on Yes			
Current Condition: SF 02	portable toilet on site prior to the Silt Fence Fair Condition - Hoppe Develop Development installed the silt fe inspection on 6/26/24. Hoppe D inspection on 7/17/24. Silt fence or wattles should be in seeding and matting. Hoppe Development was inform 10/3/24, 11/8/24 Silt fence Pending - Silt fence or wattles should be in Hoppe Development was inform	Perimeter ment was in the process of insence prior to the inspection on evelopment removed a section installed along remaining sides ned to complete by 9/4/24. Not Along construction entrance	stalling the silt fence prior 12/13/23. Hoppe Develop n of the silt fence to instal of construction entrance done as of last inspection 7/24/2024	to the inspection o oment repaired the I a construction en or the areas shoul n. Hoppe Developr Pending	n 12/6/23. Hoppe silt fence prior to the trance prior to the d be stabilized with nent was reminded on Yes			
Current Condition: SF 02 Current Condition:	portable toilet on site prior to the Silt Fence Fair Condition - Hoppe Develop Development installed the silt fe inspection on 6/26/24. Hoppe D inspection on 7/17/24. Silt fence or wattles should be in seeding and matting. Hoppe Development was inform 10/3/24, 11/8/24 Silt fence or wattles should be in Hoppe Development was inform 10/3/24, 11/8/24 Silt fence or wattles should be in Hoppe Development was inform 8/28/24, 10/3/24, 11/8/24 Streets Fair Condition - Trackout should be cleaned. Hoppe Development was inform	Perimeter ment was in the process of insence prior to the inspection on evelopment removed a section installed along remaining sides ned to complete by 9/4/24. Not Along construction entrance installed along construction entrance	stalling the silt fence prior 12/13/23. Hoppe Develop n of the silt fence to install of construction entrance done as of last inspection 7/24/2024 trance slopes. ot done as of last inspection 11/29/2023	to the inspection o oment repaired the I a construction en or the areas shoul n. Hoppe Developr Pending on. Hoppe Develop	n 12/6/23. Hoppe silt fence prior to the trance prior to the d be stabilized with nent was reminded on Yes			
Current Condition: SF 02 Current Condition: STR	portable toilet on site prior to the Silt Fence Fair Condition - Hoppe Develop Development installed the silt fe inspection on 6/26/24. Hoppe D inspection on 7/17/24. Silt fence or wattles should be in seeding and matting. Hoppe Development was inform 10/3/24. 11/8/24 Silt fence or wattles should be in Hoppe Development was inform 10/3/24. 11/8/24 Silt fence or wattles should be in Hoppe Development was inform 8/28/24. 10/3/24. 11/8/24 Streets Fair Condition - Trackout should be cleaned. Hoppe Development was inform 8/28/24. 10/3/24. 11/8/24	Perimeter ment was in the process of inserve prior to the inspection on evelopment removed a section installed along remaining sides ned to complete by 9/4/24. Not Along construction entrance installed along construction entrance	stalling the silt fence prior 12/13/23. Hoppe Develop n of the silt fence to instal of construction entrance done as of last inspection 7/24/2024 trance slopes. ot done as of last inspection 11/29/2023	to the inspection or oment repaired the I a construction en or the areas should n. Hoppe Developr Pending On. Hoppe Develop Active	n 12/6/23. Hoppe silt fence prior to the trance prior to the d be stabilized with nent was reminded on Yes oment was reminded on Yes			
Current Condition: SF 02 Current Condition: STR Current Condition:	portable toilet on site prior to the Silt Fence Fair Condition - Hoppe Develop Development installed the silt fe inspection on 6/26/24. Hoppe D inspection on 7/17/24. Silt fence or wattles should be in seeding and matting. Hoppe Development was inform 10/3/24, 11/8/24 Silt fence or wattles should be in Hoppe Development was inform 10/3/24, 11/8/24 Silt fence or wattles should be in Hoppe Development was inform 8/28/24, 10/3/24, 11/8/24 Streets Fair Condition - Trackout should be cleaned. Hoppe Development was inform	Perimeter ment was in the process of inserve prior to the inspection on evelopment removed a section installed along remaining sides ned to complete by 9/4/24. Not Along construction entrance installed along construction e	stalling the silt fence prior 12/13/23. Hoppe Develop n of the silt fence to instal of construction entrance done as of last inspection 7/24/2024 trance slopes. bt done as of last inspection 11/29/2023	to the inspection o oment repaired the I a construction en or the areas shoul n. Hoppe Developr Pending on. Hoppe Develop	n 12/6/23. Hoppe silt fence prior to the trance prior to the d be stabilized with nent was reminded on Yes			
Current Condition: SF 02 Current Condition: STR Current Condition:	portable toilet on site prior to the Silt Fence Fair Condition - Hoppe Develop Development installed the silt fe inspection on 6/26/24. Hoppe D inspection on 7/17/24. Silt fence or wattles should be in seeding and matting. Hoppe Development was inform 10/3/24. 11/8/24 Silt fence or wattles should be in Silt fence or wattles should be in Hoppe Development was inform 8/28/24, 10/3/24, 11/8/24 Silt fence or wattles should be in Hoppe Development was inform 8/28/24, 10/3/24, 11/8/24 Fair Condition - Trackout should be cleaned. Hoppe Development was inform 8/28/24, 10/3/24, 11/8/24 Straw Wattle Pending- Straw Wattle will be in	Perimeter ment was in the process of inserve prior to the inspection on evelopment removed a section installed along remaining sides ned to complete by 9/4/24. Not Along construction entrance installed along construction e	stalling the silt fence prior 12/13/23. Hoppe Develop n of the silt fence to instal of construction entrance done as of last inspection 7/24/2024 trance slopes. ot done as of last inspection 11/29/2023	to the inspection or oment repaired the I a construction en or the areas should n. Hoppe Developr Pending Active Active Pending Pending	n 12/6/23. Hoppe silt fence prior to the trance prior to the d be stabilized with nent was reminded on Yes oment was reminded on Yes			
Current Condition: SF 02 Current Condition: STR Current Condition: SW 01 Current Condition: SW 02	portable toilet on site prior to the Silt Fence Fair Condition - Hoppe Develop Development installed the silt fe inspection on 6/26/24. Hoppe D inspection on 7/17/24. Silt fence or wattles should be in seeding and matting. Hoppe Development was inform 10/3/24. 11/8/24 Silt fence Pending - Silt fence or wattles should be in Hoppe Development was inform 8/28/24. 10/3/24. 11/8/24 Trackout should be cleaned. Hoppe Development was inform 8/28/24. 10/3/24. 11/8/24	Perimeter ment was in the process of insence prior to the inspection on evelopment removed a section installed along remaining sides ned to complete by 9/4/24. Not Along construction entrance installed along construction entrance installed along construction entrance and to complete by 7/31/24. Not ADJ and Internal Streets ined to complete by 7/25/24. Not Water Quality Swale 1 istalled once swale is installed Water Quality Swale 1	stalling the silt fence prior 12/13/23. Hoppe Develop n of the silt fence to instal of construction entrance done as of last inspection 7/24/2024 trance slopes. bt done as of last inspection 11/29/2023	to the inspection or oment repaired the I a construction en or the areas should n. Hoppe Developr Pending On. Hoppe Develop Active	n 12/6/23. Hoppe silt fence prior to the trance prior to the d be stabilized with nent was reminded on Yes oment was reminded on Yes			
Current Condition: SF 02 Current Condition: STR Current Condition: SW 01 Current Condition: SW 02 Current Condition:	portable toilet on site prior to the Silt Fence Fair Condition - Hoppe Develop Development installed the silt fe inspection on 6/26/24. Hoppe D inspection on 7/17/24. Silt fence or wattles should be in seeding and matting. Hoppe Development was inform 10/3/24. 11/8/24 Silt fence or wattles should be in Pending - Silt fence or wattles should be in Hoppe Development was inform 8/28/24, 10/3/24, 11/8/24 Streets Fair Condition - Trackout should be cleaned. Hoppe Development was inform 8/28/24, 10/3/24, 11/8/24 Straw Wattle Pending - Straw Wattle Pending -	Perimeter ment was in the process of inserce prior to the inspection on levelopment removed a section installed along remaining sides ned to complete by 9/4/24. Not Along construction entrance installed along construction entrance installed along construction entrance and to complete by 7/31/24. Not ADJ and Internal Streets and to complete by 7/25/24. Not Water Quality Swale 1 Istalled once swale is installed Water Quality Swale 1 Istalled once swale is installed	stalling the silt fence prior 12/13/23. Hoppe Develop n of the silt fence to instal of construction entrance done as of last inspection 7/24/2024 trance slopes. ot done as of last inspection 11/29/2023 ot done as of last inspection 12/29/2023	to the inspection or oment repaired the I a construction en or the areas should n. Hoppe Developr Pending Active Active Pending Pending	n 12/6/23. Hoppe silt fence prior to the trance prior to the d be stabilized with nent was reminded on Yes oment was reminded on Yes oment was reminded on No			
Current Condition: SF 02 Current Condition: STR Current Condition: SW 01 Current Condition: SW 02	portable toilet on site prior to the Silt Fence Fair Condition - Hoppe Develop Development installed the silt fe inspection on 6/26/24. Hoppe D inspection on 7/17/24. Silt fence or wattles should be in seeding and matting. Hoppe Development was inform 10/3/24. 11/8/24 Silt fence or wattles should be in seeding - Silt fence or wattles should be in Hoppe Development was inform 8/28/24, 10/3/24, 11/8/24 Streets Fair Condition - Trackout should be cleaned. Hoppe Development was inform 8/28/24, 10/3/24, 11/8/24 Straw Wattle Pending - Straw Wattle	Perimeter ment was in the process of insence prior to the inspection on evelopment removed a section installed along remaining sides ned to complete by 9/4/24. Not Along construction entrance installed along construction entrance installed along construction entrance and to complete by 7/31/24. Not ADJ and Internal Streets ind to complete by 7/25/24. Not Water Quality Swale 1 istalled once swale is installed Water Quality Swale 1 istalled once swale is installed Water Quality Swale 1 istalled once swale is installed Water Quality Swale 3	stalling the silt fence prior 12/13/23. Hoppe Develop n of the silt fence to instal of construction entrance a done as of last inspection 7/24/2024 trance slopes. Det done as of last inspection 11/29/2023	to the inspection or oment repaired the I a construction en or the areas should n. Hoppe Developr Pending Active Active Pending Pending	n 12/6/23. Hoppe silt fence prior to the trance prior to the d be stabilized with nent was reminded on Yes oment was reminded on Yes			

Current Condition:	Pending- Straw Wattle will be installed once swale is installed.						
SW 05	Straw Wattle	Water Quality Swale 2	12/29/2023	Pending	No		
Current Condition:	Pending- Straw Wattle will be installed once swale is installed.						
SW 06	Straw Wattle	Water Quality Swale 2	12/29/2023	Pending	No		
Current Condition:	Pending- Straw Wattle will be installed once swale is installed.						
SW 07	Straw Wattle	Water Quality Swale 2	12/29/2023	Pending	No		
Current Condition:	Pending- Straw Wattle will be installed once swale is installed.						
SWPPP Sign	SWPPP Signs	ADJ to CE 01	11/29/2023	Active	No		
Current Condition:	Good Condition - E&A inspector installed the SWPPP sign prior to the inspection on 11/29/23.						
WO 01	Concrete Washout	On Site	5/8/2024	Pending	No		
Current Condition:	Pending - Hoppe Development installed a concrete washout on site prior to the inspection on 5/8/24. Hoppe Development remove the concrete washout prior to the inspection on 7/24/24.						
WS 01	Waste Storage Area	On Site	11/29/2023	Active	No		
Current Condition:	Good Condition - Hoppe Development installed a waste storage container prior to the inspection on 11/29/23. Hoppe Developmen installed a new waste storage container on site prior to the inspection on 4/17/24.						
Certification Statement	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."						
nspector Signature:	En Carlos			Reviewed By:	Conto Sul		