E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC **Environmental Services Dept. Manager**

D0000 0F0 004		
	-	-

	<u> </u>						
		E&A- P2022.259	.004				
Inspector: Ethan Anderson		Stage					
		1					
Project Name:	CSW-202308060						
For Week Ending:		11/9/202	4		68506		
Project Location:	1620 So						
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		<u>, , , , , , , , , , , , , , , , , , , </u>	(· · · · · · · · · · · · · · · · · · ·				
Grading:	70%						
Sanitary Sewer:	100%						
Storm Sewer:	0%						
Paving:	45%						
Seeding:	0%						
Utilities:	0%						
Overall Development:	20%						
DAIN 541 L 4440UNTO	I A	I			T		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Duration		
Cundov	0.49"				20:54 to 24:00		
Sunday Monday	0.49				14:54 to 24:00		
Tuesday	0.08"				14.54 to 25.54		
Wednesday	0.00"	11/6/2024	Foggy 56/33	2:10 PM			
Thursday	0.00"	11/0/2024	1 oggy ou/ou	2.1011			
Friday	0.05"						
Saturday	0.48"				00:54 to 7:54		
Complaints:	None						
Complaints:							
Construction Sequencing:							
Which portion(s) (i.e. drainage basis	ns) of the site have had a temporary or		The state of the s	ce in the last 14 days?			
Which portion(s) (i.e. drainage basis	ns) of the site have had a temporary or paiding Construction began (12/27)		The state of the s	ce in the last 14 days?			
Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu	uilding Construction began (12/27)	/23). Sanitary installation (4	1/24/24).	ce in the last 14 days?			
Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu Which portion(s) (i.e. drainage basis	nilding Construction began (12/27,	/23). Sanitary installation (4	1/24/24). cheduled in the next 14 days?	ce in the last 14 days?			
Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu Which portion(s) (i.e. drainage basis	uilding Construction began (12/27)	/23). Sanitary installation (4	1/24/24). cheduled in the next 14 days?	ce in the last 14 days?			
Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu	ns) of the site do not have grading, eartifieding Construction began (12/27)	/23). Sanitary installation (4 hwork, or ground disturbance st /23). Sanitary installation (4	1/24/24). cheduled in the next 14 days?	ce in the last 14 days?			
Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu What temporary or permanent stabi	ns) of the site do not have grading, eartified Construction began (12/27, illiding Construction began (12/27, illization measures listed in this section	/23). Sanitary installation (4 hwork, or ground disturbance st /23). Sanitary installation (4	1/24/24). cheduled in the next 14 days?	ce in the last 14 days?			
Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu	ns) of the site do not have grading, eartified Construction began (12/27, illiding Construction began (12/27, illization measures listed in this section	/23). Sanitary installation (4 hwork, or ground disturbance st /23). Sanitary installation (4	1/24/24). cheduled in the next 14 days?	ce in the last 14 days?			
Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu What temporary or permanent stabi	ns) of the site do not have grading, eartified Construction began (12/27, illiding Construction began (12/27, illization measures listed in this section	/23). Sanitary installation (4 hwork, or ground disturbance st /23). Sanitary installation (4	1/24/24). cheduled in the next 14 days?	ce in the last 14 days?			
Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu What temporary or permanent stabis Existing vegetation (11/29/23)	ns) of the site do not have grading, eartified Construction began (12/27, illiding Construction began (12/27, illization measures listed in this section	/23). Sanitary installation (4 hwork, or ground disturbance st /23). Sanitary installation (4	1/24/24). cheduled in the next 14 days?	ce in the last 14 days?			
Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu What temporary or permanent stabis Existing vegetation (11/29/23) Checklist Questions:	ns) of the site do not have grading, eartified Construction began (12/27, illiding Construction began (12/27, illization measures listed in this section	/23). Sanitary installation (4) hwork, or ground disturbance si /23). Sanitary installation (4) are being implemented?	4/24/24). cheduled in the next 14 days? 4/24/24).				
Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu What temporary or permanent stabis Existing vegetation (11/29/23) Checklist Questions:	ns) of the site do not have grading, earticities Construction began (12/27, ms) of the site do not have grading, earticities Construction began (12/27, ms) allization measures listed in this section ().	/23). Sanitary installation (4) hwork, or ground disturbance si /23). Sanitary installation (4) are being implemented?	4/24/24). cheduled in the next 14 days? 4/24/24).				
Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu What temporary or permanent stabis Existing vegetation (11/29/23) Checklist Questions: Are receiving waters adjace No Create Corrective Action?	ns) of the site do not have grading, earticities Construction began (12/27, ms) of the site do not have grading, earticities Construction began (12/27, ms) allization measures listed in this section ().	/23). Sanitary installation (4) hwork, or ground disturbance si /23). Sanitary installation (4) are being implemented?	4/24/24). cheduled in the next 14 days? 4/24/24).				
Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu What temporary or permanent stabis Existing vegetation (11/29/23) Checklist Questions: Are receiving waters adjace No	ns) of the site do not have grading, earticities Construction began (12/27, ms) of the site do not have grading, earticities Construction began (12/27, ms) allization measures listed in this section ().	/23). Sanitary installation (4) hwork, or ground disturbance si /23). Sanitary installation (4) are being implemented?	4/24/24). cheduled in the next 14 days? 4/24/24).				
Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu What temporary or permanent stabis Existing vegetation (11/29/23) Checklist Questions: Are receiving waters adjace No Create Corrective Action? No, See BMP Section.	ns) of the site do not have grading, eartication began (12/27, ns) of the site do not have grading, eartication Construction began (12/27, ns) illization measures listed in this section in the project free of any significant to the project free of any significant construction began (12/27, ns).	/23). Sanitary installation (4) hwork, or ground disturbance si /23). Sanitary installation (4) are being implemented?	h/24/24). cheduled in the next 14 days? h/24/24). or sediment that would be	e associated with	the construction activity?		
Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu What temporary or permanent stabis Existing vegetation (11/29/23) Checklist Questions: Are receiving waters adjace No Create Corrective Action? No, See BMP Section. Have disturbed areas been seems	ns) of the site do not have grading, earticities Construction began (12/27, ms) of the site do not have grading, earticities Construction began (12/27, ms) allization measures listed in this section ().	/23). Sanitary installation (4) hwork, or ground disturbance si /23). Sanitary installation (4) are being implemented?	h/24/24). cheduled in the next 14 days? h/24/24). or sediment that would be	e associated with	the construction activity?		
Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu What temporary or permanent stabis Existing vegetation (11/29/23) Checklist Questions: Are receiving waters adjace No Create Corrective Action? No, See BMP Section. Have disturbed areas been s needed to prevent erosion.	ns) of the site do not have grading, eartication began (12/27, ns) of the site do not have grading, eartication Construction began (12/27, ns) illization measures listed in this section in the project free of any significant to the project free of any significant construction began (12/27, ns).	/23). Sanitary installation (4) hwork, or ground disturbance si /23). Sanitary installation (4) are being implemented?	h/24/24). cheduled in the next 14 days? h/24/24). or sediment that would be	e associated with	the construction activity?		
Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu What temporary or permanent stabis Existing vegetation (11/29/23) Checklist Questions: Are receiving waters adjace No Create Corrective Action? No, See BMP Section. Have disturbed areas been a needed to prevent erosion. Yes	ns) of the site do not have grading, eartication began (12/27, ns) of the site do not have grading, eartication Construction began (12/27, ns) illization measures listed in this section in the project free of any significant to the project free of any significant construction began (12/27, ns).	/23). Sanitary installation (4) hwork, or ground disturbance si /23). Sanitary installation (4) are being implemented?	h/24/24). cheduled in the next 14 days? h/24/24). or sediment that would be	e associated with	the construction activity?		
Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu Which portion(s) (i.e. drainage basis Grading began (11/29/23). Bu What temporary or permanent stabis Existing vegetation (11/29/23) Checklist Questions: Are receiving waters adjace No Create Corrective Action? No, See BMP Section. Have disturbed areas been a needed to prevent erosion.	ns) of the site do not have grading, eartication began (12/27, ns) of the site do not have grading, eartication Construction began (12/27, ns) illization measures listed in this section in the project free of any significant to the project free of any significant construction began (12/27, ns).	/23). Sanitary installation (4) hwork, or ground disturbance si /23). Sanitary installation (4) are being implemented?	h/24/24). cheduled in the next 14 days? h/24/24). or sediment that would be	e associated with	the construction activity?		

Yes

N/A

Create Corrective Action?

Create Corrective Action?

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Are construction entrances and adjacent streets being maintained adequately?

No, See BMP Section. Is dust associated with the construction activity adequately controlled on the site?
Yes
Create Corrective Action?

N/A

Comments:

Comments:

Site was active for building construction during the last inspection.

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):

	_					
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CE 01 Construction Entrance Off 84th Street Removed						
Current Condition: Removed - Hoppe Development was paving the entrance during the inspection on 9/11/24.					1	
CE 02	Construction Entrance	Stony Hill Road	7/17/2024	Active	No	
Current Condition:	Good Condition - 75% effective					
	Hoppe Development was in the process of installing a construction entrance to the east at Stony Hill Road prior to the 7/17/24. Hoppe Development installed a rock construction entrance prior to the inspection on 7/31/24.					
EB 01	* * * * * * * * * * * * * * * * * * * *	I	12/29/2023	Pending	No	
	Erosion Control Matting	Water Quality Swale 1		Pending	INU	
Current Condition: Pending- Matting will be installed after final grade is established. EB 02 Erosion Control Matting Water Quality Swale 3 12/29/2023 Pending						
Current Condition:	Erosion Control Matting Pending- Matting will be installe	Water Quality Swale 3	12/29/2023	Pending	No	
EB 03		1		Б :	I	
	Erosion Control Matting	Water Quality Swale 2	12/29/2023	Pending	No	
Current Condition:	Pending- Matting will be installe				1	
EB 04	Erosion Control Matting	End of Culvert Pipe	12/29/2023	Pending	No	
Current Condition:	Pending- Matting will be installe				1	
IP 1	Inlet protection	Culvert Pipe 1	7/24/2024	Active	No	
Current Condition:	Good Condition - Hoppe Develo					
IP 2	Inlet protection	Culvert Pipe 2	7/24/2024	Active	No	
Current Condition:	Good Condition - Hoppe Develo			pipe prior to the ins	spection on 7/31/24.	
MS 01	Material Storage	On Site	5/8/2024	Active	No	
Current Condition:	Good Condition - Hoppe Develo	opment began storing construc	tion material on site prior	to the inspection of	on 5/8/24.	
PT 01	Portable Toilet	On Site	4/17/2024	Active	No	
Current Condition:	Good Condition - Hoppe Develo					
	Development installed and securemoved the secondary portable portable toilet on site prior to the	e toilet prior to the inspection of				
SF 01 Silt Fence Perimeter 12/13/2023 Act					Yes	
Current Condition: Fair Condition - Hoppe Development was in the process of installing the silt fence prior to the ins					n 12/6/23 Hoppe	
	inspection on 7/17/24. Silt fence or wattles should be in seeding and matting. Hoppe Development was inform					
	10/3/24. 11/8/24					
SF 02	Silt fence	Along construction entrance	7/24/2024	Pending	Yes	
Current Condition:	Pending -	•				
	Silt fence or wattles should be installed along construction entrance slopes.					
	Hoppe Development was inform	ned to complete by 7/31/24. No	ot done as of last inspection	on. Hoppe Develop	oment was reminded	
	8/28/24, 10/3/24 , 11/8/24	ı				
STR	Streets	ADJ and Internal Streets	11/29/2023	Active	Yes	
Current Condition:	Fair Condition -					
	Trackout should be cleaned.					
Hoppe Development was informed to complete by 7/25/24. Not done as of last inspection. Hoppe Development was informed to complete by 7/25/24. Not done as of last inspection.					oment was reminded	
SW 01	8/28/24, 10/3/24, 11/8/24 Strow Wattle	Water Quality Swale 4	12/20/2022	Donding	No	
300 01	Straw Wattle	Water Quality Swale 1	12/29/2023	Pending	No	
	Donding Strow Mattle will be to					
Current Condition:		I		D "	1	
Current Condition: SW 02	Straw Wattle	Water Quality Swale 1	12/29/2023	Pending	No	
Current Condition: SW 02 Current Condition:	Straw Wattle Pending- Straw Wattle will be in	Water Quality Swale 1 stalled once swale is installed	12/29/2023	<u> </u>		
Current Condition: SW 02 Current Condition: SW 03	Straw Wattle Pending- Straw Wattle will be in Straw Wattle	Water Quality Swale 1 estalled once swale is installed Water Quality Swale 3	12/29/2023 12/29/2023	Pending Pending	No No	
Current Condition: SW 02 Current Condition:	Straw Wattle Pending- Straw Wattle will be in	Water Quality Swale 1 estalled once swale is installed Water Quality Swale 3	12/29/2023 12/29/2023	<u> </u>		

Current Condition:	Pending- Straw Wattle will be installed once swale is installed.					
SW 05	Straw Wattle	Water Quality Swale 2	12/29/2023	Pending	No	
Current Condition:	Pending- Straw Wattle will be installed once swale is installed.					
SW 06	Straw Wattle	Water Quality Swale 2	12/29/2023	Pending	No	
Current Condition:	Pending- Straw Wattle will be installed once swale is installed.					
SW 07	Straw Wattle	Water Quality Swale 2	12/29/2023	Pending	No	
Current Condition:	Pending- Straw Wattle will be installed once swale is installed.					
SWPPP Sign	SWPPP Signs	ADJ to CE 01	11/29/2023	Active	No	
Current Condition:	Good Condition - E&A inspector	r installed the SWPPP sign pri	or to the inspection on 11	/29/23.		
WO 01	Concrete Washout	On Site	5/8/2024	Pending	No	
Current Condition:	Pending - Hoppe Development installed a concrete washout on site prior to the inspection on 5/8/24. Hoppe Development removed the concrete washout prior to the inspection on 7/24/24.					
WS 01	Waste Storage Area	On Site	11/29/2023	Active	No	
Current Condition:	Good Condition - Hoppe Development installed a waste storage container prior to the inspection on 11/29/23. Hoppe Development installed a new waste storage container on site prior to the inspection on 4/17/24.					
Certification Statement	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."					
Inspector Signature:	En Carlon			Reviewed By:	6.4 S.C.	