Increasing Teach Mark ODECC C		2006.056.01		Stage	
nspector: Zach Jilek, CPESC, C					
Project Name:	Ire	on Horse- Ashla	na, NE	3	
For Week Ending:		3/8/2008			
Grading:	100	%			
Sanitary Sewer:	900				
Storm Sewer:	909				
Paving:	909				
Seeding:	1009				
Utilities: Overall Development:	90° 50°				
RAIN FALL AMOUNTS	Amount in inches	Date inspected			
Sunday:	0.00"			Week	
Monday	0.00"				
Tuesday	0.00"	02/12/08			
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
Sunday	0.01"			Week	
Sunday: Monday	0.01" 0.00"				
Monday Tuesday	0.00"	02/19/08			
Wednesday	0.00"	52,10,00			
Thursday	0.00"		1		
Friday	0.00"				
Saturday	0.00"				
				Week	
Sunday:	0.00"				
Monday	0.28"				
Tuesday	0.00"				
Wednesday Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
				Week 4 /	
Sunday:	0.12 "				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday Saturday	0.02" 0.00"				
Saturday	0.00				
Complaints:	None				
oompiante.					
Construction Sequencing: Which portion(s) (i.e. drainage basins) o	f the site have had a tempo	ary or permanent consistion	of grading parthwork	or around disturbance	
the last 14 days?	i the site have had a tellipol	ary or permanent cessation	r or graung, earmwork	, or ground disturbance i	
Entire site; grading completed and	stabilized prior to Sprin	g 2005.			
		-			
Which portion(s) (i.e. drainage basins) o	f the site do not have gradir	ig, earthwork, or ground dis	sturbance scheduled in	the next 14 days? :	
		-			
Entire site; grading completed and	stabilized prior to Sprin	g 2005.			
What temporary or permanent stabilizati Dense Vegetation, seeding/soddin					
Comments:					
Comments:					
Site is in overall good condition. He	ome construction is acti	ve on site.			
Findings / Corrective Actions (D	ate):		·		
Findings / Corrective Actions (D	ate):				

Unique Name	Туре	Location	Projected Install Date	Status		Description of Maintenance/Activity:
	Permanent	N00d00m00s				
PDP A	Detention Pond	W00d00m00s	In Place	Active	No	Repairs Needed/Planned:

Current Condition:	Good Condition	<u> </u>						
		N00d00m00s						
SF 1	Silt Fence	W00d00m00s	In Place	Active	No			
Current Condition:	Good Condition- Protecting run-on from adjacent corn field.							
		N00d00m00s						
SF 2	Silt Fence	W00d00m00s	In Place	Active	No			
Current Condition:	Good Condition							
	Remove & Replace	Remove & Replaced on 3/2006 by Hausman						
		N00d00m00s						
SF 3	Silt Fence	W00d00m00s	In Place	Active	No			
Current Condition:	Good Condition							
	Maintanced on 4/2	Maintanced on 4/2006 by Hausman						
		N00d00m00s						
SF 4	Silt Fence	W00d00m00s	In Place	Active	No			
Current Condition:	Good Condition							
	Remove & Replaced on 3/2006 by Hausman							
		N00d00m00s						
SF 5	Silt Fence	W00d00m00s	In Place	Active	No			
Current Condition:	Good Condition							
	Maintanced on 4/2	Maintanced on 4/2006 by Hausman						
		N00d00m00s						
SF 6	Silt Fence	W00d00m00s	In Place	Active	No			
Current Condition:	Good Condition							
		N00d00m00s						
SF 7	Silt Fence	W00d00m00s	In Place	Active	No			
Current Condition:	Good Condition			•				
		N00d00m00s						
STR	Streets	W00d00m00s	In Place	Active	No			
Current Condition:	Good Condtion-No	Good Condtion-No major signs of track off.						
	1 11/2							
ector Signature: And And	y k. Jilek							