E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC
Environmental Services Dept. Manager

Entire site; grading completed and stabilized prior to Spring 2005.

Entire site; grading completed and stabilized prior to Spring 2005.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Engineering Answers

Environmental Services Dept. N	ianagei	E&A- P2006	056 001				
Inspector: Joe Manning		LQA- F2000	.030.001		Stage		
mapeetor. voe murring		lr/	on Horse		Otago		
Project Name:			-202206238		3		
For Week Ending:		10/14/2023					
Project Location:	Hwy	Hwy 6 & Iron Horse Drive- Ashland, NE (Saunders County)					
Grading:	100%	I		1			
Sanitary Sewer:	100%						
Storm Sewer:	100%						
Paving:	100%						
Seeding:	100%						
Utilities: Overall Development:	100% 85%		_		_		
Overali Developilient.	6570						
RAIN FALL AMOUNTS	Amount in tenths/Storm Duration	Date inspected	Weather Conditions	Time	Made		
Sunday:	0.15"				Week		
Monday:	0.01"			1			
Tuesday:	0.00"						
Wednesday:	0.00"						
Thursday:	0.00"						
Friday: Saturday:	0.01" 0.18"						
Saturday:	0.18				Week		
Sunday:	0.00"				Week		
Monday:	0.00"						
Tuesday:	0.00"						
Wednesday:	0.00"						
Thursday:	0.00"						
Friday: Saturday:	0.15" 0.00"						
Saturday.	0.00				Week		
Sunday:	0.00"				Week		
Monday:	0.00"						
Tuesday:	0.00"						
Wednesday:	0.00"						
Thursday:	0.00"						
Friday:	0.00"						
Saturday:	0.00"				Week		
Sunday:	0.00"				vveek		
Monday:	0.00"	10/2/2023	Sunny 91	2:40 PM			
Tuesday:	1.02"				12:35 PM to 10:55 PI		
Wednesday:	0.00"	10/4/2023	Sunny 65	1:30 PM			
Thursday:	0.01"						
Friday: Saturday:	0.03" 0.00"						
Jaturuay.	0.00				Week		
Sunday:	0.00"				week		
Monday:	0.00"			+			
Monday: Tuesday:	0.00"			1			
ruesday: Wednesday:	0.00"			+			
-	0.00 0.97"			+	9:20 AM - 11:50 AM		
Thursday:		10/13/2023	Cloudy 53/45	11:00 AM	9.20 AW - 11:30 AW		
Friday:	0.03"	10/13/2023	Gloudy 55/45	11:00 AW			
Saturday:	0.01"						
Complaints:	None						
Construction Secure sing.							
Construction Sequencing:	of the cite have bed a territoria	m, or norman	on of grading, earthwork, or grou	nd disturbance in the 1-	ot 14 days?		

Nhat temporary or permanent stabilization measures listed in this section are being implemented? Dense Vegetation, seeding/sodding, matting, re-seeding 5/2006, paving, and landscaping. **Checklist Questions:** Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Yes Create Corrective Action? N/A Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion. Yes Create Corrective Action? Are waste materials (concrete, construction material, hazardous, etc.) being managed properly? Create Corrective Action? No - See BMP Section. Are construction entrances and adjacent streets being maintained adequately? Create Corrective Action? No - See BMP Section. Is dust associated with the construction activity adequately controlled on the site? Create Corrective Action? N/A Comments: Comments: Home construction is active on a few lots. Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP section. Unique Name Location Projected Install Date Status Maintenance Type

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
IF 1	Inlet	Lot 110	In Place	Active	No	
Current Condition:	Active - This structure was previously referred to as a sediment basin, but is actually functioning as a slope					
	drain/area inlet. As-of the 11/26/18 inspection, silt fence is in place behind the structure and straw wattles are					
	located downhill from the outlet pipe.					
Lot 25	Individual Lot	Lot 25	6/2/2023	Active	No	
Current Condition:	Good Condition - Marque Custom Builders began construction on the lot prior to the inspection on 6/02/23. Due to					
	grade of the lot, no BMPs will be recommended at this time. A dirt pile was observed in the ROW and on Lot 24					
			Custom Builders removed the			
			along the west side of the lo			
			e silt fence prior to the ins	spection on 10/02/	23. E&A inspector will	
		recommendations as	<u> </u>			
Lot 33	Individual Lot	Lot 33	1/19/2023	Active	Yes	
Current Condition:	Active - An unknow	wn builder began constri	uction on the lot prior to the i	nspection on 1/19/2	23.	
	The lot should be	stabilized.				
						
1 1 1 7			e builder as of 10/03/23. No			
Lot 47	Individual Lot	Lot 47	12/14/2022	Active	Yes	
Current Condition:	Fair Condition - New Chapter Homes began construction on the lot prior to the inspection on 12/14/2022. Due to grade of the lot, no BMPs will be recommended at this time. New Chapter Homes removed the dirt pile from the					
			ncrete waste from the lot price			
	Homes secured a portable toilet on the lot prior to the inspection on 2/14/23. New Chapter Homes stood up the portable toilet prior to the inspection on 7/04/23. New Chapter Homes resecured the portable toilet prior to the					
		· · · · · · · · · · · · · · · · · · ·	·	· ·	the state of the s	
	inspection on 7/12/23. New Chapter Homes resecured a portable toilet on the lot prior to the inspection on 8/09/23. New Chapter Homes sodded the lot prior to the inspection on 8/28/23.					
	Tron Chapter From	oo ooddaa ano iot piiloi ta				
	The areas adjoining the lot disturbed for construction should be stabilized and construction debris should be removed.					
	New Chapter Home	es was informed to comp	olete by 9/04/23. Not done a	s of the last inspe	ection.	
Lot 57	Silt Fence	Lot 57	6/1/2020	Active	No	
Current Condition:	Active - An unknow	wn builder began constru	uction on the lot prior to the i	nspection on 6/01/2	20. The lot has vegetated	
	as of 10/05/20. The	e lot is currently vacant.				
Lot 61	Silt Fence	Lot 61	9/28/2021	Active	No	
Current Condition:	Removed - The Ho	ome Company sodded tl	ne lot prior to the inspection	on 6/10/22.		
Lot 82	Silt Fence	Lot 82	, ,	Removed		
Current Condition:	Removed - Paradis	se Homes sodded the pr	ior to the inspection on 9/2/2	2.	•	
Lot 1 R VI	Silt Fence	Lot 1 R VI	8/17/2017	Active	No	

Current Condition:	Good Condition - Boyer Young repaired the silt fence on the lot prior to the 7/3/18 inspection. Boyer Young removed some of the damaged silt fence and repaired the runs left in place prior to inspection on 7/02/19. As of the inspection on 7/02/19, volunteer vegetation has filled in sufficiently to prevent erosion, therefore seeding is no longer required at this time. Boyer Young removed the damaged runs of silt fence from the lot prior to the inspection on 11/11/20. Lot was formerly identified as Lot 113. Some portions of the silt fence were loose from the t-posts during the inspection on 6/24/21. E&A inspector retied a portion of the silt fence during the inspection on 8/10/21. E&A inspector will make recommendations for the remainder of the loose portion of silt fence once the lot becomes active.					
Lot 2 R VI	Individual Lot	Lot R VI	10/4/2023	Active	No	
Current Condition:	Active - An unknown contractor began excavation on the lot prior to the inspection on 10/04/23. Due to the grade of the lot and vegetation, no BMPs will be recommended at this time. E&A inspector will monitor.					
Lot 152	Individual Lot	Lot 152		Removed		
Current Condition: Lot 155	the inspection on 5	/19/23. Citadel Homes r	prior to the inspection on 10/2 removed the silt fence from the silt be made once Lot 151 I 9/3/2018	he lot prior to the ins	·	
Current Condition:	Fair Condition - Widhalm Custom Homes installed silt fence on the lot to protect sodded lot 154 prior to inspection on 9/3/18. Silt fence recommendations will no longer be made as of 8/28/23. E&A inspector will monitor and recommend repairs once lot becomes disturbed/active.					
Lot 156	Silt Fence	Lot 156	1	Removed		
Current Condition:			prior to the inspection on 8/8		N -	
Lot 175	Individual Lot	Lot 175	10/2/2023	Active	No	
Current Condition:			excavation on the lot prior no BMPs will be recommer			
Lot 176	Individual Lot	Lot 176	10/2/2023	Active	No	
Current Condition:	Active - An unkno	wn contractor began	excavation on the lot prior	to the inspection	on 10/02/23. Due to the	
1.4477	monitor.		no BMPs will be recommer			
Lot 177	Individual Lot	Lot 177	4/12/2023	Active	No	
Current Condition: Lot 178	Individual Lot	Lot 178	on on the lot prior to the insp 7/6/2022	Active	Yes	
	straw wattles along the road north of the lot prior to the inspection on 1/03/23. This is not a sufficient BMP based on the location of the lot. Gateway Homes installed silt fence along the front side of the lot prior to the inspection of 7/12/23. 1.) Silt fence should be installed on the north side of the lot or the lot should be stabilized. 2.) Street in front of the lot should be cleaned. 3.) The silt fence along the front of the lot should be repaired. 1.) Gateway Homes was informed to complete by 8/15/22. Not done as of last inspection. Gateway Homes was reminded on 9/2/22, 11/22/22, 12/15/22, 3/17/23, 6/12/23, 6/30/23, 8/02/23 2.) Gateway Homes was informed to complete by 12/15/22. Not done as of the last inspection. Gateway Homes was reminded on 3/17/23, 6/12/23, 6/30/23, 8/02/23 3.) Gateway Homes was informed to complete by 8/09/23. Not done as of the last inspection.					
Lot 179	Individual Lot	Lot 179	7/6/2022	Pending	Yes	
Current Condition:	Pending - Gateway Homes began construction prior to the inspection on 7/6/22. Gateway Homes cleaned the street in front of the lot prior to the inspection on 6/29/23. Silt fence should be installed on the north side of the lot or the lot should be stabilized. Gateway Homes was informed to complete by 8/15/22. Not done as of last inspection. Gateway Homes was reminded on 9/2/22, 11/22/22, 12/15/22, 3/17/23, 6/12/23, 6/30/23, 8/02/23					
Lot 180	Individual Lot	Lot 180	7/6/2022	Pending	Yes	
Current Condition:	Pending - Gateway Homes began construction prior to the inspection on 7/6/22. Gateway Homes cleaned the street in front of the lot prior to the inspection on 6/29/23. Silt fence should be installed on the north side of the lot or the lot should be stabilized. Gateway Homes was informed to complete by 7/13/22. Not done as of last inspection. Gateway Homes was reminded on 8/8/22, 9/2/22, 11/22/22, 12/15/22, 3/17/23, 6/12/23, 6/30/23, 8/02/23					
Lot 181	Individual Lot	Lot 181	7/6/2022	Active	No	
Current Condition:		lomes began construction	on prior to the inspection on			
Lot 182	Individual Lot	Lot 182	3/17/2023	Active	Yes	

Current Condition:	Fair Condition - JD Builders, Inc. began construction on the lot prior to the inspection on 3/17/23. A dirt pile was observed in the ROW during the inspection on 3/17/23. A portable toilet was on the lot during the inspection on 3/17/23. JD Builders, Inc. removed the dirt pile from the ROW prior to the inspection on 4/12/23. JD Builders, Inc. stood up the portable toilet prior to the inspection on 4/17/23. JD Builders, Inc. cleaned the street along the lot prior to the inspection on 6/29/23. 1.) The portable toilet should be secured at least fifty feet from the nearest storm inlet. 2.) The street along the lot should be cleaned.				
	1.) JD Builders, Inc. was informed to complete by 3/24/23. Not done as of the last inspection. JD Builders, Inc. reminded on 8/09/23.				
1.1100	2.) JD Builders, Inc. was informed to complete by 8/10/23. Not done as of the last inspection.				
Lot 183 Current Condition:		Lot 183 Homes Inc. began cons irt pile prior to the inspec	4/12/2023 struction on the lot prior to th ction on 4/17/23.	Active e inspection on 4/12	No 2/23. David A.D. Homes
Lot 184	Individual Lot	Lot 184		Removed	
Current Condition:			prior to the inspection on 7/6		No
Lot 185 Current Condition:	Individual Lot	Lot 185	4/12/2023 the lot prior to the inspection	Active	No uilders removed the dirt
	pile from the ROW	prior to the inspection o	n 4/20/23. E&A inspector wil	I monitor BMP insta	
Lot 190	Individual Lot	Lot 190	8/28/2023	Active	No
Current Condition:	Active - An unknow Individual Lot	/n contractor disturbed to	he lot prior to the inspection		spector will monitor.
Lot 194 Current Condition:			I and removed all waste from t	Removed	spection on 10/24/22
Carront Condition.		Journal the lot b			
Lot 199	Individual Lot	Lot 199	11/21/2022	Active	No
Current Condition:			ruction on the lot and installe		
			lders secured a portable toile		
	•		outh side of the lot was dama silt fence prior to the inspection	•	pection on 6/02/23. IVIK
Lot 200	Individual Lot	Lot 200	I I I I I I I I I I I I I I I I I I I	Removed	
Current Condition:			prior to the 8/14/23 inspection		
	Permanent	41°02'43.47"N			
PDP A	Detention Pond	96°20'36.65"W	In Place	Active	No
Current Condition: SB 1	Sediment Basin	his is a pond as of 1993 Lot 109		Removed	
Current Condition:	Removed - Followin	ng the 11/26/18 inspecti	on, this structure is no longe opears to be an area inlet/slo	r being considered	
SF 3	Silt Fence	Lot 197		Removed	
Current Condition:			nce during the inspection on		
SF 5	Silt Fence	South side of lake		Removed	
Current Condition:			ence during the inspection on		
SF 8	Silt Fence	40' South of SF 5	Lence during the inspection on	Removed	
Current Condition:	Removed- the msp	East of Lots 119 and	lince during the inspection on	3/22/17.	
SF 9	Silt Fence	120	In Place	Active	No
Current Condition:			d partially removed the silt fe		ion on 12/5/17. The
SF 10	Silt Fence	Behind Lot 190	to the inspection on 9/01/2	Removed	
Current Condition:	rveilloven - The sill	41°02'28.55"N	51 to the hispection on 9/01/2	. 1 .	
STR	Streets	96°20'36.35"W	In Place	Active	No
Current Condition:			ed the street in front of Lot 5		
SWPPP Sign	SWPPP Sign	Three signs on site	at Iron Horse Drive and Hus	Active	No No
Current Condition:	Road entrance. The	e sign at the South Lake	at Iron Horse Drive and Hwy eview Way and South Bend F spection on 7/02/19. The SW	Road entrance was	visible again due to the
	had been knocked	over prior to inspection	on 7/23/19. E&A inspector re led a SWPPP sign in the pa	einstalled the downe	ed SWPPP sign during
Certification Statement:	supervision in acco evaluated the informathose persons direct knowledge and belifalse information in	ordance with a system de mation submitted. Based ctly responsible for gathe ief, true, accurate, and c	ument and all attachments we esigned to assure that qualifi d on my inquiry of the person ering the information, the info complete. I am aware that the fines and imprisonment for k	ed personnel prope or persons who ma ormation submitted ere are significant p	rly gathered and anage the system or is, to the best of my
Inspector Signature:	Ge lin			Reviewed By:	Sut Su