E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Engineering Answers

Zachary A. Jilek, CPESC, CISE				Engineering	Answers		
Environmental Services Dept.		&A - P2019.032.0	00				
Inspector: Bryce Wright					Stage		
		Komnton	Crook 2				
		Kempten Creek 2 CSW-202106167					
Project Name:							
For Week Ending:		12/24/2022					
Project Location:	North 168th Street	and Bennington Roa	d - Bennington, NE (Dou	glas County)	68007		
Grading:	5%						
Sanitary Sewer:	0%						
Storm Sewer:	0%						
Paving:	0%						
Seeding:	0%						
Utilities:	0%						
Overall Development:	0%						
		I	l	T	T		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	West		
Sunday:	0.00"				Week		
Monday	0.02"						
Tuesday	0.00"	12/20/2022	Sunny 8	11:10 AM			
Wednesday	0.00"						
Thursday	0.00"						
Friday Saturday	0.00"						
Grading Began (11/29/22). What temporary or permanent Existing Vegetation (11/29/22). Checklist Questions:	e basins) of the site do not have grate translation measures listed in the project free of any significant signs of eros	is section are being	implemented?		days?		
Yes	project free or any significant signs of eros	sion or seament that wot	ilu be associated with the cons	struction activity?			
Create Corrective Action?							
N/A							
Have disturbed areas been seeded o Yes Create Corrective Action? N/A	or otherwise stabilized as required? List ina	octive portions of the proj	ect and if stabilization measur	e are adequate or needec	d to prevent erosion.		
Are waste materials (concrete, const	truction material, hazardous, etc.) being ma	anaged properly?					
No							
Create Corrective Action? No, see BMP section							
, 555 5 5500011							
-	cent streets being maintained adequately?						
No Create Corrective Action?							
No, See BMP section							
,							
	tion activity adequately controlled on the s	ite?					
Yes Create Corrective Action?							
oreate Corrective Action?							

N/A

Comments:

The site was **in**active during the last inspection.

Findings / Corrective Actions (Date):
Findings / Corrective Actions (Date):
1.) Some maintenance is required at this time.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CE 1	Construction Entrance	X-11	11/4/2022	Pending	Yes	
Current Condition:	Pending -					
	A construction entrance should be installed.					
	Ruff Grading and HRC Development were informed to complete by 12/20/22. Not done as of the last inspection.					
D1	Diversion	D-8 to K-8	11/4/2022	Pending	No	
Current Condition:	Pending - Diversion will be in			1 chang	140	
	· ·	,		Danidia a	N-	
D2 Current Condition:	Diversion Pending - Diversion will be in	East of SB B	11/4/2022	Pending	No	
	-			Γ	Γ	
D3	Diversion	Southeast of SB A	11/4/2022	Pending	No	
Current Condition:	Pending - Diversion will be in	1		Т	T	
ET 1	Erosion Control Terraces	B-9 to G-10	11/4/2022	Pending	No	
Current Condition:	Pending - The erosion contro	l terraces will be installe	ed when the area is near the	final grade.	ı	
ET 2	Erosion Control Terraces	B-9 to I-10	11/4/2022	Pending	No	
Current Condition:	Pending - The erosion contro	l terraces will be installe	d when the area is near the	final grade.		
ET 3	Erosion Control Terraces	B-7 to K-10	11/4/2022	Pending	No	
Current Condition:	Pending - The erosion contro	l terraces will be installe	ed when the area is near the	final grade.	_	
ET 4	Erosion Control Terraces	I-7 to M-10	11/4/2022	Pending	No	
Current Condition:	Pending - The erosion contro	I terraces will be installe	ed when the area is near the	final grade.		
ET 5	Erosion Control Terraces	Q-10 to Q-8	11/4/2022	Pending	No	
Current Condition:	Pending - The erosion contro	l terraces will be installe	ed when the area is near the	final grade.		
ET 6	Erosion Control Terraces	R-10 to R-7	11/4/2022	Pending	No	
Current Condition:	Pending - The erosion contro	l terraces will be installe	ed when the area is near the	final grade.		
ET 7	Erosion Control Terraces		11/4/2022	Pending	No	
Current Condition:	Pending - The erosion contro	l terraces will be installe	ed when the area is near the	final grade.		
FT 1	Fuel Tank	On site	12/6/2022	Active	Yes	
Current Condition:	Fair Condition - Ruff Grading	brought a fuel tank on s	site prior to the inspection or	n 12/6/22.		
	A secondary containment be	rm should be installed a	round the fuel tank.			
	Ruff Grading and HRC Deve	lanment were informed t	to complete by 12/12/22 No	et done so of the lar	at inapportion Duff	
	Grading and HRC Developm			of dolle as of the las	st inspection. Run	
MS 1	Material Storage Area	On site	11/4/2022	Pending	No	
Current Condition:	Pending - There is currently i					
	the E&A inspector will continu		J		5 ,	
SB A	Sediment Basin	Z-9	11/4/2022	Pending	No	
Current Condition:	Pending - Basin will be instal	led when grading in the	area starts.		•	
SB B	Sediment Basin	L-7	11/4/2022	Pending	No	
Current Condition:	Pending - Basin will be instal			<u>a</u>		
SF 1	Silt fence	West edge of site	11/29/2022	Active	No	
Current Condition:	Good Condition - HRC Deve				1 140	
SF 2	Silt fence	West edge of site	11/29/2022	Active	No	
Current Condition:	Good Condition - HRC Deve			<u> </u>		
WO 1	Concrete Washout	On site	11/4/2022	Pending	No	
Current Condition:	Pending - Concrete washout				1.10	
				D "	l N	
WS 1 Current Condition:	Waste Storage Area	On site	11/4/2022	Pending	No No	
Current Condition:		Pending - There is currently no need for a designated waste storage area on-site due to no waste materials being generated or stored on-site; the E&A inspector will continue to monitor.				
	generated of stored on-site, i	Bennington Road, N.	Thanks to monitor.		T	
STR	Streets	168th Street	11/4/2022	Active	No	
Current Condition:	Good Condition - No trackou		11/7/2022	7.0076	1 140	
SWPPP Sign	SWPPP Notification Sign	Adjacent to CE 1	11/4/2022	Pending	No	
Current Condition:	Good Condition - SWPPP in					

Certification Statement:	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."			
Inspector Signature:	Brya M Waght	Reviewed By:		