E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Engineering Answers

	Uanagar Managar			Engineering Ansi	VETS	
Environmental Services Dept. N	nanagei	E&A - P2019.032.	000			
Inspector: Bryce Wright					Stage	
	Kampton Crook 2					
		Kempten Creek 2 CSW-202106167				
Project Name:						
For Week Ending:		1/7/2	2023			
oject Location: North 168th Street and Bennington Road - Bennington, NE (Douglas Cou					68007	
Grading:	5	i%				
Sanitary Sewer:	0	1%				
Storm Sewer:	0	%				
Paving:	0	%				
Seeding:	0	%				
Utilities:	0	%				
Overall Development:	0	1%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time		
					Week	
Sunday:	0.00"					
Monday	0.44"					
Tuesday	0.11"	1/3/2023	Foggy 33	11:05 AM		
Wednesday	0.00"					
Thursday Friday	0.00"					
Saturday	0.00"					
Complaints:						
Construction Sequencing:						
Which portion(s) (i.e. drainage	basins) of the site have had a	temporary or perma	nent cessation of grading	, earthwork, or groun	d disturbance ir	
Which portion(s) (i.e. drainage the last 14 days?	basins) of the site have had a	temporary or perma	nent cessation of grading	, earthwork, or groun	d disturbance ir	
Which portion(s) (i.e. drainage the last 14 days? Grading Began (11/29/22).						
Which portion(s) (i.e. drainage the last 14 days? Grading Began (11/29/22). Which portion(s) (i.e. drainage						
Which portion(s) (i.e. drainage the last 14 days? Grading Began (11/29/22).						
Which portion(s) (i.e. drainage the last 14 days? Grading Began (11/29/22). Which portion(s) (i.e. drainage	basins) of the site do not hav	re grading, earthwork	, or ground disturbance s			
Which portion(s) (i.e. drainage the last 14 days? Grading Began (11/29/22). Which portion(s) (i.e. drainage Grading Began (11/29/22).	basins) of the site do not hav	re grading, earthwork	, or ground disturbance s			
Which portion(s) (i.e. drainage the last 14 days? Grading Began (11/29/22). Which portion(s) (i.e. drainage Grading Began (11/29/22). What temporary or permanent s	basins) of the site do not hav	re grading, earthwork	, or ground disturbance s			
Which portion(s) (i.e. drainage the last 14 days? Grading Began (11/29/22). Which portion(s) (i.e. drainage Grading Began (11/29/22). What temporary or permanent s	basins) of the site do not hav	re grading, earthwork	, or ground disturbance s			
Which portion(s) (i.e. drainage the last 14 days? Grading Began (11/29/22). Which portion(s) (i.e. drainage Grading Began (11/29/22). What temporary or permanent sexisting Vegetation (11/29/22). Checklist Questions:	basins) of the site do not hav	re grading, earthwork	i, or ground disturbance sing implemented?	cheduled in the next		
Which portion(s) (i.e. drainage the last 14 days? Grading Began (11/29/22). Which portion(s) (i.e. drainage Grading Began (11/29/22). What temporary or permanent sexisting Vegetation (11/29/22). Checklist Questions: Are receiving waters adjacent to the process of the last of	basins) of the site do not hav	re grading, earthwork	i, or ground disturbance sing implemented?	cheduled in the next		
Which portion(s) (i.e. drainage the last 14 days? Grading Began (11/29/22). Which portion(s) (i.e. drainage Grading Began (11/29/22). What temporary or permanent sexisting Vegetation (11/29/22). Checklist Questions: Are receiving waters adjacent to the proyes	basins) of the site do not hav	re grading, earthwork	i, or ground disturbance sing implemented?	cheduled in the next		
Which portion(s) (i.e. drainage the last 14 days? Grading Began (11/29/22). Which portion(s) (i.e. drainage Grading Began (11/29/22). What temporary or permanent sexisting Vegetation (11/29/22). Checklist Questions: Are receiving waters adjacent to the process of the last of	basins) of the site do not hav	re grading, earthwork	i, or ground disturbance sing implemented?	cheduled in the next		
Which portion(s) (i.e. drainage the last 14 days? Grading Began (11/29/22). Which portion(s) (i.e. drainage Grading Began (11/29/22). What temporary or permanent sexisting Vegetation (11/29/22). Checklist Questions: Are receiving waters adjacent to the proyes Create Corrective Action?	basins) of the site do not hav	re grading, earthwork	i, or ground disturbance sing implemented?	cheduled in the next		
Which portion(s) (i.e. drainage the last 14 days? Grading Began (11/29/22). Which portion(s) (i.e. drainage Grading Began (11/29/22). What temporary or permanent sexisting Vegetation (11/29/22). Checklist Questions: Are receiving waters adjacent to the proyes Create Corrective Action? N/A	basins) of the site do not have stabilization measures listed in the stabilization me	re grading, earthwork in this section are bei	ing implemented?	nstruction activity?	14 days?	
Which portion(s) (i.e. drainage the last 14 days? Grading Began (11/29/22). Which portion(s) (i.e. drainage Grading Began (11/29/22). What temporary or permanent sexisting Vegetation (11/29/22). Checklist Questions: Are receiving waters adjacent to the proyes Create Corrective Action? N/A Have disturbed areas been seeded or o	basins) of the site do not have stabilization measures listed in the stabilization me	re grading, earthwork in this section are bei	ing implemented?	nstruction activity?	14 days?	
Which portion(s) (i.e. drainage the last 14 days? Grading Began (11/29/22). Which portion(s) (i.e. drainage Grading Began (11/29/22). What temporary or permanent sexisting Vegetation (11/29/22). Checklist Questions: Are receiving waters adjacent to the proyes Create Corrective Action? N/A Have disturbed areas been seeded or on Yes	basins) of the site do not have stabilization measures listed in the stabilization me	re grading, earthwork in this section are bei	ing implemented?	nstruction activity?	14 days?	
Which portion(s) (i.e. drainage the last 14 days? Grading Began (11/29/22). Which portion(s) (i.e. drainage of the last 14 days? Grading Began (11/29/22). What temporary or permanent so the second of the last temporary or permanent so the last temporary or perm	basins) of the site do not have stabilization measures listed in the stabilization me	re grading, earthwork in this section are bei	ing implemented?	nstruction activity?	14 days?	
Which portion(s) (i.e. drainage the last 14 days? Grading Began (11/29/22). Which portion(s) (i.e. drainage Grading Began (11/29/22). What temporary or permanent sexisting Vegetation (11/29/22). Checklist Questions: Are receiving waters adjacent to the proyes Create Corrective Action? N/A Have disturbed areas been seeded or on Yes	basins) of the site do not have stabilization measures listed in the stabilization me	re grading, earthwork in this section are bei	ing implemented?	nstruction activity?	14 days?	

Is dust associated with the construction activity adequately controlled on the site?

No

Create Corrective Action?
No, see BMP section

Create Corrective Action?
No, See BMP section

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?
N/A

Comments:

The site was inactive during the last inspection. Site was covered with light snow as of the inspection on 1/3/23.

Findings / Corrective Actions (Date):
Findings / Corrective Actions (Date):
1.) Some maintenance is required at this time.

Unique Name	Туре	Location	Projected Install Date	Status	Maintena
CE 1	Construction Entrance	X-11	11/4/2022	Pending	Yes
Current Condition:	Pending - A construction entrance sl				
	Ruff Grading and HRC De	velopment were informed	d to complete by 12/20/22. N	lot done as of the	last inspection
D1	Diversion	D-8 to K-8	11/4/2022	Pending	No
Current Condition:	Pending - Diversion will be	e installed when the area	is near the final grade.		
D2	Diversion	East of SB B	11/4/2022	Pending	No
Current Condition:	Pending - Diversion will be	installed when the area	is near the final grade.		
D3	Diversion	Southeast of SB A	11/4/2022	Pending	No
Current Condition:	Pending - Diversion will be				
ET 1	Erosion Control Terraces		11/4/2022	Pending	No
Current Condition:			lled when the area is near th		110
ET 2	Erosion Control Terraces		11/4/2022	Pending	No
Current Condition:			lled when the area is near th		INU
ET 3	Erosion Control Terraces		11/4/2022	Pending	No
Current Condition:			lled when the area is near th		110
ET 4	Erosion Control Terraces		11/4/2022	Pendina	No
Current Condition:			lled when the area is near th		140
		1	1	-	N.
ET 5 Current Condition:	Erosion Control Terraces		11/4/2022 lled when the area is near th	Pending	No
					NI.
ET 6 Current Condition:	Erosion Control Terraces		11/4/2022 lled when the area is near th	Pending	No
	- C				N.
ET 7 Current Condition:	Erosion Control Terraces		11/4/2022 lled when the area is near th	Pending	No
			1		
FT 1 Current Condition:	Fuel Tank	On site	12/6/2022 n site prior to the inspection	Active	Yes
MS 1	Grading and HRC Develor	velopment were informed oment were reminded on	around the fuel tank. I to complete by 12/13/22. N 12/15/22.	lot done as of the	
MS 1 Current Condition:	Ruff Grading and HRC De Grading and HRC Develop Material Storage Area	evelopment were informed oment were reminded on On site	around the fuel tank. I to complete by 12/13/22. No. 12/15/22. 11/4/2022	lot done as of the	No
Current Condition:	Ruff Grading and HRC De Grading and HRC Develo Material Storage Area Good Condition-Material a	evelopment were informed on On site und vehicle staging area of	around the fuel tank. to complete by 12/13/22. No. 12/15/22. 11/4/2022 occurring on-site by Ruff fue	lot done as of the Active I tanker as of 12/2	No 26/22
Current Condition: SB A	Ruff Grading and HRC De Grading and HRC Develor Material Storage Area Good Condition-Material a Sediment Basin	evelopment were informed on On site and vehicle staging area of Z-9	around the fuel tank. d to complete by 12/13/22. N 12/15/22. 11/4/2022 ccurring on-site by Ruff fue 11/4/2022	lot done as of the	No
Current Condition: SB A Current Condition:	Ruff Grading and HRC De Grading and HRC Develop Material Storage Area Good Condition-Material a Sediment Basin Pending - Basin will be ins	velopment were informed on On site and vehicle staging area of Z-9	around the fuel tank. d to complete by 12/13/22. No. 12/15/22. 11/4/2022 cocurring on-site by Ruff fuel 11/4/2022 e area starts.	Active I tanker as of 12/2 Pending	No 26/22 No
Current Condition: SB A Current Condition: SB B	Ruff Grading and HRC De Grading and HRC Develop Material Storage Area Good Condition-Material a Sediment Basin Pending - Basin will be ins Sediment Basin	velopment were informed on On site and vehicle staging area of Z-9 stalled when grading in the L-7	around the fuel tank. d to complete by 12/13/22. No. 12/15/22. 11/4/2022 ccurring on-site by Ruff fue 11/4/2022 e area starts. 11/4/2022	lot done as of the Active I tanker as of 12/2	No 26/22
Current Condition: SB A Current Condition: SB B Current Condition:	Ruff Grading and HRC De Grading and HRC Develop Material Storage Area Good Condition-Material a Sediment Basin Pending - Basin will be ins Sediment Basin Pending - Basin will be ins	velopment were informed on On site and vehicle staging area of talled when grading in the stalled when grading in	around the fuel tank. to complete by 12/13/22. No. 12/15/22. 11/4/2022 e area starts. 11/4/2022 e area starts.	Active I tanker as of 12/2 Pending Pending	No 26/22 No No
Current Condition: SB A Current Condition: SB B Current Condition: SF 1	Ruff Grading and HRC Decelor Grading and HRC Develor Material Storage Area Good Condition-Material a Sediment Basin Pending - Basin will be ins Sediment Basin Pending - Basin will be ins Silt fence	velopment were informed on on site and vehicle staging area of talled when grading in the L-7 stalled when grading in the West edge of site	around the fuel tank. d to complete by 12/13/22. No. 12/15/22. 11/4/2022 e area starts. 11/4/2022 e area starts. 11/4/2022 e area starts.	Active I tanker as of 12/2 Pending Pending Active	No 26/22 No
Current Condition: SB A Current Condition: SB B Current Condition: SF 1 Current Condition:	Ruff Grading and HRC December of Grading and HRC Develop Material Storage Area Good Condition-Material a Sediment Basin Pending - Basin will be ins Sediment Basin Pending - Basin will be ins Silt fence Good Condition - HRC De	velopment were informed on On site and vehicle staging area of talled when grading in the L-7 stalled when grading in the West edge of site velopment installed the s	around the fuel tank. It to complete by 12/13/22. No. 12/15/22. 11/4/2022 e area starts. 11/4/2022 e area starts. 11/29/2022 ilt fence prior to the inspecti	Active Pending Pending Active Active	No 26/22
Current Condition: SB A Current Condition: SB B Current Condition: SF 1 Current Condition: SF 2	Ruff Grading and HRC December Grading and HRC Develop Material Storage Area Good Condition-Material a Sediment Basin Pending - Basin will be ins Sediment Basin Pending - Basin will be ins Silt fence Good Condition - HRC Desilt fence	velopment were informed on on site and vehicle staging area of the staging area of the staging area of the staging area of the staging in the staging when grading in the west edge of site velopment installed the subsets of the stage of site west edge of site west edge of site	around the fuel tank. to complete by 12/13/22. No. 12/15/22. 11/4/2022 e area starts. 11/4/2022 e area starts. 11/29/2022 ilt fence prior to the inspection 11/29/2022	Active Pending Pending Active	No 26/22 No No
Current Condition: SB A Current Condition: SB B Current Condition: SF 1 Current Condition: SF 2 Current Condition:	Ruff Grading and HRC December Grading and HRC Develop Material Storage Area Good Condition-Material a Sediment Basin Pending - Basin will be ins Sediment Basin Pending - Basin will be ins Silt fence Good Condition - HRC Desilt fence Good Condition - HRC Desilt fence Good Condition - HRC Designation	velopment were informed on on site and vehicle staging area of talled when grading in the L-7 stalled when grading in the West edge of site velopment installed the set ve	around the fuel tank. d to complete by 12/13/22. No. 12/15/22. 11/4/2022 e area starts. 11/4/2022 e area starts. 11/29/2022 illt fence prior to the inspectifit fence prior to the inspectific fence prior to the inspectifit fence prior to the inspectific fence prior to the inspection f	Active Pending Active Active Active Active Active Active Active Active On on 11/29/22. Active On on 11/29/22.	No
Current Condition: SB A Current Condition: SB B Current Condition: SF 1 Current Condition: SF 2 Current Condition: WO 1	Ruff Grading and HRC December Grading and HRC Develop Material Storage Area Good Condition-Material a Sediment Basin Pending - Basin will be ins Sediment Basin Pending - Basin will be ins Silt fence Good Condition - HRC Desilt Concrete Washout	velopment were informed on on site on	around the fuel tank. It to complete by 12/13/22. No. 12/15/22. 11/4/2022 Decurring on-site by Ruff fuel 11/4/2022 The area starts. 11/4/2022 The area starts. 11/29/2022 The fence prior to the inspection 11/29/2022 The area starts the inspection 11/4/2022	Active Pending Pending Active	No No No No No No
Current Condition: SB A Current Condition: SB B Current Condition: SF 1 Current Condition: SF 2 Current Condition:	Ruff Grading and HRC December Grading and HRC Develop Material Storage Area Good Condition-Material a Sediment Basin Pending - Basin will be ins Sediment Basin Pending - Basin will be ins Silt fence Good Condition - HRC Desilt fence Good Condition - HRC Desilt fence Good Condition - HRC Designation	velopment were informed on on site on	around the fuel tank. It to complete by 12/13/22. No. 12/15/22. 11/4/2022 Decurring on-site by Ruff fuel 11/4/2022 The area starts. 11/4/2022 The area starts. 11/29/2022 The fence prior to the inspection 11/29/2022 The area starts the inspection 11/4/2022	Active Pending Active Active Active Active Active Active Active Active On on 11/29/22. Active On on 11/29/22.	No
Current Condition: SB A Current Condition: SB B Current Condition: SF 1 Current Condition: SF 2 Current Condition: WO 1 Current Condition: WS 1	Ruff Grading and HRC Decelor Grading and HRC Develor Material Storage Area Good Condition-Material a Sediment Basin Pending - Basin will be ins Sediment Basin Pending - Basin will be ins Silt fence Good Condition - HRC Desilt fence Good Conditi	velopment were informed on on site and vehicle staging area of the	around the fuel tank. d to complete by 12/13/22. No. 12/15/22. 11/4/2022 e area starts. 11/4/2022 e area starts. 11/29/2022 dilt fence prior to the inspection of the insp	Active Pending Active Pending Active On on 11/29/22. Active On on 11/29/22. Pending Pending	No
Current Condition: SB A Current Condition: SB B Current Condition: SF 1 Current Condition: SF 2 Current Condition: WO 1 Current Condition:	Ruff Grading and HRC Decelor Grading and HRC Develor Material Storage Area Good Condition-Material a Sediment Basin Pending - Basin will be ins Sediment Basin Pending - Basin will be ins Silt fence Good Condition - HRC Desilt fence Good Conditi	velopment were informed on on site and vehicle staging area of the	around the fuel tank. d to complete by 12/13/22. No. 12/15/22. 11/4/2022 e area starts. 11/4/2022 e area starts. 11/29/2022 dilt fence prior to the inspection of the insp	Active Pending Active Pending Active On on 11/29/22. Active On on 11/29/22. Pending Pending	No
Current Condition: SB A Current Condition: SB B Current Condition: SF 1 Current Condition: SF 2 Current Condition: WO 1 Current Condition: WS 1 Current Condition:	Ruff Grading and HRC Decelor Grading and HRC Develor Material Storage Area Good Condition-Material at Sediment Basin Pending - Basin will be instance Good Condition - HRC Deside Good Condition - HRC	velopment were informed on on site and vehicle staging area of the	around the fuel tank. d to complete by 12/13/22. No. 12/15/22. 11/4/2022 e area starts. 11/4/2022 e area starts. 11/29/2022 dilt fence prior to the inspection of the insp	Active Pending Active Pending Active On on 11/29/22. Active On on 11/29/22. Pending Pending	No
Current Condition: SB A Current Condition: SB B Current Condition: SF 1 Current Condition: SF 2 Current Condition: WO 1 Current Condition: WS 1 Current Condition:	Ruff Grading and HRC Decelor Grading and HRC Develor Material Storage Area Good Condition-Material a Sediment Basin Pending - Basin will be ins Sediment Basin Pending - Basin will be ins Silt fence Good Condition - HRC Desilt fence Good Conditi	velopment were informed on on site and vehicle staging area of the	around the fuel tank. d to complete by 12/13/22. No. 12/15/22. 11/4/2022 e area starts. 11/29/2022 eit fence prior to the inspecti 11/29/2022 eith fence prior to the inspecti 11/4/2022 e when paving begins. 11/4/2022 ed waste storage area on-sicontinue to monitor.	Active I tanker as of 12/2 Pending Pending Active On on 11/29/22. Active On on 11/29/22. Pending Pending Pending Pending te due to no wast	No No No No No e materials being

	"I certify, under penalty of law, that this document a direction or supervision in accordance with a syste properly gathered and evaluated the information supersons who manage the system or those persons the information submitted is, to the best of my known am aware that there are significant penalties for su of fines and imprisonment for knowing violations."	m designed to assure that qualified personnel abmitted. Based on my inquiry of the person or directly responsible for gathering the information, wledge and belief, true, accurate, and complete. I
Inspector Signature:	Braza M Zlazht	Reviewed By: