Inspector: Mike Jacobso	E&A - P2009		Stage	
Project Name:	Kenned	Kennedy Town Center		
For Week Ending:	2			
-				
Grading:	100%			
Sanitary Sewer:	100%			
Storm Sewer:	100%			
Paving: Seeding:	100%			
Utilities:	100%	1		
Overall Development:	24%			
RAIN FALL AMOUNTS	Amount in inches	Date inspected	-	
VAINT ALL AMOUNTO	7 till Gallet III III Glieb	Date inspected	Wee	
Sunday:	0.00"			
Monday	0.01"			
Tuesday	0.00"	01/13/09		
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"		Wee	
Sunday:	0.00"			
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday Saturday	0.00" 0.01"			
	0.01		Wee	
Sunday:	0.05"			
Monday	0.02"			
Tuesday	0.00"			
Wednesday Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
			Week	
Sunday:	0.00"; 0.00"			
Monday Tuesday	0.00"; 0.12" 0.00"; 0.00"			
Wednesday	0.00"; 0.00"			
Thursday	0.00"; 0.00"			
Friday	0.00"; 0.36 "			
Saturday	0.00"; 0.00"			
	late			
O a manufactura	None.			
Complaints:				
Construction Sequencing	n:			
Which portion(s) (i.e. drainage l	basins) of the site have had a tempo	orary or permanent cessation of gra	ading, earthwork, or grou	
disturbance in the last 14 days	?			
Entire Site, Grading was co	ompleted and entire site was se	eeded Fall 2006.		
Which portion(s) (i.e. drainage I	basins) of the site do not have gradi	ng, earthwork, or ground disturbar	ce scheduled in the next	
days?:	•	-		
Entire Site, Grading was co	ompleted and entire site was se	eeded Fall 2006.		
-				
What temporary or permanent	stabilization measures listed in this	section are being implemented?		
	zed entrance, Paved streets (1		2007)	
	111101100, 1 0100 0110010 (1	5, 2551 j, 1 avod chilanoc (11/	/	

Comments:

Site is stabilized with vegetative cover. Site idle.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1) No maintenance is required in the BMP section.

	_		Projected	.		Description of Maintenance/Activity
Unique Name	Туре	Location	Install Date	Status	Maintenance	Maintenance/Activity
		N41d00m00s				Repairs
CE A	Construction Entrance	W96d00m00s		Removed	No	Needed/Planned:
Current Condition:	Removed paved entrance					
DD 4	Consta	N41d00m00s	In Diago	A -4i	Nie	
DD 1 Current Condition:	Swale Good Condition - Partially re	W96d00m00s	In Place	Active	No	-
Current Condition.	Good Condition - Partially II	I	g or street.			1
		N41d00m00s				
DD 2	Swale	W96d00m00s		Removed		
Current Condition:	Removed due to paving of	street.				
		N41d00m00s				
SB A	Sediment Basin	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - 19% filled					
	Cleaned out 10/2007 by Da	ve Hausman.				
		N41d00m00s				
SB B	Sediment Basin	W96d00m00s	10/6/2007	Active	No	
Current Condition:	Good Condition - 30% filled					
	-Cleaned out 10/2007 by D	1	1			
OF A	Cilk Farrage	N41d00m00s	In Diago	A =4:	Nie	
SF A Current Condition:	Silt Fence Good Condition	W96d00m00s	In Place	Active	No	+
ourrent condition.	Silt fence was backfilled and by Ed Jochim.	d a berm and area in	let was constructe	ed as of inspect	ion on 12/11/08	
		N41d00m00s				1
SF B	Silt Fence	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition Maintenance was complete	, ,	on 5/7/08 by CS.		<u></u>	
		N41d00m00s	- / /			
SF C Current Condition:	Silt Fence Good Condition	W96d00m00s	9/25/2006	Active	No	1
Current Condition:	Maintenance was complete		on 4/24/08 by CS.		_	
SF D	Silt Fence	N41d00m00s W96d00m00s		Removed		
Current Condition:	Silt Fence removed and div	1	in this area.			
		N41d00m00s				
STR	Street Cleaning	W96d00m00s		Active	No	
Current Condition:	Good Condition- No major s	signs of track off.				
SWPPP Sign	SWPPP Sign	Three signs on site.	8/8/2008	Active	No	
Current Condition:	Good Condition A sign has been installed at Ave entrances.				*	
nspector Signature:	State of Jawlan		Reviewed By:	Zadrany L	Jilde	