Inspector: Mike Jacobson	E&A - P200			Stage
Project Name:		r	2	
•	Kennedy Town Center			68147
For Week Ending:		3/8/2009		
Grading:	100%			
Sanitary Sewer:	100%			
Storm Sewer:	100%			
Paving:	100%			
Seeding:	100%			
Utilities:	100%			
Overall Development:	24%	1		
			1 1	
RAIN FALL AMOUNTS	Amount in inches	Date inspected		
	0.00			Wee
Sunday:	0.00"		<u> </u>	
Monday Fuosday	0.01" 0.00"			
Tuesday Wednesday	0.00"	<u> </u>	 	
Thursday	0.00			
Friday	0.41"			
Saturday	0.00"	1	1	
	· · · ·	·		Week
Sunday:	0.00"			
Monday	0.00"			
Fuesday	0.04"	08/04/09		
Wednesday	0.00"			
Thursday Friday	0.00 0.91"	08/07/09		
Saturday	0.00"	00/01/03		
Complaints:	None.			
Construction Sequencing Which portion(s) (i.e. drainage ba	: asins) of the site have had a tempo	prary or permanent cess	ation of grading, eart	hwork. or grou
disturbance in the last 14 days?				
Linute Site, Grading was cor	mpleted and entire site was se	ecueu Faii 2000.		
Which portion(s) (i.e. drainage ba days? :	asins) of the site do not have gradi	ing, earthwork, or ground	d disturbance schedu	lled in the nex
Entire Site, Grading was cor	mpleted and entire site was se	eeded Fall 2006.		
What temporary or permanent of	abilization measures listed in this	section are being imploy	mented?	
	ed entrance, Paved streets (1			-seed nart
the lot to west of SB B(4/200	09); Re-seeded the north eas d around the SB A and SB B(t corner of the lot whe		
Comments:				
Comments:	tive cover. Home constructio	n is active in the sout	h west corner of th	ne site.
Findings / Corrective Action				
Findings / Corrective Action	ons (Date): ence is damaged and will be i	removed Mike Staffa	rd was informed to	
maintenance by 8/14/09.		Choved. Wike Stall0		Somplete

2) Some maintenance is required in the BMP section.

Unique Name	Туре	Location	Projected Install Date	Status	Description of Maintenance/Activity:
CE A	Construction Entrance	N41d00m00s W96d00m00s		Removed	Repairs Needed/Planned:

Current Condition:	Removed paved entrance	1					
		N41d00m00s					
DD 1	Swale	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition - Partially removed due to paving of street.						
	Diversion ditch was redefi	ned prior to inspection	on 4/8/09 by M.E	. Collins.			
		N41d00m00s					
DD 2	Swale	W96d00m00s		Removed			
Current Condition:	Removed due to paving o			Removed			
		N41d00m00s					
SB A	Sediment Basin	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition - 21% fille	ed					
	Cleaned out 10/2007 by D	ave Hausman. Erosior	n maintenance wa	as completed prior	to inspect		
	on 4/8/09 by M.E. Collins.						
		N41d00m00s					
SB B	Sediment Basin	W96d00m00s	10/6/2007	Active	No		
Current Condition:	Good Condition - 10% fille	ed					
	Cleanout and riser mainte	nance was completed	on 4/1/09 by M.E	. Collins.			
		N41d00m00s					
SF A	Silt Fence	W96d00m00s	In Place	Active	Yes		
Current Condition:	Fair Condition- Partially re	emoved due to good ve	getation and a be	erm installed.			
	One area of lot level silt fence is damaged and needs to be repaired.						
	Mike Stafford was informed to complete maintenance by 8/14/09.						
	Mike Statford was informe	ed to complete mainten	ance by 8/14/09.				
		N41d00m00s					
SF B	Silt Fence	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition	ad prior to increation of	m 7/00/00 hu CC	for doveloper Mik	o Kuooro		
	Maintenance was complet		on 7722/09 by CS	tor developer with	e Kucera.		
05.0		N41d00m00s	0/05/0000	A			
SF C	Silt Fence	W96d00m00s	9/25/2006	Active	No		
Current Condition:	Good Condition Silt fence was repaired pri	ior to inspection on 7/8	100 by CS for Do	olopor Miko Kuco	aro.		
	Sill tence was repaired pri	-			ia.		
		N41d00m00s		Demovied			
SF D Current Condition:	Silt Fence Silt Fence removed and d	W96d00m00s	in this area	Removed			
Current Condition:	Sill Fence femoved and d	N41d00m00s	in this area.				
STR	Street Cleaning	W96d00m00s		Active	No		
Current Condition:	Good Condition- No major			Active	INU		
current condition.			1	Г Г			
SW/DDD Sign	SWPPP Sign	Two signs on site.	8/8/2008	Active	No		
SWPPP Sign Current Condition:	Good Condition	i wo signs on site.	0/0/2000	Active	INU		
Current Condition:	A SWPPP sign has been	installed at 10th & Cha	ndler Road and	22nd & Chandler I	Road		
	entrances.				loau		
					1		
		1	1	7. 1	1110		
pector Signature:	aprend Jawlow		Reviewed Bv:	Zachany K.	alel		