	E&A - P200	6.135.000		0:	
Inspector: Mike Jacobson				Stage	
Project Name:	Kenned	er	2		
For Week Ending:	2				
Grading:	100%				
Sanitary Sewer:	100%				
Storm Sewer:	98%				
Paving:	100%				
Seeding:	100%				
Utilities:	0%				
Overall Development:	13%				
RAIN FALL AMOUNTS	Amount in inches	Date inspected			
IVAINT ALL AMOUNTS	7 WHO GIRL III WONDO	Date inspected		Week	
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"	02/14/08			
Friday	0.00"	52/11/00			
Saturday	0.00"	1			
Daturday	0.00			Week 2	
Sunday:	0.01"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
Complaints:	None.				
disturbance in the last 14 days?	asins) of the site have had a temp		essation of grading, ear	thwork, or grou	
Which portion(s) (i.e. drainage bases 14 days? :	asins) of the site do not have grad	ling, earthwork, or gro	ound disturbance sched	luled in the next	
Entire Site, Grading was cor	mpleted and entire site was s	eeded Fall 2006.			
	abilization measures listed in this				
Seeding (Fall 2006), stabiliz	ed entrance, Paved streets (10/2007), Paved er	ntrance (11/2007)		
Comments:					
Comments:	<u> </u>				
Site is stabilized with veget	ative cover. No activity on site	e at time of last ins	pection.		
Findings / Corrective Action	ons (Date):				
Findings / Corrective Action	ons (Date):				
 No maintenance is requir 	ed in the BMP section.				

Unique Name	Туре	Location	Projected Install Date	Status		Description of Maintenance/Activity:
CE A	Construction Entrance	N41d00m00s W96d00m00s		Removed		Repairs Needed/Planned:
Current Condition:	Removed paved entrance				•	
SB A	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No	

Current Condition:	Good Condition - 6% filled					
	Cleanedout 10/2007 by D	ave Hausman.				
		N41d00m00s				
SB B	Sediment Basin	W96d00m00s	10/6/2007	Active	No	
Current Condition:	Good Condition - 15% fille	d				
	-Cleanedout 10/2007 by D	ave Hausman.				
		N41d00m00s				
SF A	Silt Fence	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition					
	-Maintenanced 10/29/07 b	y CS.				
		N41d00m00s				
SF B	Silt Fence	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition					
	-Maintenanced 6/26/07 by	developer.				
		N41d00m00s				
SF C	Silt Fence	W96d00m00s	9/25/2006	Active	No	
Current Condition:	Good Condition					
	-Maintenanced 5/22/07					
		N41d00m00s				
SF D	Silt Fence	W96d00m00s		Removed		
Current Condition:	Silt Fence removed and di	version ditch installed	in this area.			
·		N41d00m00s				
STR	Street Cleaning	W96d00m00s		Active	No	
Current Condition:	Good Condition - No major signs of track off.					
	11000			Todo 1 1	.1.)c	
ector Signature:	Status Jawson		Reviewed By: Zachary L. Jilk			