| | E&A - P20 | 06.135.000 | | |
|---|------------------------------------|-------------------------------------|-------------------------------|--|
| Inspector: Mike Jacobsor | | | Stage 3 | |
| Project Name: | Kenne | Kennedy Town Center | | |
| For Week Ending: | 1 | 68147 | | |
| Gradina | 100 | 0/ | | |
| Grading: Sanitary Sewer: | 100 | | | |
| Storm Sewer: | 100 | | | |
| Paving: | 100 | | | |
| Seeding: | 100 | | | |
| Utilities: | 100 | % | | |
| Overall Development: | 25 | % | | |
| RAIN FALL AMOUNTS | Amount in inches | Date inspected | | |
| | | | Week 1 | |
| Sunday: | 0.00" | | | |
| Monday | 0.00" | | | |
| Tuesday | 0.24" | | | |
| Wednesday | 0.22" | | | |
| Thursday | 0.00" | | | |
| Friday | 0.02" | | | |
| Saturday | 0.00" | | March 0/2 | |
| Sunday: | 0.00" | | Week 2/3 | |
| Monday | 0.00" | | | |
| Tuesday | 0.00" | | | |
| Wednesday | 0.47" | | | |
| Thursday | 0.84" | | | |
| Friday | 0.01" 0.06" | 10/23/09 10/24/09 | | |
| Saturday | 0.06 | 10/24/09 | Week 3 | |
| Sunday: | 0.00" | | THE COLOR | |
| Monday | 0.00" | | | |
| Tuesday | 0.00" | | | |
| Wednesday | 0.00" | | | |
| Thursday Friday | 0.70" 0.01" | 10/30/09 | | |
| Saturday | 0.00" | 10/30/09 | | |
| Call and y | | | Week 4/5 | |
| Sunday: | 0.00"; 0.00" | | | |
| Monday | 0.00"; 0.00" | | | |
| Tuesday Wednesday | 0.00"; 0.00" | | | |
| Thursday | 0.00"; 0.00" 0.00"; 0.00" | | | |
| Friday | 0.00"; 0.00" | | | |
| Saturday | 0.00"; 0.00" | | | |
| | None. | · · | | |
| Complaints: | _ | | | |
| | | | | |
| Construction Sequencing | | | | |
| Which portion(s) (i.e. drainage b disturbance in the last 14 days? | | porary or permanent cessation of g | grading, earthwork, or ground | |
| Entire Site, Grading was co | mpleted and entire site was | seeded Fall 2006. | | |
| Which portion(s) (i.e. drainage b days? : | asins) of the site do not have gra | iding, earthwork, or ground disturb | ance scheduled in the next 14 | |
| - | mpleted and entire site was | seeded Fall 2006. | | |
| | | | | |
| | | is section are being implemented? | | |
| | | (10/2007), Paved entrance (11 | | |
| the lot to west of SB B(4/20 installed(4/2009); Re-seede | | ast corner of the lot where the a | area inlet was | |

the lot to west of SB B(4/2009); Re-seeded the north east corner of installed(4/2009); Re-seeded around the SB A and SB B(4/2009)

Comments:

Comments:

Site is stabilized with vegetative cover. Home construction is completed in the south west corner of the site for now.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date): 1) No maintenance is required in the BMP section.

| Unique Name | Туре | Location | Projected Install Date | Status | Maintenance | Description of Maintenance/Activity |
|----------------------------|--|--------------------------|---------------------------|------------------|------------------|--|
| Onique Name | Туре | Location | instan Date | Status | Maintenance | |
| | | N41d00m00s | | | | Repairs |
| CE A | Construction Entrance | W96d00m00s | | Removed | No | Needed/Planned: |
| Current Condition: | Removed paved entrance | | | | Т | - |
| | Questa | N41d00m00s | L. Divers | A | N | |
| DD 1 Current Condition: | Swale Good Condition - Partially re | W96d00m00s | In Place | Active | No | - |
| Current Condition: | Diversion ditch was redefine | | | . Collins. | | |
| | | N41d00m00s | | | | |
| DD 2 | Swale | W96d00m00s | | Removed | | |
| Current Condition: | Removed due to paving of | street. | | | | |
| | | N41d00m00s | | | | |
| SB A | Sediment Basin | W96d00m00s | In Place | Active | No | - |
| Current Condition: | Good Condition - 22% filled Cleaned out 10/2007 by Da on 4/8/09 by M.E. Collins. | | n maintenance wa | as completed pri | or to inspection | |
| SB B | Sediment Basin | N41d00m00s W96d00m00s | 10/6/2007 | Active | No | |
| Current Condition: | Good Condition - 19% filled | | | | | |
| | Cleanout and riser maintena | ance was completed of | on 4/1/09 by M.E. | . Collins. | | |
| | | N41d00m00s | | | | |
| SF A | Silt Fence | W96d00m00s | In Place | Active | No | |
| Current Condition: | Good Condition- Partially re Maintenance was complete | 0 | 0 | | | |
| SF B | Silt Fence | N41d00m00s W96d00m00s | In Place | Active | No | |
| Current Condition: | Good Condition | | | (| | |
| | Maintenance was complete | | on 7/22/09 by CS | for developer iv | ike Kucera. | |
| | | N41d00m00s | | | | |
| SF C | Silt Fence Good Condition | W96d00m00s | 9/25/2006 | Active | No | - |
| Current Condition: | Silt fence was repaired prio | r to inspection on 7/8/ | /09 by CS for Dev | veloper Mike Ku | cera. | |
| SF D | Silt Fence | N41d00m00s W96d00m00s | | Removed | | |
| Current Condition: | Silt Fence removed and div | ersion ditch installed | in this area. | | | |
| | | N41d00m00s | | | | |
| STR | Street Cleaning | W96d00m00s | | Active | No | |
| Current Condition: | Good Condition- No major s | signs of track off. | | | | |
| SWPPP Sign | SWPPP Sign | Two signs on site. | 8/8/2008 | Active | No | |
| Current Condition: | Good Condition A SWPPP sign has been in entrances. | | | | • | |
| spector Signature: | apaleel Jawlom | | Reviewed By: | Zachany k | . filek | |