E&A - P2006.135.000										
Inspector: Mike Jacobson				Stage						
Project Name:	Kenned	r	3							
For Week Ending:	12		68147							
Grading:	100%									
Sanitary Sewer:	100%									
Storm Sewer:	100%									
Paving:	100%									
Seeding:	100%									
Utilities:	100%									
Overall Development:	25%									
RAIN FALL AMOUNTS	Amount in inches	Date inspected								
	0.00			Week 1						
Sunday:	0.00"									
Monday	0.00"									
Tuesday	0.00"									
Wednesday	0.00"									
Thursday	0.00"	11/19/09								
Friday	0.00"									
Saturday	0.00"			W1 0/0						
Sunday:	0.00"			Week 2/3						
Monday	0.00"									
Tuesday	0.63"									
Wednesday	0.00"	11/25/09								
Thursday	0.00"									
Friday	0.00"									
Saturday	0.00"									
				Week 3						
Sunday:	0.00"									
Monday	0.00"									
Tuesday Wednesday	0.00"									
Thursday	0.00"									
Friday	0.00"									
Saturday	0.00"									
				Week 4/5						
Sunday:	0.16"									
Monday	0.04"									
Tuesday	0.37"									
Wednesday	0.08"									
Thursday	0.00"									
Friday Saturday	0.00"									
Saturday	0.00									
	None.									
Complaints:										
Complainte:										
	ı									
Construction Sequencing:										
		rary or permanent cessa	ation of grading, eart	hwork, or ground						
Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?										
Entire Site, Grading was con	npleted and entire site was se	eded Fall 2006.								
Entire Site, Grading was completed and entire site was seeded Fall 2006.										
Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:										
Entire Site, Grading was completed and entire site was seeded Fall 2006.										

What temporary or permanent stabilization measures listed in this section are being implemented?

Seeding (Fall 2006), stabilized entrance, Paved streets (10/2007), Paved entrance (11/2007); Re-seed part of the lot to west of SB B(4/2009); Re-seeded the north east corner of the lot where the area inlet was installed(4/2009); Re-seeded around the SB A and SB B(4/2009)

Comments:
Comments:
Site is stabilized with vegetative cover. No activity on site as of last inspection.
Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1) No maintenance is required in the BMP section.

			Projected			Description of
Unique Name	Туре	Location	Install Date	Status	Maintenance	Maintenance/Activity
		N41d00m00s				Repairs
CE A	Construction Entrance	W96d00m00s		Removed	No	Needed/Planned:
Current Condition:	Removed paved entrance	VV 30000111003		Removed	140	Necuca/i laililea.
Guiront Gonation.	rtomovou pavou omanico	N41d00m00s				
DD 1	Swale	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - Partially re			7101170	110	
	Diversion ditch was redefine			. Collins.		
		N41d00m00s				
DD 2	Swale	W96d00m00s		Removed		
Current Condition:	Removed due to paving of s		•	T	1	
		N41d00m00s				
SB A	Sediment Basin	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - 22% filled					
	Cleaned out 10/2007 by Davon 4/8/09 by M.E. Collins.	ve Hausman. Erosior	n maintenance wa	as completed pri	or to inspection	
	on 4/6/09 by M.E. Collins.					
		N41d00m00s				
SB B	Sediment Basin	W96d00m00s	10/6/2007	Active	No	
Current Condition:	Good Condition - 19% filled					
	Cleanout and riser maintena		on 4/1/09 by M.E	. Collins.	1	
		N41d00m00s				
SF A	Silt Fence	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition- Partially re					
	Maintenance was completed		T 6/17/09 by Wilk	le Stallolu.	1	
SF B	Silt Fence	N41d00m00s W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition	W 9000011100S	III Flace	Active	INO	1
Current Condition.	Maintenance was completed					
	mamoranee was sempleted	N41d00m00s	T		1	-
SF C	Silt Fence	W96d00m00s	9/25/2006	Active	No	
Current Condition:	Good Condition	VV 90000111005	9/23/2000	Active	INU	
our cit condition.	Silt fence was repaired prior	to inspection on 7/8	/09 by CS for Dev	veloper Mike Ku	cera.	
		N41d00m00s	1			
SF D	Silt Fence	W96d00m00s		Removed		
Current Condition:	Silt Fence removed and dive		in this area.	rtomovou		1
		N41d00m00s				
STR	Street Cleaning	W96d00m00s		Active	No	
Current Condition:	Good Condition- No major s	igns of track off.	•		1	
SWPPP Sign	SWPPP Sign	Two signs on site.	8/8/2008	Active	No	
Current Condition:	Good Condition	i wo signs on site.	0/0/2000	7.0076	INO	1
	A SWPPP sign has been in:	stalled at 19th & Cha	indler Road and	22nd & Chandle	r Road	
	entrances.					
	11000			— , ,	4116	
pector Signature:	destect Jawson		Reviewed By:	Lachary L	. /lilel	