E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Erosion Control Specialist- Manager

ENGINEERING • PLANNING • FIELD SERVICES

Erosion Control Specialist- Manage		D0000 465 006			
	E&A - I	P2006.135.000			
Inspector: Mike Jacobson, CISEC					Stage
	Kennedy Town Center				3
Project Name:		NÉR110532			
•					
For Week Ending:		5/14/2011			
Project Location:	25th & Chandle	er Road- Bellevue, N	IE (Sarpy Count	y)	68147
	1	T	1		
Grading:	100%				
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	100%				
Seeding:	100%				
Jtilities:	100%				
Overall Development:	25%				
	1	1	1		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected			
					Weel
Sunday:	0.00"	ļ	ļ		
Monday	0.00"		<b></b>		
Tuesday	0.00"	<del> </del>	<del>                                     </del>		
Wednesday	0.00"	<del> </del>	<del> </del>		
Thursday Friday	0.90"	-	1		
Friday Saturday	1.26" Trace	04/16/11	1		
Saturday	Hace	04/10/11			
Sunday:	0.01"	04/17/11			
Monday	0.01"	0.,,			
Гuesday	0.65"	04/19/11			
Wednesday	0.00"	04/20/11			
Thursday	Trace				
Friday	0.02"				
Saturday	0.00"				
Sunday:	Trace				
Monday	0.43"				
Гuesday Vednesday	0.04" Trace				
Thursday	0.00"				
Friday	0.04"				
Saturday	0.03"				
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				-
Wednesday	Trace				
Thursday	0.03"	ļ	ļ		
Friday	0.00"		<b></b>		
Saturday	0.00"				
Sunday	0.00"				Weel
Sunday: Monday	0.00"	+	+		
Tuesday	0.00"	<del> </del>	<del> </del>		
Vednesday	0.98"	5/11/2011			
Thursday	0.43"	5/12/2011			
riday	0.00"				
Saturday	0.00"				
	None	<u> </u>		<u> </u>	
Complaints:					
		<u> </u>	l		
Construction Sequencing:	- Markey bank and a re-			and distant	be less 44 de la C
Which portion(s) (i.e. drainage basins) of the	e site have had a temporary or permai	nent cessation of grading	g, earthwork, or grou	ınd disturbance in t	ne last 14 days?
Entire Site Grading was sampled a	nd optire site was seeded E-II 0	2006			
intire Site, Grading was completed a	niu entine site was seeded Fall 2	.000.			

Which portion(s) (i.e. drainage b	pasins) of the site do not have	grading, earthwork, or ground dis	sturbance scheduled i	n the next 14 days?	:	
Entire Site, Grading was co	ompleted and entire site w	as seeded Fall 2006.				
What temporary or permanent s	tabilization measures listed in	this section are being implement	ed?			
0 ( //	,	ets (10/2007), Paved entrand a inlet was installed(4/2009)	, ,,		,	09); Re-
Comments:		·				

## Comments:

Site is stabilized with vegetative cover. Condo construction is active along 24th and 23rd Street in the Southwest section of the site.

## Findings / Corrective Actions (Date):

## Findings / Corrective Actions (Date):

- 1) There is some trash in a few areas and it needs to be cleaned up. Commercial Seeding was informed to complete maintenance by 4/25/11. Maintenance not completed as of inspection on 4/20/11 but contractor still has five more days to complete maintenance. Maintenance was completed prior to inspection on 5/12/11 by CS.
- 2) Some maintenance is required in the BMP section.

			Projected	I			
Unique Name	Туре	Location	Install Date	Status	Maintenance		
		N41d00m00s					
CE A	Construction Entrance	W96d00m00s		Removed	No		
Current Condition:	Removed paved entrance	W 9000011100S		Removed	INU		
Current Condition.							
DD 4	0 1	N41d00m00s		A - 12	NI.		
DD 1	Swale	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition - Partially ren	, ,		Nalliaa			
	Diversion ditch was redefined	prior to inspection on	4/8/09 by M.E. C	Joiins.			
		N144 100 00 -					
<b>DD</b> 0	0.0010	N41d00m00s		D			
DD 2	Swale	W96d00m00s		Removed			
Current Condition:	Removed due to paving of str	eet.	ı				
POD A	Misc/Other	Lots 61-72		Removed			
Current Condition:	Silt fence was removed due to	o the lots being sodde	d prior to inspecti	ion on 5/12/2/11 b	y builder.		
POD B	Misc/Other	Lots 37-60	2/9/2011	Active	Yes		
Current Condition:	No BMP's needed at this time	e Active home constru	uction in POD.				
	There is some construction de	ebris on lot 60 and it n	eeds to be cleane	ed up.			
	Rod w/ Townhomes LLC was	informed to complete	maintenance by	4/15/11. Maintena	ance was complete		
	prior to inspection on 5/12/11 by builder.						
		N41d00m00s					
SB A	Sediment Basin	W96d00m00s	In Place	Active	No		
Current Condition:		W96d00III00S	III Place	Active	INO		
Current Condition:	Good Condition - 22% filled						
	Cleaned out 10/2007 by Dave Hausman. Erosion maintenance was completed prior to inspection on by M.E. Collins.						
	by M.E. Collins.						
		N41d00m00s					
SB B	Sediment Basin	W96d00m00s	10/6/2007	Active	No		
Current Condition:	Good Condition - 23% filled Cleanout and riser maintenance was completed on 4/1/09 by M.E. Collins.						
		East side of					
SF Al-1	Silt fence- Area Inlet	Kennedy Ave	4/27/2011	Pendina	Yes		
Current Condition:	Pending	10.11.00, 7.10					
	. Graining						
	Area inlet is partially buried and it needs to be cleaned out and silt fence needs to be installed around inlet.						
	purious position and it house to be vicalled out and off forter house to be installed distribution in terms in the house to be installed distribution.						
	Commercial Seeding was info	ormed to complete ma	intenance by 4/27	7/11. As of 4/21/1	1 Developer Mike		
	Kucera has not paid a previou		*				
	before they will complete this				pa)		
	, and the process with						
			I	1			
		N41d00m00s					
SF A	Silt Fence	W96d00m00s		Removed			
Current Condition:	Partially removed due to good						
	The remainder of silt fence was removed prior to inspection on 4/4/11 by Commercial Seeding.						
		N/41d00m000					
SF B	Silt Fence	N41d00m00s W96d00m00s		Removed			

Current Condition:	Silt fence run was removed due to good vegetation and no activity in the area at this time prior to inspection on 3/24/10 by CS. Note: Silt fence may need to be reinstalled once there is construction activity in the area.						
SF C	Silt Fence	N41d00m00s W96d00m00s		Removed			
Current Condition:	Silt fence run was removed of	Silt fence run was removed due to good vegetation prior to inspection on 3/24/10 by CS.					
SF D	Silt Fence	N41d00m00s W96d00m00s		Removed			
Current Condition:	Silt Fence removed and diversion ditch installed in this area.						
STR	Street Cleaning	N41d00m00s W96d00m00s		Active	No		
Current Condition:	Good Condition- No major signs of track off.						
SWPPP Sign	SWPPP Sign	Two signs on site.	8/8/2008	Active	No		
Current Condition:	Good Condition A SWPPP sign has been ins Ave entrances.	stalled at 19th & Chandle	er Road, 22nd 8	Chandler Road	and 25th and Sautter		
Inspector Signature:	Lef Jawlan			Reviewed By:	Zachany R. Jilok		