E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com

E&A CONSULTING GROUP, INC

Erosion Control Specialist- Manage		ENG		
	E&A - I	P2006.135.000		
Inspector: Mike Jacobson, CISEC				Stage
	Ker	nnedy Town Center		3
Project Name:				
For Wook Ending:				
For Week Ending:	OF4h 9 Chandle	Carratus)	68147	
Project Location:	25th & Chandle	County)	00147	
Grading:	100%			
Sanitary Sewer:	100%			
Storm Sewer:	100%			
Paving:	100%			
Seeding:	100%			
Utilities:	100%			
Overall Development:	25%			
	2070	l l		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected		
TOTAL PROPERTY	Sant in toritio	Date Hopeoted		Week
Sunday:	0.00"			- Treek
Monday	Trace			
Tuesday	Trace			
Wednesday	Trace			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			Week
Sunday:	0.00"			Week
Monday	0.11"			
Tuesday	Trace	02/21/12		
Wednesday	0.01"			
Thursday	0.05"			
Friday	0.01"			
Saturday	0.00"			
Sunday:	0.00"			Week
Monday	0.00"			+
Tuesday	0.69"			
Wednesday	0.00"	02/29/12		
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
	0.00			Week
Sunday:	0.00"			
Monday Tuesday	0.00"			
Wednesday	Trace			
Thursday	0.00"			1
Friday	0.00"			
Saturday	0.00"			
				Week
Sunday:	N/A	N/A		
Monday	N/A	N/A		
Tuesday Wednesday	N/A N/A	N/A N/A		
Thursday	N/A	N/A		+
Friday	N/A	N/A		1
Saturday	N/A	N/A		1
	•			
Complaints:	None			
Construction Sequencing:		l		
Which portion(s) (i.e. drainage basins) of the	site have had a temporary or permar	nent cessation of grading, earthwork	, or ground disturbance in	the last 14 days?

Which portion(s) (i.e. drainage basins) of the	site do not have grading, earthwork,	or ground disturbance s	cheduled in the nex	t 14 days? :			
Entire Site, Grading was completed and entire site was seeded Fall 2006.							
What temporary or permanent stabilization m	easures listed in this section are bei	ing implemented?					
Seeding (Fall 2006), stabilized entrand seeded the north east corner of the lot							

Comments:

Condo construction is active along 23rd and 22nd Street in the Southwest section of the site.

As of inspection on 1/24/12 Lot 1 Kennedy Town Center Replat Four is being removed from the SWPPP.

As of 3/5/12 Lot 1 Kennedy Town Center Replat Three and lot 2 Kennedy Town Center Replat Three is being removed from the SWPPP.

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section.
- 2) There is some trash on lot 3 and it needs to be cleaned up. Developer Mike Kucera was informed to clean up by 2/28/12. Maintenance not

			Projected			
Unique Name	Туре	Location	Install Date	Status	Maintena	
		N41d00m00s				
CE A	Construction Entrance	W96d00m00s		Removed	No	
Current Condition:	Removed paved entrance		I.			
		N41d00m00s				
DD 1	Swale	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - Partially rer					
	Diversion ditch was redefined	d prior to inspection on	4/8/09 by M.E. C	Collins.		
		N/44/100 00 -				
DD 2	Swale	N41d00m00s W96d00m00s		Removed		
Current Condition:	Removed due to paving of str			Removed		
Current Condition.	Tremoved due to paving or su	1001.				
POD A	Misc/Other	Lots 61-72		Removed		
Current Condition:	Good Condition-	1	I			
	Silt fence check in the outlot	on the North side of lot	72 was removed	d during inspection	n on 11/22/11 b	
	inspector.					
POD B	Misc/Other	Lots 37-60	2/9/2011	Active	No	
Current Condition:		No BMP is installed on lots- Active home construction in POD.				
	Silt fence was removed from	Silt fence was removed from the lot prior to inspection on 8/12/11 by Rod w/ Townhomes LLC.				
		N41d00m00s				
SB A	Sediment Basin	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - 22% filled	·	•			
	Cleaned out 10/2007 by Dave by M.E. Collins.	Cleaned out 10/2007 by Dave Hausman. Erosion maintenance was country by M.E. Collins.				
		N41d00m00s				
SB B	Sediment Basin	W96d00m00s	10/6/2007	Active	No	
Current Condition:	Good Condition - 23% filled					
	Cleanout and riser maintenar		4/1/09 by M.E. C	ollins.		
		East side of				
SF AI-1	Silt fence- Area Inlet This is on lot 2 Kennedy Tow	Kennedy Ave	(0 /5 /4 0 /1 :	Removed	II.:. OMDE	
Current Condition:	This is on lot 2 Kennedy Tow	n Center replat 3 and a	as of 3/5/12 this i	ot was removed to	rom this SWPF	
		N41d00m00s				
SF A	Silt Fence	W96d00m00s		Removed		
Current Condition:	Partially removed due to goo					
	The remainder of silt fence was removed prior to inspection on 4/4/11 by Commercial Seeding.					
		N41d00m00s				
SF B	Silt Fence	W96d00m00s		Removed		
Current Condition:	Silt fence run was removed d					
	on 3/24/10 by CS. Note: Silt fence may need to be reinstalled once there is construction activity in the					
		N41d00m00s				
SF C	Silt Fence	W96d00m00s	L	Removed		
Current Condition:	Silt fence run was removed d		prior to inspectio	n on 3/24/10 by C	S.	
		N41d00m00s				
SF D	Silt Fence	W96d00m00s		Removed		

		N41d00m00s				
STR	Street Cleaning	W96d00m00s		Active	Yes	
Current Condition:	Fair Condition- 1) There is some minor signs of mud in the curb line along Kennedy Ave and it needs to be cleaned up. 2) The sidewalk just West of SB A along Chandler has some mud and it needs to be cleaned up. 3) There is some minor signs of track off coming from the active construction on lot 1 Replat 4 and it needs to be cleaned up. 1) Developer Mike Kucera was informed to clean up by 2/22/12. As of 3/7/12 the street with mud in the curb line has been removed due to replating of the lots in this area. 2) Developer Mike Kucera was informed to clean up by 2/22/12. Maintenance not completed as of last inspection. 3) Duane Watson w/ Village Builders was informed to clean up by 2/22/12. Street was cleaned up prior to inspection on 2/29/12 by Duane Watson w/ Village Builders.					
SWPPP Sign Current Condition:	SWPPP Sign	Two signs on site.	8/8/2008	Active	No	
Current Condition:	A SWPPP sign has been installed at 19th & Chandler Road, 22nd & Chandler Road and 25th and Sautter Ave entrances.					
Inspector Signature:			Reviewed By:	Zachany L. Jiluk		