· · · · · · · · · · · · · · · · · · ·							
	E&A - P200	6.135.000					
Inspector: Mike Jacobson			Stage				
Project Name:	Kenned	r 2					
For Week Ending:	5/24/2008						
		-					
Grading:	100%						
Sanitary Sewer:	100%						
Storm Sewer:	98%						
Paving: Seeding:	100%						
Utilities:	0%						
Overall Development:	13%						
•	•	•	<u>н</u>				
RAIN FALL AMOUNTS	Amount in inches	Date inspected					
• ·			Week				
Sunday: Mondov	0.00"	05/11/08					
Monday Tugodov	0.00"						
Tuesday Wednesday	0.00"	05/14/09					
Wednesday Thursday	0.00"	05/14/08					
Friday	0.00"						
Saturday	0.00"						
		·	Week 2				
Sunday:	0.00"						
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.00"						
Thursday Friday	0.27"	05/00/00					
Friday Saturday	1.05" 0.28"	05/23/08					
Complaints:	None.						
Construction Sequencing: Which portion(s) (i.e. drainage ba disturbance in the last 14 days? Entire Site, Grading was con	· · ·		sation of grading, earthwork, or grou				
Which portion(s) (i.e. drainage ba 14 days? : Entire Site, Grading was con			nd disturbance scheduled in the next				
What temporary or permanent sta	bilization measures listed in this	section are being imple	emented?				
Seeding (Fall 2006), stabilize							
	,	<i>,</i> ,	. ,				
Comments:							
Comments: Site is stabilized with vegetal Utility construction is active o	on site. Storm sewer construct		t 19th & Chandler Rd. entrance. a.				
Findings / Corrective Actio Findings / Corrective Actio 1) During inspection on 4/25, needs to be repaired by 5/2/(is still active in this area. Silt 2) Two area inlets need silt for few extra days was given due	ns (Date): ns (Date): /08 various lot corners have /08 or when utilities are comp fence maintenance to be co ence installed around them.	been damaged by ui leted. As of inspectio mpleted as soon as	ility construction contractor and on on 5/23/08 utility construction				

Hadama Maria	T	I ti	Projected	01-11-1	Malufaura	Description of Maintenance/Activity:		
Unique Name	Туре	Location	Install Date	Status	Maintenance	Maintenance/Activity.		
05.4		N41d00m00s				Repairs		
CE A Current Condition:	Construction Entrance Removed paved entrance	W96d00m00s		Removed	No	Needed/Planned:		
Current Condition.	Removed paved entrance					ł		
	Quark	N41d00m00s		A	N			
DD 1 Current Condition:	Swale Good Condition - Partially re	W96d00m00s	In Place	Active	No	+		
ourion condition.			9 0. 0. 000			+		
	Swele	N41d00m00s		Demoved				
DD 2 Current Condition:	Swale Removed due to paving of s	W96d00m00s street.		Removed		ł		
	<u> </u>	N41d00m00s						
SB A	Sediment Basin	W96d00m00s	In Place	Active	Yes			
Current Condition:	Condition: Good Condition - 11% filled Cleanedout 10/2007 by Dave Hausman.							
	Rip rap needs to be added to the outlet pipe. Mike Kucera was directed to complete maintenance by 6/3/08. A few extra days was given due to							
	the holiday weekend.							
05.5		N41d00m00s		A				
SB B Current Condition:	Sediment Basin Good Condition - 20% filled	W96d00m00s	10/6/2007	Active	No	$\frac{1}{2}$		
current condition.	-Cleanedout 10/2007 by Da							
		N41d00m00s						
SF A Current Condition:	Silt Fence Fair Condition	W96d00m00s	In Place	Active	Yes	-		
Current Condition:								
	1) One area is undermined just east of 19th & Chandler Rd. along Chandler Rd. Due to this being							
	a continuous problem in this							
	remain in current condition and than will be removed once the berm and area inlet construction is completed. 2) During inspection on 5/23/08 a few areas are undermined and needs to be backfilled and compacted. 1) MBC is directed to start this maintenance when storm sewer construction is active on site. During inspection on 5/23/08 MBC is actively doing storm sewer construction on chandler, but							
	this maintenance has yet to							
	2)Mike Kucera was directed to the holiday weekend.							
	to the holiday freekena.							
		N41d00m00s]		
SF B	Silt Fence	W96d00m00s	In Place	Active	No	ł		
Current Condition:	Good Condition Maintenance was completed prior to inspection on 5/7/08 by CS.							
		N41d00m00s				1		
SF C	Silt Fence	W96d00m00s	9/25/2006	Active	No	ļ		
Current Condition:	Good Condition							
	Maintenance was completed prior to inspection on 4/24/08 by CS.							
SF D	Silt Fence	N41d00m00s W96d00m00s		Removed				
Current Condition:	Silt Fence removed and div		in this area.		•	1		
		N41d00m00s						
STR Current Condition:	Street Cleaning Good Condition	W96d00m00s	l	Active	Yes	ł		
Surrent Condition:	Current Condition: Good Condition During inspection on 5/23/08 there was minor signs of runoff. Also one area of the sidewalk had minor signs of runoff.							
	Mike Kucera was directed to clean streets. Mike Kucera was also directed to clean sidewalk.							
					<u>, 1).</u>	+		
Inspector Signature:	of about Jawlow	J	Reviewed By:	Zachany k	, Jilel	ļ		