E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager E & A CONSULTING GROUP, INC.

ENGINEERING · PLANNING · ENVIRONMENTAL & FIELD SERVICES

Environmental Services Dept.	. Manager	ENGIN	EERING • PLANNING • ENVIRONM	VENTAL & FIELD SERVICES			
		E&A - P2006.135.0	00				
Inspector: Alex Emerson				Stage			
		Kennedy To	wn Center	3			
Project Name:		NER11	0532				
For Week Ending:		8/9/2014					
Project Location:	25th & Chandler Road- Bellevue, NE (Sarpy County)						
Project Location: 25th & Chandler Road- Bellevue, NE (Sarpy County) 68147							
Grading:		100%					
Sanitary Sewer:		100%					
Storm Sewer:		100%					
Paving:		100%					
Seeding:		100%					
Utilities:		100%					
Overall Development:		30%					
Overall Development:		30%					
	Amount in tenths						
RAIN FALL AMOUNTS	Amount in tentris	Date inspected	Weather Conditions	Maak 4			
Sunday:	0.00"			Week 1			
Monday.	0.00						
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"						
outurady	0.00			Week 2			
Sunday:	0.00"						
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.02"						
Saturday	0.00"						
				Week 3			
Sunday:	0.00"						
Monday	0.00"						
Tuesday	0.00"	07/29/14	80/57 Partly Cloudy				
Wednesday	0.00"						
Thursday	0.05"						
Friday	0.00"						
Saturday	0.00"						
Sunday	0.72"			Week 4			
Sunday:	0.73"	09/04/44	95/67 Dorth: Cloudy				
Monday Tuesday	0.13"	08/04/14	85/67 Partly Cloudy				
Wednesday	0.14" 1.77"						
Thursday	0.11"	08/07/14	78/68 Cloudy				
Friday	0.00"	00/07/14					
Saturday	0.04"						
				Week 5			
Sunday:	N/A	N/A	N/A				
Monday	N/A	N/A	N/A				
Tuesday	N/A	N/A	N/A				
Wednesday	N/A	N/A	N/A				
Thursday	N/A	N/A	N/A				
Friday	N/A	N/A	N/A				

Saturday	N/A	N/A	N/A		
	·	•			
	None				
Complaints:					
					r
					Į
Construction Sequencing:	the basis had a family and a second				144.4
Which portion(s) (i.e. drainage basins) of the	site have had a temporary or perma	nent cessation of grading	g, earthwork, or ground disturi	bance in the las	1 14 days?
Entire Site, Grading was completed an	nd entire site was seeded Fall 2	2006.			
Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :					
Entire Site, Grading was completed an	nd entire site was seeded Fall 2	2006.			
What temporary or permanent stabilization n	neasures listed in this section are be	ing implemented?			
Seeding (Fall 2006), stabilized entrance, Paved streets (10/2007), Paved entrance (11/2007); Re-seed part of the lot to west of SB B(4/2009); Re- seeded the north east corner of the lot where the area inlet was installed(4/2009); Re-seeded around the SB A and SB B(4/2009); The disturbed areas of the South section of lot 5 Kennedy Town Center Replat Three was re-seeded prior to inspection on 7/18/12; The West side slope of Basin B was hydro seeded (8/2012); The East side of Basin B was sodded 9/13/12; The West side of the R.O.W. along 19th Circle was seeded(10/10/12)					
Comments:					
Comments: One lot is under construction at this til	me. Dirt is being stockpiled on I	ots 10-11 and 81, wit	h a vegetated buffer.		
Findings / Corrective Actions (Date):				

Findings / Corrective Actions (Date): 1) Some maintenance is required in the BMP section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
	51	N41d00m00s			
CE A	Construction Entrance	W96d00m00s		Removed	
Current Condition:	Removed paved entrance				
		N41d00m00s			
DD 1	Swale	W96d00m00s	In Place	Active	No
Current Condition:	Good Condition - Partially removed due to paving of street.				
	Diversion ditch was redefined		4/8/09 by M.E. Collins.		
		N41d00m00s			
DD 2	Swale	W96d00m00s		Removed	
Current Condition:	Removed due to paving of stre				
		Lot 4 Kennedy			
Lot 4 Kennedy Town Center Replat		Town Center Replat			
Three	Silt Fence	Three	10/10/2012	Active	No
Current Condition:	Good Condition				
	Silt fence check was installed				
POD B	Misc/Other	Lots 28-44	2/9/2011	Active	No
Current Condition:	Good Condition-Inspector retied the silt fence during inspection on 7/29/14.				
POD C	Misc/Other	Lots 10-27	11/28/2012	Active	Yes
Current Condition:	Active-Concrete spoils were removed by Legacy Homes prior to inspection on 8/4/14. Lot 15 is staked for excavation as of inspection on 6/21/14. The lot is active as of inspection on 6/27/14. Legacy Homes was requested to install a silt fence check in the NE corner of lot 15 once the basement is excavated. Not done as of last inspection.				
POD D	Misc/Other	Lots 1-9	8/23/2013	Active	Yes

Current Condition:	Active- Lot 2,9 were sodded threat of runoff as of inspect		to inspection on 6/21/	/14. Concrete debri	s provides no	
	There is a disturbed area on lot 8 as of inspection on 6/21/14.					
	Legacy Homes was requested to install a silt fence check on the NE corner of lot 8 by 6/28/14. Not done as o last inspection.					
SB A	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No	
Current Condition:		Good Condition - 23% filled Cleaned out 10/2007 by Dave Hausman. Erosion maintenance was completed prior to inspection on 4/8/09 by M.E. Collins.				
		N41d00m00s				
SB B	Sediment Basin	W96d00m00s	10/6/2007	Active	No	
Current Condition:	Good Condition - 25% filled					
		Cleanout and riser maintenance was completed on 4/1/09 by M.E. Collins. The East side of the basin was sodded prior to inspection on 9/13/12 by Duane w/ Village Builders.				
	The East side of the basin V	N41d00m00s	ction on 9/13/12 by D	uane w/ village Bul	iders.	
SF A	Silt Fence	W96d00m00s		Removed		
Current Condition:			n installed.	Removed		
	Partially removed due to good vegetation and a berm installed. The remainder of silt fence was removed prior to inspection on 4/4/11 by Commercial Seeding.					
		N41d00m00s			5	
SF B	Silt Fence	W96d00m00s		Removed		
Current Condition:	Silt fence run was removed	Silt fence run was removed due to good vegetation and no activity in the area at this time prior to inspection				
	on 3/24/10 by CS. Note: Silt fence may need to be reinstalled once there is construction activity in the area.					
		N41d00m00s				
SF C	Silt Fence	W96d00m00s		Removed		
Current Condition:	Silt fence run was removed	N41d00m00s	prior to inspection on 3	3/24/10 by CS.		
SF D	Silt Fence	W96d00m00s		Removed		
Current Condition:	Silt Fence removed and div		is area	Kemoveu		
ourient condition.		N41d00m00s				
STR	Street Cleaning	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition-No major signs of trackoff. Runoff from lot 9 was cleaned by Legacy Homes prior to inspection on 6/27/14.					
SWPPP Sign	SWPPP Sign	Two signs on site.	8/8/2008	Active	No	
Current Condition:	Good Condition A SWPPP sign has been in SWPPP sign was removed	stalled at 22nd & Chandle		I Sautter Ave entrar	nces.	
pector Signature:	22			Reviewed By:	Ednary K.J	