E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager E & A CONSULTING GROUP, INC.

ENGINEERING · PLANNING · ENVIRONMENTAL & FIELD SERVICES

	E&	A - P2006.135.00	00		
Inspector: Alex Emerson					Stage
		Kennedy To	wn Center		3
Project Name:		NER11			
For Week Ending:		10/11/2014			
Project Location:	25th & Chandler Road- Bellevue, NE (Sarpy County)				68147
Grading:	10	0%			
Sanitary Sewer:	10	0%			
Storm Sewer:	10	0%			
Paving:	10	0%			
Seeding:	10	0%			
Utilities:	10	0%			
Overall Development:	3	0%			
	1	T			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions		
					Week 1
Sunday:	0.00"				
Monday	0.00"				
Tuesday Wednesday	0.19" 0.01"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.19"				
,					Week 2
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.01"				
Wednesday	0.01"				
Thursday Friday	0.00"				
Saturday	0.00"				
outurouy	0.00				Week 3
Sunday:	0.00"				
Monday	0.00"				
Tuesday	1.50"				
Wednesday	2.49"	10/01/14	76/61 Cloudy		
Thursday	0.05"				
Friday	0.00"				
Saturday					Week 4
Sunday:	0.00"				Week 4
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				MaaleE
Sunday:	N/A	N/A	N/A		Week 5
Monday	N/A	N/A	N/A N/A		
Tuesday	N/A	N/A	N/A		
Wednesday	N/A	N/A	N/A		
Thursday	N/A	N/A	N/A		
Friday	N/A	N/A	N/A		

Saturday	N/A	N/A	N/A		
	None				
Complaints:	-				
				1	1
Construction Sequencing:				ļ	Į
Which portion(s) (i.e. drainage basins) of the	site have had a temporary or perma	nent cessation of gradin	g. earthwork, or ground distur	hance in the las	t 14 days?
	· · · · · · · · · · · · · · · · · · ·				
Entire Site, Grading was completed a	nd entire site was seeded Fall 2	2006.			
					1
Which portion(s) (i.e. drainage basins) of the	, site de net heue greding, certhuerd	an analysis diaturkanaa .	a hadulad in the yeart of devel		
which portion(s) (i.e. drainage basins) of the	site do not have grading, earthwork	, or ground disturbance	scheduled in the next 14 days	r :	
Entire Site, Grading was completed a	nd entire site was seeded Fall 2	2006.			
What temporary or permanent stabilization r	neasures listed in this section are be	ing implemented?			
Seeding (Fall 2006), stabilized entran- seeded the north east corner of the lo		,			· /·
areas of the South section of lot 5 Ke		· · · ·		· · · ·	
B was hydro seeded (8/2012); The Ea			•		
		o, 10, 12, 110 11001 0			000000(10/10/12)
Comments:					-
Comments:					
One lot is under construction at this ti	me. Dirt is being stockpiled on	lots 10-11 and 81, wit	th a vegetated buffer.		
Findings / Corrective Actions (Date	• •	· ·	-		

Findings / Corrective Actions (Date): 1) Some maintenance is required in the BMP section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
		N41d00m00s				
CE A	Construction Entrance	W96d00m00s		Removed		
Current Condition:	Removed paved entrance					
		N41d00m00s				
DD 1	Swale	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - Partially removed due to paving of street.					
	Diversion ditch was redefined prior to inspection on 4/8/09 by M.E. Collins.					
		N41d00m00s				
DD 2	Swale	W96d00m00s		Removed		
Current Condition:	Removed due to paving of street.					
		Lot 4 Kennedy				
Lot 4 Kennedy Town Center Replat		Town Center Replat				
Three	Silt Fence	Three	10/10/2012	Active	No	
Current Condition:	Good Condition					
	Silt fence check was installed		,			
POD B	Misc/Other	Lots 28-44	2/9/2011	Active	No	
Current Condition:	Good Condition-Inspector retied the silt fence during inspection on 7/29/14.					
POD C	Misc/Other	Lots 10-27	11/28/2012	Active	Yes	
Current Condition:	Active-Concrete spoils were removed by Legacy Homes prior to inspection on 8/4/14.					
	Lot 15 is staked for excavation as of inspection on 6/21/14. The lot is active as of inspection on 6/27/14.					
	Legacy Homes was requested excavated. Not done as of last				ne basement is	
POD D	Misc/Other	Lots 1-9	8/23/2013	Active	No	
Current Condition:	Active- The distrubed area on lot 8 has established natural vegetation as of inspection on 8/22/14. No lots ar active in this POD.					
	O a dias and D a sin	N41d00m00s		A	Nie	
SB A	Sediment Basin	W96d00m00s	In Place	Active	No	

Current Condition:	Good Condition - 23% filled					
	Cleaned out 10/2007 by Dave Hausman. Erosion maintenance was completed prior to inspection on 4/8/09					
	by M.E. Collins.	N41d00m00s				
SB B	Sediment Basin	W96d00m00s	10/6/2007	Active	No	
Current Condition:	Good Condition - 25% filled	Weddenheed	10/0/2001	/1011/0	110	
	Cleanout and riser maintenance was completed on 4/1/09 by M.E. Collins.					
	The East side of the basin was sodded prior to inspection on 9/13/12 by Duane w/ Village Builders.					
		N41d00m00s				
SF A	Silt Fence	W96d00m00s		Removed		
Current Condition:	Partially removed due to good vegetation and a berm installed.					
	The remainder of silt fence		ection on 4/4/11 by 0	Commercial Seeding	J.	
		N41d00m00s				
SF B	Silt Fence	W96d00m00s		Removed		
Current Condition:	Silt fence run was removed					
	on 3/24/10 by CS. Note: Silt	fence may need to be rein	nstalled once there is	s construction activi	ty in the area.	
		N41d00m00s				
SF C	Silt Fence	W96d00m00s		Removed		
Current Condition:	Silt fence run was removed		ior to inspection on 3	3/24/10 by CS.		
	Silt Fence	N41d00m00s		Demonst		
SF D Current Condition:	Silt Fence removed and dive	W96d00m00s		Removed		
Current Condition:	Sill Ferice removed and divi	N41d00m00s	s alea.			
STR	Street Cleaning	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition-No major si	ons of trackoff. Runoff from		by Legacy Homes	prior to	
	inspection on 6/27/14.					
SWPPP Sign	SWPPP Sign	Two signs on site.	8/8/2008	Active	No	
Current Condition:	Good Condition	- · · ·				
	A SWPPP sign has been in:	stalled at 22nd & Chandler	Road and 25th and	Sautter Ave entran	ces.	
	SWPPP sign was removed	from 19th Street as of insp	pection on 3/28/12.			
	10_				_	
C				Reviewed By:	adrany K. J.	
spector Signature:					0 0	