E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

E & A CONSULTING GROUP, INC. ENGINEERING • PLANNING • ENVIRONMENTAL & FIELD SERVICES

Environmental Services Dept.			EERING • PLANNING • ENVIROI	NMENTAL & FIELD SERVICES	
		E&A - P2006.135.00	00		
Inspector: Alex Emerson				Stage	
		Kennedy To	wn Center	3	
Project Name:		NER11	0532		
For Week Ending:		1/10/2015			
Project Location:	2546	25th & Chandler Road- Bellevue, NE (Sarpy County)			
Project Location.	25111	& Chandler Road- Bell	evue, NE (Sarpy County)	68147	
Grading:		100%			
Sanitary Sewer:		100%			
Storm Sewer:		100%			
		<u> </u>			
Paving:		100%			
Seeding:		100%			
Utilities:		100%			
Overall Development:		30%			
			T T		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions		
				Week 1	
Sunday:	0.16"				
Monday	0.78"				
Tuesday	0.00"	12/16/14	28/18 Partly Sunny		
Wednesday	0.00"				
Thursday	0.02"				
Friday	0.00"				
Saturday	0.00"				
				Week 2	
Sunday:	0.00"				
Monday	0.59"				
Tuesday	0.22"	12/23/14	37/33 Cloudy		
Wednesday	0.02"				
Thursday	0.00"				
Friday	0.01"				
Saturday	0.00"				
	2.22			Week 3	
Sunday:	0.00"				
Monday	0.01"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00			Woods 4	
Sunday:	0.00"			Week 4	
Monday:	0.00"			-	
Tuesday	0.00"			+	
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
				Week 5	
Sunday:	N/A	N/A	N/A	- Week a	
Monday	N/A	N/A	N/A		
Tuesday	N/A	N/A	N/A		
Wednesday	N/A	N/A	N/A		
Thursday	N/A	N/A	N/A		
Friday	N/A	N/A	N/A		

Saturday	N/A	N/A	N/A		
	None				
Complaints:					
Construction Sequencing:					
Which portion(s) (i.e. drainage basins) of the	e site have had a temporary or pern	nanent cessation of gradin	ng, earthwork, or ground distur	bance in the las	st 14 days?
Entire Site, Grading was completed a	and entire site was seeded Fal	1 2006.			
Which portion(s) (i.e. drainage basins) of the	e site do not have grading, earthwo	ork, or ground disturbance	scheduled in the next 14 days	?:	
Entire Site, Grading was completed a	and entire site was seeded Fal	1 2006.			
What temporary or permanent stabilization	measures listed in this section are	being implemented?	•	•	•
Seeding (Fall 2006), stabilized entrar	nce, Paved streets (10/2007),	Paved entrance (11/20	007); Re-seed part of the le	ot to west of S	SB B(4/2009); Re-
seeded the north east corner of the le					
areas of the South section of lot 5 Ke	ennedy Town Center Replat Th	rree was re-seeded pri	or to inspection on 7/18/12	2: The West s	side slope of Basin
B was hydro seeded (8/2012); The E					
, =					
				Т	Т
Summary Questions:					
Are approved entrances and adjacent stree	ts being maintained adequately?				
Yes	3				
Are receiving waters adjacent to the project	t free of any significant signs of ero	osion or sediment that wou	uld be associated with the con-	struction activity	y?
Yes			T		_
				<u> </u>	
Checklist Questions:					
Are waste materials (concrete, consruction	material, hazardous, etc.) being ma	inaged properly?			
Yes			1		T
Is dust associated with the construction ac	tivity adequately controlled on the	site?	<u> </u>		
Yes	arry adequatery controlled on the c	ino.			
	T			1	T
Comments:	1		1		-1
Comments:					
No lots are under construction at this	s time. Dirt is being stockpiled	on lots 10-11 and 81, v	with a vegetated buffer.		
Findings / Corrective Actions (Date			<u> </u>		-
F. I. 10 15.					
Findings / Corrective Actions (Date	•				
11) Some maintenance is required in t	IND RIVIP SACTION				

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
		N41d00m00s				
CE A	Construction Entrance	W96d00m00s		Removed		
Current Condition:	Removed paved entrance					
		N41d00m00s				
DD 1	Swale	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - Partially removed due to paving of street.					
	Diversion ditch was redefined prior to inspection on 4/8/09 by M.E. Collins.					
		N41d00m00s				
DD 2	Swale	W96d00m00s		Removed		
Current Condition:	Removed due to paving of street.					
		Lot 4 Kennedy				
Lot 4 Kennedy Town Center Replat		Town Center Replat				
Three	Silt Fence	Three	10/10/2012	Active	No	
Current Condition:	Good Condition-Silt fence check was installed prior to inspection on 10/10/12 by CS.					
POD B	Misc/Other	Lots 28-44	2/9/2011	Active	No	
Current Condition:	Good Condition-Inspector retie	ed the silt fence during	g inspection on 7/29/14.			
POD C	Misc/Other	Lots 10-27	11/28/2012	Active	Yes	

	Let 4.4 wee disturbed by	construction on let 45	of increation or 40%	22/44		
	Lot 14 was disturbed during	construction on lot 15 as	s of inspection on 10/2	23/14.		
	Legacy Homes was requeste	ed to seed the disturbed	area by 11/6/14. Not	done as of last insp	ection.	
POD D	Misc/Other	Lots 1-9	8/23/2013	Active	No	
Current Condition:	Active- The distrubed area of active in this POD.	on lot 8 has established n	atural vegetation as	of inspection on 8/2	2/14. No	
SB A	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - 23% filled Cleaned out 10/2007 by Dav by M.E. Collins.	Cleaned out 10/2007 by Dave Hausman. Erosion maintenance was completed prior to inspection on 4				
		N41d00m00s				
SB B	Sediment Basin	W96d00m00s	10/6/2007	Active	No	
Current Condition:	Cleanout and riser maintena	Good Condition - 25% filled Cleanout and riser maintenance was completed on 4/1/09 by M.E. Collins. The East side of the basin was sodded prior to inspection on 9/13/12 by Duane w/ Village Builders.				
OF A	Oile Faran	N41d00m00s		Damand		
SF A Current Condition:	Partially removed due to goo	Silt Fence W96d00m00s Removed Partially removed due to good vegetation and a berm installed. The remainder of silt fence was removed prior to inspection on 4/4/11 by Commercial Seeding.				
		N41d00m00s	•			
SF B	Silt Fence	W96d00m00s		Removed		
Current Condition:	Silt fence run was removed on 3/24/10 by CS. Note: Silt	fence may need to be re				
SF C	Silt Fence	N41d00m00s W96d00m00s		Removed		
Current Condition:	Silt fence run was removed		rior to inspection on			
SF D	Silt Fence	N41d00m00s W96d00m00s		Removed		
Current Condition:	Silt Fence removed and dive		nis area.			
		N41d00m00s				
STR	Street Cleaning	W96d00m00s	In Place	Active	No	
O	Good Condition-No major signs of trackoff. Runoff from lot 9 was cleaned by Legacy Homes prior to inspection on 6/27/14.					
Current Condition:	1110pcction on 6/2//11.					
	SWPPP Sign	Two signs on site.	8/8/2008	Active	No	
SWPPP Sign Current Condition:		stalled at 22nd & Chandle	er Road and 25th and	1	Nonces.	