E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

**Engineering Answers** 

| Environmental Services Dept. I |   | P2006.135.00   | 10                 |        |  |
|--------------------------------|---|----------------|--------------------|--------|--|
| Inspector: Matthew Russell     | Lux   | 1 2000.100.00  |                    | Stage  |  |
| Project Name:                  | Kennedy Town Center<br>NER110532                            |                |                    | 3      |  |
| For Week Ending:               |   |                |                    |        |  |
| Project Location:              | 4/14/2018 25th & Chandler Road- Bellevue, NE (Sarpy County) |                |                    |        |  |
|                                | · · · · · · · · · · · · · · · · · · ·                       |                |                    |        |  |
| Grading:                       | 100%  |                |                    |        |  |
| Sanitary Sewer:                | 100%  |                |                    |        |  |
| Storm Sewer:                   | 100%  |                |                    |        |  |
| Paving:                        | 100%  |                |                    |        |  |
| Seeding:                       | 100%  |                |                    |        |  |
| Utilities:                     | 100%  |                |                    |        |  |
| Overall Development:           | 100%  |                |                    |        |  |
| RAIN FALL AMOUNTS              | Amount in tenths  | Date inspected | Weather Conditions |        |  |
| RAIN FALL AMOUNTS              | Amount in tentils   | Date Inspected | Weather Conditions | Week   |  |
| Sunday:                        | 0.00"   |                |                    | - Week |  |
| Monday                         | 0.00"   |                |                    |        |  |
| Tuesday                        | 0.00"   |                |                    |        |  |
| Wednesday                      | 0.00"   |                |                    |        |  |
| Thursday                       | 0.00"   |                |                    |        |  |
| Friday                         | 1.20"   |                |                    |        |  |
| Saturday                       | 0.00"   |                |                    | WI-    |  |
| Orași de co                    | 0.400   |                |                    | Week   |  |
| Sunday:                        | 0.12"   | 03/19/18       | Doin 54/22         |        |  |
| Monday                         | 0.09"   | 03/19/18       | Rain 51/33         |        |  |
| Tuesday                        | 0.07"   |                |                    |        |  |
| Wednesday                      | 0.00"   |                |                    |        |  |
| Thursday                       | 0.00"   |                |                    |        |  |
| Friday                         | 0.02"<br>0.75"  |                |                    |        |  |
| Saturday                       | 0.75  |                |                    | Week   |  |
| Sunday:                        | 0.00"   |                |                    | Week   |  |
| Monday                         | 0.23"   |                |                    |        |  |
| Tuesday                        | 0.00"   | 03/27/18       | P Cloudy 51/30     |        |  |
| Wednesday                      | 0.00"   | 00/2///0       | . cloudy clied     |        |  |
| Thursday                       | 0.01"   |                |                    |        |  |
| Friday                         | 0.00"   |                |                    |        |  |
| Saturday                       | 0.00"   |                |                    |        |  |
| <b>-</b>                       |   |                |                    | Week   |  |
| Sunday:                        | 0.00"   |                |                    |        |  |
| Monday                         | 0.00"   |                |                    |        |  |
| Tuesday                        | 0.00"   |                |                    |        |  |
| Wednesday                      | 0.00"   |                |                    |        |  |
| Thursday                       | 0.00"   |                |                    |        |  |
| Friday                         | 0.00"   |                |                    |        |  |
| Saturday                       | 0.00"   |                |                    |        |  |
|                                |   |                |                    | Week   |  |
| Sunday:                        | 0.00"   |                |                    |        |  |
| Monday                         | 0.00"   |                |                    |        |  |
| Tuesday                        | 0.00"   |                |                    |        |  |
| Wednesday                      | 0.00"   |                |                    |        |  |
| Thursday                       | 0.00"   |                |                    |        |  |

| Friday                                 | 0.00"                            |                           |                         |                       |                  |              |
|--|----------------------------------|---------------------------|-------------------------|-----------------------|------------------|--------------|
| Saturday                               | 0.02"                            |                           |                         |                       |                  |              |
| -                                      | •                                | •                         |                         |                       |                  |              |
| Complaints:                            | None                             |                           |                         |                       |                  |              |
|  |                                  | 1                         | 1                       |                       |                  |              |
| Construction Sequencing:               |                                  |                           |                         |                       |                  |              |
| Which portion(s) (i.e. drainage basins | s) of the site have had a tempo  | rary or permanent cessa   | tion of grading, earthw | ork, or ground distu  | rbance in the la | ast 14 days? |
| Entire Site, Grading was comple        | eted and entire site was se      | eeded Fall 2006. All a    | ctive lots are comp     | leted as of 11/27     | /17.             |              |
| , , , ,                                |                                  |                           |                         |                       | -                |              |
| Which portion(s) (i.e. drainage basins | s) of the site do not have gradi | ng, earthwork, or ground  | disturbance scheduled   | d in the next 14 days | s? :             |              |
| Entire Site, Grading was comple        | eted and entire site was se      | eeded Fall 2006. All a    | ctive lots are comp     | leted as of 11/27     | /17.             |              |
|  |                                  |                           |                         |                       |                  |              |
| What temporary or permanent stabilize  | zation measures listed in this s | section are being implem  | ented?                  | •                     |                  |              |
| Dense vegetation (2014). All ac        | tive lots are sodded (11/2       | 7/17).                    |                         |                       |                  |              |
|  | · ·                              |                           |                         |                       |                  |              |
| Summary Questions:                     |                                  |                           |                         |                       |                  |              |
| Are approved entrances and adjacent    | t streets being maintained ade   | quately?                  |                         |                       |                  |              |
| Yes                                    |                                  |                           |                         |                       |                  | •            |
|  |                                  |                           |                         |                       |                  |              |
| Are receiving waters adjacent to the   | project free of any significant  | signs of erosion or sedin | nent that would be asso | ociated with the con  | struction activ  | ity?         |
| Yes                                    |                                  |                           |                         |                       |                  |              |
|  |                                  |                           |                         |                       |                  |              |
| Checklist Questions:                   |                                  |                           |                         |                       |                  |              |
| Are waste materials (concrete, const   | ruction material, hazardous, et  | c.) being managed prope   | rly?                    |                       |                  |              |
| Yes                                    | <del></del>                      |                           |                         |                       |                  |              |
| Are waste materials (concrete, constr  | ruction material hazardous et    | c ) being managed prope   | rly2                    |                       |                  |              |
| Yes                                    | detion material, nazardous, et   | c., being managed prope   | ily:                    |                       |                  |              |
|  |                                  |                           |                         |                       |                  |              |
| Comments:                              | <u> </u>                         |                           | !                       |                       |                  |              |
| Comments:                              |                                  |                           |                         |                       |                  |              |
| The site is complete. All lots are     | e sodded. Future commerc         | cial lots may begin co    | nstruction at a later   | date.                 |                  |              |
| Findings / Corrective Actions          | (Date):                          |                           |                         |                       |                  |              |
| Findings / Corrective Actions          | (Date):                          |                           | ·                       |                       | ·                |              |
| 1) No maintenance is required a        | at this time.                    |                           |                         |                       |                  |              |

|                    | 1  |  |                           |               |                    |  |
|--------------------|--|--|---------------------------|---------------|--------------------|--|
| Unique Name        | Туре   | Location   | Projected Install Date    | Status        | Maintenance        |  |
| CW                 | Concrete Washout   | TBD  |                           | Removed       |                    |  |
| Current Condition: | Removed - Paving on site has   | Removed - Paving on site has ceased as of inspection on 11/6/17. |                           |               |                    |  |
| DD 1               | Swale  | East of SB A   | In Place                  | Active        | No                 |  |
| Current Condition: | Good Condition-The diversion   | ditch remains in plac  | ce on the east side of SB | A as of inspe | ection on 1/15/15. |  |
| Lot 4 Replat 3     | Silt Fence   | Lot 4 Replat 3   |                           | Removed       |                    |  |
| Current Condition: | Removed- this area is part of the Corwin Toyota SWPPP as of 7/30/16. See Corwin Toyota SWPPP for details.                          |  |                           |               |                    |  |
| Lot 81             | Concrete Washout   | Lot 81   |                           | Removed       |                    |  |
| Current Condition: | Removed- this area is part of the Corwin Toyota SWPPP as of 7/30/16. The concrete washout has been removed.                        |  |                           |               |                    |  |
| POD B              | Silt Fence   | Lots 28-44   |                           | Removed       |                    |  |
| Current Condition: | Removed - All lots were sodde  | Removed - All lots were sodded prior to inspection on 11/6/17.   |                           |               |                    |  |
| POD C              | Silt Fence   | Lots 10-27   |                           | Removed       |                    |  |
| Current Condition: | Removed - Bo with 4C Construction sodded lot 24 prior to inspection on 9/26/17. All lots in this pod are sodded.                   |  |                           |               |                    |  |
| POD D              | Silt Fence   | Lots 1-9   |                           | Removed       |                    |  |
| Current Condition: | Removed- Lot 2 was sodded by 4C Construction prior to inspection on 7/13/16. All lots in the Pod are now stabilized as of 7/13/16. |  |                           |               |                    |  |
| SB A               | Sediment Basin   | Lot 75   | In Place                  | Active        | No                 |  |
| Current Condition: | Good Condition - 23% filled  |  |                           |               |                    |  |
| SB B               | Sediment Basin   | Outlot A   | 10/6/2007                 | Active        | No                 |  |
| Current Condition: | Good Condition - 25% filled  |  |                           |               |                    |  |
| STR                | Street Cleaning  | In Place   | In Place                  | Active        | No                 |  |
| Current Condition: | Good Condition - All lots have been sodded and the streets were cleaned prior to inspection on 11/6/17.                            |  |                           |               |                    |  |

| SWPPP Sign           | SWPPP Notification Sign   | One Sign | 8/8/2008     | Active   | No |  |  |  |
|----------------------|---|----------|--------------|----------|----|--|--|--|
|                      | Good Condition-22nd and Chandler Rd. The SWPPP sign at 25th and Sautter Ave could not be located and will not be reinstalled as of inspection on 12/1/15. |          |              |          |    |  |  |  |
| Inspector Signature: | Dino  |          | Reviewed By: | Posts Si | 4) |  |  |  |