Inspector: Mike Jacobson	E&A - P200		Stage
Project Name:		y Town Center	2
-		•	
For Week Ending:	9	/27/2008	
<b>O</b> ue l'est	4000/		
Grading:	100%		
Sanitary Sewer:	100%		
Storm Sewer:	98%		
Paving:	100%		
Seeding:	100%		
Utilities:	75%		
Overall Development:	22%		
RAIN FALL AMOUNTS	Amount in inches	Date inspected	
		Date hispected	Wee
Sunday:	0.00"		Wet
Monday	0.00"		
Tuesday	0.00"	09/16/08	
Wednesday	0.00"		
Thursday	0.00"		
Friday	0.00"		
Saturday	0.00"		
			Week
Sunday:	0.00"		
Monday	0.45"	09/22/08	
Tuesday	0.01"		
Wednesday	0.00"		
Thursday	0.00"	09/25/08	
Friday	0.00"		
Saturday	0.00		
	None.		
Complaints:			
	-		
<b>Construction Sequencing</b>			
Which portion(s) (i.e. drainage b	asins) of the site have had a tempo	ary or permanent cessation of	of grading, earthwork, or grour
disturbance in the last 14 days?			
Entire Site, Grading was co	mpleted and entire site was se	eded Fall 2006.	
Which nortion(s) (i.e. drainage b	asins) of the site do not have gradir	a earthwork or ground dist	urbance scheduled in the next
days? :		ig, cartinioni, or ground alor	
Entire Site, Grading was co	mpleted and entire site was se	eded Fall 2006.	
	abilization measures listed in this s		
Seeding (Fall 2006), stabiliz	ed entrance, Paved streets (1	0/2007), Paved entrance	(11/2007)
Comments:			
Comments:			
Comments:			
	ative cover. Utility construction	is active on site but not	at the time of leat increativ
			al the time of tast inspecto

## Findings / Corrective Actions (Date):

1) A few lot corner silt fence was damaged by the utility company and needs to be replace. On 9/15/08 Developer Mike Kucera was emailed and informed that maintenance needs to be completed and was given the option to line up his own maintenance or to have us line up the maintenance for him. Once this is determined maintenance will be lined up accordantly.

2) Some maintenance is required in the BMP section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
		N41d00m00s				
CE A	Construction Entrance	W96d00m00s		Removed	No	
Current Condition:	Removed paved entrance	Weddolinood		Removed		
					1	
		N41d00m00s				
DD 1	Swale	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - Partially re	emoved due to paving	g of street.			
DD 2	Swale	N41d00m00s W96d00m00s		Removed		
Current Condition:	Removed due to paving of street.					
SB A	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - 17% filled					
	Cleaned out 10/2007 by Dav					
		N41d00m00s				
SB B	Sediment Basin	W96d00m00s	10/6/2007	Active	No	
Current Condition:	Good Condition - 28% filled					
	-Cleanedout 10/2007 by Da					
		N41d00m00s	L. Dissa	A	Mar	
SF A Current Condition:	Silt Fence Fair Condition	W96d00m00s	In Place	Active	Yes	
	continuous problem in this area an area inlet and a berm will be constructed. Silt fence to remain in current condition and than will be removed once the berm and area inlet construction is completed. MBC is directed to start this maintenance when storm sewer construction is active on site. During inspection on 5/23/08 MBC is actively doing storm sewer construction on Chandler Rd, but this maintenance has yet to be completed. MBC to remain on site until maintenance is completed. Due to the rains maintenance was unable to be completed; New completion date will be 6/12/08. Due to the rains maintenance was unable to be completed; New completion date will be 6/19/08. Due to the rains maintenance was unable to be completed; New completion date will be 6/27/08. Due to the rains maintenance was unable to be completed; New completion date will be 6/27/08. Due to the rains maintenance was unable to be completed; New completion date will be 6/27/08. Due to the rains maintenance was unable to be completed; New completion date will be 6/27/08. Due to the rains maintenance was unable to be completed; New completion date will be 6/27/08. Due to the rains maintenance was unable to be completed; New completion date will be 7/5/08. this was assigned to E&A Engineer Troy Shaven to create storm sewer construction plan to add inlet. Troy Shaven was let go by the company. As of 9/15/08 plans were assigned to E&A erosion control man					
		N41d00m00s				
SF B	Silt Fence	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition					
	Maintenance was completed		n 5/7/08 by CS.			
SF C	Silt Fence	N41d00m00s W96d00m00s	9/25/2006	Active	No	
Current Condition:	Good Condition Maintenance was completed		•	•		
SF D	Silt Fence	N41d00m00s W96d00m00s		Removed		
Current Condition:	Silt Fence removed and dive	ersion ditch installed	in this area.			

		N41d00m00s				
STR	Street Cleaning	W96d00m00s		Active	No	
Current Condition:	Good Condition- No major signs of track off.					
SWPPP Sign	SWPPP Sign	Three signs on site.	8/8/2008	Active	No	
Current Condition:	Good Condition A sign has been installed at Ave entrances.	the 19th & Chandler	Road, 22nd & Cł	nandler Road and	I 25th & Sautter	
Inspector Signature:	Jahard Jawlom		Reviewed By:	Zadhany k	. Jilde	