Inchestor: Zachary A. Blek CRESS (.194.000	Storo		
Inspector: Zachary A. Jilek, CPESC, (Itora Villas @ Waterford	Stage 3		
Project Name:	NI	Kiltera Villas @ Waterford			
For Week Ending:		6/13/2009			
Grading:	100%	6			
Sanitary Sewer:	1009				
Storm Sewer:	100%	6			
Paving:	100%				
Seeding:	1009				
Utilities: Overall Development:	100%				
Overall Development:	407	6			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected			
KAIN I ALL AMOUNTO		Date inspected	Week		
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.16"				
Wednesday	0.95"	05/13/09			
Thursday	0.01"	+			
Friday Saturday	0.01" 0.00"	05/16/09			
Jakuruay	0.00	03/10/09	Week 2		
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00" 0.03"				
Saturday	0.03		Week		
Sunday:	0.00"		Week		
Monday	0.00"				
Tuesday	0.12"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"	05/29/09			
Saturday	0.00"		VM = -1- 4/		
Sunday:	0.00", 0.34 "	None; 6/7/09	Week 4/		
Monday	0.04", 0.11"	6/1/09; None			
Tuesdav	0.10", 0.04"	0/1/00, 140110			
Wednesday	0.00", 0.00"				
Thursday	0.00", 0.00"				
Friday	0.00", 0.63 "				
Saturday	2.11 ", 0.00"	6/6/2009;6/13/09			
	Nama				
Complaints:	None				
- Complainto.					
Construction Sequencing:		<u> </u>			
	te have had a temporary or	permanent cessation of grading, earthwork, or gr	ound disturbance in the		
last 14 days?	to tables this in the control of	(at an 0/00/0000			
Entire Site, grading was completed prior	to taking this project of	ver on 8/28/2008.			
Which portion(s) (i.e. drainage basins) of the s	te do not have grading, ear	thwork, or ground disturbance scheduled in the n	ext 14 days? :		
Entire Cite and discuss accorded to	to taking this part of	(or on 9/29/2009			
Entire Site, grading was completed prior	to taking this project of	ver on 8/28/2008.			
What temporary or permanent stabilization me	asures listed in this section	are being implemented?			
Existing vegetation / Sod (8-2008), seed	on S.B.'B' (removed ba	asin) (4/09),			
Comments:					
Comments:					

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) Some silt fence is down and needs to be repaired on 155th St, North of Iowa. The silt fence belongs to Steve Faller with Landmark Enterprises, and he was requested to perform repairs by 11-14-08. Not completed as of last inspection, as of 2-3-09, some silt fence re-tied, and one large area is still down. Steve Faller reminded to complete by 3-27-09. He stated that the property has been sold to the bank, Steve Faller is still believed to be responsible for the maintenance. Not completed as of last inspection.
- 2) Some required maintenance in the BMP section.

			Projected Install					
Unique Name	Туре	Location	Date	Status	Maintenance			
	Construction	N41d11m25s						
CE 1	Entrance	W96d12m40s		Removed	No			
Current Condition:	Construction En	Construction Entrance paved prior to first inspection on 8/28/08.						
IF	Inlet Filters	9 inlet filters	8-28-2008	Active	Yes			
Current Condition:	Fair condition:		1 1 111		103			
Carroni Conanion.	. an containen							
	Two inlet filets a	Two inlet filets are falling into the curb inlet, and need to be repaired.						
	Commercial Sec	Commercial Seeding / Chad with Synergy were requested to perform repairs by 5-23-09.						
		Maintenance was completed prior to inspection on 6/13/09.						
	Sediment	N41D11M27						
S.B. B	Basin	w96D12M23S		Removed	No			
Current Condition:	Basin removed b	Basin removed by MJA Trucking, completed as of 12-12-08						
		N41d11m34s						
S.F. A	Silt Fence	W96d12m23s	12/3/2008	Active	No			
Current Condition:		Good Condition- Partially removed behind stabalized lots.						
	Silt fence remov	Silt fence removed by Commercial Seeding prior to inspection on 3-27-09.						
	Silt Fence	N41d11m34s						
S.F. B	around A.I.	W96d12m23s		Active	No			
Current Condition:	Good Condition							
	Silt fence repaired by Commercial Seeding prior to inspection on 12-10-08							
		N41d11m34s						
ST 1	Sediment Trap	W96d12m23s	8/26/2008	Removed	No			
Current Condition:	Permanent water	Permanent waterfall and pond						
		N41d11m34s						
STR	Streets	W96d12m23s	8/28/2008	Active	No			
Current Condition:		Good condition-No major signs of track off						
SWPPP signs	signs	1 sign	10/27/2008	Active	No			
Current Condition:	Good Condition-							
	Installed on 10-2	27-08 on 156th and Po	otter		•			
- Zach	ary L. Gilde		L	Zachany,	k Alde			
r Signature:	wing ~. your		Reviewed By:	2300 WILL	J. ywi-			