	P2008.	194.000	
Inspector: Patrick Pierce	Stage		
Project Name:	Kil	3	
For Week Ending:			
Grading:	100%	T T	
Sanitary Sewer:	100%		
Storm Sewer:	100%		
Paving:	100%		
Seeding:	100%		
Utilities:	100%		
Overall Development:	40%		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	
Sunday	0.00"		Week 1
Sunday: Monday	0.00"		
Tuesday	0.00"	<del>                                     </del>	
Wednesday	0.00"	<del>                                     </del>	
Thursday	0.00"		
Friday	0.00"		
Saturday	0.00"		
Sunday:	0.00"		Week 2
Monday	0.17"		
Tuesday	0.00"		
Wednesday	0.00"		
Thursday	0.00"		
Friday	0.02"		
Saturday	0.00"		
	- :		Week 3
Sunday:	0.00"		
Monday	0.00"	00/00/00	
Tuesday	0.00" 0.02"	09/29/09	
Wednesday Thursday	0.02"		
Friday	0.06"		
Saturday	0.00"		
	0.00		Week 4/5
Sunday:	0.00"		
Monday	0.29"		
Tuesday	0.16"		
Wednesday	0.00"		
Thursday	0.00"		
Friday	0.00"	<u> </u>	
Saturday	0.23"	1	
Complaints	None		
Complaints:			
Construction Consum:			
Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site h last 14 days?	ave had a temporary or p	permanent cessation of grading, earthwork, or gro	ound disturbance in the
Entire Site, grading was completed prior to	taking this project over	er on 8/28/2008.	
Which portion(s) (i.e. drainage basins) of the site d	o not have grading, eart	nwork, or ground disturbance scheduled in the ne	ext 14 days? :
Entire Site, grading was completed prior to			
- 2, ging inde descriptions prior to		T	
What temporary or permanent stabilization measur	es listed in this section :	gre being implemented?	
Existing vegetation / Sod (8-2008), seed on			
Comments:			
Comments:			
The site is currently idle.			

## Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1) No required maintenance in the BMP section.

			Projected Install					
Unique Name	Туре	Location	Date	Status	Maintenance			
	Construction	N41d11m25s						
CE 1	Entrance	W96d12m40s		Removed	No			
Current Condition:	Construction Entrance paved prior to first inspection on 8/28/08.							
IF	Inlet Filters	9 inlet filters	8-28-2008	Active	No			
Current Condition:	Good Condition This was comple	Good Condition This was complete prior to inspection on 9/3/09 by Commercial Seeding.						
	Sediment	N41D11M27						
S.B. B	Basin	w96D12M23S		Removed	No			
Current Condition:	Basin removed I	Basin removed by MJA Trucking, completed as of 12-12-08						
		N41d11m34s						
S.F. A	Silt Fence	W96d12m23s	12/3/2008	Active	No			
Current Condition:		Good Condition- Partially removed behind stabilized lots.						
		-Commercial Seeding Removed Full area prior to inspection on 8/7/09						
	Silt Fence	N41d11m34s						
S.F. B	around A.I.	W96d12m23s		Active	No			
Current Condition:		Good Condition Silt fence repaired by Commercial Seeding prior to inspection on 12-10-08						
		N41d11m34s						
ST 1	Sediment Trap	W96d12m23s	8/26/2008	Removed	No			
Current Condition:	Permanent waterfall and pond							
STR	Streets	N41d11m34s W96d12m23s	8/28/2008	Active	No			
Current Condition:	Good Condition- No major signs of track off							
SWPPP signs	signs	1 sign	10/27/2008	Active	No			
Current Condition:	Good Condition-							
	Installed on 10-2	27-08 on 156th and Pot	tter					
aspector Signature:			Reviewed By:	Zadrany	k. Jilde			