Inspector: Patrick Pierce	P2008	.194.000	Stage	
	V:	Kiltera Villas @ Waterford		
Project Name:	NI	3		
For Week Ending:				
Grading:	100%	6		
Sanitary Sewer:	100%	6		
Storm Sewer:	100%	6		
Paving:	100%			
Seeding:	1009			
Utilities:	1009			
Overall Development:	40%	6		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected		
Sunday:	0.00"		Week	
Sunday: Monday	0.00 0.05"	+		
Tuesday	0.05	+		
Wednesday	0.18"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
Sunday:	0.00"		Week	
Monday	0.00"	+ + + + + + + + + + + + + + + + + + + +		
Tuesday	0.00"			
Wednesday	0.64"			
Thursday	1.29"			
Friday	0.09"	10/23/09		
Saturday	0.02"			
			Week	
Sunday:	0.02"	10/25/09		
Monday	0.01"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday Friday	0.66" 0.02"	10/30/09		
Saturday	0.02	10/30/09		
Saturday	0.00		Week 4	
Sunday:	0.00"; 0.00"	11/1/2009; None		
Monday	0.00"; 0.00"			
Tuesday	0.00"; 0.00"			
Wednesday	0.00"; 0.00"			
Thursday	0.00"; 0.00"			
Friday	0.00"; 0.00"			
Saturday	0.00"; 0.00"			
	None			
Complaints:				
Construction Servers's				
. ()(	site have had a temporary or	permanent cessation of grading, earthwork	or ground disturbance in the	
last 14 days? Entire Site, grading was completed pri	ior to taking this project o	ver on 8/28/2008.		
Which portion(s) (i.e. drainage basins) of the	site do not have grading, ear	thwork, or ground disturbance scheduled in	the next 14 days? :	
Entire Site, grading was completed pri	ior to taking this project o	ver on 8/28/2008.		
Whattamanana	and the state of t	and help a lambage set of 10		
What temporary or permanent stabilization next stabilization next stabilization / Sod (8-2008), se				
Comments:				
Comments:				
The site is currently idle.				

## Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1) No required maintenance in the BMP section.

			Projected Install				
Unique Name	Туре	Location	Date	Status	Maintenance		
	Construction	N41d11m25s					
CE 1	Entrance	W96d12m40s		Removed	No		
Current Condition:	Construction Entrance paved prior to first inspection on 8/28/08.						
IF	Inlet Filters	9 inlet filters	8-28-2008	Active	No		
Current Condition:	Good Condition This was comple	Good Condition This was complete prior to inspection on 9/3/09 by Commercial Seeding.					
S.B. B	Sediment Basin	N41D11M27 w96D12M23S		Removed	No		
Current Condition:	Basin removed b	Basin removed by MJA Trucking, completed as of 12-12-08					
S.F. A	Silt Fence	N41d11m34s W96d12m23s		Removed			
Current Condition:		Removed by Commercial Seeding prior to inspection on 11/1/09					
	Silt Fence	N41d11m34s	T				
S.F. B	around A.I.	W96d12m23s		Active	No		
Current Condition:	Good Condition Silt fence repaire	Good Condition Silt fence repaired by Commercial Seeding prior to inspection on 12-10-08					
		N41d11m34s					
ST 1	Sediment Trap	W96d12m23s	8/26/2008	Removed	No		
Current Condition:	Permanent waterfall and pond						
STR	Streets	N41d11m34s W96d12m23s	8/28/2008	Active	No		
Current Condition:	Good Condition- No major signs of track off						
SWPPP signs	signs	1 sign	10/27/2008	Active	No		
Current Condition:	Good Condition- Installed on 10-2	27-08 on 156th and Po	otter				
				Zachany	k. Ailde		
spector Signature:	- Line		Reviewed By:		J		