	P2008.	194.000					
Inspector: Patrick Pierce	<u> </u>			Stage			
Project Name:	Kil	tera Villas @ Wa	terford	3			
For Week Ending:	ek Ending: 12/12/2009						
Grading:	100%						
Sanitary Sewer:	100%						
Storm Sewer:	100%						
Paving:	100%						
Seeding:	100%						
Utilities:	100%						
Overall Development:	40%						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected					
Sunday:	0.00"			Week 1			
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"						
				Week 2			
Sunday:	0.00"						
Monday	0.02"	11/23/09					
Tuesday	0.02"						
Wednesday	0.00"						
Thursday	0.00"						
Friday Saturday	0.00"						
Saturday	0.00"			Week 3			
Sunday:	0.00"			week 3			
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"						
				Week 4/5			
Sunday:	0.23"						
Monday	0.04"						
Tuesday	1.02"						
Wednesday Thursday	<b>0.15</b> " 0.00"						
Friday	0.00"	12/11/09					
Saturday	0.00"	14/11/03					
Julianuay	10.00	<u> </u>					
Complaints:	None						
			T				
Construction Sequencing:	<u> </u>	·	<u>'</u>				
Which portion(s) (i.e. drainage basins) of the site have h	nad a temporary or p	ermanent cessation of gradi	ng, earthwork, or ground	disturbance in the			
last 14 days? Entire Site, grading was completed prior to takin	ng this project over	er on 8/28/2008.					
Which portion(s) (i.e. drainage basins) of the site do not	t have grading, eartl	nwork, or ground disturbance	e scheduled in the next 14	days?:			
Entire Site, grading was completed prior to taking	ng this project over	er on 8/28/2008.					
	1						
What temporary or permanent stabilization measures list Existing vegetation / Sod (8-2008), seed on S.B							
Comments:							

## Comments:

The site is currently idle.

An inspection was not conducted on 12/9/09 due to very dangerous driving and winter conditions even though the perception was over a ½" due to heavy amounts of snow in the metro area. An inspection will be conducted as soon as conditions allow for each site. Please contact Zach Jilek w/ E&A Consulting Group, Inc. with any questions (402-895-4700).

A drive through inspection was conducted on 12/11/09. There did not appear to be any new maintenance on site, inspector will verify this upon next inspection or whenever the snow melts.

## Findings / Corrective Actions (Date):

## Findings / Corrective Actions (Date):

1) No required maintenance in the BMP section.

			Projected Install					
Unique Name	Туре	Location	Date	Status	Maintenance			
	Construction	N41d11m25s						
CE 1	Entrance	W96d12m40s		Removed	No			
Current Condition:	Construction En	Construction Entrance paved prior to first inspection on 8/28/08.						
IF	Inlet Filters	9 inlet filters	8-28-2008	Active	No			
Current Condition:	Good Condition							
	This was complete prior to inspection on 9/3/09 by Commercial Seeding.							
	Sediment	N41D11M27						
S.B. B	Basin	w96D12M23S		Removed	No			
Current Condition:	Basin removed by MJA Trucking, completed as of 12-12-08							
		N41d11m34s						
S.F. A	Silt Fence	W96d12m23s		Removed				
Current Condition:	Removed by Co	Removed by Commercial Seeding prior to inspection on 11/1/09						
	Silt Fence	N41d11m34s						
S.F. B	around A.I.	W96d12m23s		Active	No			
Current Condition:	Good Condition Silt fence repaire	Good Condition Silt fence repaired by Commercial Seeding prior to inspection on 12-10-08						
		N41d11m34s						
ST 1	Sediment Trap	W96d12m23s	8/26/2008	Removed	No			
Current Condition:	Permanent water	Permanent waterfall and pond						
·		N41d11m34s						
STR	Streets	W96d12m23s	8/28/2008	Active	No			
Current Condition:	Good Condition-	Good Condition- No major signs of track off						
SWPPP signs	signs	1 sign	10/27/2008	Active	No			
Current Condition:	Good Condition-			,,,,,,,				
34		27-08 on 156th and Po	tter					
				Tachana.	4 1:LJC			
1 n 0 m 1 m 1			Davidson d Davi	Zadrany,	C. you			
ctor Signature:			Reviewed By:					