E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com

E&A CONSULTING GROUP, INC.

Zachary A. Jilek, CPESC, CISEC Erosion Control Specialist- Manager

ENGINEERING • PLANNING • FIELD SERVICES

Inspector: Mike Jacobson, CISE	c			Stage		
		Kiltera Villas @ Waterford NER111205				
Project Name:						
For Week Ending:		1/14/2012				
Project Location:	144	144th and Ida Streets- Omaha, NE (Douglas County)				
Grading:	100%	1				
Sanitary Sewer:	100%					
Storm Sewer:	100%					
Paving:	100%					
Seeding:	100%					
Utilities:	100%					
Overall Development:	40%					
RAIN FALL AMOUNTS	Amount in inches	Date inspected				
				Week		
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.20" 0.18"					
Wednesday Thursday	0.00"		+			
Friday	0.00"					
Saturday	0.00"					
,				Week		
Sunday:	0.00"					
Monday	0.00"					
Гuesday	0.00"					
Wednesday	0.00"					
Thursday	0.01"					
Friday	0.00"					
Saturday	0.00"			Week		
Sunday:	0.00"			Week		
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.01"					
Saturday	0.06"					
	2.22			Week		
Sunday:	0.00"					
Monday	0.00"					
Tuesday Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
	0.00			Week		
Sunday:	0.00"					
Monday	0.00"	01/10/12				
Tuesday Wednesday	0.00"	01/10/12	+			
Vednesday Fhursday	Trace Trace					
Friday	0.00"					
Saturday	0.00"					
Complaints:	None					
piantoi						

Entire Site, grading was completed prior to taki	ng this project ove	er on 8/28/2008.					
Entire Site; McArdle completed regarding of the	e lots 12-18 along	155th Street as of 6/201	1.				
Which portion(s) (i.e. drainage basins) of the site do no	t have grading, earthy	work, or ground disturbance	scheduled in the next 14	days?:			
Entire Site, grading was completed prior to taki	ng this project ove	er on 8/28/2008					
Entire One, grading was completed prior to take	ng tino project ove	. 011 0/20/2000.					
Entire Site; McArdle completed regarding of the	e lots 12-18 along	155th Street as of 6/201	1.				
What temporary or permanent stabilization measures li							
Existing vegetation / Sod (8-2008), seed on S.E	3.'B' (removed bas	in) (4/09), Lots 11-18 wa	as re-seeded (6/2011)				
Comments:	I						
Comments:							
Home construction is active on lot 12.							
Findings / Corrective Actions (Date):							
Findings / Corrective Actions (Date):	e						
Some required maintenance in the BMP sec	tion.						
			Projected Install				
Unique Name	Туре	Location	Date	Status	Maintenance		
05.4	Construction	N41d11m25s		Damassad	N-		
CE 1 Current Condition:	Entrance Construction En	W96d12m40s htrance paved prior to fire	st inspection on 8/28/0	Removed	No		
Current Condition.	Construction En	illance pavea prior to ill	31 11300011011 011 0/20/0				
IF	Inlet Filters	9 inlet filters		Removed	No		
Current Condition:	Removed by Commercial Seeding prior to inspection on 04/01/10. These inlet filters might need to be re-installed on construction is active in this area again.						
	re-installed on o	construction is active in t	his area again.				
Lot 10	Silt Fence	Lot 10		Removed			
Current Condition:		prior to inspection on 1	1/3/11 by Steve Faller		les.		
			,				
Lot 11	Silt Fence	Lot 11		Removed			
Current Condition:		odded prior to inspection	on 5/12/11 by Landm				
	The straw wattle behind the lot in the outlot was removed prior to inspection on 8/7/11 by Steve Faller						
	w/ Landmark H	lomes.					
	Sediment	N41D11M27					
S.B. B	Basin	w96D12M23S	lata d a a af 40 40 00	Removed	No		
Current Condition:	Basin removed	by MJA Trucking, comp	leted as of 12-12-08				
SF A	Silt Fence	Behind lots 12 through	4/16/2011	Active	No		
Current Condition:		18 - Active home construc		Active	No		
	Maintenance was completed prior to inspection on 1/10/12 by Steve w/ Landmark Homes.						
	Silt Fence	N41d11m34s					
S.F. B	around A.I.	W96d12m23s		Removed			
Current Condition:	This silt fence w	vas removed prior to ins	pection on 07/07/10 du	ie to dense vegeta	tion.		
		N41d11m34s					
ST 1	Sediment Trap	W96d12m23s	8/26/2008	Removed	No		
Current Condition:	Permanent water	i i			T		
CTD	Ctrt-	N41d11m34s	0/20/2000	Λ at:	NI-		
STR Current Condition:	Streets Good Condition	W96d12m23s - No major signs of trac	8/28/2008 k off	Active	No		
CaCondition	2000 Sorialion				Ι		
SWPPP signs	signs	1 sign	10/27/2008	Active	No		
Current Condition:	Good Condition						
	Installed on 10-	27-08 on 156th and Pott	ter		. 1		
Inspector Signature: Arke &	Zadnany L. Jilde						
nspector Signature: Reviewed By:							