

E&A Consulting Group, Inc.  
 330 North 117th Street  
 Omaha, NE 68154-2509  
 tel 402.895.4700  
 fax 402.895.3599  
 www.eacg.com



E&A CONSULTING GROUP, INC.  
 ENGINEERING • PLANNING • FIELD SERVICES

Zachary A. Jilek, CPESC, CISEC  
 Erosion Control Specialist- Manager

**E&A - P2008.194.000**

Inspector: Mike Jacobson, CISEC		Stage 3
Project Name:	<b>Kiltera Villas @ Waterford NER111205</b>	
For Week Ending:	<b>8/11/2012</b>	
Project Location:	144th and Ida Streets- Omaha, NE (Douglas County)	<b>68007</b>

Grading:	100%			
Sanitary Sewer:	100%			
Storm Sewer:	100%			
Paving:	100%			
Seeding:	100%			
Utilities:	100%			
Overall Development:	40%			

RAIN FALL AMOUNTS	Amount in inches	Date inspected		
<b>Week 1</b>				
Sunday:	0.00"			
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
<b>Week 2</b>				
Sunday:	0.00"			
Monday	0.00"	07/23/12		
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
<b>Week 3</b>				
Sunday:	0.00"			
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
<b>Week 4</b>				
Sunday:	0.00"			
Monday	0.00"			
Tuesday	0.05"			
Wednesday	0.21"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.01"			
<b>Week 5</b>				
Sunday:	N/A	N/A		
Monday	N/A	N/A		
Tuesday	N/A	N/A		
Wednesday	N/A	N/A		
Thursday	N/A	N/A		
Friday	N/A	N/A		
Saturday	N/A	N/A		

Complaints:	None			

Construction Sequencing:				
--------------------------	--	--	--	--

Entire Site, grading was completed prior to taking this project over on 8/28/2008.

Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as of 6/2011.

**Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :**

Entire Site, grading was completed prior to taking this project over on 8/28/2008.

Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as of 6/2011.

**What temporary or permanent stabilization measures listed in this section are being implemented?**


Existing vegetation / Sod (8-2008), seed on S.B.'B' (removed basin) (4/09), Lots 11-18 was re-seeded (6/2011)

**Comments:**

**Comments:**  
Home construction is completed on lot 9 and 12. No activity on any lots during inspection.

**Findings / Corrective Actions (Date):**

**Findings / Corrective Actions (Date):**  
1) No required maintenance in the BMP section.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance
CE 1	Construction Entrance	N41d11m25s W96d12m40s		Removed	No
<b>Current Condition:</b>	Construction Entrance paved prior to first inspection on 8/28/08.				
IF	Inlet Filters	9 inlet filters		Removed	No
<b>Current Condition:</b>	Removed by Commercial Seeding prior to inspection on 04/01/10. These inlet filters might need to be re-installed on construction is active in this area again.				
IF 1-3	Inlet Filters	Street between lots 9 and 13	5/2/2012	Active	No
<b>Current Condition:</b>	Good Condition- Inlet filter is installed next to lot 13. Inlet Filters by lots 9 and 10 was removed prior to inspection on 7/23/12 by Steve w/ Landmark Homes.				
Lot 9	Silt Fence	Lot 9		Removed	
<b>Current Condition:</b>	Silt fence was removed by Steve with Landmark Homes prior to inspection on 6/11/12 due to the lot being prepped for sod. Lot was sodded prior to inspection on 7/23/12 by Steve w/ Landmark Homes.				
S.B. B	Sediment Basin	N41D11M27 w96D12M23S		Removed	No
<b>Current Condition:</b>	Basin removed by MJA Trucking, completed as of 12-12-08				
SF A	Silt Fence	Behind lots 12 through 18	4/16/2011	Active	No
<b>Current Condition:</b>	Good Condition- Dirt piled in the R.O.W. was removed from lot 12 and a inlet filter was installed in the inlet in front of lot 12 prior to inspection on 4/2/12 by Steve w/ Landmark Homes.				
S.F. B	Silt Fence around A.I.	N41d11m34s W96d12m23s		Removed	
<b>Current Condition:</b>	This silt fence was removed prior to inspection on 07/07/10 due to dense vegetation.				
ST 1	Sediment Trap	N41d11m34s W96d12m23s	8/26/2008	Removed	No
<b>Current Condition:</b>	Permanent waterfall and pond				
STR	Streets	N41d11m34s W96d12m23s	8/28/2008	Active	No
<b>Current Condition:</b>	Good Condition- No major signs of track off.				
SWPPP signs	signs	1 sign	10/27/2008	Active	No
<b>Current Condition:</b>	Good Condition- Installed on 10-27-08 on 156th and Potter				
<b>Inspector Signature:</b> 			<b>Reviewed By:</b> 