E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

E & A CONSULTING GROUP, INC.

ENGINEERING · PLANNING · ENVIRONMENTAL & FIELD SERVICES

Environmental Services Dept. Manager E&A - P2008.194.000 Stage Inspector: Tyler Wolfe Kiltera Villas @ Waterford NER111205 Project Name: 8/10/2013 For Week Ending: Project Location: 144th and Ida Streets- Omaha, NE (Douglas County) 68007 Grading: 100% Sanitary Sewer: 100% Storm Sewer: 100% Paving: 100% Seeding: 100% Utilities: 100% Overall Development: 40% Amount in inches Date inspected RAIN FALL AMOUNTS Sunday: 0.00" Monday 0.00" Tuesday 0.00" Wednesday 0.00" 0.00" Thursday Friday 0.00 Saturday 0.00' Sunday: 0.05" Monday 0.21" Tuesday Wednesday 0.00" Thursday Friday 0.00" Saturday 0.00' Sunday: 0.00" Monday 0.04" Tuesday 0.01" Wednesday 0.00" Thursday 0.11" Friday 0.09 Saturday 0.00" Sunday: 0.00" Monday 0.02" 08/05/13 Tuesday 0.70" Wednesday 0.00' 08/07/13 Thursday 0.03 Friday 0.00" Saturday 0.00" Sunday: N/A N/A Monday N/A Tuesday N/A N/A Wednesday N/A N/A Thursday N/A N/A Friday N/A N/A Saturday None Complaints: **Construction Sequencing:**

Entire Site, grading was completed prior to taking this project over on 8/28/2008.									
Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as of 6/2011.									
	1	I	 	1					
Which portion(s) (i.e. drainage basins) of the site do not h	l nave grading, earth	work, or ground disturbance	scheduled in the next 14 o	days?:					
Entire Site, grading was completed prior to taking this project over on 8/28/2008.									
Entire one, grading was completed prior to taking this project over on 0/20/2000.									
Entire Site; McArdle completed regarding of the I	lots 12-18 along	155th Street as of 6/201	1.						
	l								
What temporary or permanent stabilization measures listed in this section are being implemented? Existing vegetation / Sod (8-2008), seed on S.B.'B' (removed basin) (4/09), Lots 11-18 was re-seeded (6/2011)									
	_ (, 0, 1, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0,	, (,,,,,,,,,,,,							
Comments:									
Comments:									
Home construction is active on lot 13, 14 and 15.									
Findings / Corrective Actions (Date):									
Findings / Corrective Actions (Date):									
Some required maintenance in the BMP section	on.								
			Projected Install						
Unique Name	Type Construction	Location N41d11m25s	Date	Status	Maintenance				
CE 1	Entrance	W96d12m40s		Removed	No				
Current Condition:	Construction Er	trance paved prior to fir	st inspection on 8/28/0	8.					
IF	Inlet Filters	9 inlet filters		Removed	No				
Current Condition:			to inspection on 04/01						
	Removed by Commercial Seeding prior to inspection on 04/01/10. These inlet filters might need to be re-installed on construction is active in this area again.								
		3 installed along 155th							
IF 1-3	Inlet Filters	Street between lots 9 and 13	5/2/2012	Active	Yes				
Current Condition:		Inlet filter is installed ne			ere removed prior to				
	inspection on 7	/23/12.							
	Inlet filter full and needs cleaned out.								
	Landmark Homes was informed to complete maintenance by 6/7/13. Landmark Homes was reminded on 6/10/13 to clean out ASAP. Builder was called on 08/07/2013 and reminded to complete this ASAP.								
	Maintenance not completed as of last inspection. Maintenance not completed as of last inspection.								
Lot 13 Current Condition:	Misc./Other	Lot 13 te was removed prior to	inspection on 5/31/13	Removed	26				
Current Condition.	Dirt and concre	te was removed phor to	1113pcction on 3/3 1/13	by Landmark Home					
Lot 14	Misc./Other	Lot 14		Removed					
Current Condition:		emptied prior to inspecti	on on 6/10/13 by Land	mark Homes.					
	Sediment	N41D11M27							
S.B. B	Basin	w96D12M23S	lata d a a af 40 40 00	Removed	No				
Current Condition:	Basin removed	by MJA Trucking, comp	leted as of 12-12-08	-					
SF A	Silt Fence	Behind lots 12 through 18	4/16/2011	Active	Yes				
Current Condition:	Fair Condition	.0	1, 10,2011	7.00.70					
	4) One area of the silt faces helpind lot 44 is design (decrees and it								
	 One area of the silt fence behind lot 14 is down/damage and it needs to be replaced. One area as of inspection on 04/19/2013 is full and the silt fence has been topped by silt. 								
	1) Steve w/ Landmark Homes was informed to complete maintenance by 4/15/13. Maintenance completion date extended to 4/17/13 due to rain event. This was not complete prior to inspection on								
	04/19/2013. Maintenance not completed as of inspection on 4/24/13 due to wet and muddy conditions,								
	therefore another seven is given to complete maintenance until 5/1/13. Maintenance not completed as of inspection on 5/5/13 due to wet and muddy conditions, therefore another seven is given to complete								
	maintenance until 5/10/13. Maintenance not completed as of last inspection due to wet and muddy								
	conditions, therefore another seven days is given to complete maintenance until 5/16/13. Builder was called on 08/07/2013 and reminded to complete this ASAP. Maintenance not completed as of last								
	inspection.								
	 Landmark Homes was called and requested to clean this out and repair it by 04/26/2013. Maintenance not completed as of inspection on 4/24/13 due to wet and muddy conditions, therefore and 								
			cuon on 4/24/13 due to	wet and muddy co	multions, therefore and				
S.F. B	Silt Fence around A.I.	N41d11m34s W96d12m23s		Removed					
Current Condition:		vas removed prior to ins	pection on 07/07/10 du		ion.				
	•								

ST 1	Sediment Trap	N41d11m34s W96d12m23s	8/26/2008	Removed	No			
Current Condition:	Permanent water	Permanent waterfall and pond						
STR	Streets	N41d11m34s W96d12m23s	8/28/2008	Active	No			
Current Condition:	Good Condition	Good Condition- No major signs of track off.						
SWPPP signs	signs	1 sign	10/27/2008	Active	No			
Current Condition:		Good Condition- Installed on 10-27-08 on 156th and Potter						
Inspector Signature:			Reviewed By:	Zadnany k	JildC			