E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

E & A CONSULTING GROUP, INC.

ENGINEERING • PLANNING • ENVIRONMENTAL & FIELD SERVICES

Inspector: Alex Emerson				Stage	
Project Name:	Kiltera Villas @ Waterford				
For Week Ending:		4/11/2015 144th and Ida Streets- Omaha, NE (Douglas County)			
Project Location:	144				
Brading:	100%	1			
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	100%				
eeding:	100%				
Jtilities:	100%				
Overall Development:	60%				
AIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions		
AINTALL AMOUNTS	A mount in mones	Date Inspected		We	
unday:	0.00"				
Monday	0.00"				
uesday Madra a davi	0.00"		<u> </u>		
Vednesday Thursday	0.00"		<u> </u>		
riday	0.00"	+			
Saturday	0.00"				
	0.00			We	
Sunday:	0.00"				
londay	0.00"				
uesday	0.44"				
Vednesday	0.00"				
hursday	0.00"				
riday	0.00"				
Saturday	0.00"				
Sundovi	0.00"			We	
Sunday: Aonday	0.00"				
luesday	0.00"				
Vednesday	0.43"				
hursday	0.33"				
Friday	0.00"	04/03/15	53/33 Partly Cloudy		
Saturday	0.00"				
				We	
Sunday:	0.00"	ļ			
londay	0.00"				
uesday	0.00"				
Vednesday	0.00"		<u> </u>		
hursday Friday	0.23" 0.00"				
Saturday	0.00"				
	0.00			We	
Sunday:	N/A	N/A	N/A		
londay	N/A	N/A	N/A		
uesday	N/A	N/A	N/A		
Vednesday	N/A	N/A	N/A		
hursday	N/A	N/A	N/A		
Friday	N/A	N/A	N/A		
aturday	N/A	N/A	N/A		

Complaints:	ļ						
Construction Sequencing:							
Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?							
Entire Site, grading was completed prior to taking this project over on 8/28/2008.							
Entire Site; McArdle completed regarding of the	ots 12-18 along	155th Street as of 6/20	11.				
Which portion(s) (i.e. drainage basins) of the site do not			ce scheduled in the next 1	4 days? :			
Entire Site, grading was completed prior to taking this project over on 8/28/2008. Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as of 6/2011.							
·							
What temporary or permanent stabilization measures list							
Existing vegetation / Sod (8-2008), seed on S.B. (10/5/2013).	B' (removed bas	sin) (4/09), Lots 11-18 w	as re-seeded (6/2011) Lots 12, 13, 14 we	ere sodded		
Summary Questions:							
Are approved entrances and adjacent streets being main	tained adequately?						
Yes							
Are receiving waters adjacent to the project free of any s	ignificant signs of	erosion or sediment that w	ould be associated with th	e construction activity	?		
Yes	ignitiount signs of			ie oonoli dollon dollony	•		
Checklist Questions:	anderes etc.) being	meneral menerals?					
Are waste materials (concrete, consruction material, haze Yes	ardous, etc.) being	managed property?					
Is dust associated with the construction activity adequat	ely controlled on th	ne site?					
Yes							
Comments:							
Comments: Home construction is active in the development.							
Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1) Some required maintenance in the BMP section.							
			Projected Install				
Unique Name	Туре	Location	Date	Status	Maintenance		
Lot 5	Silt Fence	Lot 5	2/4/2015	Pending	Yes		
Current Condition:	Pending Landmark Homes has stockpiled dirt from lot 6 on the lot as of inspection on 1/28/15.						
	Landmark Homes was requested to install SF on the back of the lot by 2/4/15. Not done as of last inspection. Landmark was reminded on 3/5/15.						
Lot 6	Silt Fence	Lot 6	2/4/2015	Pending	Yes		
Current Condition:	Pending						
	Landmark Homes has active construction on the lot and no BMP in place as of inspection on 1/28/15. Landmark Homes was requested to install SF on the back of the lot by 2/4/15. Not done as of last						
		ndmark was reminded o	n 3/5/15.				
Lot 26	Silt Fence	Lot 26	12/2/2014	Active	No		
Current Condition:		- Landmark tied SF bac					
Lot 29	Silt Fence	Lot 29	8/4/2014	Active	No		
Current Condition:	8/4/14.	I-SF check remains fror	n construction on lot 2	8 in the NW corner	as of inspection on		
Lot 33	Individual Lot	Lot 33	9/5/2014	Active	No		
Current Condition:	of inspection or	I-The sidewalks are in p 12/17/14. Landmark H e inspection on 12/17/14	omes stated that the le				

		N41d11m34s			
STR	Streets	W96d12m23s	8/28/2008	Active	No
Current Condition:	Good Condition-No major signs of trackout. Landmark Homes cleaned trackout on N 155th St prior to				
	inspection on 12/1/14.				
SWPPP signs	signs	1 sign	10/27/2008	Active	No
Current Condition:	Good Condition	-			
	Installed on 10-	27-08 on 156th and Pot	ter		
Inspector Signature:	\sim		Reviewed By:	Zachary A	C. Jilde