E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

Inguistan Niek Jantina		E&A - P2008.19		1	Stage
Inspector: Nick Jenkins					
	Kiltera Villas @ Waterford				3
Project Name:	NER111205  5/13/2017  144th and Ida Streets- Omaha, NE (Douglas County)				68007
For Week Ending:					
Project Location:					
Toject Location.	144til alid ida Streets- Ollialia, NE (Douglas County)				00007
Grading:	100%				
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	100%				
Seeding:	100%				
Utilities:	100%				
Overall Development:	75%				
			<u> </u>		
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions		
Sunday	0.15"				We
Sunday: Monday	0.15"		+		
ruesday	0.00"		+		
Nednesday Vednesday	0.00 0.02"		+		
Thursday	0.00"				
Friday	0.31"				
Saturday	0.20"	4/15/2017	Tstorm 76/59		
					We
Sunday:	0.00"				
Monday	0.00"				
Гuesday	0.30"				
Wednesday	0.59"	4/19/2017	Tstorm 72/49		
Thursday	0.00"				
Friday	0.40"				
Saturday	0.02"				
	0.07"				We
Sunday:	0.97"				
Monday	0.00" <b>0.15</b> "				
Tuesday Wednesday	0.15				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
	5.50				We
Sunday:	0.97"				
Monday	0.05"	05/01/17	Rain 54/35		
Tuesday	0.00"				
Wednesday	0.12"				
Гhursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
	0.00"				We
Sunday:	0.00"				
Monday	0.00"		+		
Tuesday Vednesday	0.00" <b>0.65</b> "	05/10/17	Tstorm 63/55		
rhursday Thursday	0.00"	03/10/17	15(0)111 63/99		
-riday	0.00"		+		
Saturday	0.00"		+		
	10.00				
	None				
Complaints:	None				

## Construction Sequencing: Vhich portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days? Entire Site, grading was completed prior to taking this project over on 8/28/2008. Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as of 6/2011 Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? Entire Site, grading was completed prior to taking this project over on 8/28/2008. Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as of 6/2011. What temporary or permanent stabilization measures listed in this section are being implemented? Existing vegetation / Sod (8-2008), seed on S.B.'B' (removed basin) (4/09), Lots 11-18 was re-seeded (6/2011) Lots 12, 13, 14 were sodded (10/5/2013). Summary Questions: Are approved entrances and adjacent streets being maintained adequately? Yes Checklist Questions: Yes Comments Comments: The development is inactive. Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1) See maintenance section for required maintenance. **Unique Name** Location **Projected Install Date** Status Maintenance Type Lot 4 Silt Fence Lot 4 Removed Removed - Landmark Homes sodded the lot prior to the 11/1/16 inspection. **Current Condition:** Lot 5 Silt Fence Lot 5 Removed Removed- Lot was sodded by Landmark Homes prior to 6/30/2016 **Current Condition:** Silt Fence Lot 6 Removed **Current Condition** Removed- Landmark Homes sodded prior to 7/16/2015. Lot 7 Silt Fence Removed Lot 7 **Current Condition:** Removed - Landmark Homes sodded the lot prior to the 11/1/16 inspection. 1/3/2016 Lot 8 Silt Fence Lot 8 Pending **Current Condition:** Active - Landmark Homes installed silt fence in the back and front of the lot prior to inspection on 4/15/17. Sediment needs removed from the adjacent lot and sidewalk. Landmark Homes was informed to complete by 4/22/17. Not done as of last inspection. Landmark Homes was reminded on 5/11/17. Lot 12 Lot 12 Silt Fence Removed **Current Condition** Removed-Landmark Homes sodded the lot prior to inspection on 12/15/15 Lot 13 Lot 13 Removed Silt Fence **Current Condition:** Removed-Landmark Homes sodded the lot prior to inspection on 12/15/15. Silt Fence Lot 26 Removed Removed- See lot 4 item as of 2/24/2016. **Current Condition:** Silt Fence Removed Lot 29 Lot 29 **Current Condition:** Removed- See lot 7 item as of 2/24/2016. Removed Lot 33 Individual Lot Lot 33 **Current Condition:** Removed- Due to the lot being sodded prior by Landmark Homes and vegetation filling in, silt fence is no longer needed as of 10/24/2015. N41d11m34s STR Streets W96d12m23s 8/28/2008 Active No Current Condition: SWPPP signs Good Condition - Landmark Homes cleaned the street prior to the 11/1/16 inspection. 10/27/2008 No signs 1 sign Active **Current Condition:** Good Condition-Installed on 10-27-08 on 156th and Potter 1.1 01

_