E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

	Environmental Services Dept. Manager E&A - P2008.194.000								
Inchestor: Chase Wickard		E&A - P2000.1	94.000	Stage					
Inspector: Chase Wickard		1,711.	,,, o.,, .	Stage					
		Kiltera Villas @ Waterford							
Project Name:		3							
For Week Ending:			7/8/2017						
Project Location:		144th and Ida Streets- Omaha, NE (Douglas County)							
	<u> </u>		,	68007					
Grading:	100%								
Sanitary Sewer:	100%								
Storm Sewer:	100%								
Paving:	100%								
Seeding: Utilities:	100% 100%								
Overall Development:	90%								
Overall Development.	9070	I							
DAIN FALL AMOUNTS	I	L	I 2						
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions	Wash					
Sunday:	0.00"			Week '					
Monday	0.00"	 							
Tuesday	0.01"								
Wednesday	0.36"								
Thursday	0.04"	1							
Friday	1.07"								
Saturday	0.01"								
				Week 2					
Sunday:	0.00"								
Monday	0.00"	06/19/17	83/62 Clear						
Tuesday	0.00"								
Wednesday	0.00"								
Thursday	0.00"								
Friday	0.00"								
Saturday	0.00"								
	2 221			Week :					
Sunday:	0.00"								
Monday	0.02"								
Tuesday	0.00"								
Wednesday	0.11" 0.37"								
Thursday Friday	0.07"								
Saturday	0.00"								
- Catulday	0.00			Week					
Sunday:	0.46"			- Vveek 4					
Monday	0.00"	 							
Tuesday	0.51"	-							
Wednesday	0.00"	07/05/17	Clear 86/65						
Thursday	0.00"	07/00/17	Clear 00/00						
Friday	0.00"	1	 						
Saturday	0.00"	 							
	10.00			Week !					
Sunday:	NA	NA		- Treek					
Monday	NA NA	NA NA							
Tuesday	NA	NA							
Wednesday	NA	NA							
Thursday	NA	NA							
Friday	NA	NA							
Saturday	NA	NA							
	•								
	None								
Complaints:									
				T					
		<u> </u>							

Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days? Entire Site, grading was completed prior to taking this project over on 8/28/2008. Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as of 6/2011. Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? Entire Site, grading was completed prior to taking this project over on 8/28/2008. Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as of 6/2011. What temporary or permanent stabilization measures listed in this section are being implemented? Existing vegetation / Sod (8-2008), seed on S.B.'B' (removed basin) (4/09), Lots 11-18 was re-seeded (6/2011) Lots 12, 13, 14 were sodded (10/5/2013). Summary Questions: Are approved entrances and adjacent streets being maintained adequately? Are receiving waters adjacent to the project Yes Checklist Questions: Comments: One house is under construction at this time. Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1) See maintenance section for required maintenance. 2) Due to construction on Lot 8; lot 9 was disturbed and has a stockpile sitting on it. During rain event silt migrated off the lot. Landmark will be directed to install a silt fence on lot 9 to control runoff. Installation to be completed by 5/24/17. Not completed as of inspection on 5/22/17 but the contractor still has two days to complete and due to multiple rain events would be allowed a extension until 5/27/17. Not done as of last inspection.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance		
Lot 4	Silt Fence	Lot 4		Removed			
Current Condition:	Removed - Lan	Removed - Landmark Homes sodded the lot prior to the 11/1/16 inspection.					
Lot 5	Silt Fence	Lot 5		Removed			
Current Condition:	Removed- Lot was sodded by Landmark Homes prior to 6/30/2016.						
Lot 6	Silt Fence	Lot 6		Removed			
Current Condition:	Removed- Landmark Homes sodded prior to 7/16/2015.						
Lot 7	Silt Fence	Lot 7		Removed			
Current Condition:	Removed - Landmark Homes sodded the lot prior to the 11/1/16 inspection.						
Lot 8	Silt Fence	Lot 8	1/3/2016	Active	Yes		
Current Condition:	Fair Condition	Fair Condition					
	Landmark Homes was informed to complete by 6/26/17.						
Lot 12	Silt Fence	Lot 12		Removed			
Current Condition:	Removed-Landmark Homes sodded the lot prior to inspection on 12/15/15.						
Lot 13	Silt Fence	Lot 13		Removed			
Current Condition:	Removed-Landmark Homes sodded the lot prior to inspection on 12/15/15.						
Lot 26	Silt Fence	Lot 26		Removed			
Current Condition:	Removed- See lot 4 item as of 2/24/2016.						
Lot 29	Silt Fence	Lot 29		Removed			
Current Condition:	Removed- See lot 7 item as of 2/24/2016.						
Lot 33	Individual Lot	Lot 33		Removed			
Current Condition:	Removed- Due to the lot being sodded prior by Landmark Homes and vegetation filling in, silt fence is no longer needed as of 10/24/2015.						
STR	Streets	N41d11m34s W96d12m23s	8/28/2008	Active	Yes		

Current Condition:	Fair Condition					
	Minor run off is present at Hanover and 155th Street.					
	Landmark was directed to clean up street by 5/18/17. Landmark was reminded to complete ASAP. Not completed as of the last inspection. Landmark was reminded on 6/20/17. Not done as of the last inspection.					
SWPPP signs	signs	1 sign	10/27/2008	Active	No	
Current Condition:	Good Condition- Installed on 10-27-08 on 156th and Potter					
Inspector Signature:		Reviewed By:	Put Sil			