E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Environmental Services Dept. Manager E&A - P2008.194.000								
Inspector: Chase Wickard		L&A - F2000.1	94.000		Stage			
Inspector: Chase Wickard								
	Kiltera Villas @ Waterford				3			
Project Name:		1	NER111205		_			
For Week Ending:		1/13/2018						
Project Location:		144th and Ida Streets- Omaha, NE (Douglas County)						
			·					
Grading:	100%							
Sanitary Sewer: Storm Sewer:	100% 100%							
Paving:	100%							
Seeding:	100%							
Utilities:	100%							
Overall Development:	90%							
		1		I				
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions					
					Week '			
Sunday:	0.00"							
Monday Tuesday	0.00"							
Wednesday	0.00"							
Thursday	0.00"							
Friday	0.00"							
Saturday	0.00"							
					Week 2			
Sunday:	0.00"							
Monday Tuesday	0.00"	12/19/2017	47/30 Clear					
Wednesday	0.00"	12/19/2017	47/30 Clear					
Thursday	0.07							
Friday	0.01							
Saturday	0.00"							
					Week 3			
Sunday:	0.00"							
Monday Tuesday	0.00"							
Wednesday	0.00"							
Thursday	0.00"							
Friday	0.00"							
Saturday	0.00"							
					Week 4			
Sunday:	0.00"							
Monday Tuesday	0.00"							
Wednesday	0.00"							
Thursday	0.00"							
Friday	0.00"							
Saturday	0.00"							
					Week 5			
Sunday:	0.00"							
Monday	0.00"							
Tuesday Wednesday	0.00"							
Thursday	0.00"							
Friday	0.00"							
Saturday	0.00"							
Saturday	0.00"							
	None							
Complaints:								
		1		I				
		1	1					

Which portion(s) (i.e. drainage basins) of the site Entire Site, grading was completed prior to			ding, earthwork, or ground distu	rbance in the last 14	days?
Entire Site; McArdle completed regarding of	-				
Which portion(s) (i.e. drainage basins) of the site Entire Site, grading was completed prior to			ice scheduled in the next 14 days	s?:	
chure Site, grading was completed prior to	taking this project ove	er on 8/28/2008.			
Entire Site; McArdle completed regarding o	of the lots 12-18 along	155th Street as of 6/207	11.		
What temporary or permanent stabilization meas					
Existing vegetation / Sod (8-2008), seed or	n S.B.'B' (removed bas	sin) (4/09), Lots 11-18 w	as re-seeded (6/2011) Lots	12, 13, 14 were soo	dded (10/5/2013).
Summary Questions:					
Are approved entrances and adjacent streets bei	ng maintained adequately	?			
Yes Are receiving waters adjacent to the project free	of any significant signs of	of arcsion or sodiment that	would be appreciated with the cor	actruction activity?	
Are receiving waters adjacent to the project free /es	of any significant signs c	of erosion of sediment that	would be associated with the col	Istruction activity :	
Chaoklist Quastions:					
Checklist Questions: Are waste materials (concrete, construction mate	erial, hazardous, etc.) beir	ng managed properly?			
/es					
s dust associated with the construction activity a res	adequately controlled on	the site?			
Comments:					
Comments:	time				
Two houses are under construction at this Findings / Corrective Actions (Date):	ume.				
Findings / Corrective Actions (Date):					
Some maintenance is required in the BMP	section.				
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
Lot 4	Silt Fence	Location Lot 4	Flojecteu instali Date	Removed	Wantenance
Current Condition:	Removed - Lan	dmark Homes sodded t	he lot prior to the 11/1/16 ins	pection.	
Lot 5	Silt Fence	Lot 5		Removed	
Current Condition: Lot 6	Removed- Lot v Silt Fence	was sodded by Landma Lot 6	rk Homes prior to 6/30/2016.	Removed	
Current Condition:		dmark Homes sodded p	rior to 7/16/2015	Reilloveu	
Lot 7	Silt Fence	Lot 7		Removed	
Current Condition:			he lot prior to the 11/1/16 ins		1
Lot 8	Silt Fence	Lot 8	he lot prior to the inspection	Removed	
Current Condition: Lot 9	Active Lot	Lot 9	12/19/2017	Active	No
Current Condition:	Active - Landn		struction on the lot prior t		
	0				
Lot 12	Silt Fence	Lot 12	e lot prior to inspection on 12	Removed	
Current Condition: Lot 13	Silt Fence	Lot 13	e for prior to inspection on 12	Removed	
Current Condition:			e lot prior to inspection on 12		·
Lot 21	Silt Fence	Lot 21	9/19/2017	Active	No
Current Condition:		spector previously recon s are now needed. The	nmended Landmark Homes i inspector will monitor.	install silt fence. Du	ie to the grading of
Lot 23	Silt Fence	Lot 23	11/3/2017	Active	No
Current Condition:		- Landmark Homes beg	an construction on the lot pr		
		es installed silt fence or need for more BMP's.			
Lot 26	will monitor the Silt Fence	need for more BMP's.		Removed	
Lot 26 Current Condition:	will monitor the Silt Fence Removed- See	need for more BMP's. Lot 26 lot 4 item as of 2/24/20		Removed	
Lot 26 Current Condition: Lot 29	will monitor the Silt Fence Removed- See Silt Fence	Lot 26 Lot 26 lot 4 item as of 2/24/20 Lot 29	16.		
Lot 26 Current Condition:	will monitor the Silt Fence Removed- See Silt Fence	need for more BMP's. Lot 26 lot 4 item as of 2/24/20	16.	Removed	
Lot 26 Current Condition: Lot 29 Current Condition:	will monitor the Silt Fence Removed- See Silt Fence Removed- See Individual Lot Removed- Due	Lot 26 Lot 26 lot 4 item as of 2/24/20 Lot 29 lot 7 item as of 2/24/20 Lot 33 to the lot being sodded	16.	Removed Removed Removed	
Lot 26 Current Condition: Lot 29 Current Condition: Lot 33	will monitor the Silt Fence Removed- See Silt Fence Removed- See Individual Lot Removed- Due	Lot 26 Lot 26 lot 4 item as of 2/24/20 Lot 29 lot 7 item as of 2/24/20 Lot 33 to the lot being sodded as of 10/24/2015.	16. 16.	Removed Removed Removed	
Lot 26 Current Condition: Lot 29 Current Condition: Lot 33	will monitor the Silt Fence Removed- See Silt Fence Removed- See Individual Lot Removed- Due longer needed a Streets	Lot 26 Lot 26 lot 4 item as of 2/24/20 Lot 29 lot 7 item as of 2/24/20 Lot 33 to the lot being sodded as of 10/24/2015. N41d11m34s W96d12m23s	16. 16. prior by Landmark Homes a 8/28/2008	Removed Removed Removed nd vegetation filling Active	in, silt fence is no
Lot 26 Current Condition: Lot 29 Current Condition: Lot 33 Current Condition:	will monitor the Silt Fence Removed- See Silt Fence Removed- See Individual Lot Removed- Due longer needed a Streets	Lot 26 Lot 26 lot 4 item as of 2/24/20 Lot 29 lot 7 item as of 2/24/20 Lot 33 to the lot being sodded as of 10/24/2015. N41d11m34s W96d12m23s	16. 16. prior by Landmark Homes a	Removed Removed Removed nd vegetation filling Active	in, silt fence is no

	Good Condition- Installed on 10-27-08 on 156th and Potter	
Inspector Signature:	\sim	Reviewed By: