E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Environmental Services Dept. Mana	agei	E&A - P2008.19	94.000				
Inspector: Chase Wickard		2001 1200011		Stage			
	Kiltera Villas @ Waterford						
Preiset Name:							
Project Name:							
For Week Ending:		7/14/2018 144th and Ida Streets- Omaha, NE (Douglas County)					
Project Location:		144th and Ida Stree	ets- Omana, NE (Douglas County)	68007			
Grading:	100%						
Sanitary Sewer:	100%						
Storm Sewer:	100%						
Paving: Seeding:	100% 100%						
Utilities:	100%						
Overall Development:	90%						
•							
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions				
	0.00"			Week 1			
Sunday: Monday	0.06"						
Tuesday	0.00"						
Wednesday	0.00"	06/13/18	79/60 Scattered Clouds				
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"			Week 0			
Sunday:	0.00"			Week 2			
Monday	1.38"						
Tuesday	2.39"						
Wednesday	1.22"	06/20/18	72/61 Rain				
Thursday	0.08"						
Friday	0.00"						
Saturday	0.00"			Week 3			
Sunday:	0.00"			Week 5			
Monday	0.73"						
Tuesday	0.01"						
Wednesday	0.00"	06/27/18	87/65 Clear				
Thursday	0.00"						
Friday Saturday	0.00" 0.61"						
	0.01			Week 4			
Sunday:	0.27"			Week +			
Monday	0.00"		1				
Tuesday	0.01"	7/3/2018	90/72 Clear				
Wednesday	0.17"						
Thursday Friday	0.03" 0.00"						
Saturday	0.00"						
				Week 5			
Sunday:	0.00"						
Monday	0.00"						
Tuesday	0.00"						
Wednesday Thursday	0.00"						
Friday	0.00 [*]						
Saturday	0.00"		1				
		•	•	•			
	None						
Complaints:							
<u> </u>			1				
	I	ļ					

Construction Sequencing: /hich portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days? Entire Site, grading was completed prior to taking this project over on 8/28/2008. Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as of 6/2011. Nhich portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? : Entire Site, grading was completed prior to taking this project over on 8/28/2008. Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as of 6/2011. What temporary or permanent stabilization measures listed in this section are being implemented? Existing vegetation / Sod (8-2008), seed on S.B.'B' (removed basin) (4/09), Lots 11-18 was re-seeded (6/2011) Lots 12, 13, 14 were sodded (10/5/2013). Summary Questions: cent streets being maintained adequately? entrances and a No, See BMP section Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Yes Checklist Questions: are waste materials (concrete, construction material, hazardous, etc.) being managed properly? Yes Is dust associated with the construction activity adequately controlled on the site? Yes Comments: Comments: Three houses are under construction at this time. Findings / Corrective Actions (Date) Findings / Corrective Actions (Date): Some maintenance is required in the BMP section. Projected Install Date Unique Name Location Maintenance Туре Status Lot 1 Replat 1 Silt Fence Lot 21 9/19/2017 Pending Yes Current Condition: Pendina-Silt fence is needed on the eastern side of the lot. Landmark Homes was informed to complete by 6/19/18. Not done as of the last inspection Lot 2 Silt Fence Lot 2 2/20/2018 Active No Active- Landmark Homes began construction on the lot prior to the inspection on 2/20/18. The inspector will **Current Condition:** monitor the need for more BMP's. Silt Fence Lot 3 Lot 3 Removed **Current Condition:** Removed - Landmark Homes sodded the lot prior to the inspection on 4/27/18. Silt Fence Lot 4 Removed Lot 4 Current Condition: Removed - Landmark Homes sodded the lot prior to the 11/1/16 inspection. Lot 5 Silt Fence Lot 5 Removed Removed- Lot was sodded by Landmark Homes prior to 6/30/2016 **Current Condition** Lot 6 Silt Fence Lot 6 Removed Removed- Landmark Homes sodded prior to 7/16/2015. **Current Condition:** Silt Fence Lot 7 Removed Lot 7 **Current Condition:** Removed - Landmark Homes sodded the lot prior to the 11/1/16 inspection. Removed Lot 8 Silt Fence Lot 8 **Current Condition:** Removed - Landmark Homes sodded the lot prior to the inspection on 7/27/17. Lot 9 Lot 9 Active Lot 12/19/2017 Active **Yes Current Condition:** Fair Condition - The inspector previously recommended silt fence in the front of the lot. Due to sidewalk installation silt fence is no longer needed on the front of the lot as of the inspection on 5/22/18 The silt fence needs repaired on the back of the lot. Landmark was informed to complete by 5/29/18. Not done as of the last inspection. Landmark Homes was reminded on 6/14/18. Lot 12 Silt Fence Lot 12 Removed Removed-Landmark Homes sodded the lot prior to inspection on 12/15/15. **Current Condition:** Silt Fence Removed Lot 13 Removed-Landmark Homes sodded the lot prior to inspection on 12/15/15. **Current Condition:** Silt Fence Lot 21 Removed Lot 21 **Current Condition:** Removed - The lot was mislabeled. The active lot is lot 1 R1

Pending

Current Condition:	Pending - Landmark Homes began construction on the lot prior to the inspection on 6/20/18.							
	 The dirt pile needs removed from the ROW. Silt fence needs installed on the eastern side of the lot. 							
	Landmark Homes was informed to complete by 7/4/18. Not done as of the last inspection. Landmark Homes was informed to complete by 7/4/18. Not done as of the last inspection.							
Lot 26	Silt Fence	Lot 26		Removed				
Current Condition:	Removed- See	lot 4 item as of 2/24/202	16.					
Lot 29	Silt Fence	Lot 29		Removed				
Current Condition:	Removed- See lot 7 item as of 2/24/2016.							
Lot 33	Individual Lot	Lot 33		Removed				
Current Condition:	Removed- Due to the lot being sodded prior by Landmark Homes and vegetation filling in, silt fence is no longer needed as of 10/24/2015.							
		N41d11m34s						
STR	Streets	W96d12m23s	8/28/2008	Active	Yes			
Current Condition:	Fair Condition -							
	The streets need cleaned in front of lot 1 and lot 23. Landmark Homes was informed to complete by 6/14/18. Not done as of the last inspection. Landmark Homes was reminded on 6/29/18.							
SWPPP Sign	SWPPP Sign	1 sign	10/27/2008	Active	No			
Current Condition:	Good Condition- Installed on 10-27-08 on 156th and Potter							
Inspector Signature:				Reviewed By:	Cato Sul			