E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC
Environmental Services Dept. Manager

Engineering Answers

Environmental Services Dept. Manage	er			ngineering Answers		
		E&A - P2008.19	4.000			
Inspector: Matthew Vanicek				Stage		
		3				
Project Name:		NER111205 5/11/2019				
For Week Ending:						
Project Location:		68007				
Cuadina	1 1000/	1				
Grading: Sanitary Sewer:	100%		+			
Storm Sewer:	100%					
Paving:	100%	5				
Seeding:	100%					
Utilities: Overall Development:	100% 97%					
Overali Development:	97%	0				
DAIN FALL AMOUNTS	A	Data in a satural	\\\+\\\\\\\\\\\\\\\\\\\\\\			
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions	Week		
Sunday:	0.00"			Week		
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.03"	4/17/2019	71/49 Rain			
Thursday Friday	0.00"					
Saturday	0.00"		+			
	0.00			Week		
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00" 0.48"					
Saturday	0.46			Week		
Sunday	0.01"			vveek		
Sunday: Monday	0.00"					
Tuesday	0.01"		+			
Wednesday	0.07"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.24"			111		
Sunday:	0.08"			Week		
Monday	0.08		+			
Tuesday	0.06"					
Wednesday	1.17"					
Thursday	0.00"	5/9/2019	54/40 Cloudy			
Friday Saturday	0.00" 0.44"					
Joanni day	0.44			Week		
Sunday:	N/A	N/A		Week		
Monday	N/A	N/A				
Tuesday	N/A	N/A				
Wednesday Thursday	N/A N/A	N/A N/A				
Friday	N/A N/A	N/A				
Saturday	N/A	N/A				
				•		
	None					
Complaints:						
		T		1		
Construction Sequencing:		1				

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire Site, grading was completed prior to taking this project over on 8/28/2008. Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as of 6/2011.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :

Entire Site, grading was completed prior to taking this project over on 8/28/2008. Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation / Sod (8-2008), seed on S.B.'B' (removed basin) (4/09), Lots 11-18 was re-seeded (6/2011) Lots 12, 13, 14 were sodded (10/5/2013).

Summary Questions:

Are approved entrances and adjacent streets being maintained adequately?

ceiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Checklist Questions:

crete, construction material, hazardous, etc.) being managed properly?

Is dust associated with the construction activity adequately controlled on the site?

Comments:

Comments:

One house is under construction at this time.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1. Some maintenance is required in the BMP section.
- 2. Lot 10 should be seeded/stabilized due to being disturbed from construction on lot 9. Landmark Homes was informed to complete by 8/31/18. Not done as of the last inspection. Landmark Homes was reminded on 9/26/18, 11/9/18, 3/16/19, 4/19/19

		1			I			
Unique Name	Type	Location	Projected Install Date	Status	Maintenance			
Lot 1 Replat 1	Silt Fence	Lot 21	•	Removed				
Current Condition:	Removed - Land	Removed - Landmark Homes sodded the lot prior to the inspection on 8/15/18.						
Lot 2	Silt Fence	Lot 2		Removed				
Current Condition:	Removed - Land	dmark Homes sodded th	e lot prior to the inspection or	8/22/18.				
Lot 3	Silt Fence	Lot 3	'	Removed				
Current Condition:	Removed - Land	dmark Homes sodded th	e lot prior to the inspection or	4/27/18.	!			
Lot 9	Active Lot	Lot 9		Removed				
Current Condition:			e lot prior to the inspection or		!			
Lot 10	Silt Fence	Lot 10	9/25/2019	Active	Yes			
	Landmark Home	The silt fence needs repaired/retied in the back of the lot. Landmark Homes was informed to complete by 10/2/18. Not done as of the last inspection. Landmark Homes was reminded on 11/9/18, 1/24/19, 3/16/19, 4/19/19						
Lot 23	Individual Lot	Lot 23	6/20/2018	Pending	Yes			
Current Condition:	Landmark Home Silt fence needs Landmark Home	Pending - Landmark Homes installed silt fence on the eastern side of the lot prior to the inspection on 7/29/1 Landmark Homes removed the silt fence to pour the driveway and sidewalk prior to the inspection on 4/17/1 Silt fence needs to be reinstalled along the street OR the lot should be stabilized. Landmark Homes was informed to complete by 10/2/18. Not done as of the last inspection. Landmark Homes was reminded on 11/9/18, 1/24/19, 3/16/19, 4/19/19						
STR	Streets	N41d11m34s W96d12m23s	8/28/2008	Active	No			
Current Condition:	Good Condition	- Landmark Homes clea	ned the streets prior to the ins	pection on 11/27/18	3.			
SWPPP Sign	SWPPP Sign	1 sign	10/27/2008	Active	No			
Current Condition:	Good Condition Installed on 10-2	- 27-08 on 156th and Potte	er					
ector Signature:	Van			Reviewed By:	St Su			