E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC
Environmental Services Dept. Manager

**Engineering Answers** 

Environmental Services Dept. Manag	er			Engineering Ans	WEIS	
		E&A - P2008.19	94.000	,	_	
Inspector: Matthew Vanicek					Stage	
		Kiltera Villas @ Waterford				
Project Name:		NER111205 8/10/2019				
For Week Ending:						
Project Location:		y)	68007			
Grading: Sanitary Sewer:	1009					
Storm Sewer:	1009					
Paving:	1009					
Seeding:	1009					
Utilities:	1009					
Overall Development:	979	6				
DAIN FALL AMOUNTO	T	I	l I			
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions		Week	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.78"	07/16/19	90/74 Partly Cloudy			
Wednesday	0.00"					
Thursday Friday	0.00"					
Saturday	0.00"					
outuruuy	0.00				Week	
Sunday:	0.55"	7/21/2019	74/67 Cloudy			
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.01"					
Friday	0.00"					
Saturday	0.00"				Week	
Sunday:	0.07"				week	
Sunday: Monday	0.00"		+			
Tuesday	0.11"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"				Ma a la	
Sunday:	0.00"				Week	
Monday	0.00"		+			
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday Saturday	0.00"					
	0.00				Week	
Sunday:	N/A	N/A				
Monday	N/A	N/A				
Tuesday	N/A	N/A				
Wednesday Thursday	N/A N/A	N/A N/A				
Friday	N/A N/A	N/A				
Saturday	N/A	N/A				
-			'	•		
Completes	None					
Complaints:						
	+		Т	T T		
Construction Sequencing:	I	1				

# Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire Site, grading was completed prior to taking this project over on 8/28/2008. Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as of 6/2011.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :

Entire Site, grading was completed prior to taking this project over on 8/28/2008. Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as of 6/2011.

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation / Sod (8-2008), seed on S.B.'B' (removed basin) (4/09), Lots 11-18 was re-seeded (6/2011) Lots 12, 13, 14 were sodded (10/5/2013).

## Summary Questions:

Are approved entrances and adjacent streets being maintained adequately?

Yes

receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Are

# Checklist Questions:

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly

Yes

Is dust associated with the construction activity adequately controlled on the site?

Yes

#### Comments:

## Comments:

One house is under construction at this time.

# Findings / Corrective Actions (Date):

# Findings / Corrective Actions (Date):

1. Some maintenance is required in the BMP section.

2. Lot 10 should be seeded/stabilized due to being disturbed from construction on lot 9. Landmark Homes was informed to complete by 8/31/18. Not done as of the last inspection. Landmark Homes was reminded on 9/26/18, 11/9/18, 3/16/19, 4/19/19. Landmark Homes repaired the silt fence at the back of the lot and

installed silt fence along the front of the lot prior to the inspection on 5/20/19.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance		
Lot 1 Replat 1	Silt Fence	Lot 21	-	Removed			
Current Condition:	Removed - Landmark Homes sodded the lot prior to the inspection on 8/15/18.						
Lot 2	Silt Fence	Lot 2		Removed			
Current Condition:	Removed - Landmark Homes sodded the lot prior to the inspection on 8/22/18.						
Lot 3	Silt Fence	Lot 3		Removed			
Current Condition:	Removed - Landmark Homes sodded the lot prior to the inspection on 4/27/18.						
Lot 9	Active Lot	Lot 9		Removed			
Current Condition:	Removed - Land	dmark Homes sodded th	e lot prior to the inspection or	n 7/29/18.			
Lot 10	Silt Fence	Lot 10	9/25/2019	Active	No		
Lot 10 Current Condition:	Silt Fence		9/25/2019 aired the silt fence at the back				
-	Silt Fence Good Condition		aired the silt fence at the back				
-	Silt Fence Good Condition	- Landmark Homes repa	aired the silt fence at the back				
Current Condition:	Silt Fence Good Condition front of the lot po	- Landmark Homes repartion to the inspection on Lot 23	aired the silt fence at the back	of the lot and insta			
Current Condition:	Silt Fence Good Condition front of the lot po	- Landmark Homes repartion to the inspection on Lot 23	aired the silt fence at the back 5/20/19.	of the lot and insta			
Current Condition:	Silt Fence Good Condition front of the lot po	- Landmark Homes repartion to the inspection on E Lot 23 dmark Homes sodded th	aired the silt fence at the back 5/20/19.	of the lot and insta			
Current Condition:  Lot 23  Current Condition:	Silt Fence Good Condition front of the lot pi Individual Lot Removed - Land	- Landmark Homes repartor to the inspection on ELDT 23  dmark Homes sodded the N41d11m34s  W96d12m23s	aired the silt fence at the back 5/20/19. e lot prior to the inspection or	Removed 15/20/19. Active	lled silt fence along		
Current Condition:  Lot 23  Current Condition:  STR	Silt Fence Good Condition front of the lot pi Individual Lot Removed - Land	- Landmark Homes repartor to the inspection on ELDT 23  dmark Homes sodded the N41d11m34s  W96d12m23s	aired the silt fence at the back 5/20/19. e lot prior to the inspection or 8/28/2008	Removed 15/20/19. Active	lled silt fence along		
Current Condition:  Lot 23  Current Condition:  STR  Current Condition:	Silt Fence Good Condition front of the lot pi Individual Lot Removed - Land Streets Good Condition	- Landmark Homes repartor to the inspection on ELOT 23  dmark Homes sodded the N41d11m34s W96d12m23s - Landmark Homes clear 1 sign	aired the silt fence at the back 5/20/19.  e lot prior to the inspection or 8/28/2008 and the streets prior to the ins	Removed  5/20/19.  Active spection on 11/27/18	lled silt fence along  No 3.		

Inspector Signature:

Reviewed By:

Get Sol