E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Environmental Services Dept. Manag	er			Liigineein		
	1	E&A - P2008.19	4.000		Stage	
Inspector: Matthew Vanicek						
		3				
Project Name:		Kiltera Villas @ Waterford NER111205 9/14/2019 144th and Ida Streets- Omaha, NE (Douglas County)				
For Week Ending: Project Location:						
Froject Location.		68007				
Grading:	100%					
Sanitary Sewer:	100%					
Storm Sewer:	100%					
Paving:	100%					
Seeding:	100%					
Utilities: Overall Development:	100% 97%					
Overali Development:	97%					
DAIN FALL AMOUNTS		la	W 4 0 FF	1		
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions		Week	
Sunday:	2.14"				vveek	
Monday	0.36"	8/12/2019	84/70 Tstorm			
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.22"					
Friday	0.00"					
Saturday	0.00"					
					Week	
Sunday:	0.00"					
Monday Tuesday	0.00"					
	0.33"					
Wednesday	0.00"					
Thursday						
Friday	0.00"			_		
Saturday	0.00"					
	0.000				Week	
Sunday:	0.00"					
Monday	0.20"					
Tuesday Wednesday	0.00" 0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.18"					
					Week	
Sunday:	0.00"					
Monday	0.00"			1		
Tuesday	0.00"					
Wednesday Thursday	0.00" 0.00"		+	+		
Friday	0.00"		+	+		
Saturday	0.05"		+	+		
					Week	
Sunday:	0.00"					
Monday	0.06"					
Tuesday	0.74"	9/10/2019	86/66 Tstorm			
Wednesday	0.29"					
Thursday	0.01"			-		
Friday Saturday	0.00" 0.04"			+		
Jaturuay	0.04	1		-1		
	None					
Complaints:	INOILE					
. ,						
Construction Sequencing:	•				•	

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire Site, grading was completed prior to taking this project over on 8/28/2008. Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as of 6/2011.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :

Entire Site, grading was completed prior to taking this project over on 8/28/2008. Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as of 6/2011.

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation / Sod (8-2008), seed on S.B.'B' (removed basin) (4/09), Lots 11-18 was re-seeded (6/2011) Lots 12, 13, 14 were sodded (10/5/2013).

Summary Questions:

Are approved entrances and adjacent streets being maintained adequately?

Yes

receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Are

Checklist Questions:

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly

Hette Van

Yes

Is dust associated with the construction activity adequately controlled on the site?

Yes

Comments:

Comments:

The site was inactive during the last inspection. One vacant lot remains.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1. No maintenance is needed at this time.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance			
Lot 1 Replat 1	Silt Fence	Lot 21		Removed				
Current Condition:	Removed - Landmark Homes sodded the lot prior to the inspection on 8/15/18.							
Lot 2	Silt Fence	Lot 2		Removed				
Current Condition:	Removed - Landmark Homes sodded the lot prior to the inspection on 8/22/18.							
Lot 3	Silt Fence	Lot 3		Removed				
Current Condition:	Removed - Landmark Homes sodded the lot prior to the inspection on 4/27/18.							
Lot 9	Active Lot	Lot 9		Removed				
Current Condition:	Removed - Landmark Homes sodded the lot prior to the inspection on 7/29/18.							
Lot 10	Silt Fence	Lot 10	9/25/2019	Active	No			
Current Condition:		Good Condition - Landmark Homes repaired the silt fence at the back of the lot and installed silt fence along the						
	front of the lot pr	front of the lot prior to the inspection on 5/20/19.						
Lot 23	Individual Lot	Lot 23		Removed				
Current Condition:	Removed - Landmark Homes sodded the lot prior to the inspection on 5/20/19.							
		N41d11m34s						
STR	Streets	W96d12m23s	8/28/2008	Active	No			
Current Condition:	Good Condition- Landmark Homes cleaned the streets prior to the inspection on 11/27/18.							
SWPPP Sign	SWPPP Sign	1 sign	10/27/2008	Active	No			
Current Condition:	Good Condition-							
	Installed on 10-27-08 on 156th and Potter							

Inspector Signature:

Reviewed By:

Set Su